ACTIVE	LAST_CHANGED_BY	INSPECT_DT	NOTES	ID	INV_DATE	UNIQUEID	INSPECT_TM	SPP_COM	SPP_BOT	SPACETYPE	MULTI-STEM	DBH	COND	PRIMARYMT	INSPECT	DEFECT	RESIDRISK	FAIL	TARGET	LIKELIHOOD	CONSEQ	RATING	RISKASSESS	ADDRESS	STREET	SIDE	ONSTR	X	Y	LATITUDE	LONGITUDE
1	Greg Baldwin (DRG)	2022/08/02		289	2022/08/02	GrBa20220802072709	7:29:19	Maple, Norway	Acer platanoides	Wooded Space	No	29	Poor	Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Acre Bridge Rd	197443.64	897035.2	42.3238	-71.531
1	Greg Baldwin (DRG)	2022/08/02		299	2022/08/02	GrBa20220802072823	7:29:08	Maple, Norway	Acer platanoides	Wooded Space	No	25	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Acre Bridge Rd	197439.35	897015.1	42.32362	-71.5311
1	Greg Baldwin (DRG)	2022/08/02		309	2022/08/02	GrBa20220802073130	7:33:13	Maple, Norway	Acer platanoides	Wooded Space	No	27	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Medium	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Acre Bridge Rd	197435.67	896996.8	42.32346	-71.5311
1	Greg Baldwin (DRG)	2022/08/18	dbh estimated; poison ivy fruiting bodies; frass; possible	319	2022/08/02	GrBa20220802073456	10:49:59	Tree, Unknown	Unknown Tree	Wooded Space	No	20	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Significant	Low	Yes	1	Acre Bridge Rd	Front	Acre Bridge Rd	197444.44	897081.3	42.32422	-71.531
1	Greg Baldwin (DRG)	2022/08/18	ganoderma	325	2022/08/02	GrBa20220802073958	10:49:59	Maple, Norway	Acer platanoides	Wooded Space	No	34	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Medium	Unlikely	Severe	Low	Yes	1	Acre Bridge Rd	Front	Acre Bridge Rd	197448.1	897111.1	42.32448	-71.531
1	Greg Baldwin (DRG)	2022/08/18	borderline	335	2022/08/02	GrBa20220802074344	10:49:59	Oak, Black	Quercus velutina	Wooded Space	No	8	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	1	Acre Bridge Rd	Front	Acre Bridge Rd	197453.02	897138.1	42.32473	-71.5309
1	Greg Baldwin (DRG)	2022/08/18		349	2022/08/02	GrBa20220802074630	10:49:59	Oak, Black	Quercus velutina	Wooded Space	No	11	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	1	Acre Bridge Rd	Front	Acre Bridge Rd	197462.24	897269.6	42.32591	-71.5308
1	Greg Baldwin (DRG)	2022/08/18	borderline	358	2022/08/02	GrBa20220802074846	10:49:59	Oak, Black	Quercus velutina	Wooded Space	No	11	Fair	Routine Prune	None	Dead And Dying Branches	Low	Improbable	Very Low	Unlikely	Minor	Low	Yes	1	Acre Bridge Rd	Front	Acre Bridge Rd	197467.95	897355.9	42.32669	-71.5307
1	Greg Baldwin (DRG)	2022/08/02		371	2022/08/02	GrBa20220802075637	7:57:29	Oak, Black	Quercus velutina	Wooded Space	No	17	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Acre Bridge Rd	197440.37	897538.9	42.32834	-71.5311
1	Greg Baldwin (DRG)	2022/08/02		382	2022/08/02	GrBa20220802075739	7:59:33	Oak, Black	Quercus velutina	Wooded Space	No	12	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Acre Bridge Rd	197442.79	897534.2	42.32829	-71.531
1	Greg Baldwin (DRG)	2022/08/02	dbh estimated; poison ivy	393	2022/08/02	GrBa20220802075816	7:59:33	Oak, Black	Quercus velutina	Wooded Space	No	19	Fair	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Acre Bridge Rd	197445.84	897529.1	42.32825	-71.531
1	Greg Baldwin (DRG)	2022/08/02	multiple whips	651	2022/08/02	GrBa20220802071706	7:18:10	Elm, American	Ulmus americana	Open Space	Yes	1	Fair	Train	None	Tree Architecture	Low	Improbable	Very Low	Unlikely	Negligible	Low	Yes	265	Boston Rd	Side	Acre Bridge Rd	197478.66	897424.7	42.32731	-71.5306
1	Greg Baldwin (DRG)	2022/08/02		659	2022/08/02	GrBa20220802071924	7:19:51	Elm, American	Ulmus americana	Open Space	No	3	Fair	Train	None	Tree Architecture	Low	Possible	Low	Unlikely	Negligible	Low	Yes	265	Boston Rd	Side	Acre Bridge Rd	197474.86	897324.5	42.32641	-71.5306
1	Greg Baldwin (DRG)	2022/08/02	dbh estimated; poison ivy	669	2022/08/02	GrBa20220802072307	7:29:27	Maple, Norway	Acer platanoides	Wooded Space	No	34	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Medium	Unlikely	Severe	Low	Yes	265	Boston Rd	Side	Acre Bridge Rd	197447.41	897054.8	42.32398	-71.531
1	Greg Baldwin (DRG)	2022/08/05		1045	2022/08/05	GrBa20220805103503	10:35:50	Oak, White	Quercus alba	Wooded Space	No	29	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	21	Highland St	Side	Atwood St	197557.17	890863.1	42.26823	-71.5296
1	Greg Baldwin (DRG)	2022/08/05		1046	2022/08/05	GrBa20220805121817	12:18:37	Maple, Red	Acer rubrum	Open Space	No	9	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	21	Atwood St	Front	Atwood St	197438.36	891278.3	42.27197	-71.5311
1	Greg Baldwin (DRG)	2022/08/05		1047	2022/08/05	GrBa20220805123339	12:34:37	Oak, Black	Quercus velutina	Open Space	No	4	Poor	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	8	Atwood St	Front	Atwood St	197447.35	891428.8	42.27333	-71.5309
1	Greg Baldwin (DRG)	2022/08/05		1050	2022/08/05	GrBa20220805100814	10:08:37	Sassafras	Sassafras albidum	Open Space	No	4	Good	Train	None	Tree Architecture	Low	Improbable	Low	Unlikely	Minor	Low	Yes	48	Atwood St	Front	Atwood St	197535.18	890902.1	42.26859	-71.5299
1	Greg Baldwin (DRG)	2022/08/05	borderline	1053	2022/08/05	GrBa20220805105552	10:56:30	Oak, Black	Quercus velutina	Open Space	No	34	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	35	Atwood St	Front	Atwood St	197452.25	891077.4	42.27016	-71.5309
1	Greg Baldwin (DRG)	2022/08/05	borderline	1055	2022/08/05	GrBa20220805121859	12:19:25	Maple, Japanese	Acer palmatum	Open Space	No	2	Fair	Train	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Negligible	Low	Yes	21	Atwood St	Front	Atwood St	197436.84	891298.5	42.27215	-71.5311
1	Greg Baldwin (DRG)	2022/08/05		1056	2022/08/05	GrBa20220805100913	10:09:46	Locust, Black	Robinia pseudoacacia	Open Space	No	4	Good	Train	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Negligible	Low	Yes	50	Atwood St	Front	Atwood St	197554.18	890878.1	42.26837	-71.5296
1	Greg Baldwin (DRG)	2022/08/05	topped; utility guy line	1057	2022/08/05	GrBa20220805103753	10:39:22	Tree, Unknown	Unknown Tree	Wooded Space	No	26	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Significant	Low	Yes	21	Highland St	Side	Atwood St	197534.41	890887.6	42.26846	-71.5299
1	Greg Baldwin (DRG)	2022/08/05		1060	2022/08/05	GrBa20220805123439	12:35:51	Ash, White	Fraxinus americana	Open Space	Yes	5	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Minor	Low	Yes	8	Atwood St	Front	Atwood St	197447.82	891427.4	42.27332	-71.5309
1	Greg Baldwin (DRG)	2022/08/05		1061	2022/08/05	GrBa20220805095355	9:54:36	Oak, White	Quercus alba	Open Space	No	16	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	20	Atwood St	Front	Atwood St	197456.05	891200	42.27127	-71.5308
1	Greg Baldwin (DRG)	2022/08/05	off ROW	1063	2022/08/05	GrBa20220805105724	10:59:29	Maple, Sugar	Acer saccharum	Open Space	No	13	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Significant	Low	Yes	33	Atwood St	Front	Atwood St	197453.13	891093.7	42.27031	-71.5309
1	Greg Baldwin (DRG)	2022/08/05	borderline	1065	2022/08/05	GrBa20220805123758	12:39:11	Maple, Red	Acer rubrum	Open Space	Yes	25	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	14	Atwood St	Front	Atwood St	197447.19	891309.2	42.27225	-71.5309
1	Greg Baldwin (DRG)	2022/08/05	borderline	1066	2022/08/05	GrBa20220805122042	12:23:10	Pine, Eastern White	Pinus strobus	Wooded Space	No	14	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	9	Atwood St	Front	Atwood St	197437.81	891384	42.27292	-71.5311
1	Greg Baldwin (DRG)	2022/08/05	large leader or limb decay	1068	2022/08/05	GrBa20220805101204	10:12:41	Maple, Red	Acer rubrum	Wooded Space	Yes	8	Poor	Prune	None	Missing Or Decayed Wood	Low	Probable	Low	Unlikely	Minor	Low	Yes	21	Highland St	Side	Atwood St	197614.04	890823.3	42.26788	-71.5289
1	Greg Baldwin (DRG)	2022/08/05		1069	2022/08/05	GrBa20220805095534	9:56:14	Cedar, Northern White	Thuja occidentalis	Open Space	Yes	14	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Minor	Low	Yes	22	Atwood St	Front	Atwood St	197462.8	891135	42.27068	-71.5308
1	Greg Baldwin (DRG)	2022/08/05	borderline	1072	2022/08/05	GrBa20220805104116	10:42:35	Tree, Unknown	Unknown Tree	Wooded Space	No	28	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Significant	Low	Yes	21	Highland St	Side	Atwood St	197528.3	890893.3	42.26851	-71.53
1	Greg Baldwin (DRG)	2022/08/05		1073	2022/08/05	GrBa20220805110021	11:02:19	Ash, White	Fraxinus americana	Wooded Space	Yes	10	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Significant	Low	Yes	27	Atwood St	Front	Atwood St	197453.86	891138.7	42.27072	-71.5309
1	Greg Baldwin (DRG)	2022/08/05		1075	2022/08/05	GrBa20220805122339	12:24:16	Cedar, Northern White	Thuja occidentalis	Open Space	No	1	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	5	Atwood St	Front	Atwood St	197438.29	891421.2	42.27326	-71.5311
1	Greg Baldwin (DRG)	2022/08/05	borderline; leaning	1076	2022/08/05	GrBa20220805124014	12:41:34	Maple, Red	Acer rubrum	Open Space	Yes	13	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Minor	Low	Yes	25	Atwood St	Front	Atwood St	197444.45	891212.1	42.27138	-71.531
1	Greg Baldwin (DRG)	2022/08/05		1079	2022/08/05	GrBa20220805110239	11:02:58	Hickory, Pignut	Carya glabra	Wooded Space	No	9	Fair	Routine Prune	None	Dead And Dying Branches	Low	Improbable	Low	Unlikely	Minor	Low	Yes	27	Atwood St	Front	Atwood St	197452.16	891158.1	42.27089	-71.5309
1	Greg Baldwin (DRG)	2022/08/05		1080	2022/08/05	GrBa20220805101333	10:14:40	Oak, Scarlet	Quercus coccinea	Wooded Space	No	12	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Minor	Low	Yes	21	Highland St	Side	Atwood St	197608.57	890826.4	42.2679	-71.529
1	Greg Baldwin (DRG)	2022/08/18	pole number 11	1081	2022/08/05	GrBa20220805095704	12:14:11	Hickory, Pignut	Carya glabra	Wooded Space	No	16	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	24	Atwood St	Front	Atwood St	197463.97	891128.1	42.27062	-71.5307
1	Greg Baldwin (DRG)	2022/08/05	off ROW; pole number 15	1084	2022/08/05	GrBa20220805104336	10:46:13	Tree, Unknown	Unknown Tree	Wooded Space	No	13	Dead	Remove	None	No Significant Defect	None	Possible	High	Somewhat Likely	Minor	Low	Yes	21	Highland St	Side	Atwood St	197509.07	890920.2	42.26875	-71.5302
1	Greg Baldwin (DRG)	2022/08/18		1087	2022/08/05	GrBa20220805122500	12:13:42	Oak, White	Quercus alba	Open Space	No	25	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	3	Atwood St	Front	Atwood St	197439.54	891457.2	42.27358	-71.531
1	Greg Baldwin (DRG)	2022/08/05		1089	2022/08/05	GrBa20220805110347	11:04:18	Hickory, Pignut	Carya glabra	Wooded Space	No	9	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	27	Atwood St	Front	Atwood St	197449.52	891177.3	42.27106	-71.5309
1	Greg Baldwin (DRG)	2022/08/05		1090	2022/08/05	GrBa20220805101528	10:16:49	Oak	Quercus species	Wooded Space	No	13	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Significant	Low	Yes	21	Highland St	Side	Atwood St	197606.63	890827.3	42.26791	-71.529
1	Greg Baldwin (DRG)	2022/08/05	borderline	1092	2022/08/05	GrBa20220805100059	10:01:30	Birch, Paper	Betula papyrifera	Open Space	No	1	Good	Train	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Very Low	Unlikely	Negligible	Low	Yes	40	Atwood St	Front	Atwood St	197462.81	891012	42.26958	-71.5308
1	Greg Baldwin (DRG)	2022/08/05	Co-dominants	1093	2022/08/05	GrBa20220805104906	10:50:07	Oak, Northern Red	Quercus rubra	Open Space	Yes	25	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	39	Atwood St	Front	Atwood St	197465.57	890986.3	42.26934	-71.5307
1	Greg Baldwin (DRG)	2022/08/05		1095	2022/08/05	GrBa20220805101709	10:17:30	Ash, White	Fraxinus americana	Wooded Space	No	8	Good	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Minor	Low	Yes	21	Highland St	Side	Atwood St	197603.75	890829.7	42.26793	-71.529
1	Greg Baldwin (DRG)	2022/08/18	borderline	1099	2022/08/05	GrBa20220805122704	10:21:42	Hickory, Pignut	Carya glabra	Open Space	No	16	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Minor	Low	Yes	46	Richards Rd	Side	Atwood St	197445.1	891549.1	42.27441	-71.531
1	Greg Baldwin (DRG)	2022/08/05		1100	2022/08/05	GrBa20220805110424	11:05:06	Maple, Red	Acer rubrum	Wooded Space	No	11	Good	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Minor	Low	Yes	27	Atwood St	Front	Atwood St	197449.05	891180.7	42.27109	-71.5309

1	Greg Baldwin (DRG)	2022/08/05	borderline	1101	2022/08/05	GrBa20220805105127	10:51:48	Oak, Scarlet Pine, Eastern	Quercus coccinea	Open Space	No	33	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	37	Atwood St	Front	Atwood St	197451.52	891014	42.26959	-71.5309
1	Greg Baldwin (DRG)	2022/08/05		1103	2022/08/05	GrBa20220805100226	10:02:51	White	Pinus strobus	Open Space	No	6	Fair	Routine Prune	None	Root Problems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	42	Atwood St	Front	Atwood St	197483.85	890973.4	42.26923	-71.5305
1	Greg Baldwin (DRG)	2022/08/18	borderline	1105	2022/08/05	GrBa20220805122735	10:21:42	Hickory, Pignut	Carya glabra	Open Space	No	16	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	46	Richards Rd	Side	Atwood St	197444.99	891552.3	42.27444	-71.531
1	Greg Baldwin (DRG)	2022/08/05	galls	1107	2022/08/05	GrBa20220805105239	10:53:19	Oak, Black	Quercus velutina	Open Space	No	2	Fair	Train	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	37	Atwood St	Front	Atwood St	197450.82	891034.8	42.26978	-71.5309
1	Greg Baldwin (DRG)	2022/08/05	borderline	1108	2022/08/05	GrBa20220805101747	10:18:43	Oak, Scarlet	Quercus coccinea	Wooded Space	No	9	Fair	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	21	Highland St	Side	Atwood St	197600.87	890830.8	42.26794	-71.5291
1	Greg Baldwin (DRG)	2022/08/05		1111	2022/08/05	GrBa20220805100302	10:04:12	Oak, Black	Quercus velutina	Open Space	No	23	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	42	Atwood St	Front	Atwood St	197486.38	890970.7	42.2692	-71.5305
1	Greg Baldwin (DRG)	2022/08/05	fruiting bodies	1112	2022/08/05	GrBa20220805121319	12:14:53	Oak, Black Pine, Eastern	Quercus velutina	Open Space	No	23	Poor	Prune	Insect/Dis	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Significant	Low	Yes	23	Atwood St	Front	Atwood St	197442	891242.7	42.27165	-71.531
1	Greg Baldwin (DRG)	2022/08/05	borderline	1115	2022/08/05	GrBa20220805122832	12:29:13	White	Pinus strobus	Open Space	No	6	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Very Low	Unlikely	Negligible	Low	Yes	2	Atwood St	Front	Atwood St	197456.99	891561.4	42.27452	-71.5308
1	Greg Baldwin (DRG)	2022/08/05		1116	2022/08/05	GrBa20220805105322	10:54:05	Hickory, Pignut	Carya glabra	Open Space	No	3	Good	Train	None	Dead And Dying Branches	Low	Improbable	Very Low	Unlikely	Negligible	Low	Yes	37	Atwood St	Front	Atwood St	197450.82	891036.7	42.2698	-71.5309
1	Greg Baldwin (DRG)	2022/08/05	tag number 22	1118	2022/08/05	GrBa20220805101955	10:31:56	Oak, Black	Quercus velutina	Wooded Space	No	26	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Low	Unlikely	Severe	Low	Yes	21	Highland St	Side	Atwood St	197592.81	890837.8	42.26801	-71.5292
1	Greg Baldwin (DRG)	2022/08/05		1120	2022/08/05	GrBa20220805121523	12:16:20	Oak, Black	Quercus velutina	Open Space	Yes	20	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	23	Atwood St	Front	Atwood St	197441.07	891251	42.27173	-71.531
1	Greg Baldwin (DRG)	2022/08/05		1122	2022/08/05	GrBa20220805100501	10:05:24	Maple, Sugar	Acer saccharum	Open Space	Yes	5	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	42	Atwood St	Front	Atwood St	197487.5	890967.5	42.26917	-71.5305
1	Greg Baldwin (DRG)	2022/08/05		1125	2022/08/05	GrBa20220805105410	10:54:26	Hickory, Pignut Pine, Eastern	Carya glabra	Open Space	No	3	Good	Train	None	Dead And Dying Branches	Low	Improbable	Very Low	Unlikely	Negligible	Low	Yes	37	Atwood St	Front	Atwood St	197450.29	891039.5	42.26982	-71.5309
1	Greg Baldwin (DRG)	2022/08/05	borderline	1126	2022/08/05	GrBa20220805123159	12:33:34	White	Pinus strobus	Open Space	No	6	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Minor	Low	Yes	6	Atwood St	Front	Atwood St	197447.59	891431.3	42.27335	-71.5309
1	Greg Baldwin (DRG)	2022/08/05		1128	2022/08/05	GrBa20220805121711	12:17:43	Maple, Red	Acer rubrum	Open Space	No	18	Poor	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	21	Atwood St	Front	Atwood St	197438.7	891275.1	42.27194	-71.531
1	Greg Baldwin (DRG)	2022/08/05	Co-dominants; trunk wounds	1129	2022/08/05	GrBa20220805103254	10:33:46	Oak, Scarlet	Quercus coccinea	Wooded Space	No	27	Poor	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	21	Highland St	Side	Atwood St	197584.75	890843.9	42.26806	-71.5293
1	Greg Baldwin (DRG)	2022/08/05		1133	2022/08/05	GrBa20220805100704	10:07:57	Oak, Black	Quercus velutina	Open Space	No	28	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	46	Atwood St	Front	Atwood St	197531.01	890908.3	42.26864	-71.5299
1	Greg Baldwin (DRG)	2022/08/18		681	2022/08/03	GrBa20220803113833	10:21:42	Oak, Black	Quercus velutina	Open Space	Yes	13	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	14	Ward Rd	Side	Bigelow Rd	194166.66	895241.7	42.30764	-71.5708
1	Greg Baldwin (DRG)	2022/08/03		682	2022/08/03	GrBa20220803121708	12:17:38	Maple, Red	Acer rubrum	Open Space	No	2	Fair	Train	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	46	Bigelow Rd	Front	Bigelow Rd	193440.94	895017.3	42.30561	-71.5796
1	Greg Baldwin (DRG)	2022/08/03		690	2022/08/03	GrBa20220803121819	12:18:53	Oak, Black	Quercus velutina	Open Space	No	10	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	46	Bigelow Rd	Front	Bigelow Rd	193437.06	895012.9	42.30557	-71.5796
1	Greg Baldwin (DRG)	2022/08/18		691	2022/08/03	GrBa20220803113922	10:21:42	Oak, White	Quercus alba	Open Space	Yes	22	Good	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	14	Ward Rd	Side	Bigelow Rd	194163.19	895243.9	42.30766	-71.5708
1	Greg Baldwin (DRG)	2022/08/03	borderline	699	2022/08/03	GrBa20220803114240	11:43:53	Maple, Red Oak, Swamp	Acer rubrum	Open Space	No	23	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	12	Bigelow Rd	Front	Bigelow Rd	193992.13	895328.2	42.30841	-71.5729
1	Greg Baldwin (DRG)	2022/08/03		714	2022/08/03	GrBa20220803114421	11:44:53	White	Quercus bicolor	Open Space	No	18	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	12	Bigelow Rd	Front	Bigelow Rd	193981.19	895325.4	42.30839	-71.573
1	Greg Baldwin (DRG)	2022/08/03		723	2022/08/03	GrBa20220803114625	11:47:43	Elm, American	Ulmus americana	Wooded Space	No	12	Dead	Remove	None	No Significant Defect	None	Possible	High	Somewhat Likely	Significant	Moderate	Yes	18	Bigelow Rd	Front	Bigelow Rd	193925.02	895289.3	42.30806	-71.5737
1	Greg Baldwin (DRG)	2022/08/03		733	2022/08/03	GrBa20220803114800	11:48:32	Maple, Red	Acer rubrum	Wooded Space	No	14	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	18	Bigelow Rd	Front	Bigelow Rd	193922.96	895288.5	42.30806	-71.5737
1	Moriah Day (DRG)	2022/08/23	pole number 14	746	2022/08/03	GrBa20220803105400	10:29:10	Elm, American	Ulmus americana	Wooded Space	No	15	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Significant	Low	Yes	47	Bigelow Rd	Front	Bigelow Rd	193432.82	895019.3	42.30563	-71.5797
1	Greg Baldwin (DRG)	2022/08/03		754	2022/08/03	GrBa20220803115144	11:52:20	Redcedar, Eastern	Juniperus virginiana	Open Space	No	7	Good	Routine Prune	None	Dead And Dying Branches	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	22	Bigelow Rd	Front	Bigelow Rd	193862.38	895248.8	42.3077	-71.5744
1	Greg Baldwin (DRG)	2022/08/18	pole number 14	756	2022/08/03	GrBa20220803105731	12:49:16	Maple, Red	Acer rubrum	Wooded Space	Yes	16	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	45	Bigelow Rd	Front	Bigelow Rd	193464.25	895048.4	42.30589	-71.5793
1	Greg Baldwin (DRG)	2022/08/03	borderline pole number 14; borderline; dbh	765	2022/08/03	GrBa20220803115313	11:53:43	Spruce, Blue	Picea pungens	Open Space	No	12	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	28	Bigelow Rd	Front	Bigelow Rd	193830.14	895224.5	42.30748	-71.5748
1	Greg Baldwin (DRG)	2022/08/18	estimated; poison ivy	768	2022/08/03	GrBa20220803105827	10:33:34	Oak, Black	Quercus velutina	Wooded Space	No	14	Fair	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	45	Bigelow Rd	Front	Bigelow Rd	193479.78	895061.3	42.30601	-71.5791
1	Greg Baldwin (DRG)	2022/08/03	borderline	774	2022/08/03	GrBa20220803115405	11:54:29	Apple	Malus species	Open Space	No	16	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	30	Bigelow Rd	Front	Bigelow Rd	193805.32	895208.4	42.30733	-71.5751
1	Greg Baldwin (DRG)	2022/08/18	pole number 13; utility pruned pole number 10; utility pruned;	778	2022/08/03	GrBa20220803110033	10:32:49	Oak, Black	Quercus velutina	Wooded Space	No	12	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Significant	Low	Yes	43	Bigelow Rd	Front	Bigelow Rd	193519.31	895083.7	42.30621	-71.5786
1	Greg Baldwin (DRG)	2022/08/18	borderline	784	2022/08/03	GrBa20220803110322	10:32:03	Elm, American	Ulmus americana	Wooded Space	No	8	Poor	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Minor	Low	Yes	37	Bigelow Rd	Front	Bigelow Rd	193650.06	895132.8	42.30665	-71.577
1	Greg Baldwin (DRG)	2022/08/03	topped	788	2022/08/03	GrBa20220803115454	11:55:33	Oak, Black	Quercus velutina	Open Space	No	10	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	30	Bigelow Rd	Front	Bigelow Rd	193794.78	895198.3	42.30724	-71.5753
1	Greg Baldwin (DRG)	2022/08/03	borderline; prune for clearance	794	2022/08/03	GrBa20220803115600	11:57:32	Plum	Prunus species	Open Space	Yes	14	Good	Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Severe	Low	Yes	32	Bigelow Rd	Front	Bigelow Rd	193763.13	895173.4	42.30702	-71.5756
1	Greg Baldwin (DRG)	2022/08/18	pole number 9; borderline	797	2022/08/03	GrBa20220803110505	10:32:03	Maple, Red	Acer rubrum	Wooded Space	No	8	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Minor	Low	Yes	37	Bigelow Rd	Front	Bigelow Rd	193674.4	895140.5	42.30672	-71.5767
1	Greg Baldwin (DRG)	2022/08/03		804	2022/08/03	GrBa20220803115757	11:58:38	Hickory, Pignut	Carya glabra	Open Space	Yes	1	Fair	Train	None	Tree Architecture	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	34	Bigelow Rd	Front	Bigelow Rd	193734.9	895156.2	42.30686	-71.576
1	Greg Baldwin (DRG)	2022/08/18	pole number 9; borderline	805	2022/08/03	GrBa20220803110644	10:32:03	Maple, Red Lilac, Japanese	Acer rubrum	Wooded Space	No	10	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	37	Bigelow Rd	Front	Bigelow Rd	193652.94	895134.6	42.30667	-71.577
1	Greg Baldwin (DRG)	2022/08/03	borderline	817	2022/08/03	GrBa20220803115926	11:59:50	Tree	Syringa reticulata	Open Space	No	1	Good	Train	None	No Significant Defect	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	34	Bigelow Rd	Front	Bigelow Rd	193721.72	895147.3	42.30678	-71.5761
1	Greg Baldwin (DRG)	2022/08/18	pole number 9; borderline	819	2022/08/03	GrBa20220803110732	10:32:03	Maple, Red Dogwood,	Acer rubrum	Wooded Space	No	9	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	37	Bigelow Rd	Front	Bigelow Rd	193688.64	895145.4	42.30677	-71.5765
1	Greg Baldwin (DRG)	2022/08/26	borderline	827	2022/08/03	GrBa20220803120013	14:51:42	Flowering	Cornus florida	Open Space	No	1	Fair	Train	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	34	Bigelow Rd	Front	Bigelow Rd	193713.9	895142.9	42.30674	-71.5762
1	Greg Baldwin (DRG)	2022/08/18	pole number 9; borderline	829	2022/08/03	GrBa20220803110842	10:30:53	Maple, Red	Acer rubrum	Wooded Space	No	9	Good	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Minor	Low	Yes	35	Bigelow Rd	Front	Bigelow Rd	193701.4	895149.9	42.30681	-71.5764
1	Greg Baldwin (DRG)	2022/08/03	trunk decay	835	2022/08/03	GrBa20220803120218	12:03:07	Hickory, Pignut	Carya glabra	Open Space	No	19	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	38	Bigelow Rd	Front	Bigelow Rd	193623.39	895110.9	42.30646	-71.5773
1	Greg Baldwin (DRG)	2022/08/18	pole number 8; borderline	839	2022/08/03	GrBa20220803111026	10:30:26	Maple, Sugar	Acer saccharum	Wooded Space	Yes	8	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Minor	Low	Yes	35	Bigelow Rd	Front	Bigelow Rd	193727.57	895163.2	42.30693	-71.5761
1	Greg Baldwin (DRG)	2022/08/03		845	2022/08/03	GrBa20220803120310	12:03:40	Oak, White	Quercus alba	Open Space	No	24	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	38	Bigelow Rd	Front	Bigelow Rd	193620.81	895110.4	42.30645	-71.5774

1	Greg Baldwin (DRG)	2022/08/03		849	2022/08/03	GrBa20220803111345	11:14:45	Redcedar, Eastern	Juniperus virginiana	Open Space	No	18	Fair	Routine Prune	None	Dead And Dying Branches	Low	Improbable	Low	Unlikely	Minor	Low	Yes	15	Bigelow Rd	Front	Bigelow Rd	193835.81	895241	42.30763	-71.5748
1	Greg Baldwin (DRG)	2022/08/18	borderline; pole number 3	857	2022/08/03	GrBa20220803112025	10:29:06	Oak, White	Quercus alba	Wooded Space	No	19	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Significant	Low	Yes	11	Bigelow Rd	Front	Bigelow Rd	194007.26	895340.2	42.30852	-71.5727
1	Greg Baldwin (DRG)	2022/08/03		858	2022/08/03	GrBa20220803120408	12:04:34	Oak, White	Quercus alba	Open Space	No	29	Fair	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	40	Bigelow Rd	Front	Bigelow Rd	193604.16	895104.4	42.3064	-71.5776
1	Greg Baldwin (DRG)	2022/08/03	borderline	868	2022/08/03	GrBa20220803120540	12:06:07	Oak, White	Quercus alba	Open Space	No	15	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	40	Bigelow Rd	Front	Bigelow Rd	193575.82	895093.5	42.3063	-71.5779
1	Greg Baldwin (DRG)	2022/08/18	borderline; pole number 3	869	2022/08/03	GrBa20220803112156	10:29:06	Maple, Red	Acer rubrum	Wooded Space	No	21	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	11	Bigelow Rd	Front	Bigelow Rd	194003.03	895340.4	42.30852	-71.5727
1	Greg Baldwin (DRG)	2022/08/03		877	2022/08/03	GrBa20220803120643	12:07:05	Oak, White	Quercus alba	Wooded Space	No	22	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	42	Bigelow Rd	Front	Bigelow Rd	193565.41	895090.4	42.30627	-71.578
1	Greg Baldwin (DRG)	2022/08/18	borderline; pole number 3	879	2022/08/03	GrBa20220803112428	10:29:06	Plum	Prunus species	Open Space	No	18	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	11	Bigelow Rd	Front	Bigelow Rd	193977.04	895335.6	42.30848	-71.5731
1	Greg Baldwin (DRG)	2022/08/03		887	2022/08/03	GrBa20220803120915	12:10:38	Oak, Black	Quercus velutina	Open Space	No	28	Fair	Prune	None	Broken And/Or Hanging Branches	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	44	Bigelow Rd	Front	Bigelow Rd	193475.83	895045.1	42.30586	-71.5791
1	Greg Baldwin (DRG)	2022/08/03	borderline; pole number 3; topped for utility	890	2022/08/03	GrBa20220803112736	11:28:02	Maple, Red	Acer rubrum	Wooded Space	No	18	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	7	Bigelow Rd	Front	Bigelow Rd	194035.06	895332.4	42.30845	-71.5723
1	Greg Baldwin (DRG)	2022/08/03	borderline	894	2022/08/03	GrBa20220803121117	12:13:48	Oak, Black	Quercus velutina	Wooded Space	No	10	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	46	Bigelow Rd	Front	Bigelow Rd	193466.77	895036.7	42.30579	-71.5792
1	Greg Baldwin (DRG)	2022/08/03	borderline; pole number 3; utility pruned	900	2022/08/03	GrBa20220803112826	11:29:12	Maple, Red	Acer rubrum	Wooded Space	No	13	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	7	Bigelow Rd	Front	Bigelow Rd	194037.12	895331.1	42.30844	-71.5723
1	Greg Baldwin (DRG)	2022/08/03		904	2022/08/03	GrBa20220803121429	12:14:52	Oak, Black	Quercus velutina	Open Space	No	9	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	46	Bigelow Rd	Front	Bigelow Rd	193450.42	895025.5	42.30569	-71.5794
1	Greg Baldwin (DRG)	2022/08/03	borderline; pole number 2; utility pruned	910	2022/08/03	GrBa20220803113019	11:30:59	Maple, Red	Acer rubrum	Wooded Space	No	11	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	5	Bigelow Rd	Front	Bigelow Rd	194054.51	895320.9	42.30835	-71.5721
1	Greg Baldwin (DRG)	2022/08/03		913	2022/08/03	GrBa20220803113348	11:35:24	Buckthorn, Glossy	Rhamnus frangula	Open Space	Yes	7	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	20	Ward Rd	Side	Bigelow Rd	194221.02	895220.1	42.30744	-71.5701
1	Greg Baldwin (DRG)	2022/08/03		920	2022/08/03	GrBa20220803121454	12:15:10	Oak, Black	Quercus velutina	Open Space	No	6	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	46	Bigelow Rd	Front	Bigelow Rd	193449.36	895024.7	42.30568	-71.5794
1	Greg Baldwin (DRG)	2022/08/03		924	2022/08/03	GrBa20220803113642	11:37:13	Oak, White	Quercus alba	Open Space	No	30	Good	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	2	Bigelow Rd	Front	Bigelow Rd	194199.04	895222.8	42.30747	-71.5704
1	Greg Baldwin (DRG)	2022/08/03	borderline	930	2022/08/03	GrBa20220803121522	12:16:13	Aspen, Bigtooth	Populus grandidentata	Open Space	No	11	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	46	Bigelow Rd	Front	Bigelow Rd	193451.18	895023.3	42.30566	-71.5794
1	Greg Baldwin (DRG)	2022/08/03		934	2022/08/03	GrBa20220803113752	11:38:31	Oak, Black	Quercus velutina	Open Space	Yes	14	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	2	Bigelow Rd	Front	Bigelow Rd	194169.13	895240.7	42.30763	-71.5707
1	Greg Baldwin (DRG)	2022/08/03		938	2022/08/03	GrBa20220803121646	12:17:05	Oak, Black	Quercus velutina	Open Space	No	8	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	46	Bigelow Rd	Front	Bigelow Rd	193444.06	895020.2	42.30564	-71.5795
1	Greg Baldwin (DRG)	2022/08/05		1048	2022/08/05	GrBa20220805132158	13:22:24	Maple, Norway	Acer platanoides	Open Space	No	25	Poor	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	45	Boston Rd	Front	Boston Rd	198435.36	894876.4	42.30437	-71.519
1	Greg Baldwin (DRG)	2022/08/05	topped	1051	2022/08/05	GrBa20220805133201	13:32:36	Plum	Prunus species	Open Space	No	13	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	35	Boston Rd	Front	Boston Rd	198266.57	894856.6	42.30419	-71.521
1	Greg Baldwin (DRG)	2022/08/05	Co-dominants	1059	2022/08/05	GrBa20220805132233	13:50:41	Maple, Silver	Acer saccharinum	Open Space	No	33	Fair	Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	45	Boston Rd	Front	Boston Rd	198425.6	894875.6	42.30436	-71.5191
1	Greg Baldwin (DRG)	2022/08/05		1062	2022/08/05	GrBa20220805133258	13:34:10	Oak, Pin	Quercus palustris	Open Space	No	23	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	35	Boston Rd	Front	Boston Rd	198245.4	894859.6	42.30422	-71.5213
1	Greg Baldwin (DRG)	2022/08/05		1067	2022/08/05	GrBa20220805132346	13:24:29	Maple, Silver	Acer saccharinum	Open Space	No	10	Poor	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	45	Boston Rd	Front	Boston Rd	198419.43	894875	42.30436	-71.5192
1	Greg Baldwin (DRG)	2022/08/18	pole number 127	1070	2022/08/05	GrBa20220805133748	11:53:33	Maple, Norway	Acer platanoides	Wooded Space	No	13	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	11	Boston Rd	Front	Boston Rd	198098.26	895023.9	42.3057	-71.5231
1	Greg Baldwin (DRG)	2022/08/05		1077	2022/08/05	GrBa20220805132451	13:26:21	Oak, Scarlet	Quercus coccinea	Open Space	No	33	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	41	Boston Rd	Front	Boston Rd	198357.81	894862.2	42.30424	-71.5199
1	Greg Baldwin (DRG)	2022/08/18	pole number 127	1078	2022/08/05	GrBa20220805133916	11:53:33	Maple, Norway	Acer platanoides	Wooded Space	No	18	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	11	Boston Rd	Front	Boston Rd	198096.44	895028.9	42.30574	-71.5231
1	Greg Baldwin (DRG)	2022/08/05		1085	2022/08/05	GrBa20220805132717	13:27:49	Oak, White	Quercus alba	Open Space	No	37	Good	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	39	Boston Rd	Front	Boston Rd	198325.77	894856.8	42.30419	-71.5203
1	Greg Baldwin (DRG)	2022/08/18		1086	2022/08/05	GrBa20220805130252	11:31:00	Maple, Norway	Acer platanoides	Wooded Space	No	10	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	135	Boston Rd	Front	Boston Rd	199268.13	894611.2	42.30198	-71.5089
1	Greg Baldwin (DRG)	2022/08/18	pole number 126	1088	2022/08/05	GrBa20220805134102	11:53:33	Pine	Pinus species	Wooded Space	No	19	Dead	Remove	None	No Significant Defect	None	Possible	High	Somewhat Likely	Significant	Moderate	Yes	11	Boston Rd	Front	Boston Rd	198086.39	895044.7	42.30588	-71.5232
1	Greg Baldwin (DRG)	2022/08/05		1096	2022/08/05	GrBa20220805132829	13:29:20	Oak, Black	Quercus velutina	Open Space	No	43	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	39	Boston Rd	Front	Boston Rd	198311.02	894855.7	42.30418	-71.5205
1	Greg Baldwin (DRG)	2022/08/18	pole number 149S; off ROW	1097	2022/08/05	GrBa20220805135425	11:35:31	Maple, Sugar	Acer saccharum	Wooded Space	No	24	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Low	Unlikely	Severe	Low	Yes	50	Boston Rd	Front	Boston Rd	198727.05	894895	42.30454	-71.5154
1	Greg Baldwin (DRG)	2022/08/05	borderline	1098	2022/08/05	GrBa20220805131348	13:14:41	Maple, Red	Acer rubrum	Open Space	No	13	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	17	White Bagley Rd	Side	Boston Rd	198651.24	894873.5	42.30434	-71.5164
1	Greg Baldwin (DRG)	2022/08/05	borderline	1106	2022/08/05	GrBa20220805140744	14:10:03	Oak, Black	Quercus velutina	Wooded Space	No	29	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Significant	Low	Yes	2	Meadow Ln	Side	Boston Rd	199282.44	894627	42.30212	-71.5087
1	Greg Baldwin (DRG)	2022/08/05	trunk wounds	1109	2022/08/05	GrBa20220805132924	13:30:20	Maple, Norway	Acer platanoides	Open Space	No	14	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	37	Boston Rd	Front	Boston Rd	198297.61	894855.6	42.30418	-71.5206
1	Greg Baldwin (DRG)	2022/08/05	borderline	1110	2022/08/05	GrBa20220805131727	13:17:56	Catalpa, Northern	Catalpa speciosa	Wooded Space	Yes	19	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	51	Boston Rd	Front	Boston Rd	198519.43	894871.6	42.30432	-71.518
1	Greg Baldwin (DRG)	2022/08/05	borderline	1119	2022/08/05	GrBa20220805131941	13:20:12	Maple, Norway	Acer platanoides	Wooded Space	No	13	Fair	Routine Prune	None	Cracks	Low	Improbable	Low	Unlikely	Significant	Low	Yes	51	Boston Rd	Front	Boston Rd	198507.56	894873	42.30434	-71.5181
1	Greg Baldwin (DRG)	2022/08/05		1123	2022/08/05	GrBa20220805133043	13:30:56	Maple, Norway	Acer platanoides	Open Space	No	13	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	37	Boston Rd	Front	Boston Rd	198287.44	894854.1	42.30417	-71.5208
1	Greg Baldwin (DRG)	2022/08/05	borderline	1130	2022/08/05	GrBa20220805132017	13:20:51	Cottonwood, Eastern	Populus deltoides	Wooded Space	No	27	Poor	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Severe	Low	Yes	49	Boston Rd	Front	Boston Rd	198505.03	894873.5	42.30434	-71.5181
1	Greg Baldwin (DRG)	2022/08/05		1131	2022/08/05	GrBa20220805133123	13:31:39	Maple, Norway	Acer platanoides	Open Space	No	11	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	35	Boston Rd	Front	Boston Rd	198273.09	894855.5	42.30418	-71.5209
1	Greg Baldwin (DRG)	2022/08/18		1049	2022/08/05	GrBa20220805143025	10:19:47	Oak, White	Quercus alba	Open Space	No	51	Fair	Prune	None	Dead And Dying Branches	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	19	Clemmons St	Front	Clemmons St	200734.85	895594.7	42.31084	-71.4911
1	Greg Baldwin (DRG)	2022/08/18	borderline	1058	2022/08/05	GrBa20220805143254	13:04:43	Maple, Sugar	Acer saccharum	Wooded Space	No	12	Poor	Prune	None	Dead And Dying Branches	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	15	Clemmons St	Front	Clemmons St	200792.04	895560.7	42.31053	-71.4904
1	Greg Baldwin (DRG)	2022/08/05	utility pruned	1071	2022/08/05	GrBa20220805143408	14:34:40	Maple, Sugar	Acer saccharum	Wooded Space	No	14	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Minor	Low	Yes	15	Clemmons St	Front	Clemmons St	200798.75	895554.9	42.31048	-71.4903

1	Greg Baldwin (DRG)	2022/08/05	utility pruned	1082	2022/08/05	GrBa20220805143526	14:36	Hickory, Pignut	Carya glabra	Wooded Space	No	22	Poor	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	15	Clemmons St	Front	Clemmons St	200803.1	895553.2	42.31046	-71.4903
1	Greg Baldwin (DRG)	2022/08/05	dbh estimated; poison ivy	1091	2022/08/05	GrBa20220805143628	14:38:00	Oak, Black	Quercus velutina	Wooded Space	No	35	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	11	Clemmons St	Front	Clemmons St	200813.15	895548.4	42.31042	-71.4901
1	Greg Baldwin (DRG)	2022/08/05		1102	2022/08/05	GrBa20220805143845	14:39:10	Maple, Sugar	Acer saccharum	Wooded Space	No	12	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	11	Clemmons St	Front	Clemmons St	200818.32	895545	42.31039	-71.4901
1	Greg Baldwin (DRG)	2022/08/05	dbh estimated; poison ivy	1113	2022/08/05	GrBa20220805143919	14:39:42	Hickory, Pignut	Carya glabra	Wooded Space	No	14	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Significant	Low	Yes	11	Clemmons St	Front	Clemmons St	200819.85	895544.2	42.31038	-71.4901
1	Greg Baldwin (DRG)	2022/08/05		1124	2022/08/05	GrBa20220805144007	14:40:23	Hickory, Pignut	Carya glabra	Wooded Space	No	13	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	11	Clemmons St	Front	Clemmons St	200835.78	895534.1	42.31029	-71.4899
1	Greg Baldwin (DRG)	2022/08/05		1132	2022/08/05	GrBa20220805142653	14:28:41	Oak, Black	Quercus velutina	Open Space	No	46	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	19	Clemmons St	Front	Clemmons St	200676.43	895614.5	42.31102	-71.4918
1	Greg Baldwin (DRG)	2022/08/05		1134	2022/08/05	GrBa20220805144058	14:41:19	Oak, Black	Quercus velutina	Wooded Space	No	39	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	11	Clemmons St	Front	Clemmons St	200841.78	895529.6	42.31025	-71.4898
1	Greg Baldwin (DRG)	2022/08/05	dbh estimated; poison ivy	1135	2022/08/05	GrBa20220805144137	14:42:16	Hickory, Pignut	Carya glabra	Wooded Space	No	23	Fair	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	11	Clemmons St	Front	Clemmons St	200849.3	895525.4	42.31021	-71.4897
1	Ashley Casello (DRG)	2022/08/26	dbh estimated; poison ivy	1136	2022/08/05	GrBa20220805144222	9:23:22	Oak, Black	Quercus velutina	Wooded Space	No	25	Poor	Prune	None	Dead And Dying Branches	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	11	Clemmons St	Front	Clemmons St	200854.01	895521.8	42.31018	-71.4896
1	Greg Baldwin (DRG)	2022/08/05	dbh estimated; poison ivy	1137	2022/08/05	GrBa20220805144320	14:45:07	Hickory, Shagbark	Carya ovata	Wooded Space	No	8	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	11	Clemmons St	Front	Clemmons St	200856.18	895520.6	42.31017	-71.4896
1	Greg Baldwin (DRG)	2022/08/05	borderline	1138	2022/08/05	GrBa20220805144422	14:44:59	Hickory, Pignut	Carya glabra	Wooded Space	No	9	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	11	Clemmons St	Front	Clemmons St	200861.24	895518.6	42.31015	-71.4896
1	Greg Baldwin (DRG)	2022/08/05	dbh estimated; poison ivy	1139	2022/08/05	GrBa20220805144551	14:47:09	Oak, Scarlet	Quercus coccinea	Wooded Space	Yes	25	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	High	Somewhat Likely	Significant	Moderate	Yes	9	Clemmons St	Front	Clemmons St	200869.35	895512.5	42.3101	-71.4895
1	Greg Baldwin (DRG)	2022/08/05	dbh estimated; poison ivy	1140	2022/08/05	GrBa20220805144712	14:49:13	Oak, White	Quercus alba	Wooded Space	No	24	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	9	Clemmons St	Front	Clemmons St	200873.06	895509.4	42.31007	-71.4894
1	Greg Baldwin (DRG)	2022/08/05	dbh estimated; poison ivy	1141	2022/08/05	GrBa20220805144915	14:50:09	Oak, Black	Quercus velutina	Wooded Space	No	39	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Significant	Low	Yes	9	Clemmons St	Front	Clemmons St	200884.4	895504.7	42.31003	-71.4893
1	Ashley Casello (DRG)	2022/08/08		1293	2022/08/08	AsCa20220808093344	9:34:15	Maple, Norway	Acer platanoides	Wooded Space	No	9	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	5	Clemmons St	Front	Clemmons St	201031.13	895548.8	42.31042	-71.4875
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy	1298	2022/08/08	AsCa20220808100945	10:14:49	Oak, Scarlet	Quercus coccinea	Open Space	No	40	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	16	Clemmons St	Front	Clemmons St	200823.8	895528.8	42.31024	-71.49
1	Ashley Casello (DRG)	2022/08/11		1300	2022/08/08	AsCa20220808093437	20:09:39	Locust, Black	Robinia pseudoacacia	Wooded Space	No	8	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Low	Unlikely	Significant	Low	Yes	5	Clemmons St	Front	Clemmons St	201033.48	895550.4	42.31044	-71.4875
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy; borderline	1307	2022/08/08	AsCa20220808101118	10:13:10	Maple, Sugar	Acer saccharum	Open Space	No	17	Good	Routine Prune	None	Dead And Dying Branches	Low	Probable	Very Low	Unlikely	Negligible	Low	Yes	16	Clemmons St	Front	Clemmons St	200817.86	895531.9	42.31027	-71.4901
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy	1309	2022/08/08	AsCa20220808093535	9:36:18	Locust, Black	Robinia pseudoacacia	Wooded Space	No	13	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Severe	Low	Yes	5	Clemmons St	Front	Clemmons St	201037.95	895551.5	42.31045	-71.4874
1	Ashley Casello (DRG)	2022/08/11		1315	2022/08/08	AsCa20220808101322	20:16:21	Maple, Sugar	Acer saccharum	Open Space	No	5	Good	Train	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Negligible	Low	Yes	16	Clemmons St	Front	Clemmons St	200822.5	895529	42.31025	-71.49
1	Ashley Casello (DRG)	2022/08/08		1319	2022/08/08	AsCa20220808093701	9:38:12	Oak, Northern Red	Quercus rubra	Wooded Space	No	25	Fair	Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Significant	Low	Yes	5	Clemmons St	Front	Clemmons St	201041.71	895554.2	42.31047	-71.4874
1	Ashley Casello (DRG)	2022/08/11		1322	2022/08/08	AsCa20220808101353	20:16:21	Maple, Sugar	Acer saccharum	Open Space	No	4	Good	Train	None	Dead And Dying Branches	Low	Probable	Very Low	Unlikely	Negligible	Low	Yes	16	Clemmons St	Front	Clemmons St	200823.39	895528.1	42.31024	-71.49
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy	1328	2022/08/08	AsCa20220808093828	9:39:42	Locust, Black	Robinia pseudoacacia	Wooded Space	No	20	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	5	Clemmons St	Front	Clemmons St	201047.41	895556.4	42.31049	-71.4873
1	Ashley Casello (DRG)	2022/08/11		1331	2022/08/08	AsCa20220808101502	20:16:21	Hickory, Pignut	Carya glabra	Open Space	No	5	Good	Train	None	No Significant Defect	Low	Improbable	Low	Unlikely	Minor	Low	Yes	16	Clemmons St	Front	Clemmons St	200823.86	895527.8	42.31023	-71.49
1	Ashley Casello (DRG)	2022/08/08		1335	2022/08/08	AsCa20220808094240	9:43:39	Hickory, Pignut	Carya glabra	Open Space	No	24	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	8	Clemmons St	Front	Clemmons St	201022.02	895529.8	42.31025	-71.4876
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy; borderline	1340	2022/08/08	AsCa20220808125021	12:51:34	Oak, White	Quercus alba	Wooded Space	No	24	Good	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Clemmons St	200669.01	895606.2	42.31094	-71.4919
1	Ashley Casello (DRG)	2022/08/08		1342	2022/08/08	AsCa20220808101607	10:16:40	Maple, Norway	Acer platanoides	Open Space	No	16	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Severe	Low	Yes	18	Clemmons St	Front	Clemmons St	200811.22	895536.5	42.31031	-71.4902
1	Ashley Casello (DRG)	2022/08/08		1346	2022/08/08	AsCa20220808094359	9:44:25	Maple, Norway	Acer platanoides	Open Space	Yes	8	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	8	Clemmons St	Front	Clemmons St	201020.14	895530.7	42.31026	-71.4876
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; poison ivy; off ROW	1350	2022/08/08	AsCa20220808125150	20:09:39	Pine, Eastern White	Pinus strobus	Wooded Space	No	20	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Severe	Low	Yes	265	Boston Rd	Side	Clemmons St	200678.59	895598.2	42.31087	-71.4918
1	Ashley Casello (DRG)	2022/08/08		1354	2022/08/08	AsCa20220808101654	10:17:29	Hickory, Pignut	Carya glabra	Open Space	No	18	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	18	Clemmons St	Front	Clemmons St	200809.86	895538.2	42.31033	-71.4902
1	Ashley Casello (DRG)	2022/08/08		1355	2022/08/08	AsCa20220808094637	9:47:56	Oak, White	Quercus alba	Open Space	No	57	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Severe	Low	Yes	8	Clemmons St	Front	Clemmons St	201011.91	895522.9	42.31019	-71.4877
1	Ashley Casello (DRG)	2022/08/08		1363	2022/08/08	AsCa20220808094939	9:50:43	Maple, Red	Acer rubrum	Open Space	Yes	10	Fair	Routine Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Negligible	Low	Yes	10	Clemmons St	Front	Clemmons St	200967.06	895497.9	42.30996	-71.4883
1	Ashley Casello (DRG)	2022/08/08		1365	2022/08/08	AsCa20220808101833	10:20:03	Oak, Scarlet	Quercus coccinea	Wooded Space	No	31	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Clemmons St	200761.48	895564.7	42.31057	-71.4908
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy	1370	2022/08/08	AsCa20220808091342	9:14:59	Oak, Scarlet	Quercus coccinea	Open Space	No	30	Fair	Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Significant	Low	Yes	7	Clemmons St	Front	Clemmons St	200929.56	895500.4	42.30999	-71.4887
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; poison ivy	1373	2022/08/08	AsCa20220808095229	20:09:39	Ash, White	Fraxinus americana	Wooded Space	No	36	Poor	Remove	None	Dead And Dying Branches	None	Possible	Medium	Unlikely	Severe	Low	Yes	10	Clemmons St	Front	Clemmons St	200907.39	895490.8	42.3099	-71.489
1	Ashley Casello (DRG)	2022/08/11	in failure	1376	2022/08/08	AsCa20220808102028	20:09:39	Tree, Unknown	Unknown Tree	Wooded Space	No	11	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Severe	Low	Yes	265	Boston Rd	Side	Clemmons St	200757.36	895567.2	42.31059	-71.4908
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy	1380	2022/08/08	AsCa20220808091544	9:16:50	Oak, White	Quercus alba	Open Space	No	26	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Severe	Low	Yes	7	Clemmons St	Front	Clemmons St	200951.48	895503.9	42.31002	-71.4885
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; poison ivy	1383	2022/08/08	AsCa20220808095449	20:09:39	Oak, White	Quercus alba	Wooded Space	No	50	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Low	Unlikely	Severe	Low	Yes	10	Clemmons St	Front	Clemmons St	200899.11	895491.9	42.30991	-71.4891
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy	1386	2022/08/08	AsCa20220808102149	10:22:40	Hickory, Pignut	Carya glabra	Wooded Space	No	24	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Clemmons St	200752.07	895570	42.31061	-71.4909
1	Ashley Casello (DRG)	2022/08/08		1392	2022/08/08	AsCa20220808091803	9:19:30	Oak, Scarlet	Quercus coccinea	Open Space	No	24	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	7	Clemmons St	Front	Clemmons St	200964.94	895506.9	42.31005	-71.4883
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy	1395	2022/08/08	AsCa20220808095733	9:58:18	Oak, White	Quercus alba	Wooded Space	No	36	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	10	Clemmons St	Front	Clemmons St	200896.81	895491.5	42.30991	-71.4891
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; poison ivy	1396	2022/08/08	AsCa20220808102251	20:09:39	Tree, Unknown	Unknown Tree	Wooded Space	No	5	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Clemmons St	200748.49	895571.8	42.31063	-71.4909
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy	1404	2022/08/08	AsCa20220808095904	9:59:52	Hickory, Pignut	Carya glabra	Wooded Space	No	10	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	14	Clemmons St	Front	Clemmons St	200860.19	895506.2	42.31004	-71.4896
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy	1405	2022/08/08	AsCa20220808092015	9:26:39	Oak, Scarlet	Quercus coccinea	Wooded Space	No	26	Fair	Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Significant	Low	Yes	5	Clemmons St	Front	Clemmons St	200982.81	895513.5	42.31011	-71.4881
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; poison ivy	1407	2022/08/08	AsCa20220808102325	20:09:39	Tree, Unknown	Unknown Tree	Wooded Space	No	5	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Clemmons St	200741.73	895574.4	42.31065	-71.491
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy	1414	2022/08/08	AsCa20220808100032	10:01:23	Hickory, Pignut	Carya glabra	Wooded Space	No	17	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	16	Clemmons St	Front	Clemmons St	200837.49	895520.1	42.31016	-71.4898
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; poison ivy	1415	2022/08/08	AsCa20220808092125	20:09:39	Tree, Unknown	Unknown Tree	Wooded Space	No	24	Dead	Remove	None	No Significant Defect	None	Possible	High	Somewhat Likely	Severe	Moderate	Yes	5	Clemmons St	Front	Clemmons St	200987.22	895516.2	42.31013	-71.488

1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy; borderline	1420	2022/08/08	AsCa20220808102433	10:25:23	Hickory, Pignut	Carya glabra	Wooded Space	No	11	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Clemmons St	200730.97	895579.5	42.3107	-71.4911
1	Ashley Casello (DRG)	2022/08/08	borderline	1422	2022/08/08	AsCa20220808092453	9:26:27	Cherry, Black	Prunus serotina	Wooded Space	No	10	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	5	Clemmons St	Front	Clemmons St	201000.21	895526.7	42.31022	-71.4879
1	Ashley Casello (DRG)	2022/08/08		1425	2022/08/08	AsCa20220808100144	10:08:05	Hickory, Pignut	Carya glabra	Wooded Space	No	13	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Severe	Low	Yes	16	Clemmons St	Front	Clemmons St	200832.97	895522.8	42.31019	-71.4899
1	Ashley Casello (DRG)	2022/08/11	borderline	1431	2022/08/08	AsCa20220808102648	20:21:08	Tree, Unknown	Unknown Tree	Wooded Space	No	5	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Clemmons St	200714.36	895586.5	42.31076	-71.4913
1	Greg Baldwin (DRG)	2022/08/18		1433	2022/08/08	AsCa20220808092711	13:23:06	Cherry, Black	Prunus serotina	Wooded Space	No	10	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Severe	Low	Yes	5	Clemmons St	Front	Clemmons St	201004.5	895529.8	42.31025	-71.4878
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy	1435	2022/08/08	AsCa20220808100613	10:08:05	Oak, Scarlet	Quercus coccinea	Wooded Space	No	30	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	16	Clemmons St	Front	Clemmons St	200831.44	895524	42.3102	-71.4899
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; poison ivy	1441	2022/08/08	AsCa20220808103201	20:09:39	Maple, Red	Acer rubrum	Wooded Space	No	16	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Low	Unlikely	Severe	Low	Yes	265	Boston Rd	Side	Clemmons St	200691.91	895595	42.31084	-71.4916
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy	1442	2022/08/08	AsCa20220808092833	9:29:36	Elm, American	Ulmus americana	Wooded Space	No	9	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	5	Clemmons St	Front	Clemmons St	201008.03	895532.5	42.31028	-71.4878
1	Ashley Casello (DRG)	2022/08/08	borderline	1446	2022/08/08	AsCa20220808100807	10:09:09	Pine, Eastern White	Pinus strobus	Wooded Space	No	11	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	16	Clemmons St	Front	Clemmons St	200827.74	895525.8	42.31022	-71.49
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy	1449	2022/08/08	AsCa20220808093025	9:31:36	Apple	Malus species	Wooded Space	Yes	8	Fair	Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	5	Clemmons St	Front	Clemmons St	201021.67	895543	42.31037	-71.4876
1	Ashley Casello (DRG)	2022/08/08		1457	2022/08/08	AsCa20220808093156	9:33:08	Maple, Norway	Acer platanoides	Wooded Space	No	8	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Significant	Low	Yes	5	Clemmons St	Front	Clemmons St	201025.66	895544	42.31038	-71.4876
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; behind fence	9	2022/07/28	GrBa20220728105102	13:26:11	Cedar, Northern White	Thuja occidentalis	Open Space	No	5	Good	N/A	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Minor	Low	No	279	Cordaville Rd	Front	Cordaville Rd	198049.84	890808.7	42.26775	-71.5236
1	Greg Baldwin (DRG)	2022/08/18		10	2022/07/28	GrBa20220728103849	12:44:17	Fir, White	Abies concolor	Open Space	No	6	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	278	Cordaville Rd	Front	Cordaville Rd	198068.62	890845.2	42.26807	-71.5234
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; behind fence	11	2022/07/28	GrBa20220728104908	13:26:11	Apple	Malus species	Open Space	No	5	Good	N/A	None	No Significant Defect	Low	Improbable	Low	Unlikely	Significant	Low	No	279	Cordaville Rd	Front	Cordaville Rd	198046.61	890810.4	42.26776	-71.5237
1	Greg Baldwin (DRG)	2022/07/28		12	2022/07/28	GrBa20220728105237	10:54:36	Apple	Malus species	Open Space	No	3	Good	N/A	None	No Significant Defect	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	279	Cordaville Rd	Front	Cordaville Rd	198045.08	890812.2	42.26778	-71.5237
1	Greg Baldwin (DRG)	2022/08/18		13	2022/07/28	GrBa20220728103626	12:44:17	Fir, White	Abies concolor	Open Space	No	7	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	278	Cordaville Rd	Front	Cordaville Rd	198069.32	890851.3	42.26813	-71.5234
1	Greg Baldwin (DRG)	2022/07/28	behind fence	14	2022/07/28	GrBa20220728104523	10:49:04	Plum	Prunus species	Open Space	No	2	Good	N/A	None	No Significant Defect	Low	Improbable	Low	Unlikely	Negligible	Low	No	279	Cordaville Rd	Front	Cordaville Rd	198047.31	890805.7	42.26772	-71.5237
1	Greg Baldwin (DRG)	2022/07/28	behind fence	16	2022/07/28	GrBa20220728104801	10:55:25	Plum	Prunus species	Open Space	No	5	Fair	N/A	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	No	279	Cordaville Rd	Front	Cordaville Rd	198047.84	890808.4	42.26774	-71.5237
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; behind fence	17	2022/07/28	GrBa20220728105147	13:26:11	Cedar, Northern White	Thuja occidentalis	Open Space	No	4	Good	N/A	None	No Significant Defect	Low	Improbable	Low	Unlikely	Negligible	Low	No	279	Cordaville Rd	Front	Cordaville Rd	198050.55	890813.9	42.26779	-71.5236
1	Greg Baldwin (DRG)	2022/08/18	pole number 130	18	2022/07/28	GrBa20220728102759	12:44:17	Dogwood, Kousa	Cornus kousa	Open Space	No	6	Good	Train	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	278	Cordaville Rd	Front	Cordaville Rd	198073.94	890877.1	42.26836	-71.5233
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; behind fence	19	2022/07/28	GrBa20220728105318	13:26:11	Apple	Malus species	Open Space	No	3	Good	N/A	None	No Significant Defect	Low	Improbable	Low	Unlikely	Negligible	Low	No	279	Cordaville Rd	Front	Cordaville Rd	198046.14	890815.6	42.26781	-71.5237
1	Greg Baldwin (DRG)	2022/07/28		20	2022/07/28	GrBa20220728110230	11:04:42	Maple, Sugar	Acer saccharum	Wooded Space	No	9	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Medium	Unlikely	Minor	Low	Yes	279	Cordaville Rd	Front	Cordaville Rd	198056.63	890834.2	42.26798	-71.5236
1	Greg Baldwin (DRG)	2022/07/28		21	2022/07/28	GrBa20220728105438	10:55:14	Apple	Malus species	Open Space	No	3	Fair	N/A	None	Dead And Dying Branches	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	279	Cordaville Rd	Front	Cordaville Rd	198048.9	890817.6	42.26783	-71.5236
1	Greg Baldwin (DRG)	2022/08/18	pole number119; borderline pole number 145; dbh estimated;	24	2022/07/28	GrBa20220728141815	12:30:57	Oak, Northern Red	Quercus rubra	Wooded Space	No	18	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	262	Cordaville Rd	Front	Cordaville Rd	198105.04	891222.2	42.27147	-71.523
1	Greg Baldwin (DRG)	2022/08/18	poison ivy	25	2022/07/29	GrBa20220729115145	12:00:45	Maple, Red	Acer rubrum	Wooded Space	Yes	22	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Very Low	Unlikely	Significant	Low	Yes	13	Cordaville Rd	Front	Cordaville Rd	197717.83	894326.6	42.29942	-71.5277
1	Greg Baldwin (DRG)	2022/07/28	borderline; end hedge row; 5	26	2022/07/28	GrBa20220728121319	12:15:16	White	Thuja occidentalis	Open Space	Yes	7	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	255	Cordaville Rd	Front	Cordaville Rd	198082.32	891248.7	42.27171	-71.5232
1	Greg Baldwin (DRG)	2022/07/29		27	2022/07/29	GrBa20220729103458	10:35:56	Oak, Black	Quercus velutina	Open Space	Yes	4	Poor	Train	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	190	Cordaville Rd	Front	Cordaville Rd	197880.54	892473.1	42.28273	-71.5257
1	Greg Baldwin (DRG)	2022/07/29		28	2022/07/29	GrBa20220729082637	8:27:25	Maple, Red	Acer rubrum	Open Space	No	26	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	181	Cordaville Rd	Front	Cordaville Rd	197856.93	892660.5	42.28442	-71.526
1	Greg Baldwin (DRG)	2022/08/18	pole number 103	29	2022/07/28	GrBa20220728132608	12:12:15	Hickory, Shagbark	Carya ovata	Wooded Space	No	9	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	9	Watkins Ln	Rear	Cordaville Rd	197967.86	891751.3	42.27623	-71.5246
1	Greg Baldwin (DRG)	2022/07/28		30	2022/07/28	GrBa20220728110716	11:08:38	Hickory, Shagbark	Carya ovata	Wooded Space	No	9	Fair	Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Minor	Low	Yes	279	Cordaville Rd	Front	Cordaville Rd	198055.34	890833.8	42.26797	-71.5236
1	Greg Baldwin (DRG)	2022/07/29	borderline	31	2022/07/29	GrBa20220729074729	7:48:25	Maple, Red	Acer rubrum	Open Space	No	15	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	205	Cordaville Rd	Front	Cordaville Rd	197885.75	892260.7	42.28082	-71.5256
1	Greg Baldwin (DRG)	2022/07/29	borderline	34	2022/07/29	GrBa20220729082845	8:30:35	Cedar, Northern White	Thuja occidentalis	Open Space	Yes	1	Good	Routine Prune	None	Dead And Dying Branches	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	175	Cordaville Rd	Front	Cordaville Rd	197857.87	892750.2	42.28523	-71.526
1	Greg Baldwin (DRG)	2022/07/29		35	2022/07/29	GrBa20220729103635	10:37:34	Cherry, Black	Prunus serotina	Wooded Space	No	11	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Probable	Low	Unlikely	Minor	Low	Yes	196	Cordaville Rd	Front	Cordaville Rd	197880.65	892452.5	42.28254	-71.5257
1	Greg Baldwin (DRG)	2022/07/28	borderline; start hedge row; 5	36	2022/07/28	GrBa20220728121403	12:15:05	Cedar, Northern White	Thuja occidentalis	Open Space	No	3	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	255	Cordaville Rd	Front	Cordaville Rd	198083.37	891245.2	42.27168	-71.5232
1	Greg Baldwin (DRG)	2022/07/28		37	2022/07/28	GrBa20220728142010	14:20:56	Plum	Prunus species	Open Space	No	3	Poor	Train	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	264	Cordaville Rd	Front	Cordaville Rd	198107.15	891213.1	42.27139	-71.5229
1	Greg Baldwin (DRG)	2022/07/29	dbh estimated; poison ivy; vines >50%; borderline	38	2022/07/29	GrBa20220729120013	12:02:44	Elm, American	Ulmus americana	Open Space	No	29	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	7	Cordaville Rd	Front	Cordaville Rd	197620.51	894855.1	42.30417	-71.5289
1	Greg Baldwin (DRG)	2022/07/29	borderline; Co-dominants	39	2022/07/29	GrBa20220729074943	7:50:54	Maple, Red	Acer rubrum	Open Space	Yes	9	Poor	Prune	None	Broken And/Or Hanging Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	203	Cordaville Rd	Front	Cordaville Rd	197882.88	892299.9	42.28117	-71.5257
1	Greg Baldwin (DRG)	2022/07/28		40	2022/07/28	GrBa20220728110915	11:10:50	Oak, Northern Red	Quercus rubra	Wooded Space	No	19	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	279	Cordaville Rd	Front	Cordaville Rd	198054.22	890833.6	42.26797	-71.5236
1	Greg Baldwin (DRG)	2022/07/28	pole number 107	41	2022/07/28	GrBa20220728133306	13:34:18	Hickory, Shagbark	Carya ovata	Wooded Space	No	10	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Significant	Low	Yes	19	Richards Rd	Side	Cordaville Rd	197996	891634.7	42.27518	-71.5243
1	Greg Baldwin (DRG)	2022/07/28	borderline	44	2022/07/28	GrBa20220728121714	12:18:35	Oak, Black	Quercus velutina	Open Space	No	36	Fair	Prune	None	Dead And Dying Branches	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	253	Cordaville Rd	Front	Cordaville Rd	198069.74	891295.5	42.27213	-71.5234
1	Greg Baldwin (DRG)	2022/07/29		45	2022/07/29	GrBa20220729103746	10:38:50	Maple, Sugar	Acer saccharum	Wooded Space	No	9	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Possible	Medium	Unlikely	Minor	Low	Yes	196	Cordaville Rd	Front	Cordaville Rd	197882.53	892451.2	42.28253	-71.5257
1	Greg Baldwin (DRG)	2022/07/28		46	2022/07/28	GrBa20220728142251	14:25:28	Elm, American	Ulmus americana	Wooded Space	No	12	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	268	Cordaville Rd	Front	Cordaville Rd	198127	891101.9	42.27039	-71.5227
1	Greg Baldwin (DRG)	2022/08/18	borderline; Co-dominants; pole number 72	47	2022/07/29	GrBa20220729083240	12:07:41	Maple, Red	Acer rubrum	Wooded Space	No	35	Poor	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Significant	Low	Yes	171	Cordaville Rd	Front	Cordaville Rd	197858.18	892776.8	42.28546	-71.526
1	Greg Baldwin (DRG)	2022/07/29	dbh estimated; poison ivy; vines >50%; borderline	48	2022/07/29	GrBa20220729120317	12:04:15	Maple, Norway	Acer platanoides	Open Space	No	8	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Possible	Low	Unlikely	Minor	Low	Yes	7	Cordaville Rd	Front	Cordaville Rd	197615.82	894870.5	42.30431	-71.5289
1	Greg Baldwin (DRG)	2022/07/29		49	2022/07/29	GrBa20220729075303	7:53:53	Maple, Red	Acer rubrum	Open Space	Yes	10	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	199	Cordaville Rd	Front	Cordaville Rd	197875.9	892382.2	42.28191	-71.5258

1	Greg Baldwin (DRG)	2022/07/28		51	2022/07/28	GrBa20220728111112	11:13:07	Cherry, Black	Prunus serotina	Wooded Space	Yes	14	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	279	Cordaville Rd	Front	Cordaville Rd	198056.34	890838.8	42.26802	-71.5236
1	Greg Baldwin (DRG)	2022/07/28	pole number 112; Co-dominants	52	2022/07/28	GrBa20220728133730	13:39:05	Maple, Red Oak, Northern	Acer rubrum	Wooded Space	No	17	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	248	Cordaville Rd	Front	Cordaville Rd	198036.78	891472.2	42.27372	-71.5238
1	Greg Baldwin (DRG)	2022/07/28	borderline	54	2022/07/28	GrBa20220728121854	12:20:07	Red	Quercus rubra	Open Space	No	25	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	251	Cordaville Rd	Front	Cordaville Rd	198066.39	891306.6	42.27223	-71.5234
1	Greg Baldwin (DRG)	2022/07/29	borderline	55	2022/07/29	GrBa20220729103912	10:43:48	Maple, Sugar	Acer saccharum	Wooded Space	No	10	Poor	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Minor	Low	Yes	196	Cordaville Rd	Front	Cordaville Rd	197882.77	892448	42.2825	-71.5257
1	Greg Baldwin (DRG)	2022/07/29		56	2022/07/29	GrBa20220729121951	12:20:21	Maple, Sugar	Acer saccharum	Open Space	No	1	Poor	Train	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	28	Cordaville Rd	Front	Cordaville Rd	197674.45	894729.9	42.30305	-71.5282
1	Greg Baldwin (DRG)	2022/07/28	borderline	58	2022/07/28	GrBa20220728142423	14:25:21	Hickory, Shagbark	Carya ovata	Wooded Space	No	15	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	272	Cordaville Rd	Front	Cordaville Rd	198124.15	891080.5	42.27019	-71.5227
1	Greg Baldwin (DRG)	2022/08/18	pole number 73; borderline	59	2022/07/29	GrBa20220729083635	12:07:41	Maple, Red	Acer rubrum	Wooded Space	No	25	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	171	Cordaville Rd	Front	Cordaville Rd	197857.83	892799.9	42.28567	-71.526
1	Greg Baldwin (DRG)	2022/07/28		60	2022/07/28	GrBa20220728111329	11:16:18	Maple, Sugar	Acer saccharum	Wooded Space	No	11	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	279	Cordaville Rd	Front	Cordaville Rd	198056.75	890841.5	42.26804	-71.5236
1	Greg Baldwin (DRG)	2022/07/29		61	2022/07/29	GrBa20220729075401	7:54:45	Maple, Red	Acer rubrum	Open Space	Yes	5	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	199	Cordaville Rd	Front	Cordaville Rd	197876.43	892377.2	42.28187	-71.5257
1	Greg Baldwin (DRG)	2022/07/28	pole number 112	62	2022/07/28	GrBa20220728133926	13:40:32	Ash, White	Fraxinus americana	Wooded Space	No	9	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	248	Cordaville Rd	Front	Cordaville Rd	198037.15	891469.6	42.2737	-71.5238
1	Greg Baldwin (DRG)	2022/07/28	borderline	64	2022/07/28	GrBa20220728122116	12:23:10	Maple, Red	Acer rubrum	Wooded Space	No	16	Poor	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Possible	Very Low	Unlikely	Significant	Low	Yes	10	Harris Dr	Side	Cordaville Rd	198051.88	891358.3	42.27269	-71.5236
1	Greg Baldwin (DRG)	2022/08/26	pole number 125	66	2022/07/28	GrBa20220728142706	8:49:41	Hickory, Shagbark	Carya ovata	Wooded Space	No	8	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Very Low	Unlikely	Significant	Low	Yes	274	Cordaville Rd	Front	Cordaville Rd	198111.72	891033	42.26977	-71.5229
1	Greg Baldwin (DRG)	2022/08/18	pole number 73; borderline	67	2022/07/29	GrBa20220729083805	12:07:41	Oak, Northern Red	Quercus rubra	Wooded Space	No	38	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	171	Cordaville Rd	Front	Cordaville Rd	197857.6	892803.8	42.28571	-71.526
1	Greg Baldwin (DRG)	2022/07/29	borderline	68	2022/07/29	GrBa20220729104042	10:41:42	Oak, Black	Quercus velutina	Wooded Space	No	8	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Minor	Low	Yes	196	Cordaville Rd	Front	Cordaville Rd	197883.71	892441.4	42.28245	-71.5257
1	Greg Baldwin (DRG)	2022/08/18	pole number 139; dbh estimated; poison ivy; borderline	69	2022/07/29	GrBa20220729122351	12:00:10	Maple, Red	Acer rubrum	Wooded Space	No	8	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Very Low	Unlikely	Significant	Low	Yes	32	Cordaville Rd	Front	Cordaville Rd	197712.97	894606.5	42.30194	-71.5277
1	Greg Baldwin (DRG)	2022/08/18	pole number 112; borderline	70	2022/07/28	GrBa20220728134038	10:21:42	Elm, American	Ulmus americana	Wooded Space	No	12	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	191	Woodland Rd	Side	Cordaville Rd	198038.09	891464.5	42.27365	-71.5238
1	Greg Baldwin (DRG)	2022/07/28		71	2022/07/28	GrBa20220728111905	11:23:21	Pine, Eastern White	Pinus strobus	Open Space	No	11	Fair	Prune	None	Broken And/Or Hanging Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	275	Cordaville Rd	Front	Cordaville Rd	198062.41	890878.9	42.26838	-71.5235
1	Greg Baldwin (DRG)	2022/07/29		72	2022/07/29	GrBa20220729075447	7:55:07	Maple, Red	Acer rubrum	Open Space	No	4	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	199	Cordaville Rd	Front	Cordaville Rd	197876.96	892374.7	42.28184	-71.5257
1	Greg Baldwin (DRG)	2022/07/28	pole number 112; borderline	75	2022/07/28	GrBa20220728122759	12:36:17	Pine, Eastern White	Pinus strobus	Wooded Space	No	13	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	6	Harris Dr	Side	Cordaville Rd	198028.58	891446	42.27348	-71.5239
1	Greg Baldwin (DRG)	2022/08/18	pole number 125	76	2022/07/28	GrBa20220728143030	12:37:50	Elm, American	Ulmus americana	Wooded Space	No	11	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Significant	Low	Yes	274	Cordaville Rd	Front	Cordaville Rd	198106.25	891004.7	42.26951	-71.523
1	Greg Baldwin (DRG)	2022/08/18	pole number 113	77	2022/07/28	GrBa20220728134238	10:21:42	Maple, Red	Acer rubrum	Wooded Space	No	12	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	191	Woodland Rd	Side	Cordaville Rd	198041.38	891453	42.27355	-71.5237
1	Greg Baldwin (DRG)	2022/07/29		78	2022/07/29	GrBa20220729104226	10:43:19	Pine, Eastern White	Pinus strobus	Wooded Space	No	33	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	196	Cordaville Rd	Front	Cordaville Rd	197882.94	892432.5	42.28236	-71.5257
1	Greg Baldwin (DRG)	2022/08/18	pole number 50; borderline; dbh estimated; poison ivy	79	2022/07/29	GrBa20220729084841	12:02:06	Maple, Red	Acer rubrum	Wooded Space	Yes	14	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	17	Cordaville Rd	Front	Cordaville Rd	197791.5	893495.7	42.29194	-71.5268
1	Greg Baldwin (DRG)	2022/07/28		80	2022/07/28	GrBa20220728112159	11:23:13	Hornbeam, European	Carpinus betulus	Open Space	No	10	Good	Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Very Low	Unlikely	Minor	Low	Yes	275	Cordaville Rd	Front	Cordaville Rd	198062.77	890884.4	42.26843	-71.5235
1	Greg Baldwin (DRG)	2022/08/18	pole number 139; dbh estimated; poison ivy; borderline	81	2022/07/29	GrBa20220729122536	12:00:10	Elm, American	Ulmus americana	Wooded Space	No	8	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	32	Cordaville Rd	Front	Cordaville Rd	197713.44	894604.3	42.30192	-71.5277
1	Greg Baldwin (DRG)	2022/07/29		82	2022/07/29	GrBa20220729075551	7:56:36	Maple, Red	Acer rubrum	Open Space	Yes	8	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	199	Cordaville Rd	Front	Cordaville Rd	197875.55	892390.6	42.28199	-71.5258
1	Greg Baldwin (DRG)	2022/08/18	pole number 113; borderline	85	2022/07/28	GrBa20220728134358	10:21:42	Maple, Red	Acer rubrum	Wooded Space	No	13	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	191	Woodland Rd	Side	Cordaville Rd	198047.79	891428.1	42.27332	-71.5237
1	Greg Baldwin (DRG)	2022/08/26	pole number126	86	2022/07/28	GrBa20220728143810	8:53:18	Elm, American	Ulmus americana	Wooded Space	No	8	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Very Low	Unlikely	Significant	Low	Yes	274	Cordaville Rd	Front	Cordaville Rd	198101.59	890992.2	42.2694	-71.523
1	Greg Baldwin (DRG)	2022/07/29	armillaria	87	2022/07/29	GrBa20220729104539	10:47:29	Maple, Red	Acer rubrum	Wooded Space	No	30	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	High	Somewhat Likely	Significant	Moderate	Yes	196	Cordaville Rd	Front	Cordaville Rd	197883.88	892424.8	42.2823	-71.5257
1	Greg Baldwin (DRG)	2022/08/18	pole number 111	88	2022/07/28	GrBa20220728123042	12:23:47	Oak, Black	Quercus velutina	Wooded Space	Yes	20	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Minor	Low	Yes	22	Richards Rd	Side	Cordaville Rd	198015.83	891494.3	42.27392	-71.5241
1	Greg Baldwin (DRG)	2022/08/18	pole number 162; borderline; leaning	89	2022/07/29	GrBa20220729090137	12:02:30	Oak, Northern Red	Quercus rubra	Wooded Space	No	18	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	15	Cordaville Rd	Front	Cordaville Rd	197757.47	893849.9	42.29513	-71.5272
1	Greg Baldwin (DRG)	2022/08/18	pole number 139; dbh estimated; poison ivy; borderline	90	2022/07/29	GrBa20220729122758	12:00:10	Oak, Scarlet	Quercus coccinea	Wooded Space	No	23	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	32	Cordaville Rd	Front	Cordaville Rd	197723.18	894551.6	42.30144	-71.5276
1	Greg Baldwin (DRG)	2022/07/28		91	2022/07/28	GrBa20220728112349	11:25:59	Pine, Eastern White	Pinus strobus	Open Space	No	10	Good	Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Significant	Low	Yes	275	Cordaville Rd	Front	Cordaville Rd	198063.88	890887.1	42.26845	-71.5235
1	Greg Baldwin (DRG)	2022/07/29	borderline	92	2022/07/29	GrBa20220729075714	7:57:39	Maple, Red	Acer rubrum	Open Space	Yes	11	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	197	Cordaville Rd	Front	Cordaville Rd	197872.91	892402.5	42.28209	-71.5258
1	Greg Baldwin (DRG)	2022/07/29	borderline; utility pruned	95	2022/07/29	GrBa20220729104836	10:49:38	Maple, Red	Acer rubrum	Wooded Space	No	9	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Minor	Low	Yes	198	Cordaville Rd	Front	Cordaville Rd	197890.45	892375	42.28185	-71.5256
1	Greg Baldwin (DRG)	2022/08/18	pole number 126; borderline	96	2022/07/28	GrBa20220728144137	12:37:50	Hickory, Shagbark	Carya ovata	Wooded Space	No	11	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	274	Cordaville Rd	Front	Cordaville Rd	198100.7	890980.1	42.26929	-71.523
1	Greg Baldwin (DRG)	2022/08/18	pole number 114	97	2022/07/28	GrBa20220728134533	12:28:54	Hickory, Shagbark	Carya ovata	Wooded Space	No	17	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Significant	Low	Yes	191	Woodland Rd	Rear	Cordaville Rd	198054.08	891404.5	42.27311	-71.5236
1	Greg Baldwin (DRG)	2022/08/18	pole number 110	98	2022/07/28	GrBa20220728123236	12:23:47	Maple, Red	Acer rubrum	Wooded Space	No	8	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Low	Unlikely	Significant	Low	Yes	22	Richards Rd	Side	Cordaville Rd	198005.9	891531.2	42.27425	-71.5242
1	Greg Baldwin (DRG)	2022/08/18	pole number 142	99	2022/07/29	GrBa20220729123151	12:00:10	Elm, American	Ulmus americana	Open Space	No	5	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	32	Cordaville Rd	Front	Cordaville Rd	197725.69	894407.3	42.30014	-71.5276
1	Greg Baldwin (DRG)	2022/08/18	pole number 161; borderline	100	2022/07/29	GrBa20220729090407	12:02:30	Maple, Red	Acer rubrum	Wooded Space	Yes	11	Poor	Routine Prune	Insect/Dis	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	15	Cordaville Rd	Front	Cordaville Rd	197753.31	893894.8	42.29553	-71.5272
1	Greg Baldwin (DRG)	2022/07/28		101	2022/07/28	GrBa20220728112448	11:25:46	Hornbeam, European	Carpinus betulus	Open Space	Yes	10	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	275	Cordaville Rd	Front	Cordaville Rd	198065.06	890892.4	42.2685	-71.5235
1	Greg Baldwin (DRG)	2022/07/29	borderline	102	2022/07/29	GrBa20220729075809	7:58:48	Maple, Red	Acer rubrum	Open Space	Yes	10	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	197	Cordaville Rd	Front	Cordaville Rd	197871.91	892418.4	42.28224	-71.5258

1	Greg Baldwin (DRG)	2022/08/18	pole number 115	105	2022/07/28	GrBa20220728134803	12:28:54	Maple, Red	Acer rubrum	Wooded Space	No	15	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	191	Woodland Rd	Rear	Cordaville Rd	198062.36	891375.4	42.27285	-71.5235
1	Greg Baldwin (DRG)	2022/08/18	pole number 126; borderline	106	2022/07/28	GrBa20220728144258	12:37:50	Ash, White	Fraxinus americana	Wooded Space	No	14	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	274	Cordaville Rd	Front	Cordaville Rd	198102.7	890989.8	42.26938	-71.523
1	Greg Baldwin (DRG)	2022/08/18	pole number 84	107	2022/07/29	GrBa20220729105014	12:13:04	Maple, Red	Acer rubrum	Wooded Space	No	8	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	200	Cordaville Rd	Front	Cordaville Rd	197891.15	892366.9	42.28177	-71.5256
1	Greg Baldwin (DRG)	2022/07/28	foliage disorder	108	2022/07/28	GrBa20220728123928	12:40:27	Maple, Red	Acer rubrum	Open Space	Yes	7	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	235	Cordaville Rd	Front	Cordaville Rd	197978.58	891646.3	42.27529	-71.5245
1	Greg Baldwin (DRG)	2022/08/18	pole number 142	109	2022/07/29	GrBa20220729123309	12:00:10	Elm, American	Ulmus americana	Open Space	Yes	6	Poor	Routine Prune	None	Dead And Dying Branches	Low	Possible	High	Somewhat Likely	Negligible	Low	Yes	32	Cordaville Rd	Front	Cordaville Rd	197726.43	894403.8	42.30011	-71.5276
1	Greg Baldwin (DRG)	2022/07/28		110	2022/07/28	GrBa20220728112624	11:26:57	Pine, Eastern White	Pinus strobus	Open Space	No	12	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	275	Cordaville Rd	Front	Cordaville Rd	198065.12	890896.2	42.26853	-71.5235
1	Greg Baldwin (DRG)	2022/08/18	pole number 153	111	2022/07/29	GrBa20220729090835	12:01:25	Tree, Unknown	Unknown Tree	Open Space	No	11	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Minor	Low	Yes	28	Cordaville Rd	Front	Cordaville Rd	197751.31	894075.3	42.29715	-71.5273
1	Greg Baldwin (DRG)	2022/07/29	borderline	112	2022/07/29	GrBa20220729075935	8:00:44	Maple, Norway	Acer platanoides	Open Space	No	23	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	197	Cordaville Rd	Front	Cordaville Rd	197871.15	892422.5	42.28227	-71.5258
1	Greg Baldwin (DRG)	2022/08/18	pole number 115; vines >50%	115	2022/07/28	GrBa20220728134936	12:29:49	Maple, Red	Acer rubrum	Wooded Space	No	10	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	189	Woodland Rd	Rear	Cordaville Rd	198065.95	891364.1	42.27275	-71.5234
1	Greg Baldwin (DRG)	2022/08/18	pole number 126; borderline	116	2022/07/28	GrBa20220728144452	12:37:50	Hickory, Shagbark	Carya ovata	Wooded Space	No	11	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Significant	Low	Yes	274	Cordaville Rd	Front	Cordaville Rd	198098.99	890970.9	42.26921	-71.523
1	Greg Baldwin (DRG)	2022/08/18	pole number 84	117	2022/07/29	GrBa20220729105133	12:13:04	Maple, Red	Acer rubrum	Wooded Space	No	8	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	200	Cordaville Rd	Front	Cordaville Rd	197891.68	892363.6	42.28174	-71.5256
1	Greg Baldwin (DRG)	2022/07/28	borderline	118	2022/07/28	GrBa20220728124148	12:43:02	Oak, Black	Quercus velutina	Open Space	Yes	23	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	237	Cordaville Rd	Front	Cordaville Rd	197978.47	891645.3	42.27528	-71.5245
1	Greg Baldwin (DRG)	2022/08/18	pole number 160; borderline	119	2022/07/29	GrBa20220729091530	12:03:19	Pine, Eastern White	Pinus strobus	Wooded Space	No	20	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	24	Cordaville Rd	Front	Cordaville Rd	197766.2	893895	42.29553	-71.5271
1	Greg Baldwin (DRG)	2022/08/18	pole number 142; borderline; utility pruned	120	2022/07/29	GrBa20220729123454	12:00:10	Elm, American	Ulmus americana	Open Space	Yes	12	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Significant	Low	Yes	32	Cordaville Rd	Front	Cordaville Rd	197728.52	894365.4	42.29977	-71.5275
1	Greg Baldwin (DRG)	2022/07/28		121	2022/07/28	GrBa20220728112708	11:28	Hornbeam, European	Carpinus betulus	Open Space	Yes	12	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	275	Cordaville Rd	Front	Cordaville Rd	198065.59	890900.3	42.26857	-71.5234
1	Greg Baldwin (DRG)	2022/07/29	borderline	123	2022/07/29	GrBa20220729080059	8:01:40	Pine, Eastern White	Pinus strobus	Open Space	No	15	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	197	Cordaville Rd	Front	Cordaville Rd	197870.45	892427.7	42.28232	-71.5258
1	Greg Baldwin (DRG)	2022/08/18	pole number 116; borderline	125	2022/07/28	GrBa20220728135121	12:29:49	Maple, Red	Acer rubrum	Wooded Space	No	11	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	189	Woodland Rd	Rear	Cordaville Rd	198069.88	891348	42.2726	-71.5234
1	Greg Baldwin (DRG)	2022/08/18	pole number 127; borderline	126	2022/07/28	GrBa20220728144628	12:37:50	Maple, Sugar	Acer saccharum	Wooded Space	No	11	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	274	Cordaville Rd	Front	Cordaville Rd	198098.05	890958.7	42.2691	-71.5231
1	Greg Baldwin (DRG)	2022/08/18		127	2022/07/29	GrBa20220729105216	10:18:58	Maple, Red	Acer rubrum	Open Space	No	9	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	202	Cordaville Rd	Front	Cordaville Rd	197891.21	892352.4	42.28164	-71.5256
1	Greg Baldwin (DRG)	2022/08/18	pole number 98; borderline	128	2022/07/28	GrBa20220728125124	12:10:00	Tree, Unknown	Unknown Tree	Wooded Space	No	14	Dead	Remove	None	No Significant Defect	None	Probable	Medium	Somewhat Likely	Significant	Moderate	Yes	224	Cordaville Rd	Front	Cordaville Rd	197935.91	891904.9	42.27762	-71.525
1	Greg Baldwin (DRG)	2022/08/18	pole number 161; borderline	129	2022/07/29	GrBa20220729091726	12:03:19	Pine, Eastern White	Pinus strobus	Wooded Space	No	14	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Significant	Low	Yes	24	Cordaville Rd	Front	Cordaville Rd	197767.03	893885.1	42.29544	-71.5271
1	Greg Baldwin (DRG)	2022/08/18	pole number 145	130	2022/07/29	GrBa20220729123753	12:00:10	Maple, Red	Acer rubrum	Open Space	No	23	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	32	Cordaville Rd	Front	Cordaville Rd	197729.1	894354.4	42.29967	-71.5275
1	Greg Baldwin (DRG)	2022/07/28		131	2022/07/28	GrBa20220728112824	11:28:56	Pine, Eastern White	Pinus strobus	Open Space	No	8	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	275	Cordaville Rd	Front	Cordaville Rd	198066.48	890903.2	42.2686	-71.5234
1	Greg Baldwin (DRG)	2022/08/26		133	2022/07/29	GrBa20220729080221	7:31:04	Maple, Red	Acer rubrum	Open Space	Yes	23	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	197	Cordaville Rd	Front	Cordaville Rd	197870.1	892437.2	42.28241	-71.5258
1	Greg Baldwin (DRG)	2022/08/18	pole number 116; borderline	135	2022/07/28	GrBa20220728135306	12:29:49	Maple, Red	Acer rubrum	Wooded Space	No	19	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	189	Woodland Rd	Rear	Cordaville Rd	198071.23	891340.2	42.27253	-71.5234
1	Greg Baldwin (DRG)	2022/08/18	pole number 127	136	2022/07/28	GrBa20220728144835	12:37:50	Elm, American	Ulmus americana	Wooded Space	No	12	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	274	Cordaville Rd	Front	Cordaville Rd	198096.58	890952.3	42.26904	-71.5231
1	Greg Baldwin (DRG)	2022/08/18		137	2022/07/29	GrBa20220729105348	10:18:58	Maple, Red	Acer rubrum	Open Space	No	12	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	202	Cordaville Rd	Front	Cordaville Rd	197891.21	892351.3	42.28163	-71.5256
1	Greg Baldwin (DRG)	2022/08/18	pole number 98; borderline	138	2022/07/28	GrBa20220728125654	12:10:00	Oak, Northern Red	Quercus rubra	Wooded Space	No	15	Poor	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	224	Cordaville Rd	Front	Cordaville Rd	197936.44	891902.1	42.27759	-71.525
1	Greg Baldwin (DRG)	2022/08/18	pole number 145; borderline	139	2022/07/29	GrBa20220729124039	12:00:10	Maple, Red	Acer rubrum	Open Space	No	31	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	32	Cordaville Rd	Front	Cordaville Rd	197730.8	894342.7	42.29956	-71.5275
1	Greg Baldwin (DRG)	2022/07/28		140	2022/07/28	GrBa20220728112919	11:30:32	Hornbeam, European	Carpinus betulus	Open Space	Yes	13	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	275	Cordaville Rd	Front	Cordaville Rd	198067.18	890907.2	42.26863	-71.5234
1	Greg Baldwin (DRG)	2022/08/18	pole number 161	141	2022/07/29	GrBa20220729092013	12:03:19	Pine, Eastern White	Pinus strobus	Wooded Space	No	22	Good	Routine Prune	None	Dead And Dying Branches	Low	Improbable	High	Unlikely	Significant	Low	Yes	24	Cordaville Rd	Front	Cordaville Rd	197766.14	893878.8	42.29539	-71.5271
1	Greg Baldwin (DRG)	2022/07/29		142	2022/07/29	GrBa20220729080415	8:04:48	Locust, Black	Robinia pseudoacacia	Open Space	No	10	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	197	Cordaville Rd	Front	Cordaville Rd	197870.28	892445	42.28248	-71.5258
1	Greg Baldwin (DRG)	2022/08/18	pole number 116	145	2022/07/28	GrBa20220728135408	12:29:49	Elm, American	Ulmus americana	Wooded Space	No	10	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	189	Woodland Rd	Rear	Cordaville Rd	198072.23	891330.3	42.27244	-71.5234
1	Greg Baldwin (DRG)	2022/08/18	pole number 128	146	2022/07/28	GrBa20220728144953	12:37:50	Cherry, Black	Prunus serotina	Wooded Space	No	9	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	274	Cordaville Rd	Front	Cordaville Rd	198097.22	890946	42.26898	-71.5231
1	Greg Baldwin (DRG)	2022/08/26	large leader or limb decay	147	2022/07/29	GrBa20220729105414	8:10	Maple, Red	Acer rubrum	Open Space	Yes	11	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	202	Cordaville Rd	Front	Cordaville Rd	197891.44	892350.2	42.28162	-71.5256
1	Greg Baldwin (DRG)	2022/08/18	pole number 99; borderline	148	2022/07/28	GrBa20220728130020	12:10:00	Maple, Red	Acer rubrum	Wooded Space	No	11	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Significant	Low	Yes	224	Cordaville Rd	Front	Cordaville Rd	197936.73	891900.1	42.27757	-71.525
1	Greg Baldwin (DRG)	2022/07/29		149	2022/07/29	GrBa20220729080454	8:05:43	Pine, Eastern White	Pinus strobus	Open Space	No	9	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	197	Cordaville Rd	Front	Cordaville Rd	197869.75	892446.8	42.28249	-71.5258
1	Greg Baldwin (DRG)	2022/07/28		150	2022/07/28	GrBa20220728113108	11:31:57	Pine, Eastern White	Pinus strobus	Open Space	No	10	Good	Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Significant	Low	Yes	275	Cordaville Rd	Front	Cordaville Rd	198067.71	890912.2	42.26868	-71.5234
1	Greg Baldwin (DRG)	2022/08/18	pole number 146; utility pruned	151	2022/07/29	GrBa20220729124254	12:01:25	Elm, American	Ulmus americana	Open Space	No	13	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	28	Cordaville Rd	Front	Cordaville Rd	197740.84	894196.8	42.29825	-71.5274
1	Greg Baldwin (DRG)	2022/08/18	pole number 164; trunk wounds	152	2022/07/29	GrBa20220729092322	12:03:19	Pine, Eastern White	Pinus strobus	Wooded Space	No	23	Poor	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	24	Cordaville Rd	Front	Cordaville Rd	197777.33	893774.5	42.29445	-71.527
1	Greg Baldwin (DRG)	2022/07/28	pole number 117	155	2022/07/28	GrBa20220728135636	13:57:53	Ash, White	Fraxinus americana	Wooded Space	Yes	16	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	193	Woodland Rd	Side	Cordaville Rd	198086.69	891286.3	42.27205	-71.5232
1	Greg Baldwin (DRG)	2022/08/18	pole number 128	156	2022/07/28	GrBa20220728145139	12:37:50	Elm, American	Ulmus americana	Wooded Space	Yes	15	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	274	Cordaville Rd	Front	Cordaville Rd	198097.16	890943.6	42.26896	-71.5231
1	Greg Baldwin (DRG)	2022/08/18	utility pruned	157	2022/07/29	GrBa20220729105532	10:18:58	Maple, Red	Acer rubrum	Open Space	No	16	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	202	Cordaville Rd	Front	Cordaville Rd	197892.27	892346.3	42.28159	-71.5256

1	Greg Baldwin (DRG)	2022/08/18	pole number 99	158	2022/07/28	GrBa20220728130216	12:10:00	Oak, Northern Red	Quercus rubra	Wooded Space	No	17	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	224	Cordaville Rd	Front	Cordaville Rd	197936.85	891892.6	42.2775	-71.525
1	Greg Baldwin (DRG)	2022/08/18	pole number 49	159	2022/07/29	GrBa20220729092825	12:03:19	Pine	Pinus species	Wooded Space	No	14	Dead	Remove	None	No Significant Defect	None	Probable	High	Likely	Minor	Moderate	Yes	24	Cordaville Rd	Front	Cordaville Rd	197798.87	893574.1	42.29264	-71.5267
1	Greg Baldwin (DRG)	2022/07/29	start hedge row; 22	161	2022/07/29	GrBa20220729080551	8:07:03	Cedar, Northern White	Thuja occidentalis	Open Space	No	1	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Very Low	Unlikely	Negligible	Low	Yes	193	Cordaville Rd	Front	Cordaville Rd	197868.81	892451.9	42.28254	-71.5258
1	Greg Baldwin (DRG)	2022/08/18	pole number 128	165	2022/07/28	GrBa20220728145304	12:37:50	Elm, American	Ulmus americana	Wooded Space	No	11	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	274	Cordaville Rd	Front	Cordaville Rd	198099.8	890923	42.26878	-71.523
1	Greg Baldwin (DRG)	2022/08/18	pole number 117	166	2022/07/28	GrBa20220728135835	12:30:57	Ash, White	Fraxinus americana	Wooded Space	Yes	11	Poor	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	262	Cordaville Rd	Front	Cordaville Rd	198087.98	891279.2	42.27198	-71.5232
1	Greg Baldwin (DRG)	2022/08/18		167	2022/07/29	GrBa20220729105612	10:18:58	Maple, Red	Acer rubrum	Open Space	No	12	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	202	Cordaville Rd	Front	Cordaville Rd	197892.38	892341.9	42.28155	-71.5256
1	Greg Baldwin (DRG)	2022/08/18	pole number 99	168	2022/07/28	GrBa20220728130401	12:10:00	Oak, Northern Red	Quercus rubra	Wooded Space	Yes	22	Poor	Prune	None	Weakly Attached Branches And Codominant Stems	Low	Possible	Medium	Unlikely	Significant	Low	Yes	224	Cordaville Rd	Front	Cordaville Rd	197938.08	891883.7	42.27742	-71.525
1	Greg Baldwin (DRG)	2022/07/28	foliage disorder	169	2022/07/28	GrBa20220728113900	11:42:15	Spruce, Norway	Picea abies	Open Space	No	21	Poor	Routine Prune	None	Other	Low	Possible	Low	Unlikely	Minor	Low	Yes	269	Cordaville Rd	Front	Cordaville Rd	198081.75	890975.9	42.26925	-71.5233
1	Greg Baldwin (DRG)	2022/08/18	pole number 49; utility pruned	170	2022/07/29	GrBa20220729093335	12:03:19	Oak, Black	Quercus velutina	Wooded Space	No	18	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	24	Cordaville Rd	Front	Cordaville Rd	197802.11	893569.5	42.2926	-71.5267
1	Greg Baldwin (DRG)	2022/07/29	end hedge row; 22	172	2022/07/29	GrBa20220729080730	8:08	Cedar, Northern White	Thuja occidentalis	Open Space	No	1	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Very Low	Unlikely	Negligible	Low	Yes	193	Cordaville Rd	Front	Cordaville Rd	197867.75	892464	42.28265	-71.5259
1	Greg Baldwin (DRG)	2022/08/18	pole number 128; vines >50%	175	2022/07/28	GrBa20220728145427	12:37:50	Ash, White	Fraxinus americana	Wooded Space	Yes	12	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Significant	Low	Yes	274	Cordaville Rd	Front	Cordaville Rd	198101.33	890910.7	42.26866	-71.523
1	Greg Baldwin (DRG)	2022/08/18	pole number 117; borderline	176	2022/07/28	GrBa20220728135943	12:30:57	Ash, White	Fraxinus americana	Wooded Space	No	10	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	262	Cordaville Rd	Front	Cordaville Rd	198089.22	891276.6	42.27196	-71.5232
1	Greg Baldwin (DRG)	2022/08/18	pole number 99; borderline	177	2022/07/28	GrBa20220728130613	12:10:00	Oak, Northern Red	Quercus rubra	Wooded Space	No	9	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	224	Cordaville Rd	Front	Cordaville Rd	197940.84	891874.8	42.27734	-71.525
1	Greg Baldwin (DRG)	2022/07/29	borderline	178	2022/07/29	GrBa20220729105751	10:58:54	Maple, Red	Acer rubrum	Open Space	Yes	22	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	202	Cordaville Rd	Front	Cordaville Rd	197896.26	892320.7	42.28136	-71.5255
1	Greg Baldwin (DRG)	2022/07/29	pole number 71; dbh estimated; poison ivy	179	2022/07/29	GrBa20220729101317	10:15:31	Pine, Eastern White	Pinus strobus	Wooded Space	No	32	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	46	Mount Vickery Rd	Side	Cordaville Rd	197870.49	892816.9	42.28583	-71.5258
1	Greg Baldwin (DRG)	2022/07/28	foliage disorder	181	2022/07/28	GrBa20220728114226	11:42:54	Spruce, Norway	Picea abies	Open Space	No	19	Poor	Routine Prune	None	Other	Low	Possible	Low	Unlikely	Minor	Low	Yes	269	Cordaville Rd	Front	Cordaville Rd	198082.77	890977.7	42.26927	-71.5232
1	Greg Baldwin (DRG)	2022/07/29		182	2022/07/29	GrBa20220729081100	8:12:27	Maple, Red	Acer rubrum	Open Space	Yes	30	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Severe	Low	Yes	189	Cordaville Rd	Front	Cordaville Rd	197863.76	892500.1	42.28297	-71.5259
1	Greg Baldwin (DRG)	2022/08/18	pole number 118	184	2022/07/28	GrBa20220728140059	12:30:57	Maple, Red	Acer rubrum	Wooded Space	No	9	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	262	Cordaville Rd	Front	Cordaville Rd	198090.74	891269.9	42.2719	-71.5231
1	Greg Baldwin (DRG)	2022/08/18	pole number 128; vines >50%	185	2022/07/28	GrBa20220728145640	12:37:50	Ash, White	Fraxinus americana	Wooded Space	No	14	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	274	Cordaville Rd	Front	Cordaville Rd	198103.8	890903	42.2686	-71.523
1	Greg Baldwin (DRG)	2022/07/29		187	2022/07/29	GrBa20220729105901	11:00:03	Oak, Northern Red	Quercus rubra	Open Space	No	30	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	204	Cordaville Rd	Front	Cordaville Rd	197894.67	892317	42.28132	-71.5255
1	Greg Baldwin (DRG)	2022/08/18	pole number 99; borderline	188	2022/07/28	GrBa20220728130729	12:10:00	Oak, Northern Red	Quercus rubra	Wooded Space	No	10	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	224	Cordaville Rd	Front	Cordaville Rd	197941.31	891873.3	42.27733	-71.525
1	Greg Baldwin (DRG)	2022/07/28	foliage disorder	189	2022/07/28	GrBa20220728114341	11:44:27	Spruce, Norway	Picea abies	Open Space	No	21	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	269	Cordaville Rd	Front	Cordaville Rd	198084.47	890988.1	42.26936	-71.5232
1	Greg Baldwin (DRG)	2022/07/29	pole number 71; dbh estimated; poison ivy; utility pruned	190	2022/07/29	GrBa20220729101535	10:16:35	Pine, Eastern White	Pinus strobus	Wooded Space	No	14	Poor	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	46	Mount Vickery Rd	Side	Cordaville Rd	197870.9	892812.5	42.28579	-71.5258
1	Greg Baldwin (DRG)	2022/07/29		192	2022/07/29	GrBa20220729081537	8:16:41	Hornbeam, European	Carpinus betulus Fraxinus	Open Space	No	10	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems Missing Or Decayed	Low	Improbable	Low	Unlikely	Minor	Low	Yes	189	Cordaville Rd	Front	Cordaville Rd	197862.77	892513.6	42.2831	-71.5259
1	Greg Baldwin (DRG)	2022/08/18	pole number 128; leaning	195	2022/07/28	GrBa20220728145818	12:37:50	Ash, White	americana	Wooded Space	No	16	Fair	Routine Prune	None	Wood	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	274	Cordaville Rd	Front	Cordaville Rd	198106.74	890895.2	42.26853	-71.5229
1	Greg Baldwin (DRG)	2022/08/18	pole number 118; borderline	196	2022/07/28	GrBa20220728140220	12:30:57	Hickory, Pignut	Carya glabra	Wooded Space	No	14	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	262	Cordaville Rd	Front	Cordaville Rd	198091.74	891265.8	42.27186	-71.5231
1	Greg Baldwin (DRG)	2022/07/29	borderline	197	2022/07/29	GrBa20220729110148	11:02:39	Oak, Northern Red	Quercus rubra	Open Space	No	36	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Severe	Low	Yes	206	Cordaville Rd	Front	Cordaville Rd	197899.42	892281.7	42.28101	-71.5255
1	Greg Baldwin (DRG)	2022/08/18	pole number 101; borderline; leaning	198	2022/07/28	GrBa20220728131141	12:10:30	Oak, Northern Red	Quercus rubra	Wooded Space	No	11	Poor	Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	228	Cordaville Rd	Front	Cordaville Rd	197953.7	891813.2	42.27679	-71.5248
1	Greg Baldwin (DRG)	2022/07/29	pole number 71	199	2022/07/29	GrBa20220729101725	10:18:03	Maple, Red	Acer rubrum	Wooded Space	No	19	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	46	Mount Vickery Rd	Side	Cordaville Rd	197870.49	892803.4	42.2857	-71.5258
1	Greg Baldwin (DRG)	2022/07/28	foliage disorder	201	2022/07/28	GrBa20220728114432	11:45:53	Spruce, Norway	Picea abies	Open Space	No	15	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	269	Cordaville Rd	Front	Cordaville Rd	198085.32	890990.5	42.26938	-71.5232
1	Greg Baldwin (DRG)	2022/07/29		202	2022/07/29	GrBa20220729081703	8:17:31	Hornbeam, European	Carpinus betulus	Open Space	No	13	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	189	Cordaville Rd	Front	Cordaville Rd	197862.83	892516.1	42.28312	-71.5259
1	Greg Baldwin (DRG)	2022/08/18	pole number 128	205	2022/07/28	GrBa20220728150041	12:37:50	Cherry, Black	Prunus serotina	Wooded Space	No	8	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	274	Cordaville Rd	Front	Cordaville Rd	198110.79	890885.6	42.26844	-71.5229
1	Greg Baldwin (DRG)	2022/08/18	pole number 118; borderline	206	2022/07/28	GrBa20220728140335	12:30:57	Elm, American	Ulmus americana	Wooded Space	No	13	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	262	Cordaville Rd	Front	Cordaville Rd	198092.87	891262.8	42.27183	-71.5231
1	Greg Baldwin (DRG)	2022/08/18	pole number 102; borderline	207	2022/07/28	GrBa20220728131321	12:10:30	Elm, American	Ulmus americana	Wooded Space	No	12	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	228	Cordaville Rd	Front	Cordaville Rd	197957.76	891795.2	42.27663	-71.5248
1	Greg Baldwin (DRG)	2022/07/29	utility pruned; lost major leader or limb	208	2022/07/29	GrBa20220729110519	11:06:52	Ash, White	Fraxinus americana	Wooded Space	No	19	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	208	Cordaville Rd	Front	Cordaville Rd	197908.57	892179	42.28008	-71.5254
1	Greg Baldwin (DRG)	2022/07/29	pole number 72; utility pruned	209	2022/07/29	GrBa20220729101849	10:19:43	Maple, Red	Acer rubrum	Wooded Space	Yes	15	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Significant	Low	Yes	46	Mount Vickery Rd	Side	Cordaville Rd	197871.36	892772.6	42.28543	-71.5258
1	Greg Baldwin (DRG)	2022/07/28		210	2022/07/28	GrBa20220728114620	11:47:24	Mulberry, White	Morus alba	Open Space	Yes	8	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	269	Cordaville Rd	Front	Cordaville Rd	198086.94	890988.6	42.26937	-71.5232
1	Greg Baldwin (DRG)	2022/07/29		214	2022/07/29	GrBa20220729081746	8:18:07	Hornbeam, European	Carpinus betulus	Open Space	No	13	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	189	Cordaville Rd	Front	Cordaville Rd	197862.36	892518.4	42.28314	-71.5259
1	Greg Baldwin (DRG)	2022/08/18	pole number 128	215	2022/07/29	GrBa20220728150222	12:37:50	Elm, American	Ulmus americana Fraxinus	Wooded Space	Yes	10	Dead	Remove	None	No Significant Defect Dead And Dying	None	Possible	Medium	Unlikely	Significant	Low	Yes	274	Cordaville Rd	Front	Cordaville Rd	198111.73	890884.5	42.26843	-71.5229
1	Greg Baldwin (DRG)	2022/08/18	pole number 118; borderline	216	2022/07/28	GrBa20220728140603	12:30:57	Ash, White	americana	Wooded Space	No	20	Poor	Routine Prune	None	Branches	Low	Possible	Low	Unlikely	Severe	Low	Yes	262	Cordaville Rd	Front	Cordaville Rd	198094.64	891256.9	42.27178	-71.5231
1	Greg Baldwin (DRG)	2022/08/18	pole number 102	217	2022/07/28	GrBa20220728131450	12:11:59	Maple, Red	Acer rubrum Fraxinus	Wooded Space	No	11	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems Missing Or Decayed	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	7	Watkins Ln	Rear	Cordaville Rd	197958.52	891791	42.27659	-71.5247
1	Greg Baldwin (DRG)	2022/07/28		218	2022/07/28	GrBa20220728114900	11:59	Ash, White	americana	Wooded Space	No	8	Poor	Remove	None	Wood	None	Possible	Medium	Unlikely	Minor	Low	Yes	269	Cordaville Rd	Front	Cordaville Rd	198087.94	890997.9	42.26945	-71.5232
1	Greg Baldwin (DRG)	2022/07/29		219	2022/07/29	GrBa20220729102033	10:22:14	Oak, Black	Quercus velutina	Open Space	No	32	Fair	Prune	None	Dead And Dying Branches	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	176	Cordaville Rd	Front	Cordaville Rd	197870.76	892734.8	42.28509	-71.5258
1	Greg Baldwin (DRG)	2022/07/29		221	2022/07/29	GrBa20220729110747	11:08:46	Oak, Northern Red	Quercus rubra	Wooded Space	No	21	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Minor	Low	Yes	218	Cordaville Rd	Front	Cordaville Rd	197909.62	892169	42.27999	-71.5253

1	Greg Baldwin (DRG)	2022/07/29		223	2022/07/29	GrBa20220729081823	8:18:42	Hornbeam, European	Carpinus betulus	Open Space	No	9	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	189	Cordaville Rd	Front	Cordaville Rd	197862.06	892520.6	42.28316	-71.5259
1	Greg Baldwin (DRG)	2022/08/18	pole number 118; borderline	226	2022/07/28	GrBa20220728140732	12:30:57	Elm, American	Ulmus americana	Wooded Space	No	12	Poor	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	262	Cordaville Rd	Front	Cordaville Rd	198093.58	891258.5	42.2718	-71.5231
1	Greg Baldwin (DRG)	2022/08/18	pole number 103	227	2022/07/28	GrBa20220728131646	12:11:59	Oak, White	Quercus alba	Wooded Space	No	13	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	7	Watkins Ln	Rear	Cordaville Rd	197961.63	891771.7	42.27642	-71.5247
1	Greg Baldwin (DRG)	2022/07/29	borderline; dbh estimated; poison ivy; utility pruned	228	2022/07/29	GrBa20220729102305	10:25:17	Spruce, Norway	Picea abies	Open Space	No	25	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	182	Cordaville Rd	Front	Cordaville Rd	197870.5	892671.2	42.28451	-71.5258
1	Greg Baldwin (DRG)	2022/07/28	topped	230	2022/07/28	GrBa20220728115333	11:58:52	Walnut, Black	Juglans nigra	Wooded Space	No	8	Poor	Routine Prune	None	Tree Architecture	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	269	Cordaville Rd	Front	Cordaville Rd	198094.18	891028.1	42.26972	-71.5231
1	Greg Baldwin (DRG)	2022/07/29	utility pruned	231	2022/07/29	GrBa20220729111000	11:10:39	Oak, Northern Red	Quercus rubra	Wooded Space	No	26	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	218	Cordaville Rd	Front	Cordaville Rd	197910.5	892163.1	42.27994	-71.5253
1	Greg Baldwin (DRG)	2022/07/29		233	2022/07/29	GrBa20220729081901	8:19:21	Hornbeam, European	Carpinus betulus	Open Space	No	11	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	189	Cordaville Rd	Front	Cordaville Rd	197861.65	892522.8	42.28318	-71.5259
1	Greg Baldwin (DRG)	2022/08/18	pole number119; off ROW	235	2022/07/28	GrBa20220728140917	12:30:57	Tree, Unknown	Unknown Tree	Wooded Space	No	17	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	262	Cordaville Rd	Front	Cordaville Rd	198099.75	891246.2	42.27169	-71.523
1	Greg Baldwin (DRG)	2022/08/18	pole number 103	237	2022/07/28	GrBa20220728131824	12:11:59	Oak, White	Quercus alba	Wooded Space	No	9	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	7	Watkins Ln	Rear	Cordaville Rd	197963.51	891769.2	42.27639	-71.5247
1	Greg Baldwin (DRG)	2022/07/28		239	2022/07/28	GrBa20220728115754	12:00:34	Tree, Unknown	Unknown Tree	Open Space	No	12	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Significant	Low	Yes	269	Cordaville Rd	Front	Cordaville Rd	198101.84	891054.6	42.26996	-71.523
1	Greg Baldwin (DRG)	2022/07/29	utility pruned	240	2022/07/29	GrBa20220729102713	10:28:07	Maple, Norway	Acer platanoides	Open Space	No	11	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	188	Cordaville Rd	Front	Cordaville Rd	197868.52	892594.1	42.28382	-71.5258
1	Greg Baldwin (DRG)	2022/07/29	topped for utility	241	2022/07/29	GrBa20220729111110	11:11:45	Redcedar, Eastern	Juniperus virginiana	Wooded Space	No	9	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	218	Cordaville Rd	Front	Cordaville Rd	197910.38	892155.8	42.27987	-71.5253
1	Greg Baldwin (DRG)	2022/07/29		244	2022/07/29	GrBa20220729081950	8:20:03	Hornbeam, European	Carpinus betulus	Open Space	No	15	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	189	Cordaville Rd	Front	Cordaville Rd	197861.77	892524.6	42.28319	-71.5259
1	Greg Baldwin (DRG)	2022/08/18	pole number119	246	2022/07/28	GrBa20220728141056	12:30:57	Oak, Northern Red	Quercus rubra	Wooded Space	No	10	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	262	Cordaville Rd	Front	Cordaville Rd	198100.28	891234.8	42.27158	-71.523
1	Greg Baldwin (DRG)	2022/08/18	pole number 103; trunk wounds; Co-dominants	247	2022/07/28	GrBa20220728131921	12:11:59	Oak, Northern Red	Quercus rubra	Wooded Space	No	12	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	7	Watkins Ln	Rear	Cordaville Rd	197962.57	891766.4	42.27637	-71.5247
1	Greg Baldwin (DRG)	2022/07/29		248	2022/07/29	GrBa20220729102824	10:28:54	Redcedar, Eastern	Juniperus virginiana	Open Space	No	3	Poor	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	184	Cordaville Rd	Front	Cordaville Rd	197869.35	892600	42.28387	-71.5258
1	Greg Baldwin (DRG)	2022/08/18	pole number 123; borderline;	249	2022/07/28	GrBa20220728120105	12:33:13	Hickory, Shagbark	Carya ovata	Wooded Space	No	23	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	265	Cordaville Rd	Front	Cordaville Rd	198107.85	891083.6	42.27022	-71.5229
1	Greg Baldwin (DRG)	2022/07/29		251	2022/07/29	GrBa20220729111256	11:13:14	Redcedar, Eastern	Juniperus virginiana	Wooded Space	No	10	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Negligible	Low	Yes	218	Cordaville Rd	Front	Cordaville Rd	197916.37	892103.5	42.2794	-71.5253
1	Greg Baldwin (DRG)	2022/07/29		253	2022/07/29	GrBa20220729082005	8:20:24	Hornbeam, European	Carpinus betulus	Open Space	No	15	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	189	Cordaville Rd	Front	Cordaville Rd	197861.77	892525.7	42.2832	-71.5259
1	Greg Baldwin (DRG)	2022/07/29	borderline	255	2022/07/29	GrBa20220729073854	7:40:07	Maple, Norway	Acer platanoides	Open Space	No	17	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	213	Cordaville Rd	Front	Cordaville Rd	197902.85	892094.8	42.27932	-71.5254
1	Greg Baldwin (DRG)	2022/08/18	pole number119; borderline	256	2022/07/28	GrBa20220728141425	12:30:57	Oak, Scarlet	Quercus coccinea	Wooded Space	No	23	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	262	Cordaville Rd	Front	Cordaville Rd	198103.39	891227.9	42.27152	-71.523
1	Greg Baldwin (DRG)	2022/08/18	pole number 103	257	2022/07/28	GrBa20220728132258	12:11:59	Maple, Sugar	Acer saccharum	Wooded Space	No	9	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	7	Watkins Ln	Rear	Cordaville Rd	197965.63	891763.9	42.27635	-71.5247
1	Greg Baldwin (DRG)	2022/08/18		258	2022/07/28	GrBa20220728120805	10:18:58	Hickory, Pignut	Carya glabra	Open Space	No	26	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	255	Cordaville Rd	Front	Cordaville Rd	198085.26	891243.3	42.27166	-71.5232
1	Greg Baldwin (DRG)	2022/08/18	pole number 95	260	2022/07/29	GrBa20220729111505	12:09	Oak, Northern Red	Quercus rubra	Wooded Space	No	17	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	218	Cordaville Rd	Front	Cordaville Rd	197925.14	892008.8	42.27855	-71.5252
1	Greg Baldwin (DRG)	2022/07/29	utility pruned	261	2022/07/29	GrBa20220729102912	10:29:36	Maple, Norway	Acer platanoides	Open Space	No	8	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	188	Cordaville Rd	Front	Cordaville Rd	197869.52	892588.9	42.28377	-71.5258
1	Greg Baldwin (DRG)	2022/07/29	growing into grate or guard	264	2022/07/29	GrBa20220729082205	8:22:40	Locust, Black	Robinia pseudoacacia	Wooded Space	No	21	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Possible	Medium	Unlikely	Significant	Low	Yes	185	Cordaville Rd	Front	Cordaville Rd	197857.14	892573.8	42.28364	-71.526
1	Greg Baldwin (DRG)	2022/08/26	pole number119; borderline	265	2022/07/28	GrBa20220728141527	8:44:54	Oak, Black	Quercus velutina	Wooded Space	No	10	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	262	Cordaville Rd	Front	Cordaville Rd	198103.69	891226	42.2715	-71.523
1	Greg Baldwin (DRG)	2022/07/29	borderline	266	2022/07/29	GrBa20220729074323	7:44:00	Maple, Red	Acer rubrum	Open Space	Yes	14	Fair	Routine Prune	None	Broken And/Or Hanging Branches	Low	Probable	Low	Unlikely	Minor	Low	Yes	211	Cordaville Rd	Front	Cordaville Rd	197896.37	892164.8	42.27995	-71.5255
1	Greg Baldwin (DRG)	2022/08/18	pole number 103	267	2022/07/28	GrBa20220728132416	12:11:59	Oak, Northern Red	Quercus rubra	Wooded Space	No	21	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	7	Watkins Ln	Rear	Cordaville Rd	197966.45	891758.2	42.27629	-71.5247
1	Greg Baldwin (DRG)	2022/08/18	pole number 95; leaning	269	2022/07/29	GrBa20220729111655	12:09	Tree, Unknown	Unknown Tree	Wooded Space	No	13	Dead	Remove	None	No Significant Defect	None	Probable	Medium	Somewhat Likely	Significant	Moderate	Yes	218	Cordaville Rd	Front	Cordaville Rd	197925.37	892005.5	42.27852	-71.5252
1	Greg Baldwin (DRG)	2022/08/26		270	2022/07/29	GrBa20220729103019	7:50:54	Redcedar, Eastern	Juniperus virginiana	Open Space	Yes	5	Poor	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	188	Cordaville Rd	Front	Cordaville Rd	197869.93	892577.6	42.28367	-71.5258
1	Greg Baldwin (DRG)	2022/07/28	borderline; start hedge row; 4	272	2022/07/28	GrBa20220728121044	12:12:09	Cedar, Northern White	Thuja occidentalis	Open Space	Yes	6	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	255	Cordaville Rd	Front	Cordaville Rd	198077.14	891267	42.27187	-71.5233
1	Greg Baldwin (DRG)	2022/07/29		274	2022/07/29	GrBa20220729082250	8:23:53	Pine, Eastern White	Pinus strobus	Wooded Space	Yes	11	Poor	Routine Prune	None	Tree Architecture	Low	Possible	Low	Unlikely	Significant	Low	Yes	185	Cordaville Rd	Front	Cordaville Rd	197857.38	892575.4	42.28365	-71.526
1	Greg Baldwin (DRG)	2022/08/18	pole number119; borderline	275	2022/07/28	GrBa20220728141632	12:30:57	Oak, Scarlet	Quercus coccinea	Wooded Space	No	21	Fair	Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	262	Cordaville Rd	Front	Cordaville Rd	198104.57	891224.4	42.27149	-71.523
1	Greg Baldwin (DRG)	2022/07/29	Co-dominants; borderline	276	2022/07/29	GrBa20220729074405	7:48:43	Maple, Norway	Acer platanoides	Open Space	No	15	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	211	Cordaville Rd	Front	Cordaville Rd	197899.71	892131	42.27965	-71.5255
1	Greg Baldwin (DRG)	2022/08/18	pole number 103	277	2022/07/28	GrBa20220728132448	12:11:59	Oak, White	Quercus alba	Wooded Space	No	9	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	7	Watkins Ln	Rear	Cordaville Rd	197967.16	891755.4	42.27627	-71.5246
1	Greg Baldwin (DRG)	2022/08/18	pole number 95	278	2022/07/29	GrBa20220729111939	12:09	Elm, American	Ulmus americana	Wooded Space	No	9	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	218	Cordaville Rd	Front	Cordaville Rd	197926.08	891991.8	42.2784	-71.5251
1	Greg Baldwin (DRG)	2022/07/29		279	2022/07/29	GrBa20220729103305	10:34:25	Oak, Black	Quercus velutina	Open Space	No	34	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	190	Cordaville Rd	Front	Cordaville Rd	197878.49	892486.1	42.28285	-71.5257
1	Greg Baldwin (DRG)	2022/07/28	borderline; end hedge row; 4	281	2022/07/28	GrBa20220728121214	12:12:57	Cedar, Northern White	Thuja occidentalis	Open Space	Yes	4	Poor	Routine Prune	None	Tree Architecture	Low	Possible	Low	Unlikely	Minor	Low	Yes	253	Cordaville Rd	Front	Cordaville Rd	198076.26	891272.1	42.27192	-71.5233
1	Greg Baldwin (DRG)	2022/07/29		283	2022/07/29	GrBa20220729082411	8:25:13	Pine, Eastern White	Pinus strobus	Wooded Space	No	19	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Minor	Low	Yes	185	Cordaville Rd	Front	Cordaville Rd	197857.38	892577.7	42.28367	-71.526
1	Ashley Casello (DRG)	2022/08/05		1239	2022/08/05	AsCa20220805082043	8:22:12	Maple, Norway	Acer platanoides	Open Space	No	16	Good	Routine Prune	None	Broken And/Or Hanging Branches	Low	Probable	Low	Unlikely	Negligible	Low	Yes	6	Cross St	Front	Cross St	197662.63	896547.9	42.31942	-71.5284
1	Greg Baldwin (DRG)	2022/08/18	pole number 2	1052	2022/08/05	GrBa20220805093730	10:44:31	Oak, Northern Red	Quercus rubra	Wooded Space	No	39	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	127	Deerfoot Rd	Front	Deerfoot Rd	196420.78	893246.1	42.28968	-71.5434

1	Greg Baldwin (DRG)	2022/08/18	pole number 1	1054	2022/08/05	GrBa20220805090239	10:45:06	Ash, White	Fraxinus americana	Wooded Space	No	14	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Significant	Low	Yes	114	Deerfoot Rd	Front	Deerfoot Rd	196442.3	893299.9	42.29017	-71.5431
1	Greg Baldwin (DRG)	2022/08/18	pole number 1	1064	2022/08/05	GrBa20220805090528	10:45:06	Ash, White	Fraxinus americana	Wooded Space	No	9	Dead	Remove	None	No Significant Defect	None	Possible	High	Somewhat Likely	Minor	Low	Yes	114	Deerfoot Rd	Front	Deerfoot Rd	196440.59	893295.1	42.29013	-71.5432
1	Greg Baldwin (DRG)	2022/08/18	pole number 1	1074	2022/08/05	GrBa20220805090835	10:45:06	Ash, White	Fraxinus americana	Wooded Space	No	8	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Significant	Low	Yes	114	Deerfoot Rd	Front	Deerfoot Rd	196432.81	893266.4	42.28987	-71.5433
1	Greg Baldwin (DRG)	2022/08/18	pole number 2	1083	2022/08/05	GrBa20220805091050	10:45:06	Maple, Red	Acer rubrum	Wooded Space	No	28	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Low	Unlikely	Significant	Low	Yes	114	Deerfoot Rd	Front	Deerfoot Rd	196432.4	893263.4	42.28984	-71.5433
1	Greg Baldwin (DRG)	2022/08/18	pole number 3	1094	2022/08/05	GrBa20220805091410	10:42	Oak, White	Quercus alba	Wooded Space	No	46	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	116	Deerfoot Rd	Front	Deerfoot Rd	196425.8	893235.5	42.28959	-71.5433
1	Greg Baldwin (DRG)	2022/08/19	pole number 6	1104	2022/08/05	GrBa20220805091659	15:15:46	Basswood, American	Tilia americana	Open Space	No	19	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	118	Deerfoot Rd	Front	Deerfoot Rd	196404.58	893136.7	42.2887	-71.5436
1	Greg Baldwin (DRG)	2022/08/05		1114	2022/08/05	GrBa20220805091950	9:26:49	Oak, White	Quercus alba	Open Space	No	40	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	120	Deerfoot Rd	Front	Deerfoot Rd	196402.04	893111.8	42.28848	-71.5436
1	Greg Baldwin (DRG)	2022/08/26	borderline; pole number 3	1121	2022/08/05	GrBa20220805093106	6:44:18	Oak, Northern Red	Quercus rubra	Wooded Space	No	20	Poor	Prune	None	Missing Or Decayed Wood	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	129	Deerfoot Rd	Front	Deerfoot Rd	196414.77	893222.4	42.28947	-71.5435
1	Greg Baldwin (DRG)	2022/08/18	pole number 2	1127	2022/08/05	GrBa20220805093456	10:44:31	Oak, Northern Red	Quercus rubra	Wooded Space	No	16	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	127	Deerfoot Rd	Front	Deerfoot Rd	196419.19	893238	42.28961	-71.5434
1	Ashley Casello (DRG)	2022/08/11		1465	2022/08/08	AsCa20220808152201	20:34:28	Oak, Northern Red	Quercus rubra	Open Space	No	26	Fair	Prune	None	Dead And Dying Branches	Low	Probable	Medium	Somewhat Likely	Minor	Low	Yes	212	Southville Rd	Side	Flanders Rd	196309.66	890705.1	42.26681	-71.5447
1	Greg Baldwin (DRG)	2022/08/04	borderline; pole number 37	689	2022/08/04	GrBa20220804070216	7:03:08	Maple, Red	Acer rubrum	Wooded Space	No	12	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	198540.71	895551.7	42.31045	-71.5177
1	Greg Baldwin (DRG)	2022/08/04	borderline; pole number 36	698	2022/08/04	GrBa20220804070435	7:05:05	Maple, Red	Acer rubrum	Wooded Space	No	12	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	198523.17	895604.2	42.31092	-71.5179
1	Greg Baldwin (DRG)	2022/08/04	pole number 35	708	2022/08/04	GrBa20220804071005	7:10:39	Ash, White	Fraxinus americana	Wooded Space	No	13	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	198513.01	895644.2	42.31128	-71.518
1	Greg Baldwin (DRG)	2022/08/04	pole number 35	713	2022/08/04	GrBa20220804071044	7:11:13	Maple, Red	Acer rubrum	Wooded Space	No	10	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Very Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	198513.71	895639.6	42.31124	-71.518
1	Greg Baldwin (DRG)	2022/08/04	pole number 41; borderline	727	2022/08/04	GrBa20220804071623	7:17:00	Maple, Norway	Acer platanoides	Wooded Space	Yes	8	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	198627.23	895402.5	42.3091	-71.5167
1	Greg Baldwin (DRG)	2022/08/04	pole number 42; dbh estimated; poison ivy	735	2022/08/04	GrBa20220804071814	7:19:22	Maple, Norway	Acer platanoides	Wooded Space	No	12	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	198646.04	895373.8	42.30885	-71.5164
1	Greg Baldwin (DRG)	2022/08/04	pole number 42	745	2022/08/04	GrBa20220804071947	7:20:51	Maple, Norway	Acer platanoides	Wooded Space	No	11	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	198652.8	895365.3	42.30877	-71.5163
1	Greg Baldwin (DRG)	2022/08/04	pole number 42	755	2022/08/04	GrBa20220804072140	7:22:50	Oak, Northern Red	Quercus rubra	Wooded Space	No	16	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	198658.3	895356.1	42.30869	-71.5163
1	Greg Baldwin (DRG)	2022/08/04	pole number 42	763	2022/08/04	GrBa20220804072215	7:22:43	Elm, American	Ulmus americana	Wooded Space	No	14	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	198660.13	895353.7	42.30867	-71.5163
1	Greg Baldwin (DRG)	2022/08/04	pole number 42	771	2022/08/04	GrBa20220804072313	7:23:45	Cherry, Black	Prunus serotina	Wooded Space	No	11	Poor	Routine Prune	None	Tree Architecture	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	198663.3	895347.9	42.30861	-71.5162
1	Greg Baldwin (DRG)	2022/08/04	pole number 45; Co-dominants	781	2022/08/04	GrBa20220804072614	7:29:04	Oak, Northern Red	Quercus rubra	Wooded Space	Yes	34	Fair	Prune	Annual Ins	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	198702	895257.2	42.3078	-71.5157
1	Greg Baldwin (DRG)	2022/08/04	pole number 46; borderline; dbh estimated; poison ivy	791	2022/08/04	GrBa20220804072947	7:31:12	Oak, Northern Red	Quercus rubra	Wooded Space	No	14	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	198722.9	895194.9	42.30724	-71.5155
1	Greg Baldwin (DRG)	2022/08/04	pole number 48	802	2022/08/04	GrBa20220804073418	7:35	Maple, Sugar	Acer saccharum	Wooded Space	No	18	Fair	Prune	None	Weakly Attached Branches And Codominant Stems	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	198731.3	895088.8	42.30628	-71.5154
1	Greg Baldwin (DRG)	2022/08/04	pole number 48; borderline	810	2022/08/04	GrBa20220804073540	7:38:45	Pine, Pitch	Pinus rigida	Wooded Space	No	18	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	198729.99	895037.8	42.30582	-71.5154
1	Greg Baldwin (DRG)	2022/08/04	pole number 48; borderline	820	2022/08/04	GrBa20220804073858	7:41:58	Maple, Red	Acer rubrum	Wooded Space	No	8	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	265	Boston Rd	Side	Framingham Rd	198730.47	895041.4	42.30585	-71.5154
1	Greg Baldwin (DRG)	2022/08/04	pole number 48; borderline	830	2022/08/04	GrBa20220804074200	7:42:41	Maple, Red	Acer rubrum	Wooded Space	No	9	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	198730.06	895045.3	42.30589	-71.5154
1	Greg Baldwin (DRG)	2022/08/04	pole number 48; borderline	840	2022/08/04	GrBa20220804074336	7:44:09	Pine, Eastern White	Pinus strobus	Wooded Space	No	13	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	198729.35	895033.1	42.30578	-71.5154
1	Greg Baldwin (DRG)	2022/08/04	borderline; pole number 35	844	2022/08/04	GrBa20220804064101	6:49:21	Hickory, Pignut	Carya glabra	Wooded Space	No	9	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	265	Boston Rd	Side	Framingham Rd	198499.37	895705	42.31183	-71.5182
1	Greg Baldwin (DRG)	2022/08/04	pole number 48	850	2022/08/04	GrBa20220804074510	7:45:44	Oak, Scarlet	Quercus coccinea	Wooded Space	No	15	Fair	Routine Prune	None	Broken And/Or Hanging Branches	Low	Probable	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	198728.47	895030	42.30575	-71.5154
1	Greg Baldwin (DRG)	2022/08/04	pole number 35	853	2022/08/04	GrBa20220804064201	6:49:28	Maple, Red	Acer rubrum	Wooded Space	No	14	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	198498.19	895702.9	42.31181	-71.5182
1	Greg Baldwin (DRG)	2022/08/04	pole number 49; borderline	860	2022/08/04	GrBa20220804074628	7:47:10	Oak, Scarlet	Quercus coccinea	Wooded Space	No	9	Poor	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	198728.87	895011.5	42.30558	-71.5154
1	Greg Baldwin (DRG)	2022/08/04	pole number 35	864	2022/08/04	GrBa20220804064240	6:49:32	Maple, Red	Acer rubrum	Wooded Space	No	12	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	198499.08	895701.2	42.31179	-71.5182
1	Greg Baldwin (DRG)	2022/08/04	pole number 49; borderline	870	2022/08/04	GrBa20220804074808	7:48:38	Maple, Sugar	Acer saccharum	Wooded Space	No	9	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	198728.7	895002	42.3055	-71.5154
1	Greg Baldwin (DRG)	2022/08/04	pole number 35	875	2022/08/04	GrBa20220804064522	7:09:57	Maple, Norway	Acer platanoides	Wooded Space	No	12	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	198509.6	895657.2	42.3114	-71.5181
1	Greg Baldwin (DRG)	2022/08/04	pole number 49; borderline	880	2022/08/04	GrBa20220804074843	7:49:13	Oak, Black	Quercus velutina	Wooded Space	No	8	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	198728.87	894999.6	42.30548	-71.5154
1	Greg Baldwin (DRG)	2022/08/04	pole number 35	885	2022/08/04	GrBa20220804064718	6:49:42	Maple, Red	Acer rubrum	Wooded Space	No	10	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	198513.87	895637.9	42.31122	-71.518
1	Greg Baldwin (DRG)	2022/08/04	pole number 49; borderline	889	2022/08/04	GrBa20220804075042	7:51:45	Oak, Black	Quercus velutina	Wooded Space	No	8	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	198729.28	894995.1	42.30544	-71.5154
1	Greg Baldwin (DRG)	2022/08/04	pole number 50; borderline	895	2022/08/04	GrBa20220804075251	7:53:29	Pine, Eastern White	Pinus strobus	Wooded Space	No	18	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	198731.45	894981.5	42.30532	-71.5154
1	Greg Baldwin (DRG)	2022/08/04	pole number 35	898	2022/08/04	GrBa20220804064811	6:49:46	Maple, Red	Acer rubrum	Wooded Space	No	10	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	198514.31	895636	42.31121	-71.518
1	Greg Baldwin (DRG)	2022/08/04	pole number 50; borderline	906	2022/08/04	GrBa20220804075354	7:54:21	Pine, Eastern White	Pinus strobus	Wooded Space	No	13	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	198731.98	894976.7	42.30527	-71.5154
1	Greg Baldwin (DRG)	2022/08/04	pole number 38	907	2022/08/04	GrBa20220804065435	7:14:37	Oak, Black	Quercus velutina	Wooded Space	No	11	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	265	Boston Rd	Side	Framingham Rd	198583.09	895465.1	42.30967	-71.5172
1	Greg Baldwin (DRG)	2022/08/04	pole number 39; borderline	916	2022/08/04	GrBa20220804065624	7:14:55	Oak, Black	Quercus velutina	Wooded Space	No	13	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	265	Boston Rd	Side	Framingham Rd	198608.96	895427.2	42.30933	-71.5169
1	Greg Baldwin (DRG)	2022/08/18	pole number 50; borderline	918	2022/08/04	GrBa20220804075728	11:35:54	Linden, Littleleaf	Tilia cordata	Wooded Space	No	24	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	50	Boston Rd	Side	Framingham Rd	198720.23	894952.4	42.30505	-71.5155

1	Greg Baldwin (DRG)	2022/08/04	borderline; pole number 37	923	2022/08/04	GrBa20220804070102	7:03:14	Maple, Red	Acer rubrum	Wooded Space	No	15	Fair	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	198538.81	895558.2	42.31051	-71.5177
1	Greg Baldwin (DRG)	2022/08/04	pole number 50	928	2022/08/04	GrBa20220804080024	8:05:16	Tree, Unknown	Unknown Tree	Wooded Space	No	33	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	10	Thayer Ln	Side	Framingham Rd	198709.28	894990.9	42.3054	-71.5157
1	Greg Baldwin (DRG)	2022/08/19	pole number 49	933	2022/08/04	GrBa20220804080333	14:58:31	Oak, Black	Quercus velutina	Wooded Space	No	16	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Possible	Medium	Unlikely	Significant	Low	Yes	8	Thayer Ln	Side	Framingham Rd	198709.46	895013.3	42.3056	-71.5157
1	Greg Baldwin (DRG)	2022/08/04	pole number 49	940	2022/08/04	GrBa20220804080558	8:06:24	Oak, Black	Quercus velutina	Wooded Space	No	12	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	8	Thayer Ln	Side	Framingham Rd	198711.28	895019.1	42.30565	-71.5156
1	Greg Baldwin (DRG)	2022/08/04	pole number 49	941	2022/08/04	GrBa20220804080733	8:08:37	Oak, Scarlet	Quercus coccinea	Wooded Space	No	26	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	8	Thayer Ln	Side	Framingham Rd	198711.1	895022.8	42.30569	-71.5156
1	Greg Baldwin (DRG)	2022/08/04	pole number 49	942	2022/08/04	GrBa20220804080841	8:09:57	Oak, Scarlet	Quercus coccinea	Wooded Space	No	14	Fair	Prune	None	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	8	Thayer Ln	Side	Framingham Rd	198713.75	895028.3	42.30574	-71.5156
1	Greg Baldwin (DRG)	2022/08/04	pole number 49	943	2022/08/04	GrBa20220804081005	8:10:27	Oak, Black	Quercus velutina	Wooded Space	No	15	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	8	Thayer Ln	Side	Framingham Rd	198712.63	895034.1	42.30579	-71.5156
1	Greg Baldwin (DRG)	2022/08/04	pole number 48	944	2022/08/04	GrBa20220804081137	8:12:17	Oak, Black	Quercus velutina	Wooded Space	No	9	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	8	Thayer Ln	Side	Framingham Rd	198717.93	895066.7	42.30608	-71.5155
1	Greg Baldwin (DRG)	2022/08/04	pole number 48	945	2022/08/04	GrBa20220804081221	8:14:19	Maple, Red	Acer rubrum	Wooded Space	No	26	Poor	Remove	None	Missing Or Decayed Wood	None	Probable	Medium	Somewhat Likely	Significant	Moderate	Yes	6	Thayer Ln	Side	Framingham Rd	198719.05	895074.8	42.30616	-71.5155
1	Greg Baldwin (DRG)	2022/08/04	pole number 48	946	2022/08/04	GrBa20220804081605	8:16:36	Oak, Black Pine, Eastern	Quercus velutina	Wooded Space	No	11	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Significant	Low	Yes	6	Thayer Ln	Side	Framingham Rd	198719.11	895102.8	42.30641	-71.5155
1	Greg Baldwin (DRG)	2022/08/18	pole number 28; borderline	947	2022/08/04	GrBa20220804085444	11:41:06	White	Pinus strobus	Wooded Space	No	11	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Significant	Low	Yes	74	Framingham Rd	Front	Framingham Rd	198380.81	896052.7	42.31496	-71.5196
1	Greg Baldwin (DRG)	2022/08/04	borderline	948	2022/08/04	GrBa20220804082056	8:21:30	Butternut	Juglans cinerea	Open Space	No	1	Good	Train	None	No Significant Defect	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	24	Framingham Rd	Front	Framingham Rd	198693.18	895234.1	42.30759	-71.5159
1	Greg Baldwin (DRG)	2022/08/18	pole number 28; borderline	949	2022/08/04	GrBa20220804085536	11:41:06	Pine, Eastern White	Pinus strobus	Wooded Space	No	16	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	74	Framingham Rd	Front	Framingham Rd	198378.46	896057.7	42.315	-71.5197
1	Greg Baldwin (DRG)	2022/08/04	borderline	950	2022/08/04	GrBa20220804092751	9:28:57	Elm, American	Ulmus americana	Wooded Space	No	19	Poor	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	9	Buffalo Run	Side	Framingham Rd	198015.36	896354.9	42.31768	-71.5241
1	Greg Baldwin (DRG)	2022/08/04	borderline	951	2022/08/04	GrBa20220804082338	8:24:24	Maple, Norway	Acer platanoides	Open Space	No	4	Fair	Train	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	28	Framingham Rd	Front	Framingham Rd	198658.4	895320.4	42.30837	-71.5163
1	Greg Baldwin (DRG)	2022/08/04	borderline	952	2022/08/04	GrBa20220804093043	9:31:15	Catalpa, Northern Pine, Eastern	Catalpa speciosa	Wooded Space	No	11	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	7	Buffalo Run	Side	Framingham Rd	198061.73	896324.4	42.3174	-71.5235
1	Greg Baldwin (DRG)	2022/08/18	pole number 28; borderline	953	2022/08/04	GrBa20220804085606	11:41:06	White	Pinus strobus	Wooded Space	No	9	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	74	Framingham Rd	Front	Framingham Rd	198377.69	896058.5	42.31501	-71.5197
1	Greg Baldwin (DRG)	2022/08/04	borderline	954	2022/08/04	GrBa20220804082507	8:26:19	Plum	Prunus species	Open Space	No	15	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	32	Framingham Rd	Front	Framingham Rd	198624.79	895376.9	42.30887	-71.5167
1	Greg Baldwin (DRG)	2022/08/18	pole number 26; borderline	955	2022/08/04	GrBa20220804090220	11:40:31	Maple, Sugar	Acer saccharum	Wooded Space	Yes	12	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Negligible	Low	Yes	80	Framingham Rd	Front	Framingham Rd	198304.06	896140	42.31574	-71.5206
1	Greg Baldwin (DRG)	2022/08/04	borderline	956	2022/08/04	GrBa20220804093141	9:32:23	Maple, Red	Acer rubrum	Wooded Space	Yes	14	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	7	Buffalo Run	Side	Framingham Rd	198069.54	896319.3	42.31736	-71.5234
1	Greg Baldwin (DRG)	2022/08/04	borderline	957	2022/08/04	GrBa20220804082636	8:27:02	Maple, Norway	Acer platanoides	Open Space	No	15	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	36	Framingham Rd	Front	Framingham Rd	198614.15	895391.1	42.309	-71.5168
1	Greg Baldwin (DRG)	2022/08/04	borderline; vines >50%	958	2022/08/04	GrBa20220804082851	8:30:27	Maple, Red	Acer rubrum	Wooded Space	No	19	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Significant	Low	Yes	36	Framingham Rd	Front	Framingham Rd	198596.81	895416.9	42.30923	-71.517
1	Greg Baldwin (DRG)	2022/08/04	borderline	959	2022/08/04	GrBa20220804093225	9:33:16	Maple, Red	Acer rubrum	Wooded Space	Yes	17	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	5	Buffalo Run	Side	Framingham Rd	198074.36	896316	42.31733	-71.5234
1	Greg Baldwin (DRG)	2022/08/04		960	2022/08/04	GrBa20220804090526	9:08:51	Pine, Scotch	Pinus sylvestris	Open Space	No	12	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	82	Framingham Rd	Front	Framingham Rd	198285.02	896158.1	42.31591	-71.5208
1	Greg Baldwin (DRG)	2022/08/04		961	2022/08/04	GrBa20220804090932	9:10:10	Pine, Scotch	Pinus sylvestris	Open Space	No	24	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	82	Framingham Rd	Front	Framingham Rd	198266.86	896170.2	42.31602	-71.521
1	Greg Baldwin (DRG)	2022/08/04		962	2022/08/04	GrBa20220804093420	9:34:52	Elm, American	Ulmus americana	Wooded Space	Yes	12	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	3	Buffalo Run	Side	Framingham Rd	198119.73	896286.3	42.31706	-71.5228
1	Greg Baldwin (DRG)	2022/08/18	pole number 30; borderline	963	2022/08/04	GrBa20220804084449	13:11:04	Ash, White	Fraxinus americana	Wooded Space	No	10	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Minor	Low	Yes	70	Framingham Rd	Front	Framingham Rd	198407.72	895990.3	42.3144	-71.5193
1	Greg Baldwin (DRG)	2022/08/04		964	2022/08/04	GrBa20220804094034	9:41:20	Cherry, Black	Prunus serotina	Wooded Space	No	12	Poor	Prune	None	Tree Architecture	Low	Possible	Medium	Unlikely	Significant	Low	Yes	103	Framingham Rd	Front	Framingham Rd	198172.8	896252	42.31675	-71.5222
1	Greg Baldwin (DRG)	2022/08/04	dbh estimated; poison ivy; borderline	965	2022/08/04	GrBa20220804113006	11:31:05	Maple, Red	Acer rubrum	Wooded Space	No	15	Fair	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	5	Cross St	Side	Framingham Rd	197763	896569.9	42.31961	-71.5271
1	Greg Baldwin (DRG)	2022/08/04	borderline	966	2022/08/04	GrBa20220804091045	9:11:31	Maple, Red	Acer rubrum	Wooded Space	No	10	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	84	Framingham Rd	Front	Framingham Rd	198242.29	896185.7	42.31616	-71.5213
1	Greg Baldwin (DRG)	2022/08/04		967	2022/08/04	GrBa20220804093517	9:35:52	Catalpa, Northern	Catalpa speciosa	Wooded Space	Yes	13	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	3	Buffalo Run	Side	Framingham Rd	198129.9	896280	42.317	-71.5227
1	Greg Baldwin (DRG)	2022/08/18	pole number 30; emerald ash borer	968	2022/08/04	GrBa20220804084647	11:41:48	Ash, White	Fraxinus americana	Wooded Space	No	14	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	High	Somewhat Likely	Significant	Moderate	Yes	72	Framingham Rd	Front	Framingham Rd	198406.72	895997.6	42.31446	-71.5193
1	Greg Baldwin (DRG)	2022/08/18		969	2022/08/04	GrBa20220804094225	13:52:22	Elm, American	Ulmus americana	Wooded Space	No	9	Good	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Minor	Low	Yes	103	Framingham Rd	Front	Framingham Rd	198175.62	896250.9	42.31674	-71.5221
1	Greg Baldwin (DRG)	2022/08/04	dbh estimated; poison ivy; borderline	970	2022/08/04	GrBa20220804113127	11:32:07	Elm, Siberian	Ulmus pumila	Wooded Space	No	24	Poor	Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Minor	Low	Yes	5	Cross St	Side	Framingham Rd	197758.89	896574.1	42.31965	-71.5272
1	Greg Baldwin (DRG)	2022/08/04		971	2022/08/04	GrBa20220804093701	9:37:48	Locust, Black	Robinia pseudoacacia	Wooded Space	Yes	19	Fair	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	1	Buffalo Run	Side	Framingham Rd	198156.29	896262.1	42.31684	-71.5224
1	Greg Baldwin (DRG)	2022/08/18	pole number 29; borderline	972	2022/08/04	GrBa20220804084914	11:41:48	Maple, Sugar	Acer saccharum	Wooded Space	No	8	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	72	Framingham Rd	Front	Framingham Rd	198393.38	896029.6	42.31475	-71.5195
1	Greg Baldwin (DRG)	2022/08/26		973	2022/08/04	GrBa20220804091830	12:47:39	Magnolia, Chinese; Saucer	Magnolia x soulangiana	Open Space	Yes	3	Fair	Train	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	114	Framingham Rd	Front	Framingham Rd	198027.94	896326.9	42.31743	-71.5239
1	Greg Baldwin (DRG)	2022/08/04		974	2022/08/04	GrBa20220804094256	9:43:22	Maple, Sugar	Acer saccharum	Wooded Space	No	17	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	103	Framingham Rd	Front	Framingham Rd	198178.09	896248.5	42.31672	-71.5221
1	Greg Baldwin (DRG)	2022/08/18	pole number 28; borderline	975	2022/08/04	GrBa20220804085319	11:41:06	Hickory, Pignut	Carya glabra	Wooded Space	No	14	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Significant	Low	Yes	74	Framingham Rd	Front	Framingham Rd	198383.57	896049.1	42.31493	-71.5196
1	Greg Baldwin (DRG)	2022/08/04		976	2022/08/04	GrBa20220804094331	9:44:12	Cherry, Black	Prunus serotina	Wooded Space	No	17	Poor	Prune	None	Tree Architecture	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	103	Framingham Rd	Front	Framingham Rd	198181.09	896246.6	42.3167	-71.5221
1	Greg Baldwin (DRG)	2022/08/04		977	2022/08/04	GrBa20220804092521	9:26:19	Ash, White	Fraxinus americana	Wooded Space	Yes	9	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	117	Framingham Rd	Front	Framingham Rd	197927.71	896418.4	42.31825	-71.5251
1	Greg Baldwin (DRG)	2022/08/04		978	2022/08/04	GrBa20220804113305	11:34:58	Maple, Sugar	Acer saccharum	Wooded Space	No	9	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	5	Cross St	Side	Framingham Rd	197746.18	896587.5	42.31977	-71.5273
1	Greg Baldwin (DRG)	2022/08/18		979	2022/08/04	GrBa20220804093827	10:18:58	Cherry, Black	Prunus serotina	Wooded Space	Yes	8	Fair	Routine Prune	None	Tree Architecture	Low	Possible	Low	Unlikely	Minor	Low	Yes	103	Framingham Rd	Front	Framingham Rd	198170.45	896253.2	42.31676	-71.5222
1	Greg Baldwin (DRG)	2022/08/04		980	2022/08/04	GrBa20220804113500	11:37:18	Pine	Pinus species	Wooded Space	No	9	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Minor	Low	Yes	5	Cross St	Side	Framingham Rd	197743.88	896587.2	42.31977	-71.5274
1	Greg Baldwin (DRG)	2022/08/04		981	2022/08/04	GrBa20220804093947	9:40:31	Locust, Black	Robinia pseudoacacia	Wooded Space	No	17	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	103	Framingham Rd	Front	Framingham Rd	198171.63	896251.1	42.31674	-71.5222
1	Greg Baldwin (DRG)	2022/08/04		982	2022/08/04	GrBa20220804114339	11:50:02	Pine, Eastern White	Pinus strobus	Wooded Space	No	23	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	5	Cross St	Side	Framingham Rd	197733.89	896595.5	42.31984	-71.5275
1	Greg Baldwin (DRG)	2022/08/04	dbh estimated; poison ivy; borderline	983	2022/08/04	GrBa20220804112751	11:28:48	Elm, Siberian	Ulmus pumila	Wooded Space	No	22	Poor	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	5	Cross St	Side	Framingham Rd	197776.81	896555.4	42.31948	-71.527
1	Greg Baldwin (DRG)	2022/08/04	Co-dominants	984	2022/08/04	GrBa20220804094428	9:46:06	Maple, Red	Acer rubrum	Open Space	No	40	Fair	Prune	None	Root Problems	Low	Possible	Low	Unlikely	Minor	Low	Yes	103	Framingham Rd	Front	Framingham Rd	198198.48	896233.7	42.31659	-71.5219

1	Greg Baldwin (DRG)	2022/08/04		985	2022/08/04	GrBa20220804113801	11:38:36	Maple, Red	Acer rubrum	Wooded Space	Yes	14	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	5	Cross St	Side	Framingham Rd	197742.65	896591.7	42.31981	-71.5274
1	Greg Baldwin (DRG)	2022/08/04	borderline	986	2022/08/04	GrBa20220804112915	11:29:47	Elm, Siberian	Ulmus pumila	Wooded Space	No	15	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Very Low	Unlikely	Significant	Low	Yes	5	Cross St	Side	Framingham Rd	197765.82	896566.9	42.31959	-71.5271
1	Greg Baldwin (DRG)	2022/08/04	lost major leader or limb	987	2022/08/04	GrBa20220804114846	11:50:38	Maple, Norway	Acer platanoides	Wooded Space	Yes	11	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	5	Cross St	Side	Framingham Rd	197728.25	896600.9	42.31989	-71.5276
1	Greg Baldwin (DRG)	2022/08/04		988	2022/08/04	GrBa20220804114449	11:49:55	Maple, Red	Acer rubrum	Wooded Space	No	15	Poor	Routine Prune	None	Broken And/Or Hanging Branches	Low	Probable	Low	Unlikely	Minor	Low	Yes	5	Cross St	Side	Framingham Rd	197734.72	896597	42.31986	-71.5275
1	Greg Baldwin (DRG)	2022/08/18	dbh estimated; poison ivy	989	2022/08/04	GrBa20220804112305	11:37:43	Oak, White	Quercus alba	Wooded Space	No	31	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	83	Newton St	Rear	Framingham Rd	197824.4	896505.7	42.31903	-71.5264
1	Greg Baldwin (DRG)	2022/08/04		990	2022/08/04	GrBa20220804114606	11:46:35	Maple, Norway	Acer platanoides	Wooded Space	No	8	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Significant	Low	Yes	5	Cross St	Side	Framingham Rd	197732.31	896598.6	42.31987	-71.5275
1	Greg Baldwin (DRG)	2022/08/04		991	2022/08/04	GrBa20220804115112	11:51:50	Maple, Red	Acer rubrum	Wooded Space	No	15	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	101	Newton St	Side	Framingham Rd	197710.57	896615.6	42.32002	-71.5278
1	Greg Baldwin (DRG)	2022/08/04	dbh estimated; poison ivy; start hedge	992	2022/08/04	GrBa20220804113903	11:39:35	Maple, Sugar	Acer saccharum	Wooded Space	Yes	12	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	5	Cross St	Side	Framingham Rd	197738.77	896594.4	42.31983	-71.5274
1	Greg Baldwin (DRG)	2022/08/04	row; 7	993	2022/08/04	GrBa20220804120657	12:08:30	Cedar, Northern White	Thuja occidentalis	Wooded Space	No	9	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	197548.81	896743.9	42.32118	-71.5297
1	Greg Baldwin (DRG)	2022/08/18	dbh estimated; poison ivy; utility pruned	994	2022/08/04	GrBa20220804122739	11:39:26	Elm, Siberian	Ulmus pumila	Wooded Space	No	21	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	127	Framingham Rd	Front	Framingham Rd	197782.81	896573.8	42.31965	-71.5269
1	Greg Baldwin (DRG)	2022/08/18	dbh estimated; poison ivy	995	2022/08/04	GrBa20220804112537	11:37:43	Maple, Sugar	Acer saccharum	Wooded Space	No	11	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	83	Newton St	Rear	Framingham Rd	197811.89	896518.2	42.31915	-71.5265
1	Greg Baldwin (DRG)	2022/08/04	borderline	996	2022/08/04	GrBa20220804124440	12:45:30	Maple, Red	Acer rubrum	Wooded Space	Yes	13	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	13	Buffalo Run	Side	Framingham Rd	197852.79	896497.2	42.31896	-71.526
1	Greg Baldwin (DRG)	2022/08/04		997	2022/08/04	GrBa20220804115239	11:53:39	Maple, Red	Acer rubrum	Wooded Space	Yes	10	Fair	Routine Prune	None	Tree Architecture	Low	Possible	Low	Unlikely	Significant	Low	Yes	101	Newton St	Side	Framingham Rd	197703.83	896618.9	42.32005	-71.5279
1	Greg Baldwin (DRG)	2022/08/04		998	2022/08/04	GrBa20220804114121	11:50:08	Maple, Sugar	Acer saccharum	Wooded Space	No	10	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Significant	Low	Yes	5	Cross St	Side	Framingham Rd	197735.01	896594.6	42.31984	-71.5275
1	Greg Baldwin (DRG)	2022/08/04	dbh estimated; poison ivy	999	2022/08/04	GrBa20220804121011	12:10:56	Cedar, Northern White	Thuja occidentalis	Wooded Space	No	11	Poor	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	197585.6	896714.4	42.32091	-71.5293
1	Greg Baldwin (DRG)	2022/08/18	dbh estimated; poison ivy; utility pruned	1000	2022/08/04	GrBa20220804122904	11:39:26	Elm, Siberian	Ulmus pumila	Wooded Space	No	15	Fair	Routine Prune	None	Tree Architecture	Low	Possible	Low	Unlikely	Significant	Low	Yes	127	Framingham Rd	Front	Framingham Rd	197794.97	896560.3	42.31953	-71.5267
1	Greg Baldwin (DRG)	2022/08/04		1001	2022/08/04	GrBa20220804125428	12:55:11	Maple, Sugar	Acer saccharum	Open Space	Yes	11	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	1	Maplecrest Dr	Side	Framingham Rd	198280.04	896180.9	42.31611	-71.5209
1	Greg Baldwin (DRG)	2022/08/04		1002	2022/08/04	GrBa20220804124700	12:47:39	Oak, Northern Red	Quercus rubra	Wooded Space	No	13	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	11	Buffalo Run	Side	Framingham Rd	197901.04	896446.2	42.3185	-71.5255
1	Greg Baldwin (DRG)	2022/08/04		1003	2022/08/04	GrBa20220804115343	11:54:16	Elm, American	Ulmus americana	Wooded Space	Yes	11	Fair	Routine Prune	None	Tree Architecture	Low	Possible	Medium	Unlikely	Minor	Low	Yes	101	Newton St	Side	Framingham Rd	197702.81	896620.7	42.32007	-71.5279
1	Greg Baldwin (DRG)	2022/08/04	dbh estimated; poison ivy; borderline	1004	2022/08/04	GrBa20220804121118	12:11:52	Cedar, Northern White	Thuja occidentalis	Wooded Space	No	12	Poor	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	197594.53	896707.7	42.32085	-71.5292
1	Greg Baldwin (DRG)	2022/08/18		1005	2022/08/04	GrBa20220804123024	11:39:26	Cottonwood, Eastern	Populus deltoides	Wooded Space	No	23	Fair	Routine Prune	None	Tree Architecture	Low	Possible	Very Low	Unlikely	Severe	Low	Yes	127	Framingham Rd	Front	Framingham Rd	197799.32	896555	42.31948	-71.5267
1	Greg Baldwin (DRG)	2022/08/04	borderline	1006	2022/08/04	GrBa20220804125515	12:56:22	Spruce, Blue	Picea pungens	Open Space	No	12	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	1	Maplecrest Dr	Side	Framingham Rd	198279.57	896183	42.31613	-71.5209
1	Greg Baldwin (DRG)	2022/08/04	armillaria	1007	2022/08/04	GrBa20220804123453	12:38:06	Oak, Northern Red	Quercus rubra	Wooded Space	No	33	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Medium	Unlikely	Significant	Low	Yes	15	Buffalo Run	Side	Framingham Rd	197823.35	896529	42.31925	-71.5264
1	Greg Baldwin (DRG)	2022/08/04	borderline; leaning	1008	2022/08/04	GrBa20220804120026	12:01:28	Ash, White	Fraxinus americana	Wooded Space	No	15	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	197521.96	896777.7	42.32148	-71.5301
1	Greg Baldwin (DRG)	2022/08/04	dbh estimated; poison ivy; borderline	1009	2022/08/04	GrBa20220804121224	12:13:28	Cedar, Northern White	Thuja occidentalis	Wooded Space	Yes	13	Poor	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	197603.52	896702.3	42.3208	-71.5291
1	Greg Baldwin (DRG)	2022/08/04	borderline	1010	2022/08/04	GrBa20220804125651	13:01:22	Maple, Norway	Acer platanoides	Open Space	No	11	Poor	Routine Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Minor	Low	Yes	89	Framingham Rd	Front	Framingham Rd	198307.31	896162.6	42.31595	-71.5205
1	Greg Baldwin (DRG)	2022/08/04	pole number 29	1011	2022/08/04	GrBa20220804131035	13:11:39	Oak	Quercus species	Wooded Space	No	9	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	198420.49	896017.9	42.31465	-71.5192
1	Greg Baldwin (DRG)	2022/08/04		1012	2022/08/04	GrBa20220804120209	12:03:53	Maple, Norway	Acer platanoides	Wooded Space	No	11	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	197530.19	896764.9	42.32137	-71.53
1	Greg Baldwin (DRG)	2022/08/18		1013	2022/08/04	GrBa20220804121911	11:39:26	Pine, Eastern White	Pinus strobus	Wooded Space	No	15	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	127	Framingham Rd	Front	Framingham Rd	197737.56	896612.9	42.32	-71.5274
1	Greg Baldwin (DRG)	2022/08/04		1014	2022/08/04	GrBa20220804123850	12:39:24	Oak, Northern Red	Quercus rubra	Wooded Space	No	10	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	15	Buffalo Run	Side	Framingham Rd	197830.99	896522.1	42.31918	-71.5263
1	Greg Baldwin (DRG)	2022/08/04		1015	2022/08/04	GrBa20220804125840	12:59:18	Apple	Malus species	Open Space	Yes	12	Fair	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	89	Framingham Rd	Front	Framingham Rd	198315.95	896154.5	42.31587	-71.5204
1	Greg Baldwin (DRG)	2022/08/04		1016	2022/08/04	GrBa20220804123945	12:40:33	Oak, Northern Red	Quercus rubra	Wooded Space	No	15	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	15	Buffalo Run	Side	Framingham Rd	197835.57	896516.1	42.31913	-71.5263
1	Greg Baldwin (DRG)	2022/08/18		1017	2022/08/04	GrBa20220804122117	11:39:26	Cherry, Black	Prunus serotina	Wooded Space	No	10	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	127	Framingham Rd	Front	Framingham Rd	197741.15	896611.7	42.31999	-71.5274
1	Greg Baldwin (DRG)	2022/08/04	pole number 29; dbh estimated; poison ivy	1018	2022/08/04	GrBa20220804131206	13:12:54	Elm, American	Ulmus americana	Wooded Space	No	13	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	198421.9	896015.4	42.31462	-71.5191
1	Greg Baldwin (DRG)	2022/08/04	borderline	1019	2022/08/04	GrBa20220804125923	13:01:14	Maple, Norway	Acer platanoides	Open Space	No	18	Poor	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	89	Framingham Rd	Front	Framingham Rd	198322	896154.8	42.31588	-71.5204
1	Greg Baldwin (DRG)	2022/08/04	borderline	1020	2022/08/04	GrBa20220804120309	12:03:42	Maple, Norway	Acer platanoides	Wooded Space	Yes	11	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	197535.83	896756.5	42.32129	-71.5299
1	Greg Baldwin (DRG)	2022/08/04	pole number 29	1021	2022/08/04	GrBa20220804132500	13:26:50	Oak	Quercus species	Wooded Space	No	26	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	265	Boston Rd	Side	Framingham Rd	198427.45	895994	42.31443	-71.5191
1	Greg Baldwin (DRG)	2022/08/04	pole number 29	1022	2022/08/04	GrBa20220804131333	13:20:43	Apple	Malus species	Wooded Space	No	12	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	198424.46	896007.9	42.31456	-71.5191
1	Greg Baldwin (DRG)	2022/08/18	dbh estimated; poison ivy; end hedge	1023	2022/08/04	GrBa20220804122205	11:39:26	Elm, American	Ulmus americana	Wooded Space	No	8	Fair	Routine Prune	None	Tree Architecture	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	127	Framingham Rd	Front	Framingham Rd	197745.26	896607.7	42.31995	-71.5274
1	Greg Baldwin (DRG)	2022/08/04	row; 7	1024	2022/08/04	GrBa20220804120509	12:08:43	Cedar, Northern White	Thuja occidentalis	Wooded Space	No	12	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Framingham Rd	197554.34	896739	42.32113	-71.5297
1	Greg Baldwin (DRG)	2022/08/04		1025	2022/08/04	GrBa20220804124115	12:41:33	Oak, Northern Red	Quercus rubra	Wooded Space	No	13	Poor	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Possible	Low	Unlikely	Minor	Low	Yes	15	Buffalo Run	Side	Framingham Rd	197837.57	896514	42.31911	-71.5262
1	Greg Baldwin (DRG)	2022/08/04	pole number 29	1026	2022/08/04	GrBa20220804132705	13:28	Maple, Sugar	Acer saccharum	Wooded Space	No	8	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	198429.86	895987.9	42.31438	-71.519
1	Greg Baldwin (DRG)	2022/08/04	pole number 28	1027	2022/08/04	GrBa20220804130358	13:10:20	Elm, American	Ulmus americana	Wooded Space	No	11	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	198388.94	896080.1	42.31521	-71.5195
1	Greg Baldwin (DRG)	2022/08/18		1028	2022/08/04	GrBa20220804122256	11:39:26	Elm, American	Ulmus americana	Wooded Space	No	11	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	127	Framingham Rd	Front	Framingham Rd	197746.9	896605.7	42.31994	-71.5273
1	Greg Baldwin (DRG)	2022/08/04	pole number 29	1029	2022/08/04	GrBa20220804131443	13:20:43	Ash, White	Fraxinus americana	Wooded Space	No	9	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	265	Boston Rd	Side	Framingham Rd	198425.4	896004.3	42.31452	-71.5191

1	Greg Baldwin (DRG)	2022/08/04	borderline	1030	2022/08/04	GrBa20220804124245	12:43:20	Apple	Malus species	Wooded Space	No	10	Poor	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Possible	Low	Unlikely	Minor	Low	Yes	15	Buffalo Run	Side	Framingham Rd	197843.09	896509.3	42.31907	-71.5262
1	Greg Baldwin (DRG)	2022/08/04	off ROW; pole number 29	1031	2022/08/04	GrBa20220804130628	13:08:30	Oak	Quercus species	Wooded Space	No	12	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	198406.92	896052.8	42.31496	-71.5193
1	Greg Baldwin (DRG)	2022/08/04	pole number 29; dbh estimated; poison ivy	1032	2022/08/04	GrBa20220804132812	13:29:37	Oak, Black	Quercus velutina	Wooded Space	No	12	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	198433.68	895974	42.31425	-71.519
1	Greg Baldwin (DRG)	2022/08/04	pole number 28; dbh estimated; poison ivy	1033	2022/08/04	GrBa20220804132942	13:30:29	Maple, Red	Acer rubrum	Wooded Space	No	8	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	198440.02	895947.5	42.31401	-71.5189
1	Greg Baldwin (DRG)	2022/08/04	pole number 29	1034	2022/08/04	GrBa20220804131603	13:20:43	Ash, White	Fraxinus americana	Wooded Space	No	18	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	265	Boston Rd	Side	Framingham Rd	198425.75	896000.9	42.31449	-71.5191
1	Greg Baldwin (DRG)	2022/08/18	lost major leader or limb	1035	2022/08/04	GrBa20220804122317	11:39:26	Oak, Scarlet	Quercus coccinea	Wooded Space	Yes	20	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	127	Framingham Rd	Front	Framingham Rd	197748.2	896604.4	42.31992	-71.5273
1	Greg Baldwin (DRG)	2022/08/04	borderline	1036	2022/08/04	GrBa20220804124322	12:44:09	Maple, Red	Acer rubrum	Wooded Space	No	15	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	15	Buffalo Run	Side	Framingham Rd	197845.21	896506.5	42.31904	-71.5261
1	Greg Baldwin (DRG)	2022/08/04	pole number 29	1037	2022/08/04	GrBa20220804132045	13:22:25	Oak	Quercus species	Wooded Space	No	9	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	198426.98	895999	42.31447	-71.5191
1	Greg Baldwin (DRG)	2022/08/04	pole number 28; dbh estimated; poison ivy	1038	2022/08/04	GrBa20220804133102	13:31:33	Elm, American	Ulmus americana	Wooded Space	No	8	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	198444.6	895930.8	42.31386	-71.5189
1	Greg Baldwin (DRG)	2022/08/04	pole number 28; dbh estimated; poison ivy; borderline	1039	2022/08/04	GrBa20220804133159	13:32:54	Maple, Red	Acer rubrum	Wooded Space	No	15	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	198447.07	895924.6	42.31381	-71.5188
1	Greg Baldwin (DRG)	2022/08/04	pole number 29	1040	2022/08/04	GrBa20220804132347	13:24:30	Maple, Sugar	Acer saccharum	Wooded Space	No	13	Fair	Routine Prune	None	Dead And Dying Branches	Low	Improbable	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	198427.92	895997.4	42.31446	-71.5191
1	Greg Baldwin (DRG)	2022/08/04	pole number 29	1041	2022/08/04	GrBa20220804132437	13:24:57	Ash, White	Fraxinus americana	Wooded Space	No	9	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	198428.1	895996.1	42.31445	-71.5191
1	Greg Baldwin (DRG)	2022/08/04	pole number 32; dbh estimated; poison ivy	1042	2022/08/04	GrBa20220804133333	13:34:41	Apple	Malus species	Wooded Space	Yes	13	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	198450.89	895900.2	42.31359	-71.5188
1	Greg Baldwin (DRG)	2022/08/04	pole number 33	1043	2022/08/04	GrBa20220804133625	13:37:17	Maple, Red	Acer rubrum	Wooded Space	No	13	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Very Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	198476.12	895800.6	42.31269	-71.5185
1	Greg Baldwin (DRG)	2022/08/04	pole number 34; borderline	1044	2022/08/04	GrBa20220804133921	13:39:53	Oak, Black	Quercus velutina	Wooded Space	No	15	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Framingham Rd	198486.99	895758.9	42.31231	-71.5184
1	Greg Baldwin (DRG)	2022/07/28		162	2022/07/28	GrBa20220728113411	11:35:51	Plum	Prunus species	Open Space	No	7	Poor	Remove	None	Dead And Dying Branches	None	Possible	Low	Unlikely	Minor	Low	Yes	271	Cordaville Rd	Side	Hammond St	198075.78	890930.7	42.26884	-71.5233
1	Greg Baldwin (DRG)	2022/08/03	dbh estimated; poison ivy; utility pruned	685	2022/08/03	GrBa20220803130750	13:09:57	Maple, Red	Acer rubrum	Open Space	No	35	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	6	High St	Front	High St	194096.24	894825.5	42.30389	-71.5716
1	Greg Baldwin (DRG)	2022/08/03	dbh estimated; behind fence	688	2022/08/03	GrBa20220803134714	13:48:00	Catalpa, Northern	Catalpa speciosa	Open Space	No	22	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Severe	Low	Yes	28	High St	Front	High St	194011.42	894332.8	42.29945	-71.5726
1	Greg Baldwin (DRG)	2022/08/03		694	2022/08/03	GrBa20220803130959	13:10:24	Redcedar, Eastern	Juniperus virginiana	Open Space	No	2	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	6	High St	Front	High St	194096.06	894823.6	42.30387	-71.5716
1	Greg Baldwin (DRG)	2022/08/03	dbh estimated; behind fence	697	2022/08/03	GrBa20220803134834	13:49:08	Aspen, Quaking	Populus tremuloides	Open Space	No	5	Poor	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	28	High St	Front	High St	194013.05	894319.1	42.29933	-71.5726
1	Greg Baldwin (DRG)	2022/08/03	large leader or limb decay	700	2022/08/03	GrBa20220803123135	12:32:30	Maple, Red	Acer rubrum	Open Space	No	21	Poor	Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Significant	Low	Yes	9	High St	Front	High St	194024.93	894627.4	42.30211	-71.5725
1	Greg Baldwin (DRG)	2022/08/03		706	2022/08/03	GrBa20220803131053	13:11:20	Aspen, Bigtooth	Populus grandidentata	Open Space	No	8	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	6	High St	Front	High St	194090.4	894800.8	42.30367	-71.5717
1	Greg Baldwin (DRG)	2022/08/03	dbh estimated; behind fence	706	2022/08/03	GrBa20220803134934	13:50:04	Spruce, Norway	Picea abies	Open Space	No	20	Good	Routine Prune	None	Dead And Dying Branches	Low	Improbable	Low	Unlikely	Severe	Low	Yes	28	High St	Front	High St	194012.87	894315.1	42.29929	-71.5726
1	Greg Baldwin (DRG)	2022/08/03	poor location	709	2022/08/03	GrBa20220803135147	13:53:50	Elm, American	Ulmus americana	Open Space	No	2	Fair	Train	None	Tree Architecture	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	27	High St	Front	High St	194002.19	894335	42.29947	-71.5727
1	Greg Baldwin (DRG)	2022/08/03	topped for utility	711	2022/08/03	GrBa20220803131144	13:12:12	Redcedar, Eastern	Juniperus virginiana	Open Space	No	10	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	6	High St	Front	High St	194089.98	894798.6	42.30365	-71.5717
1	Greg Baldwin (DRG)	2022/08/03	borderline; utility pruned	712	2022/08/03	GrBa20220803135444	13:55:54	Maple, Red	Acer rubrum	Open Space	No	23	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	25	High St	Front	High St	193989.83	894386.4	42.29994	-71.5729
1	Greg Baldwin (DRG)	2022/08/03	root decay	715	2022/08/03	GrBa20220803123444	12:37:12	Oak, Black	Quercus velutina	Wooded Space	No	49	Poor	Prune	Annual Ins	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Significant	Low	Yes	9	High St	Front	High St	194032.41	894645.8	42.30227	-71.5724
1	Greg Baldwin (DRG)	2022/08/03	borderline; utility pruned	720	2022/08/03	GrBa20220803135556	13:58:13	Maple, Red	Acer rubrum	Open Space	No	25	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	25	High St	Front	High St	193988.95	894390	42.29997	-71.5729
1	Greg Baldwin (DRG)	2022/08/03		722	2022/08/03	GrBa20220803131247	13:14:58	Hickory, Pignut	Carya glabra	Open Space	No	28	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	10	High St	Front	High St	194070.06	894738.7	42.30311	-71.5719
1	Greg Baldwin (DRG)	2022/08/03	leaning	724	2022/08/03	GrBa20220803123839	12:41:09	Oak, Black	Quercus velutina	Wooded Space	No	38	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	9	High St	Front	High St	194033.83	894650	42.30231	-71.5724
1	Greg Baldwin (DRG)	2022/08/03		728	2022/08/03	GrBa20220803131524	13:15:44	Hickory, Pignut	Carya glabra	Open Space	No	5	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	10	High St	Front	High St	194059.1	894710.4	42.30285	-71.5721
1	Greg Baldwin (DRG)	2022/08/03	borderline; utility pruned; Co-dominants	731	2022/08/03	GrBa20220803135655	13:57:55	Maple, Red	Acer rubrum	Open Space	No	24	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	25	High St	Front	High St	193985.9	894402.1	42.30008	-71.5729
1	Greg Baldwin (DRG)	2022/08/03		734	2022/08/03	GrBa20220803124114	12:41:56	Oak, White	Quercus alba	Wooded Space	No	24	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	5	High St	Front	High St	194041.5	894679.4	42.30257	-71.5723
1	Greg Baldwin (DRG)	2022/08/03	borderline; utility pruned	738	2022/08/03	GrBa20220803131556	13:16:43	Plum	Prunus species	Open Space	No	11	Good	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Minor	Low	Yes	10	High St	Front	High St	194059.69	894708.6	42.30284	-71.572
1	Greg Baldwin (DRG)	2022/08/03	borderline	741	2022/08/03	GrBa20220803135848	13:59:23	Maple, Red	Acer rubrum	Open Space	No	17	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Minor	Low	Yes	25	High St	Front	High St	193979.22	894426.3	42.30029	-71.573
1	Greg Baldwin (DRG)	2022/08/03		743	2022/08/03	GrBa20220803124213	12:42:43	Elm, American	Ulmus americana	Wooded Space	No	10	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	5	High St	Front	High St	194044.27	894689.5	42.30266	-71.5722
1	Greg Baldwin (DRG)	2022/08/03		748	2022/08/03	GrBa20220803131737	13:19:38	Oak	Quercus species	Open Space	No	36	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	12	High St	Front	High St	194055.03	894695.8	42.30272	-71.5721
1	Greg Baldwin (DRG)	2022/08/03	borderline	750	2022/08/03	GrBa20220803140009	14:01:21	Birch, Black	Betula lenta	Open Space	Yes	16	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	23	High St	Front	High St	193974.65	894438.3	42.3004	-71.5731
1	Greg Baldwin (DRG)	2022/08/03	borderline	752	2022/08/03	GrBa20220803124320	12:43:56	Maple, Red	Acer rubrum	Wooded Space	No	9	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	5	High St	Front	High St	194048.52	894707.5	42.30283	-71.5722
1	Greg Baldwin (DRG)	2022/08/03	borderline; lost major leader or limb	757	2022/08/03	GrBa20220803132019	13:22:26	Oak, Black	Quercus velutina	Open Space	Yes	29	Poor	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	12	High St	Front	High St	194046.48	894662.2	42.30242	-71.5722
1	Greg Baldwin (DRG)	2022/08/03		760	2022/08/03	GrBa20220803124451	12:45:27	Hickory, Shagbark	Carya ovata	Open Space	No	11	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Significant	Low	Yes	5	High St	Front	High St	194056.65	894733.3	42.30306	-71.5721
1	Greg Baldwin (DRG)	2022/08/03		762	2022/08/03	GrBa20220803140201	14:02:37	Maple, Red	Acer rubrum	Open Space	No	25	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	23	High St	Front	High St	193970.31	894454.9	42.30055	-71.5731
1	Greg Baldwin (DRG)	2022/08/03	utility pruned	769	2022/08/03	GrBa20220803132313	13:23:56	Maple, Sugar	Acer saccharum	Open Space	No	10	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	14	High St	Front	High St	194044.54	894657.7	42.30238	-71.5722
1	Greg Baldwin (DRG)	2022/08/03		772	2022/08/03	GrBa20220803124545	12:46:20	Hickory, Pignut	Carya glabra	Open Space	No	7	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	5	High St	Front	High St	194058.01	894737.8	42.3031	-71.5721
1	Greg Baldwin (DRG)	2022/08/03	borderline	773	2022/08/03	GrBa20220803140452	14:05:18	Maple, Red	Acer rubrum	Open Space	No	17	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Severe	Low	Yes	15	High St	Front	High St	193971.94	894500.4	42.30096	-71.5731
1	Greg Baldwin (DRG)	2022/08/03		777	2022/08/03	GrBa20220803132424	13:24:44	Hickory, Pignut	Carya glabra	Open Space	Yes	2	Good	Train	None	Tree Architecture	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	12	High St	Front	High St	194045.83	894660.7	42.30241	-71.5722

1	Greg Baldwin (DRG)	2022/08/03		782	2022/08/03	GrBa20220803124717	12:48	Oak, Black	Quercus velutina	Open Space	Yes	34	Fair	Prune	None	Dead And Dying Branches	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	5	High St	Front	High St	194060.95	894743.3	42.30315	-71.572
1	Greg Baldwin (DRG)	2022/08/03		785	2022/08/03	GrBa20220803132518	13:25:54	Oak, White	Quercus alba	Open Space	Yes	21	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	14	High St	Front	High St	194041.24	894650.4	42.30231	-71.5723
1	Greg Baldwin (DRG)	2022/08/03	borderline	786	2022/08/03	GrBa20220803140520	14:05:48	Birch, Black	Betula lenta	Open Space	Yes	13	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Minor	Low	Yes	15	High St	Front	High St	193971.94	894502.4	42.30098	-71.5731
1	Greg Baldwin (DRG)	2022/08/03		792	2022/08/03	GrBa20220803124825	12:49:15	Hickory, Pignut	Carya glabra	Open Space	No	18	Fair	Prune	None	Broken And/Or Hanging Branches	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	5	High St	Front	High St	194062.49	894748	42.30319	-71.572
1	Greg Baldwin (DRG)	2022/08/03	borderline; hangers	795	2022/08/03	GrBa20220803140702	14:07:56	Maple, Red	Acer rubrum	Open Space	Yes	18	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Severe	Low	Yes	15	High St	Front	High St	193978.07	894528.4	42.30121	-71.573
1	Greg Baldwin (DRG)	2022/08/03		798	2022/08/03	GrBa20220803132602	13:26:30	Hickory, Pignut	Carya glabra	Open Space	Yes	4	Good	Train	None	No Significant Defect	Low	Improbable	Low	Unlikely	Minor	Low	Yes	14	High St	Front	High St	194038.23	894639.1	42.30221	-71.5723
1	Greg Baldwin (DRG)	2022/08/03		800	2022/08/03	GrBa20220803124951	12:50:39	Oak, White	Quercus alba	Open Space	No	24	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	1	High St	Front	High St	194063.96	894752.3	42.30323	-71.572
1	Greg Baldwin (DRG)	2022/08/03	borderline	806	2022/08/03	GrBa20220803140806	14:09:26	Maple, Red	Acer rubrum	Open Space	Yes	10	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	15	High St	Front	High St	193981.08	894535.1	42.30127	-71.573
1	Greg Baldwin (DRG)	2022/08/03		808	2022/08/03	GrBa20220803132711	13:27:31	Oak, Black	Quercus velutina	Open Space	Yes	39	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	14	High St	Front	High St	194035.28	894632.2	42.30215	-71.5723
1	Greg Baldwin (DRG)	2022/08/03		811	2022/08/03	GrBa20220803125049	12:51:50	Hickory, Pignut	Carya glabra	Open Space	No	20	Good	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	1	High St	Front	High St	194067.73	894759.4	42.30329	-71.5719
1	Greg Baldwin (DRG)	2022/08/03	borderline	815	2022/08/03	GrBa20220803141035	14:10:59	Hickory, Pignut	Carya glabra	Open Space	No	12	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	11	High St	Front	High St	194004.23	894585.4	42.30173	-71.5727
1	Greg Baldwin (DRG)	2022/08/03		818	2022/08/03	GrBa20220803133015	13:31:27	Maple, Red	Acer rubrum	Wooded Space	No	20	Poor	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Significant	Low	Yes	18	High St	Front	High St	194006.84	894572.4	42.30161	-71.5727
1	Greg Baldwin (DRG)	2022/08/03		821	2022/08/03	GrBa20220803125215	12:52:35	Pine, Eastern White	Pinus strobus	Open Space	No	6	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	1	High St	Front	High St	194068.56	894764.7	42.30334	-71.5719
1	Greg Baldwin (DRG)	2022/08/03	borderline	823	2022/08/03	GrBa20220803141201	14:12:30	Hickory, Pignut	Carya glabra	Open Space	Yes	7	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Negligible	Low	Yes	9	High St	Front	High St	194015.89	894608.2	42.30193	-71.5726
1	Greg Baldwin (DRG)	2022/08/03	borderline	825	2022/08/03	GrBa20220803133205	13:34:29	Maple, Red	Acer rubrum	Wooded Space	Yes	24	Fair	Prune	Annual Ins	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	18	High St	Front	High St	193992.22	894536	42.30128	-71.5729
1	Greg Baldwin (DRG)	2022/08/03	borderline	832	2022/08/03	GrBa20220803141325	14:13:45	Maple, Red	Acer rubrum	Open Space	Yes	13	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	9	High St	Front	High St	194020.3	894615.3	42.302	-71.5725
1	Greg Baldwin (DRG)	2022/08/03		833	2022/08/03	GrBa20220803125257	12:53:18	Pine, Eastern White	Pinus strobus	Open Space	No	9	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	1	High St	Front	High St	194068.97	894766.9	42.30336	-71.5719
1	Greg Baldwin (DRG)	2022/08/03		836	2022/08/03	GrBa20220803133436	13:35:21	Oak, Black	Quercus velutina	Wooded Space	No	15	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	22	High St	Front	High St	193988.04	894527.7	42.30121	-71.5729
1	Greg Baldwin (DRG)	2022/08/26		842	2022/08/03	GrBa20220803125320	15:17:21	Redcedar, Eastern	Juniperus virginiana	Open Space	No	4	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	1	High St	Front	High St	194069.62	894768	42.30337	-71.5719
1	Greg Baldwin (DRG)	2022/08/03	borderline	848	2022/08/03	GrBa20220803133614	13:36:58	Maple, Red	Acer rubrum	Open Space	No	10	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	22	High St	Front	High St	193988.27	894523.6	42.30117	-71.5729
1	Greg Baldwin (DRG)	2022/08/03		851	2022/08/03	GrBa20220803125437	12:55:17	Oak, White	Quercus alba	Open Space	No	28	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	1	High St	Front	High St	194074.22	894784.6	42.30352	-71.5719
1	Greg Baldwin (DRG)	2022/08/03	borderline	859	2022/08/03	GrBa20220803133721	13:37:49	Birch, Black	Betula lenta	Open Space	No	11	Good	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Minor	Low	Yes	22	High St	Front	High St	193984.38	894509.4	42.30104	-71.573
1	Greg Baldwin (DRG)	2022/08/03		862	2022/08/03	GrBa20220803125541	12:56:05	Hemlock, Eastern	Tsuga canadensis	Open Space	No	10	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	1	High St	Front	High St	194076.87	894791.2	42.30358	-71.5718
1	Greg Baldwin (DRG)	2022/08/03	borderline	867	2022/08/03	GrBa20220803133823	13:38:50	Maple, Red	Acer rubrum	Open Space	Yes	5	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	22	High St	Front	High St	193981.2	894500.1	42.30096	-71.573
1	Greg Baldwin (DRG)	2022/08/03		872	2022/08/03	GrBa20220803125637	12:57:27	Oak, White	Quercus alba	Open Space	No	21	Fair	Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	1	High St	Front	High St	194077.22	894795	42.30361	-71.5718
1	Greg Baldwin (DRG)	2022/08/03		878	2022/08/03	GrBa20220803133857	13:39:27	Hickory, Pignut	Carya glabra	Open Space	Yes	14	Fair	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	22	High St	Front	High St	193980.55	894497.1	42.30093	-71.573
1	Greg Baldwin (DRG)	2022/08/03		882	2022/08/03	GrBa20220803125731	12:58:00	Hickory, Pignut	Carya glabra	Open Space	No	15	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	1	High St	Front	High St	194078.52	894796.3	42.30363	-71.5718
1	Greg Baldwin (DRG)	2022/08/03		886	2022/08/03	GrBa20220803134017	13:40:51	Oak, Black	Quercus velutina	Open Space	No	39	Poor	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	22	High St	Front	High St	193978.66	894484.9	42.30082	-71.573
1	Greg Baldwin (DRG)	2022/08/03	Co-dominants	893	2022/08/03	GrBa20220803125917	13:00:49	Oak, White	Quercus alba	Open Space	No	44	Fair	Prune	Annual Ins	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	1	High St	Front	High St	194081.76	894806.2	42.30372	-71.5718
1	Greg Baldwin (DRG)	2022/08/03	dbh estimated; poison ivy	899	2022/08/03	GrBa20220803134108	13:43:21	Oak, Black	Quercus velutina	Open Space	No	37	Poor	Prune	None	Missing Or Decayed Wood	Low	Probable	Low	Unlikely	Significant	Low	Yes	22	High St	Front	High St	193977.18	894471.4	42.3007	-71.573
1	Greg Baldwin (DRG)	2022/08/03		903	2022/08/03	GrBa20220803130208	13:02:28	Redcedar, Eastern	Juniperus virginiana	Open Space	No	6	Good	Routine Prune	None	Dead And Dying Branches	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	1	High St	Front	High St	194091.09	894852.7	42.30413	-71.5717
1	Moriah Day (DRG)	2022/08/23		908	2022/08/03	GrBa20220803134432	10:30:44	Redcedar, Eastern	Juniperus virginiana	Open Space	No	1	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	24	High St	Front	High St	193992.73	894410.7	42.30015	-71.5729
1	Greg Baldwin (DRG)	2022/08/03	borderline	914	2022/08/03	GrBa20220803130339	13:04:16	Hickory, Pignut	Carya glabra	Wooded Space	No	11	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	1	High St	Front	High St	194091.22	894869.1	42.30428	-71.5717
1	Moriah Day (DRG)	2022/08/23		917	2022/08/03	GrBa20220803134500	10:30:44	Pine, Eastern White	Pinus strobus	Open Space	No	1	Fair	Routine Prune	None	Dead And Dying Branches	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	24	High St	Front	High St	193994.72	894402.7	42.30008	-71.5728
1	Greg Baldwin (DRG)	2022/08/03	borderline	925	2022/08/03	GrBa20220803130418	13:05:00	Elm, American	Ulmus americana	Wooded Space	No	8	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	1	High St	Front	High St	194091.4	894870.3	42.30429	-71.5717
1	Greg Baldwin (DRG)	2022/08/03	dbh estimated; behind fence	926	2022/08/03	GrBa20220803134619	13:47:09	Catalpa, Northern	Catalpa speciosa	Open Space	No	14	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Negligible	Low	Yes	28	High St	Front	High St	194011.13	894337.1	42.29949	-71.5726
1	Greg Baldwin (DRG)	2022/08/03	utility pruned	935	2022/08/03	GrBa20220803130546	13:09:44	Maple, Red	Acer rubrum	Open Space	No	32	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Significant	Low	Yes	6	High St	Front	High St	194099.01	894838.5	42.30401	-71.5716
1	Ashley Casello (DRG)	2022/08/05		1215	2022/08/05	AsCa20220805141305	14:13:46	Maple, Sugar	Acer saccharum	Open Space	No	6	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	5	Newton St	Side	Howes Ct	198028.21	895159.2	42.30691	-71.5239
1	Greg Baldwin (DRG)	2022/08/18	lost major leader or limb	686	2022/08/03	GrBa20220803090633	12:50:05	Hickory, Pignut	Carya glabra	Wooded Space	No	10	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	10	Jacobs Ln	Front	Jacobs Ln	195139.75	894565.1	42.30155	-71.5589
1	Greg Baldwin (DRG)	2022/08/18		932	2022/08/03	GrBa20220803090504	12:50:05	Hickory, Pignut Oak, Northern	Carya glabra	Wooded Space	No	15	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	10	Jacobs Ln	Front	Jacobs Ln	195141.16	894562.4	42.30153	-71.5589
1	Greg Baldwin (DRG)	2022/08/02	pole number 13; borderline	287	2022/08/02	GrBa20220802135632	14:34:32	Red	Quercus rubra	Wooded Space	Yes	15	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	6	Jacobs Ln	Side	Lovers Ln	195271.48	894367.5	42.29977	-71.5573
1	Greg Baldwin (DRG)	2022/08/02	pole number 13	295	2022/08/02	GrBa20220802135752	14:34:10	Hickory, Pignut Oak, Northern	Carya glabra	Wooded Space	No	22	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	6	Jacobs Ln	Side	Lovers Ln	195268.78	894373	42.29982	-71.5574
1	Greg Baldwin (DRG)	2022/08/02	pole number 13; borderline	306	2022/08/02	GrBa20220802135900	14:33:54	Red	Quercus rubra	Wooded Space	No	20	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	8	Jacobs Ln	Side	Lovers Ln	195262.14	894378.9	42.29988	-71.5575
1	Greg Baldwin (DRG)	2022/08/02	pole number 13; borderline	313	2022/08/02	GrBa20220802140030	14:34:27	Birch, Black	Betula lenta	Wooded Space	No	10	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	8	Jacobs Ln	Side	Lovers Ln	195259.97	894381.5	42.2999	-71.5575
1	Greg Baldwin (DRG)	2022/08/02	pole number 13 1/2	320	2022/08/02	GrBa20220802140248	14:10:02	Hickory, Pignut	Carya glabra	Wooded Space	No	15	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Significant	Low	Yes	8	Jacobs Ln	Side	Lovers Ln	195250.69	894396.8	42.30004	-71.5576
1	Greg Baldwin (DRG)	2022/08/02	pole number 13 1/2	331	2022/08/02	GrBa20220802140338	14:09:58	Ash, White	Fraxinus americana	Wooded Space	No	13	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	High	Somewhat Likely	Minor	Low	Yes	8	Jacobs Ln	Side	Lovers Ln	195250.34	894400.2	42.30007	-71.5576

1	Greg Baldwin (DRG)	2022/08/02	fruiting bodies; cavity or decay; pole number 13 1/2	341	2022/08/02	GrBa20220802140622	14:09:52	Hickory, Pignut	Carya glabra	Wooded Space	No	20	Poor	Routine Prune	Insect/Dis	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Significant	Low	Yes	8	Jacobs Ln	Side	Lovers Ln	195248.28	894401.7	42.30008	-71.5576
1	Greg Baldwin (DRG)	2022/08/02	pole number 13 1/2	352	2022/08/02	GrBa20220802140810	14:09:39	Maple, Red	Acer rubrum	Wooded Space	No	10	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	8	Jacobs Ln	Side	Lovers Ln	195244.76	894409.2	42.3001	-71.5577
1	Greg Baldwin (DRG)	2022/08/02	pole number 14	361	2022/08/02	GrBa20220802141051	14:14:32	Maple, Sugar	Acer saccharum	Wooded Space	No	23	Good	Routine Prune	None	Root Problems	Low	Improbable	High	Unlikely	Significant	Low	Yes	8	Jacobs Ln	Side	Lovers Ln	195240.12	894418.1	42.30023	-71.5577
1	Greg Baldwin (DRG)	2022/08/02	pole number 14	370	2022/08/02	GrBa20220802141237	14:16:51	Birch, Black	Betula lenta	Wooded Space	No	23	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	5	Jacobs Ln	Side	Lovers Ln	195238.26	894421.6	42.30026	-71.5577
1	Greg Baldwin (DRG)	2022/08/02	pole number 14	381	2022/08/02	GrBa20220802141337	14:16:51	Birch, Black	Betula lenta	Wooded Space	No	16	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	5	Jacobs Ln	Side	Lovers Ln	195235.91	894425	42.30029	-71.5578
1	Greg Baldwin (DRG)	2022/08/03	pole number 14	390	2022/08/02	GrBa20220802141541	8:47:27	Oak, Northern Red	Quercus rubra	Wooded Space	No	15	Fair	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	5	Jacobs Ln	Side	Lovers Ln	195224.98	894443.4	42.30046	-71.5579
1	Greg Baldwin (DRG)	2022/08/02	pole number 14 1/2	398	2022/08/02	GrBa20220802141815	14:18:58	Oak, Northern Red	Quercus rubra	Wooded Space	No	41	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Very Low	Unlikely	Significant	Low	Yes	5	Jacobs Ln	Side	Lovers Ln	195220.16	894452.7	42.30054	-71.558
1	Greg Baldwin (DRG)	2022/08/02	pole number 14 1/2	408	2022/08/02	GrBa20220802141927	14:21:22	Hickory, Pignut	Carya glabra	Wooded Space	No	19	Fair	Routine Prune	None	Root Problems	Low	Possible	Low	Unlikely	Severe	Low	Yes	5	Jacobs Ln	Side	Lovers Ln	195216.94	894457.7	42.30059	-71.558
1	Greg Baldwin (DRG)	2022/08/03	pole number 14 1/2	418	2022/08/02	GrBa20220802142125	8:44:43	Oak, White	Quercus alba	Wooded Space	No	24	Fair	Prune	None	Root Problems	Low	Improbable	High	Unlikely	Significant	Low	Yes	23	Lovers Ln	Front	Lovers Ln	195213.97	894465.5	42.30066	-71.558
1	Greg Baldwin (DRG)	2022/08/02	pole number 14 1/2	430	2022/08/02	GrBa20220802142404	14:27:46	Hickory, Pignut	Carya glabra	Wooded Space	No	17	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Significant	Low	Yes	23	Lovers Ln	Front	Lovers Ln	195211.86	894467.8	42.30068	-71.5581
1	Greg Baldwin (DRG)	2022/08/18	borderline; pole number 14 1/2	438	2022/08/02	GrBa20220802142619	10:40:55	Oak, Northern Red	Quercus rubra	Wooded Space	No	23	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	20	Lovers Ln	Front	Lovers Ln	195221.97	894465.3	42.30065	-71.5579
1	Greg Baldwin (DRG)	2022/08/02	root decay	441	2022/08/02	GrBa20220802130901	13:11:51	Oak, Northern Red	Quercus rubra	Wooded Space	No	25	Poor	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	3	Lovers Ln	Front	Lovers Ln	195427	893969.4	42.29619	-71.5555
1	Greg Baldwin (DRG)	2022/08/18	pole number 14 1/2	447	2022/08/02	GrBa20220802142908	10:40:55	Hickory, Pignut	Carya glabra	Wooded Space	No	27	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	20	Lovers Ln	Front	Lovers Ln	195227.55	894458	42.30059	-71.5579
1	Greg Baldwin (DRG)	2022/08/02	borderline	448	2022/08/02	GrBa20220802131228	13:14:03	Oak, Northern Red	Quercus rubra	Wooded Space	No	32	Poor	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	3	Lovers Ln	Front	Lovers Ln	195416.37	893981.4	42.2963	-71.5556
1	Greg Baldwin (DRG)	2022/08/02		460	2022/08/02	GrBa20220802131329	13:13:55	Maple, Sugar	Acer saccharum	Wooded Space	No	9	Good	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	3	Lovers Ln	Front	Lovers Ln	195414.2	893984.4	42.29633	-71.5556
1	Greg Baldwin (DRG)	2022/08/18	pole number 13 1/2; root decay	461	2022/08/02	GrBa20220802143149	10:40:55	Oak, Northern Red	Quercus rubra	Wooded Space	No	30	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Severe	Low	Yes	20	Lovers Ln	Front	Lovers Ln	195262.43	894394.6	42.30002	-71.5575
1	Greg Baldwin (DRG)	2022/08/02	borderline	469	2022/08/02	GrBa20220802131417	13:15:11	Oak, Northern Red	Quercus rubra	Wooded Space	No	18	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	3	Lovers Ln	Front	Lovers Ln	195405.62	893993.9	42.29641	-71.5557
1	Greg Baldwin (DRG)	2022/08/18	pole number 13; borderline	475	2022/08/02	GrBa20220802143644	10:40:55	Birch, Black	Betula lenta	Wooded Space	No	9	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Minor	Low	Yes	20	Lovers Ln	Front	Lovers Ln	195273.3	894382.6	42.29991	-71.5573
1	Greg Baldwin (DRG)	2022/08/02		478	2022/08/02	GrBa20220802131540	13:18:27	Oak, Northern Red	Quercus rubra	Wooded Space	No	37	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	3	Lovers Ln	Front	Lovers Ln	195393.16	894009.8	42.29655	-71.5559
1	Greg Baldwin (DRG)	2022/08/18	pole number 13; borderline	484	2022/08/02	GrBa20220802143727	10:40:55	Elm, American	Ulmus americana	Wooded Space	No	8	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	20	Lovers Ln	Front	Lovers Ln	195274.35	894381.2	42.2999	-71.5573
1	Greg Baldwin (DRG)	2022/08/02	borderline; dbh estimated; poison ivy	488	2022/08/02	GrBa20220802131700	13:18:13	Oak, Northern Red	Quercus rubra	Wooded Space	No	28	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	3	Lovers Ln	Front	Lovers Ln	195390.05	894015.3	42.2966	-71.5559
1	Greg Baldwin (DRG)	2022/08/18	pole number 12 1/2	495	2022/08/02	GrBa20220802143942	10:40:55	Hickory, Pignut	Carya glabra	Wooded Space	No	15	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Significant	Low	Yes	20	Lovers Ln	Front	Lovers Ln	195281.4	894367.7	42.29978	-71.5572
1	Greg Baldwin (DRG)	2022/08/02		497	2022/08/02	GrBa20220802131942	13:20:26	Oak, Northern Red	Quercus rubra	Wooded Space	No	32	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Significant	Low	Yes	5	Lovers Ln	Front	Lovers Ln	195386.3	894029	42.29673	-71.5559
1	Greg Baldwin (DRG)	2022/08/18	pole number 12 1/2	505	2022/08/02	GrBa20220802144115	10:40:55	Hickory, Pignut	Carya glabra	Wooded Space	No	15	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Significant	Low	Yes	20	Lovers Ln	Front	Lovers Ln	195286.25	894359.8	42.29971	-71.5572
1	Greg Baldwin (DRG)	2022/08/02		507	2022/08/02	GrBa20220802132102	13:21:42	Hickory, Pignut	Carya glabra	Wooded Space	No	14	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Significant	Low	Yes	5	Lovers Ln	Front	Lovers Ln	195384.66	894041.1	42.29684	-71.556
1	Greg Baldwin (DRG)	2022/08/18	pole number 12 1/2	517	2022/08/02	GrBa20220802144239	10:40:55	Hickory, Pignut	Carya glabra	Wooded Space	No	20	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	20	Lovers Ln	Front	Lovers Ln	195290.42	894355.8	42.29967	-71.5571
1	Greg Baldwin (DRG)	2022/08/02	No Root Flare; lost major leader or limb	519	2022/08/02	GrBa20220802132430	13:25:38	Maple, Red	Acer rubrum	Wooded Space	No	20	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	9	Lovers Ln	Front	Lovers Ln	195375.17	894100.8	42.29737	-71.5561
1	Greg Baldwin (DRG)	2022/08/18	pole number 12	527	2022/08/02	GrBa20220802144325	10:40:55	Ash, White	Fraxinus americana	Wooded Space	No	20	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	20	Lovers Ln	Front	Lovers Ln	195295.59	894347.9	42.2996	-71.5571
1	Greg Baldwin (DRG)	2022/08/02		529	2022/08/02	GrBa20220802132600	13:26:30	Birch, Black	Betula lenta	Wooded Space	No	9	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	9	Lovers Ln	Front	Lovers Ln	195374.29	894106.8	42.29743	-71.5561
1	Greg Baldwin (DRG)	2022/08/02	pole number 11 1/2	535	2022/08/02	GrBa20220802144733	14:48:17	Birch, Black	Betula lenta	Wooded Space	No	14	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	20	Lovers Ln	Front	Lovers Ln	195311.74	894325.8	42.2994	-71.5569
1	Greg Baldwin (DRG)	2022/08/02	cavity or decay	539	2022/08/02	GrBa20220802132634	13:28:26	Oak, Northern Red	Quercus rubra	Wooded Space	Yes	33	Poor	Routine Prune	Advanced	Missing Or Decayed Wood	Moderate	Possible	High	Somewhat Likely	Significant	Moderate	Yes	9	Lovers Ln	Front	Lovers Ln	195373.76	894108.2	42.29744	-71.5561
1	Greg Baldwin (DRG)	2022/08/02	pole number 11 1/2; dbh estimated; poison ivy	545	2022/08/02	GrBa20220802144845	14:50:21	Maple, Red	Acer rubrum	Wooded Space	Yes	22	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	20	Lovers Ln	Front	Lovers Ln	195322.37	894310	42.29926	-71.5567
1	Greg Baldwin (DRG)	2022/08/02		547	2022/08/02	GrBa20220802132828	13:29:36	Birch, Black	Betula lenta	Wooded Space	No	10	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Minor	Low	Yes	9	Lovers Ln	Front	Lovers Ln	195374.24	894110.1	42.29746	-71.5561
1	Greg Baldwin (DRG)	2022/08/18	borderline	552	2022/08/02	GrBa20220802145047	13:11:04	Birch, Black	Betula lenta	Open Space	No	12	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Significant	Low	Yes	20	Lovers Ln	Front	Lovers Ln	195333.36	894292.9	42.2991	-71.5566
1	Greg Baldwin (DRG)	2022/08/02		557	2022/08/02	GrBa20220802133113	13:33:10	Oak, Black	Quercus velutina	Wooded Space	No	32	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	9	Lovers Ln	Front	Lovers Ln	195372.48	894116.9	42.29752	-71.5561
1	Greg Baldwin (DRG)	2022/08/02	lost main leader	564	2022/08/02	GrBa20220802145315	14:54:22	Maple, Red	Acer rubrum	Open Space	Yes	8	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	18	Lovers Ln	Front	Lovers Ln	195344.16	894275.7	42.29895	-71.5565
1	Greg Baldwin (DRG)	2022/08/02	Co-dominants; root decay	567	2022/08/02	GrBa20220802133312	13:40:54	Oak, Northern Red	Quercus rubra	Wooded Space	No	30	Poor	Prune	Advanced	Missing Or Decayed Wood	Moderate	Possible	High	Somewhat Likely	Significant	Moderate	Yes	9	Lovers Ln	Front	Lovers Ln	195371.89	894121.9	42.29756	-71.5561
1	Greg Baldwin (DRG)	2022/08/18	emerald ash borer	574	2022/08/02	GrBa20220802145425	12:50:32	Ash, White	Fraxinus americana	Open Space	Yes	10	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	18	Lovers Ln	Front	Lovers Ln	195344.93	894274.9	42.29894	-71.5565
1	Greg Baldwin (DRG)	2022/08/02		577	2022/08/02	GrBa20220802133547	13:36:08	Oak, Northern Red	Quercus rubra	Wooded Space	No	20	Fair	Routine Prune	None	Tree Architecture	Low	Possible	Low	Unlikely	Significant	Low	Yes	9	Lovers Ln	Front	Lovers Ln	195371.07	894128.7	42.29763	-71.5561
1	Greg Baldwin (DRG)	2022/08/02		582	2022/08/02	GrBa20220802145812	14:58:49	Oak, White	Quercus alba	Wooded Space	No	21	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	14	Lovers Ln	Front	Lovers Ln	195356.14	894243.3	42.29866	-71.5563
1	Greg Baldwin (DRG)	2022/08/02		587	2022/08/02	GrBa20220802133610	13:36:59	Hickory, Pignut	Carya glabra	Wooded Space	No	22	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	9	Lovers Ln	Front	Lovers Ln	195372.48	894129.5	42.29763	-71.5561
1	Greg Baldwin (DRG)	2022/08/02	trunk wounds; crown dieback	592	2022/08/02	GrBa20220802145942	15:00:19	Oak, White	Quercus alba	Wooded Space	No	22	Poor	Prune	None	Missing Or Decayed Wood	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	14	Lovers Ln	Front	Lovers Ln	195362.71	894228.2	42.29852	-71.5562
1	Greg Baldwin (DRG)	2022/08/02		596	2022/08/02	GrBa20220802133705	13:37:55	Hickory, Pignut	Carya glabra	Wooded Space	No	19	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Minor	Low	Yes	9	Lovers Ln	Front	Lovers Ln	195369.9	894133.9	42.29767	-71.5561
1	Greg Baldwin (DRG)	2022/08/02		602	2022/08/02	GrBa20220802150142	15:02:09	Oak, White	Quercus alba	Wooded Space	No	28	Poor	Prune	None	Missing Or Decayed Wood	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	14	Lovers Ln	Front	Lovers Ln	195370.63	894200.7	42.29827	-71.5561
1	Greg Baldwin (DRG)	2022/08/02		605	2022/08/02	GrBa20220802133859	13:40:48	Hickory, Pignut	Carya glabra	Wooded Space	No	22	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	11	Lovers Ln	Front	Lovers Ln	195367.26	894143.3	42.29776	-71.5562
1	Greg Baldwin (DRG)	2022/08/18		611	2022/08/02	GrBa20220802150251	13:04:05	Hickory, Pignut	Carya glabra	Wooded Space	No	9	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Minor	Low	Yes	14	Lovers Ln	Front	Lovers Ln	195370.58	894207.2	42.29833	-71.5561
1	Greg Baldwin (DRG)	2022/08/02	trunk wounds	618	2022/08/02	GrBa20220802133931	13:40:40	Oak, White	Quercus alba	Wooded Space	No	23	Fair	Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Significant	Low	Yes	11	Lovers Ln	Front	Lovers Ln	195369.5	894144.7	42.29777	-71.5562
1	Greg Baldwin (DRG)	2022/08/02		622	2022/08/02	GrBa20220802150555	15:06:49	Oak, White	Quercus alba	Open Space	No	33	Dead	Remove	None	No Significant Defect	None	Possible	High	Somewhat Likely	Significant	Moderate	Yes	6	Lovers Ln	Front	Lovers Ln	195376.53	894138.3	42.29771	-71.5561
1	Greg Baldwin (DRG)	2022/08/02		630	2022/08/02	GrBa20220802134133	13:42:07	Hickory, Pignut	Carya glabra	Wooded Space	No	20	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	11	Lovers Ln	Front	Lovers Ln	195366.21	894161	42.29792	-71.5562
1	Greg Baldwin (DRG)	2022/08/02		633	2022/08/02	GrBa20220802150814	15:09:54	Oak, Northern Red	Quercus rubra	Open Space	No	35	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	4	Lovers Ln	Front	Lovers Ln	195387.42	894074.9	42.29714	-71.5559
1	Greg Baldwin (DRG)	2022/08/02		642	2022/08/02	GrBa20220802134331	13:43:55	Hickory, Pignut	Carya glabra	Open Space	No	22	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Significant	Low	Yes	15	Lovers Ln	Front	Lovers Ln	195351.92	894235.8	42.29859	-71.5564
1	Greg Baldwin (DRG)	2022/08/02		644	2022/08/02	GrBa20220802151003	15:11:11	Tree, Unknown	Unknown Tree	Wooded Space	No	38	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Significant	Low	Yes	4	Lovers Ln	Front	Lovers Ln	195390.7	894051.2	42.29693	-71.5559
1	Greg Baldwin (DRG)	2022/08/18	pole number 12	652	2022/08/02	GrBa20220802134542	10:21:42	Hickory, Pignut	Carya glabra	Wooded Space	No	18	Fair	Routine Prune	None	Root Problems	Low	Improbable	Low	Unlikely	Severe	Low	Yes	4	Jacobs Ln	Side	Lovers Ln	195303.23	894323.6	42.29938	-71.557
1	Greg Baldwin (DRG)	2022/08/02		655	2022/08/02	GrBa20220802151145	15:12:41	Hickory, Pignut	Carya glabra	Wooded Space	No	14	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	4	Lovers Ln	Front	Lovers Ln	195392.11	894042.3	42.29685	-71.5559

1	Greg Baldwin (DRG)	2022/08/02	pole number 12	660	2022/08/02	GrBa20220802134612	14:45:59	Hickory, Pignut	Carya glabra	Wooded Space	No	24	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	4	Jacobs Ln	Side	Lovers Ln	195301.18	894325.3	42.29939	-71.557
1	Greg Baldwin (DRG)	2022/08/27	topped for utility	666	2022/08/02	GrBa20220802151324	9:11:25	Oak, Northern Red	Quercus rubra	Open Space	No	18	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	2	Lovers Ln	Front	Lovers Ln	195408.13	894006.2	42.29652	-71.5557
1	Greg Baldwin (DRG)	2022/08/02		668	2022/08/02	GrBa20220802151457	15:15:34	Spruce, Norway	Picea abies	Open Space	No	5	Fair	Routine Prune	None	Dead And Dying Branches	Low	Improbable	Low	Unlikely	Minor	Low	Yes	2	Lovers Ln	Front	Lovers Ln	195410.42	894002.6	42.29649	-71.5557
1	Greg Baldwin (DRG)	2022/08/02	pole number 12	671	2022/08/02	GrBa20220802134950	14:45:53	Hickory, Pignut	Carya glabra	Wooded Space	No	18	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	4	Jacobs Ln	Side	Lovers Ln	195291.31	894341.6	42.29954	-71.5571
1	Greg Baldwin (DRG)	2022/08/02		673	2022/08/02	GrBa20220802151548	15:16:19	Spruce, Norway	Picea abies	Open Space	No	9	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	2	Lovers Ln	Front	Lovers Ln	195412.48	894000.5	42.29647	-71.5556
1	Greg Baldwin (DRG)	2022/08/02	off ROW; pole number 12 1/2	675	2022/08/02	GrBa20220802135157	14:42:35	Cherry, Black	Prunus serotina	Wooded Space	Yes	14	Dead	Remove	None	No Significant Defect	None	Possible	High	Somewhat Likely	Minor	Low	Yes	6	Jacobs Ln	Side	Lovers Ln	195282.77	894345.6	42.29958	-71.5572
1	Greg Baldwin (DRG)	2022/08/02		677	2022/08/02	GrBa20220802151633	15:16:56	Spruce, Norway	Picea abies	Open Space	No	12	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	2	Lovers Ln	Front	Lovers Ln	195415.01	893997.7	42.29645	-71.5556
1	Greg Baldwin (DRG)	2022/08/02	borderline	679	2022/08/02	GrBa20220802151725	15:17:46	Spruce, Norway	Picea abies	Open Space	No	5	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	2	Lovers Ln	Front	Lovers Ln	195420.36	893993.8	42.29641	-71.5555
1	Greg Baldwin (DRG)	2022/08/02		680	2022/08/02	GrBa20220802151801	15:18:28	Spruce, Norway	Picea abies	Open Space	No	13	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Minor	Low	Yes	2	Lovers Ln	Front	Lovers Ln	195422.24	893990.9	42.29638	-71.5555
1	Greg Baldwin (DRG)	2022/08/03		683	2022/08/03	GrBa20220803083036	8:32:58	Hickory, Pignut	Carya glabra	Open Space	No	12	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	22	Lovers Ln	Front	Lovers Ln	195192.04	894507	42.30103	-71.5583
1	Greg Baldwin (DRG)	2022/08/03		684	2022/08/03	GrBa20220803075235	7:53:35	Oak, White	Quercus alba	Wooded Space	No	12	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Significant	Low	Yes	26	Lovers Ln	Front	Lovers Ln	195054.34	894674.7	42.30254	-71.56
1	Greg Baldwin (DRG)	2022/08/03		687	2022/08/03	GrBa20220803094055	9:41:20	Maple, Norway	Acer platanoides	Open Space	No	13	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Severe	Low	Yes	41	Lovers Ln	Front	Lovers Ln	194923.04	894814.1	42.30379	-71.5616
1	Greg Baldwin (DRG)	2022/08/03		692	2022/08/03	GrBa20220803083302	8:33:52	Birch, Black	Betula lenta	Open Space	No	3	Good	Train	None	No Significant Defect	Low	Improbable	Low	Unlikely	Minor	Low	Yes	22	Lovers Ln	Front	Lovers Ln	195193.27	894505.7	42.30102	-71.5583
1	Greg Baldwin (DRG)	2022/08/03		693	2022/08/03	GrBa20220803075503	7:55:18	Oak, Black	Quercus velutina	Wooded Space	No	22	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	24	Lovers Ln	Front	Lovers Ln	195061.98	894670.6	42.3025	-71.5599
1	Greg Baldwin (DRG)	2022/08/03		695	2022/08/03	GrBa20220803094202	9:42:44	Oak, White	Quercus alba	Open Space	No	31	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	41	Lovers Ln	Front	Lovers Ln	194908.23	894822.6	42.30387	-71.5618
1	Greg Baldwin (DRG)	2022/08/03		701	2022/08/03	GrBa20220803083355	8:34:48	Hickory, Pignut	Carya glabra	Open Space	No	13	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	22	Lovers Ln	Front	Lovers Ln	195193.68	894503.9	42.301	-71.5583
1	Greg Baldwin (DRG)	2022/08/03	hangers	703	2022/08/03	GrBa20220803075540	7:56:24	Hickory, Pignut	Carya glabra	Wooded Space	No	8	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	24	Lovers Ln	Front	Lovers Ln	195061.75	894667.9	42.30248	-71.5599
1	Greg Baldwin (DRG)	2022/08/03		704	2022/08/03	GrBa20220803094345	9:44:06	Maple, Norway	Acer platanoides	Open Space	No	5	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	41	Lovers Ln	Front	Lovers Ln	194857.63	894849.5	42.30411	-71.5624
1	Greg Baldwin (DRG)	2022/08/03		705	2022/08/03	GrBa20220803090755	9:08:53	Hickory, Pignut	Carya glabra	Open Space	No	19	Good	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	29	Lovers Ln	Front	Lovers Ln	195132.41	894573.6	42.30163	-71.559
1	Greg Baldwin (DRG)	2022/08/03		707	2022/08/03	GrBa20220803071802	7:19:55	Oak, White	Quercus alba	Open Space	No	32	Good	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	40	Lovers Ln	Front	Lovers Ln	194899.72	894834.7	42.30398	-71.5619
1	Greg Baldwin (DRG)	2022/08/03		710	2022/08/03	GrBa20220803071958	7:21:24	Oak, White	Quercus alba	Open Space	No	27	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	40	Lovers Ln	Front	Lovers Ln	194904.54	894834.5	42.30398	-71.5618
1	Greg Baldwin (DRG)	2022/08/03		716	2022/08/03	GrBa20220803083523	8:35:58	Hophornbeam, Eastern	Ostrya virginiana	Open Space	No	3	Fair	Train	None	Broken And/Or Hanging Branches	Low	Improbable	Low	Unlikely	Minor	Low	Yes	22	Lovers Ln	Front	Lovers Ln	195196.09	894502.2	42.30099	-71.5583
1	Greg Baldwin (DRG)	2022/08/03		717	2022/08/03	GrBa20220803094408	9:44:48	Maple, Norway	Acer platanoides	Open Space	No	11	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	41	Lovers Ln	Front	Lovers Ln	194856.22	894850.4	42.30412	-71.5624
1	Greg Baldwin (DRG)	2022/08/03		718	2022/08/03	GrBa20220803075711	7:57:58	Oak, Black	Quercus velutina	Wooded Space	No	12	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Significant	Low	Yes	24	Lovers Ln	Front	Lovers Ln	195065.69	894667	42.30247	-71.5598
1	Greg Baldwin (DRG)	2022/08/03		719	2022/08/03	GrBa20220803090938	9:10:03	Hickory, Pignut	Carya glabra	Wooded Space	No	19	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	High	Somewhat Likely	Negligible	Low	Yes	29	Lovers Ln	Front	Lovers Ln	195123.77	894584.9	42.30173	-71.5591
1	Greg Baldwin (DRG)	2022/08/03		721	2022/08/03	GrBa20220803072201	7:22:32	Oak, White	Quercus alba	Open Space	No	52	Good	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	40	Lovers Ln	Front	Lovers Ln	194913.94	894828.6	42.30392	-71.5617
1	Greg Baldwin (DRG)	2022/08/03		725	2022/08/03	GrBa20220803072335	7:24:15	Hickory, Pignut	Carya glabra	Open Space	No	11	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	40	Lovers Ln	Front	Lovers Ln	194922.52	894823	42.30387	-71.5616
1	Greg Baldwin (DRG)	2022/08/03		726	2022/08/03	GrBa20220803094520	9:45:35	Maple, Norway	Acer platanoides	Open Space	No	10	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	41	Lovers Ln	Front	Lovers Ln	194853.93	894851.5	42.30413	-71.5624
1	Greg Baldwin (DRG)	2022/08/03		729	2022/08/03	GrBa20220803075802	7:58:39	Oak, Black	Quercus velutina	Wooded Space	No	17	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	24	Lovers Ln	Front	Lovers Ln	195067.21	894664.5	42.30245	-71.5598
1	Greg Baldwin (DRG)	2022/08/03		730	2022/08/03	GrBa20220803083605	8:36:28	Hophornbeam, Eastern	Ostrya virginiana	Open Space	No	5	Fair	Routine Prune	None	Dead And Dying Branches	Low	Improbable	Low	Unlikely	Minor	Low	Yes	22	Lovers Ln	Front	Lovers Ln	195198.15	894500.7	42.30097	-71.5582
1	Greg Baldwin (DRG)	2022/08/03		732	2022/08/03	GrBa20220803091033	9:10:46	Hickory, Pignut	Carya glabra	Wooded Space	No	9	Fair	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	29	Lovers Ln	Front	Lovers Ln	195119.13	894591	42.30178	-71.5592
1	Greg Baldwin (DRG)	2022/08/03		736	2022/08/03	GrBa20220803094541	9:46:05	Hickory, Pignut	Carya glabra	Open Space	No	9	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	41	Lovers Ln	Front	Lovers Ln	194851.05	894852.6	42.30414	-71.5624
1	Greg Baldwin (DRG)	2022/08/03		737	2022/08/03	GrBa20220803072447	7:25:02	Hickory, Pignut	Carya glabra	Open Space	No	10	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	40	Lovers Ln	Front	Lovers Ln	194927.4	894820.7	42.30385	-71.5615
1	Greg Baldwin (DRG)	2022/08/03	leaning	739	2022/08/03	GrBa20220803083630	8:37:09	Birch, Black	Betula lenta	Open Space	No	5	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	22	Lovers Ln	Front	Lovers Ln	195199.38	894498.9	42.30096	-71.5582
1	Greg Baldwin (DRG)	2022/08/03		740	2022/08/03	GrBa20220803075851	7:59:54	Hickory, Pignut	Carya glabra	Open Space	No	20	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	24	Lovers Ln	Front	Lovers Ln	195076.49	894653.2	42.30234	-71.5597
1	Greg Baldwin (DRG)	2022/08/03		742	2022/08/03	GrBa20220803091127	9:11:52	Maple, Sugar	Acer saccharum	Wooded Space	Yes	8	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Minor	Low	Yes	29	Lovers Ln	Front	Lovers Ln	195115.96	894595	42.30182	-71.5592
1	Greg Baldwin (DRG)	2022/08/03	trunk decay	747	2022/08/03	GrBa20220803072527	7:26:47	Oak, White	Quercus alba	Open Space	No	27	Fair	Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Severe	Low	Yes	40	Lovers Ln	Front	Lovers Ln	194924.22	894821.4	42.30386	-71.5616
1	Greg Baldwin (DRG)	2022/08/03	cavity or decay	749	2022/08/03	GrBa20220803083752	8:39:54	Hickory, Pignut	Carya glabra	Open Space	No	12	Poor	Routine Prune	Advanced	Missing Or Decayed Wood	Moderate	Possible	High	Somewhat Likely	Significant	Moderate	Yes	22	Lovers Ln	Front	Lovers Ln	195201.14	894493.5	42.30091	-71.5582
1	Greg Baldwin (DRG)	2022/08/03	fruiting bodies	751	2022/08/03	GrBa20220803080000	8:00:54	Oak, White	Quercus alba	Open Space	No	22	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Very Low	Unlikely	Severe	Low	Yes	24	Lovers Ln	Front	Lovers Ln	195078.08	894651.8	42.30233	-71.5597
1	Greg Baldwin (DRG)	2022/08/03		753	2022/08/03	GrBa20220803091156	9:13:40	Hickory, Pignut	Carya glabra	Wooded Space	No	14	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	29	Lovers Ln	Front	Lovers Ln	195115.79	894596.4	42.30183	-71.5592
1	Greg Baldwin (DRG)	2022/08/03		758	2022/08/03	GrBa20220803083958	8:40:28	Hickory, Pignut	Carya glabra	Open Space	No	12	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	22	Lovers Ln	Front	Lovers Ln	195203.2	894491	42.30089	-71.5582
1	Greg Baldwin (DRG)	2022/08/03		759	2022/08/03	GrBa20220803072708	7:27:30	Hickory, Pignut	Carya glabra	Open Space	No	17	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	40	Lovers Ln	Front	Lovers Ln	194929.28	894819.6	42.30384	-71.5615
1	Greg Baldwin (DRG)	2022/08/03		761	2022/08/03	GrBa20220803091246	9:13:32	Hickory, Pignut	Carya glabra	Wooded Space	Yes	12	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	29	Lovers Ln	Front	Lovers Ln	195111.03	894600.6	42.30187	-71.5593
1	Greg Baldwin (DRG)	2022/08/18		764	2022/08/03	GrBa20220803080202	10:37:14	Hickory, Pignut	Carya glabra	Wooded Space	No	20	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	5	Saddle Hill Ln	Rear	Lovers Ln	195099.35	894627.7	42.30212	-71.5594
1	Greg Baldwin (DRG)	2022/08/03		766	2022/08/03	GrBa20220803084108	8:41:27	Hickory, Pignut	Carya glabra	Open Space	No	15	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Significant	Low	Yes	22	Lovers Ln	Front	Lovers Ln	195205.9	894488	42.30086	-71.5581
1	Greg Baldwin (DRG)	2022/08/03		767	2022/08/03	GrBa20220803072810	7:29:51	Oak, Black	Quercus velutina	Open Space	Yes	13	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	38	Lovers Ln	Front	Lovers Ln	194941.5	894810.9	42.30376	-71.5614

1	Greg Baldwin (DRG)	2022/08/03		770	2022/08/03	GrBa20220803091409	9:14:33	Oak, White	Quercus alba	Wooded Space	No	14	Fair	Prune	None	Weakly Attached Branches And Codominant Stems	Low	Possible	Low	Unlikely	Significant	Low	Yes	29	Lovers Ln	Front	Lovers Ln	195108.68	894603.2	42.3019	-71.5593
1	Greg Baldwin (DRG)	2022/08/03	borderline; vines >50%	775	2022/08/03	GrBa20220803084212	8:43:36	Maple, Norway	Acer platanoides	Open Space	No	7	Good	Routine Prune	None	No Significant Defect	Low	Possible	Low	Unlikely	Significant	Low	Yes	22	Lovers Ln	Front	Lovers Ln	195210.13	894484.5	42.30083	-71.5581
1	Greg Baldwin (DRG)	2022/08/18	vines >50%	776	2022/08/03	GrBa20220803080224	10:37:14	Hickory, Pignut	Carya glabra	Wooded Space	No	17	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Very Low	Unlikely	Severe	Low	Yes	5	Saddle Hill Ln	Rear	Lovers Ln	195101.7	894625.7	42.3021	-71.5594
1	Greg Baldwin (DRG)	2022/08/03	Co-dominants	779	2022/08/03	GrBa20220803072956	7:30:43	Hickory, Pignut	Carya glabra	Open Space	No	20	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	38	Lovers Ln	Front	Lovers Ln	194942.97	894809.6	42.30375	-71.5613
1	Greg Baldwin (DRG)	2022/08/03	cavity or decay; trunk decay	780	2022/08/03	GrBa20220803091525	9:16:22	Hickory, Pignut	Carya glabra	Wooded Space	No	20	Poor	Routine Prune	Advanced	Missing Or Decayed Wood	Moderate	Possible	High	Somewhat Likely	Significant	Moderate	Yes	29	Lovers Ln	Front	Lovers Ln	195107.68	894604.6	42.30191	-71.5593
1	Greg Baldwin (DRG)	2022/08/18	pole number 14 1/2	783	2022/08/03	GrBa20220803084653	10:40:55	Hickory, Pignut	Carya glabra	Wooded Space	No	13	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	20	Lovers Ln	Front	Lovers Ln	195232.1	894450	42.30052	-71.5578
1	Greg Baldwin (DRG)	2022/08/18	borderline	787	2022/08/03	GrBa20220803080427	10:37:14	Hickory, Pignut	Carya glabra	Wooded Space	No	14	Fair	Prune	None	Dead And Dying Branches	Low	Possible	High	Somewhat Likely	Significant	Moderate	Yes	5	Saddle Hill Ln	Rear	Lovers Ln	195119.14	894606.5	42.30192	-71.5592
1	Greg Baldwin (DRG)	2022/08/03		789	2022/08/03	GrBa20220803073102	7:31:24	Maple, Sugar	Acer saccharum	Open Space	No	11	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	38	Lovers Ln	Front	Lovers Ln	194944.38	894808.4	42.30374	-71.5613
1	Greg Baldwin (DRG)	2022/08/03	root decay	790	2022/08/03	GrBa20220803091711	9:18:19	Oak, White	Quercus alba	Wooded Space	No	23	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	31	Lovers Ln	Front	Lovers Ln	195104.92	894608.8	42.30195	-71.5594
1	Greg Baldwin (DRG)	2022/08/03		793	2022/08/03	GrBa20220803084822	8:50:44	Hickory, Pignut	Carya glabra	Wooded Space	No	13	Poor	Routine Prune	None	Tree Architecture	Low	Possible	Very Low	Unlikely	Significant	Low	Yes	23	Lovers Ln	Front	Lovers Ln	195201.02	894478.9	42.30078	-71.5582
1	Greg Baldwin (DRG)	2022/08/18	borderline	796	2022/08/03	GrBa20220803080605	10:37:14	Hickory, Pignut	Carya glabra	Wooded Space	No	16	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Significant	Low	Yes	5	Saddle Hill Ln	Rear	Lovers Ln	195125.08	894599.5	42.30186	-71.5591
1	Greg Baldwin (DRG)	2022/08/03		799	2022/08/03	GrBa20220803073235	7:32:50	Maple, Sugar	Acer saccharum	Open Space	No	8	Poor	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	38	Lovers Ln	Front	Lovers Ln	194949.37	894804.1	42.3037	-71.5613
1	Greg Baldwin (DRG)	2022/08/03		801	2022/08/03	GrBa20220803091843	9:19:29	Hickory, Pignut	Carya glabra	Wooded Space	No	12	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	31	Lovers Ln	Front	Lovers Ln	195088.88	894628.4	42.30212	-71.5596
1	Greg Baldwin (DRG)	2022/08/03		803	2022/08/03	GrBa20220803084928	8:49:54	Hickory, Pignut	Carya glabra	Wooded Space	No	15	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	23	Lovers Ln	Front	Lovers Ln	195198.55	894484.4	42.30083	-71.5582
1	Greg Baldwin (DRG)	2022/08/18		807	2022/08/03	GrBa20220803080707	10:37:14	Hickory, Pignut	Carya glabra	Wooded Space	No	17	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Minor	Low	Yes	5	Saddle Hill Ln	Rear	Lovers Ln	195126.02	894597.2	42.30184	-71.5591
1	Greg Baldwin (DRG)	2022/08/03		809	2022/08/03	GrBa20220803073254	7:33:39	Maple, Sugar	Acer saccharum	Open Space	No	5	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Negligible	Low	Yes	38	Lovers Ln	Front	Lovers Ln	194960.13	894794.9	42.30362	-71.5611
1	Greg Baldwin (DRG)	2022/08/03		812	2022/08/03	GrBa20220803085022	8:50:37	Hickory, Pignut	Carya glabra	Wooded Space	No	16	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Significant	Low	Yes	23	Lovers Ln	Front	Lovers Ln	195193.67	894489.7	42.30087	-71.5583
1	Greg Baldwin (DRG)	2022/08/18	borderline	813	2022/08/03	GrBa20220803080840	10:37:14	Birch, Black	Betula lenta	Wooded Space	No	15	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Significant	Low	Yes	7	Saddle Hill Ln	Rear	Lovers Ln	195127.43	894595	42.30182	-71.5591
1	Greg Baldwin (DRG)	2022/08/03		814	2022/08/03	GrBa20220803073413	7:35	Oak, White	Quercus alba	Open Space	No	31	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	38	Lovers Ln	Front	Lovers Ln	194964.06	894791.3	42.30359	-71.5611
1	Greg Baldwin (DRG)	2022/08/03	leaning	816	2022/08/03	GrBa20220803092048	9:21:47	Oak, White	Quercus alba	Wooded Space	No	29	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Severe	Low	Yes	33	Lovers Ln	Front	Lovers Ln	195062.91	894656.5	42.30237	-71.5599
1	Greg Baldwin (DRG)	2022/08/03		822	2022/08/03	GrBa20220803092223	9:24:12	Hickory, Pignut	Carya glabra	Wooded Space	No	16	Dead	Remove	None	No Significant Defect	None	Possible	High	Somewhat Likely	Significant	Moderate	Yes	33	Lovers Ln	Front	Lovers Ln	195047.93	894669.9	42.3025	-71.5601
1	Greg Baldwin (DRG)	2022/08/18		824	2022/08/03	GrBa20220803081006	10:37:14	Hickory, Pignut	Carya glabra	Wooded Space	No	13	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Negligible	Low	Yes	7	Saddle Hill Ln	Rear	Lovers Ln	195130.25	894592.3	42.3018	-71.5591
1	Greg Baldwin (DRG)	2022/08/03		826	2022/08/03	GrBa20220803085138	8:52:15	Hickory, Pignut	Carya glabra	Wooded Space	No	16	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Significant	Low	Yes	23	Lovers Ln	Front	Lovers Ln	195190.5	894493.7	42.30091	-71.5583
1	Greg Baldwin (DRG)	2022/08/03	borderline	828	2022/08/03	GrBa20220803073557	7:36:32	Hickory, Pignut	Carya glabra	Wooded Space	No	8	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	36	Lovers Ln	Front	Lovers Ln	194975.81	894777.8	42.30347	-71.5609
1	Greg Baldwin (DRG)	2022/08/03	frost cracking	834	2022/08/03	GrBa20220803081221	10:37:14	Hickory, Pignut	Carya glabra	Wooded Space	No	15	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	7	Saddle Hill Ln	Rear	Lovers Ln	195133.01	894586.2	42.30174	-71.559
1	Greg Baldwin (DRG)	2022/08/03		837	2022/08/03	GrBa20220803085228	8:54:08	Hickory, Pignut	Carya glabra	Wooded Space	Yes	22	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	25	Lovers Ln	Front	Lovers Ln	195183.69	894503.1	42.30099	-71.5584
1	Greg Baldwin (DRG)	2022/08/03	borderline	838	2022/08/03	GrBa20220803073701	7:37:25	Maple, Norway	Acer platanoides	Wooded Space	No	12	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	36	Lovers Ln	Front	Lovers Ln	194977.16	894774.8	42.30344	-71.5609
1	Greg Baldwin (DRG)	2022/08/18		841	2022/08/03	GrBa20220803081449	13:11:04	Hickory, Pignut	Carya glabra	Wooded Space	No	16	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Severe	Low	Yes	7	Saddle Hill Ln	Rear	Lovers Ln	195136.65	894583.6	42.30172	-71.559
1	Greg Baldwin (DRG)	2022/08/03		843	2022/08/03	GrBa20220803092646	9:27:33	Oak, White	Quercus alba	Wooded Space	No	37	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	41	Lovers Ln	Front	Lovers Ln	194996.58	894722.7	42.30297	-71.5607
1	Greg Baldwin (DRG)	2022/08/03		846	2022/08/03	GrBa20220803085417	8:54:50	Hickory, Pignut	Carya glabra	Wooded Space	Yes	17	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	25	Lovers Ln	Front	Lovers Ln	195176.82	894514.4	42.3011	-71.5585
1	Greg Baldwin (DRG)	2022/08/03		847	2022/08/03	GrBa20220803073850	7:39:37	Oak, Black	Quercus velutina	Wooded Space	No	34	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	36	Lovers Ln	Front	Lovers Ln	194986.38	894756.2	42.30327	-71.5608
1	Greg Baldwin (DRG)	2022/08/18	borderline; vines >50%	852	2022/08/03	GrBa20220803081644	10:37:14	Hickory, Pignut	Carya glabra	Wooded Space	No	13	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	7	Saddle Hill Ln	Rear	Lovers Ln	195140.23	894580	42.30169	-71.5589
1	Greg Baldwin (DRG)	2022/08/03	leaning	854	2022/08/03	GrBa20220803092820	9:29:22	Oak, Black	Quercus velutina	Wooded Space	No	29	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Very Low	Unlikely	Significant	Low	Yes	41	Lovers Ln	Front	Lovers Ln	194984.31	894746.8	42.30319	-71.5608
1	Greg Baldwin (DRG)	2022/08/03		855	2022/08/03	GrBa20220803085539	8:56:07	Oak, White	Quercus alba	Wooded Space	No	30	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Significant	Low	Yes	25	Lovers Ln	Front	Lovers Ln	195172.29	894518.5	42.30113	-71.5585
1	Greg Baldwin (DRG)	2022/08/03	epicormic sprouts	856	2022/08/03	GrBa20220803074043	7:41:50	Oak, White	Quercus alba	Wooded Space	No	30	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	36	Lovers Ln	Front	Lovers Ln	194989.61	894751.2	42.30323	-71.5608
1	Greg Baldwin (DRG)	2022/08/03		861	2022/08/03	GrBa20220803092953	9:30:20	Maple, Norway	Acer platanoides	Wooded Space	No	13	Fair	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	41	Lovers Ln	Front	Lovers Ln	194980.73	894751.7	42.30323	-71.5609
1	Greg Baldwin (DRG)	2022/08/18		863	2022/08/03	GrBa20220803081807	10:37:14	Hickory, Pignut	Carya glabra	Wooded Space	No	8	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	7	Saddle Hill Ln	Rear	Lovers Ln	195145.87	894570.9	42.3016	-71.5589
1	Greg Baldwin (DRG)	2022/08/03		865	2022/08/03	GrBa20220803085628	8:56:57	Hickory, Pignut	Carya glabra	Wooded Space	No	10	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Significant	Low	Yes	25	Lovers Ln	Front	Lovers Ln	195171.94	894521.2	42.30116	-71.5586
1	Greg Baldwin (DRG)	2022/08/03		866	2022/08/03	GrBa20220803074243	7:44:14	Oak, Black	Quercus velutina	Wooded Space	No	44	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	28	Lovers Ln	Front	Lovers Ln	194998.3	894734.2	42.30307	-71.5607
1	Greg Baldwin (DRG)	2022/08/18		871	2022/08/03	GrBa20220803081927	10:37:14	Hickory, Pignut	Carya glabra	Wooded Space	No	11	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Very Low	Unlikely	Significant	Low	Yes	7	Saddle Hill Ln	Rear	Lovers Ln	195152.28	894565.3	42.30155	-71.5588
1	Greg Baldwin (DRG)	2022/08/03		873	2022/08/03	GrBa20220803085725	8:57:45	Hickory, Pignut	Carya glabra	Wooded Space	No	25	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Severe	Low	Yes	25	Lovers Ln	Front	Lovers Ln	195166.65	894527.1	42.30121	-71.5586
1	Greg Baldwin (DRG)	2022/08/03	borderline	874	2022/08/03	GrBa20220803093105	9:32:13	Cherry, Black	Prunus serotina	Wooded Space	No	11	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	41	Lovers Ln	Front	Lovers Ln	194970.28	894768.3	42.30338	-71.561
1	Greg Baldwin (DRG)	2022/08/03		876	2022/08/03	GrBa20220803074419	7:45:37	Oak, White	Quercus alba	Open Space	No	12	Good	Routine Prune	None	Dead And Dying Branches	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	28	Lovers Ln	Front	Lovers Ln	195001.23	894730.5	42.30304	-71.5606
1	Greg Baldwin (DRG)	2022/08/18		881	2022/08/03	GrBa20220803081956	10:37:14	Hickory, Pignut	Carya glabra	Wooded Space	No	15	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Very Low	Unlikely	Significant	Low	Yes	7	Saddle Hill Ln	Rear	Lovers Ln	195152.57	894563.8	42.30154	-71.5588
1	Greg Baldwin (DRG)	2022/08/18		883	2022/08/03	GrBa20220803085858	10:21:42	Hickory, Pignut	Carya glabra	Wooded Space	No	22	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Significant	Low	Yes	10	Jacobs Ln	Side	Lovers Ln	195153.26	894547.2	42.30139	-71.5588
1	Greg Baldwin (DRG)	2022/08/03		884	2022/08/03	GrBa20220803093323	9:33:52	Hickory, Pignut	Carya glabra	Wooded Space	No	9	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	41	Lovers Ln	Front	Lovers Ln	194949.54	894795.3	42.30362	-71.5613
1	Greg Baldwin (DRG)	2022/08/03	lost major leader or limb	888	2022/08/03	GrBa20220803074540	7:46:37	Oak, White	Quercus alba	Open Space	No	18	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	28	Lovers Ln	Front	Lovers Ln	195002	894728.7	42.30302	-71.5606
1	Greg Baldwin (DRG)	2022/08/18		891	2022/08/03	GrBa20220803082059	10:37:14	Hickory, Pignut	Carya glabra	Wooded Space	No	15	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	7	Saddle Hill Ln	Rear	Lovers Ln	195153.92	894561.5	42.30152	-71.5588

1	Greg Baldwin (DRG)	2022/08/18		892	2022/08/03	GrBa20220803090014	10:21:42	Hickory, Pignut	Carya glabra	Wooded Space	No	14	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Significant	Low	Yes	10	Jacobs Ln	Side	Lovers Ln	195147.56	894554.2	42.30145	-71.5588
1	Greg Baldwin (DRG)	2022/08/03		896	2022/08/03	GrBa20220803093423	9:34:47	Maple, Norway	Acer platanoides	Wooded Space	No	11	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	41	Lovers Ln	Front	Lovers Ln	194942.9	894800.4	42.30367	-71.5613
1	Greg Baldwin (DRG)	2022/08/03		897	2022/08/03	GrBa20220803074717	7:48:31	Hickory, Pignut	Carya glabra	Open Space	No	23	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	28	Lovers Ln	Front	Lovers Ln	195010.57	894717.5	42.30292	-71.5605
1	Greg Baldwin (DRG)	2022/08/18		901	2022/08/03	GrBa20220803090037	10:21:42	Ash, White	Fraxinus americana	Wooded Space	No	15	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	High	Somewhat Likely	Significant	Moderate	Yes	10	Jacobs Ln	Side	Lovers Ln	195145.92	894556.6	42.30148	-71.5589
1	Greg Baldwin (DRG)	2022/08/18	borderline; vines >50%	902	2022/08/03	GrBa20220803082221	10:37:14	Hickory, Pignut	Carya glabra	Wooded Space	No	19	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Negligible	Low	Yes	7	Saddle Hill Ln	Rear	Lovers Ln	195157.03	894559.1	42.3015	-71.5587
1	Greg Baldwin (DRG)	2022/08/03	borderline	905	2022/08/03	GrBa20220803093606	9:36:32	Maple, Sugar	Acer saccharum	Wooded Space	No	9	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	41	Lovers Ln	Front	Lovers Ln	194941.67	894799.2	42.30366	-71.5613
1	Greg Baldwin (DRG)	2022/08/03		909	2022/08/03	GrBa20220803074833	7:49:27	Oak, White	Quercus alba	Open Space	No	10	Fair	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	28	Lovers Ln	Front	Lovers Ln	195014.86	894711.3	42.30287	-71.5605
1	Greg Baldwin (DRG)	2022/08/18		911	2022/08/03	GrBa20220803090312	10:21:42	Hickory, Pignut	Carya glabra	Wooded Space	No	8	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	10	Jacobs Ln	Side	Lovers Ln	195144.28	894558	42.30149	-71.5589
1	Greg Baldwin (DRG)	2022/08/18		912	2022/08/03	GrBa20220803082357	10:36:46	Hickory, Pignut	Carya glabra	Open Space	No	22	Poor	Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Significant	Low	Yes	22	Lovers Ln	Front	Lovers Ln	195170.54	894536.2	42.30129	-71.5586
1	Greg Baldwin (DRG)	2022/08/03		915	2022/08/03	GrBa20220803093656	9:37:14	Maple, Norway	Acer platanoides	Wooded Space	No	11	Good	Routine Prune	None	Cracks	Low	Improbable	High	Unlikely	Significant	Low	Yes	41	Lovers Ln	Front	Lovers Ln	194939.61	894802.8	42.30369	-71.5614
1	Greg Baldwin (DRG)	2022/08/03	borderline	919	2022/08/03	GrBa20220803075004	7:50:36	Hickory, Pignut	Carya glabra	Open Space	No	9	Fair	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	26	Lovers Ln	Front	Lovers Ln	195043.71	894686.2	42.30264	-71.5601
1	Greg Baldwin (DRG)	2022/08/18		921	2022/08/03	GrBa20220803082706	10:36:46	Birch, Black	Betula lenta	Open Space	No	7	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	22	Lovers Ln	Front	Lovers Ln	195173.3	894533.2	42.30127	-71.5585
1	Greg Baldwin (DRG)	2022/08/18		922	2022/08/03	GrBa20220803090415	10:21:42	Hickory, Pignut	Carya glabra	Wooded Space	No	21	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	10	Jacobs Ln	Side	Lovers Ln	195143.98	894560.1	42.30151	-71.5589
1	Greg Baldwin (DRG)	2022/08/03	borderline	927	2022/08/03	GrBa20220803075104	7:52:05	Oak, Black	Quercus velutina	Wooded Space	No	15	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	26	Lovers Ln	Front	Lovers Ln	195053.58	894677.8	42.30257	-71.56
1	Greg Baldwin (DRG)	2022/08/03	borderline	929	2022/08/03	GrBa20220803093807	9:38:58	Oak, Scarlet	Quercus coccinea	Wooded Space	No	13	Fair	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	41	Lovers Ln	Front	Lovers Ln	194931.8	894807.3	42.30373	-71.5615
1	Greg Baldwin (DRG)	2022/08/18		931	2022/08/03	GrBa20220803082732	10:36:46	Oak, White	Quercus alba	Open Space	No	18	Good	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Significant	Low	Yes	22	Lovers Ln	Front	Lovers Ln	195173.65	894531.4	42.30125	-71.5585
1	Greg Baldwin (DRG)	2022/08/03	borderline	936	2022/08/03	GrBa20220803093918	9:39:48	Maple, Norway	Acer platanoides	Wooded Space	No	14	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	41	Lovers Ln	Front	Lovers Ln	194930.74	894807.7	42.30374	-71.5615
1	Greg Baldwin (DRG)	2022/08/03		937	2022/08/03	GrBa20220803082857	8:33:29	Hickory, Pignut	Carya glabra	Open Space	No	10	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	22	Lovers Ln	Front	Lovers Ln	195191.34	894508.1	42.30104	-71.5583
1	Greg Baldwin (DRG)	2022/08/03		939	2022/08/03	GrBa20220803094028	9:40:53	Maple, Norway	Acer platanoides	Open Space	No	13	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Severe	Low	Yes	41	Lovers Ln	Front	Lovers Ln	194924.51	894813.1	42.30378	-71.5616
1	Greg Baldwin (DRG)	2022/08/18	borderline	1117	2022/08/05	GrBa20220805141023	10:18:58	Oak, Northern Red	Quercus rubra	Wooded Space	No	30	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Severe	Low	Yes	2	Meadow Ln	Front	Meadow Ln	199303.31	894627.1	42.30212	-71.5084
1	Greg Baldwin (DRG)	2022/08/01		290	2022/08/01	GrBa20220801122648	12:27:41	Hickory, Pignut	Carya glabra	Wooded Space	No	11	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	142	Middle Rd	Front	Middle Rd	197302.87	892912.3	42.28668	-71.5327
1	Greg Baldwin (DRG)	2022/08/01	borderline	292	2022/08/01	GrBa20220801132709	13:27:32	Hickory, Pignut	Carya glabra	Wooded Space	No	10	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	2	Leeds Way	Side	Middle Rd	197299.7	892976.2	42.28726	-71.5327
1	Greg Baldwin (DRG)	2022/08/01		294	2022/08/01	GrBa20220801104230	10:42:43	Maple, Norway	Acer platanoides	Open Space	No	11	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	12	Middle Rd	Front	Middle Rd	197407.88	894860.1	42.30422	-71.5314
1	Greg Baldwin (DRG)	2022/08/01		296	2022/08/01	GrBa20220801084600	8:46:36	Oak, Northern Red	Quercus rubra	Wooded Space	No	22	Fair	Prune	None	Dead And Dying Branches	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	95	Middle Rd	Front	Middle Rd	197489.9	893911.4	42.29568	-71.5304
1	Greg Baldwin (DRG)	2022/08/01		300	2022/08/01	GrBa20220801122817	12:28:49	Maple, Red	Acer rubrum	Wooded Space	No	9	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	142	Middle Rd	Front	Middle Rd	197302.92	892895.3	42.28653	-71.5327
1	Greg Baldwin (DRG)	2022/08/01	borderline; start hedgerow; 6	302	2022/08/01	GrBa20220801104310	10:45:37	Cedar, Northern White	Thuja occidentalis	Open Space	Yes	11	Poor	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	12	Middle Rd	Front	Middle Rd	197403.05	894851	42.30414	-71.5315
1	Greg Baldwin (DRG)	2022/08/18	pole number 59	303	2022/08/01	GrBa20220801132932	12:04:51	Oak, Northern Red	Prunus serotina	Wooded Space	No	10	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	151	Middle Rd	Front	Middle Rd	197332.63	893094	42.28832	-71.5323
1	Greg Baldwin (DRG)	2022/08/01		305	2022/08/01	GrBa20220801084805	8:48:19	Oak, Northern Red	Quercus rubra	Wooded Space	No	32	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Significant	Low	Yes	95	Middle Rd	Front	Middle Rd	197489.49	893919.5	42.29575	-71.5304
1	Greg Baldwin (DRG)	2022/08/01		311	2022/08/01	GrBa20220801084902	8:49:21	Maple, Red	Acer rubrum	Wooded Space	No	11	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	95	Middle Rd	Front	Middle Rd	197488.14	893923	42.29578	-71.5305
1	Greg Baldwin (DRG)	2022/08/01		312	2022/08/01	GrBa20220801122930	12:30:19	Oak, Scarlet	Quercus coccinea	Wooded Space	No	27	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Minor	Low	Yes	146	Middle Rd	Front	Middle Rd	197303.15	892887.5	42.28646	-71.5327
1	Greg Baldwin (DRG)	2022/08/01	borderline; end hedgerow; 6	316	2022/08/01	GrBa20220801104430	10:45:30	Cedar, Northern White	Thuja occidentalis	Open Space	No	12	Poor	Routine Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	12	Middle Rd	Front	Middle Rd	197396.76	894841.5	42.30405	-71.5316
1	Greg Baldwin (DRG)	2022/08/18	pole number 59; large leader or limb decay	317	2022/08/01	GrBa20220801133102	12:04:51	Maple, Red	Acer rubrum	Wooded Space	Yes	12	Poor	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	151	Middle Rd	Front	Middle Rd	197333.69	893096.8	42.28834	-71.5323
1	Greg Baldwin (DRG)	2022/08/01		321	2022/08/01	GrBa20220801085101	8:51:20	Oak, Northern Red	Quercus rubra	Wooded Space	No	35	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Severe	Low	Yes	91	Middle Rd	Front	Middle Rd	197485.36	893948.2	42.29601	-71.5305
1	Greg Baldwin (DRG)	2022/08/01		322	2022/08/01	GrBa20220801104659	10:47:25	Maple, Red	Acer rubrum	Open Space	No	19	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	18	Middle Rd	Front	Middle Rd	197339.29	894754.1	42.30326	-71.5323
1	Greg Baldwin (DRG)	2022/08/01	borderline	323	2022/08/01	GrBa20220801123109	12:32:09	Maple, Red	Acer rubrum	Open Space	No	10	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Minor	Low	Yes	146	Middle Rd	Front	Middle Rd	197305.31	892846.7	42.28609	-71.5327
1	Greg Baldwin (DRG)	2022/08/18		326	2022/08/01	GrBa20220801133316	10:18:58	Oak, White	Quercus alba	Open Space	No	33	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	149	Middle Rd	Front	Middle Rd	197349.23	893138.2	42.28872	-71.5321
1	Greg Baldwin (DRG)	2022/08/01	trunk decay; borderline	330	2022/08/01	GrBa20220801085228	8:54:34	Oak, Northern Red	Quercus rubra	Wooded Space	No	26	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	91	Middle Rd	Front	Middle Rd	197485.07	893956.2	42.29608	-71.5305
1	Greg Baldwin (DRG)	2022/08/18	trunk decay	332	2022/08/01	GrBa20220801133357	10:18:58	Oak, Northern Red	Quercus rubra	Open Space	No	39	Poor	Prune	Advanced	Missing Or Decayed Wood	Moderate	Possible	High	Somewhat Likely	Significant	Moderate	Yes	147	Middle Rd	Front	Middle Rd	197353.59	893165.5	42.28896	-71.5321
1	Greg Baldwin (DRG)	2022/08/18	borderline; pole number 18	333	2022/08/01	GrBa20220801105313	11:54:19	Oak, Swamp White	Quercus bicolor	Wooded Space	No	33	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	22	Middle Rd	Front	Middle Rd	197366.75	894449.8	42.30053	-71.5319
1	Greg Baldwin (DRG)	2022/08/01	borderline	337	2022/08/01	GrBa20220801123326	12:34:11	Ash, White	Fraxinus americana	Wooded Space	No	17	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	150	Middle Rd	Front	Middle Rd	197306.24	892817.7	42.28583	-71.5327
1	Greg Baldwin (DRG)	2022/08/01		339	2022/08/01	GrBa20220801085731	8:57:54	Pine, Eastern White	Pinus strobus	Wooded Space	No	12	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	85	Middle Rd	Front	Middle Rd	197477.31	894100.6	42.29738	-71.5306
1	Greg Baldwin (DRG)	2022/08/01	borderline; cavity or decay	342	2022/08/01	GrBa20220801133831	13:44:40	Pine, Eastern White	Pinus strobus	Open Space	No	48	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Severe	Low	Yes	145	Middle Rd	Front	Middle Rd	197354.97	893241.8	42.28965	-71.5321
1	Greg Baldwin (DRG)	2022/08/18	pole number 19	343	2022/08/01	GrBa20220801105518	11:54:19	Oak, Northern Red	Quercus rubra	Wooded Space	No	14	Good	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Significant	Low	Yes	22	Middle Rd	Front	Middle Rd	197377.32	894429.9	42.30035	-71.5318
1	Greg Baldwin (DRG)	2022/08/01		345	2022/08/01	GrBa20220801123451	12:35:30	Hickory, Shagbark	Carya ovata	Wooded Space	No	13	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	150	Middle Rd	Front	Middle Rd	197305.7	892792.6	42.28561	-71.5327
1	Greg Baldwin (DRG)	2022/08/01		350	2022/08/01	GrBa20220801134505	13:46:02	Hickory, Pignut	Carya glabra	Wooded Space	No	16	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	145	Middle Rd	Front	Middle Rd	197354.03	893257.6	42.28979	-71.5321
1	Greg Baldwin (DRG)	2022/08/01		351	2022/08/01	GrBa20220801085756	8:58:11	Pine, Eastern White	Pinus strobus	Wooded Space	No	12	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	85	Middle Rd	Front	Middle Rd	197477.08	894102.7	42.2974	-71.5306
1	Greg Baldwin (DRG)	2022/08/18	borderline	354	2022/08/01	GrBa20220801074256	12:04:11	Linden, Littleleaf	Tilia cordata	Wooded Space	Yes	11	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	125	Middle Rd	Front	Middle Rd	197433.11	893460.6	42.29162	-71.5311

1	Greg Baldwin (DRG)	2022/08/18	pole number 19; borderline; utility pruned	355	2022/08/01	GrBa20220801105626	11:54:19	Pine, Eastern White	Pinus strobus	Wooded Space	No	11	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Minor	Low	Yes	22	Middle Rd	Front	Middle Rd	197380.56	894423.9	42.30029	-71.5318
1	Greg Baldwin (DRG)	2022/08/01		357	2022/08/01	GrBa20220801123547	12:36:35	Hickory, Shagbark	Carya ovata	Wooded Space	No	11	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	150	Middle Rd	Front	Middle Rd	197303.23	892782	42.28551	-71.5327
1	Greg Baldwin (DRG)	2022/08/01	borderline	360	2022/08/01	GrBa20220801134659	13:47:39	Basswood, American	Tilia americana	Open Space	No	4	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Minor	Low	Yes	218	Turnpike Rd	Side	Middle Rd	197356.1	893289.3	42.29008	-71.5321
1	Greg Baldwin (DRG)	2022/08/01		362	2022/08/01	GrBa20220801085904	9:00:42	Maple, Red	Acer rubrum	Wooded Space	No	16	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Medium	Unlikely	Significant	Low	Yes	85	Middle Rd	Front	Middle Rd	197475.51	894149.1	42.29782	-71.5306
1	Greg Baldwin (DRG)	2022/08/01		364	2022/08/01	GrBa20220801074724	7:48:06	Oak, Northern Red	Quercus rubra	Open Space	Yes	8	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	123	Middle Rd	Front	Middle Rd	197448.06	893514.8	42.29211	-71.5309
1	Greg Baldwin (DRG)	2022/08/18	pole number 22	365	2022/08/01	GrBa20220801110008	11:56:58	Oak	Quercus species	Open Space	No	22	Dead	Remove	None	No Significant Defect	None	Possible	Very Low	Unlikely	Significant	Low	Yes	42	Middle Rd	Front	Middle Rd	197430.97	894334	42.29948	-71.5312
1	Greg Baldwin (DRG)	2022/08/01		367	2022/08/01	GrBa20220801123733	12:37:57	Birch, Black	Betula lenta	Wooded Space	No	10	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	150	Middle Rd	Front	Middle Rd	197292.1	892738.5	42.28512	-71.5328
1	Greg Baldwin (DRG)	2022/08/01		369	2022/08/01	GrBa20220801134817	13:49:04	Oak, White	Quercus alba	Open Space	Yes	31	Fair	Prune	None	Dead And Dying Branches	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	218	Turnpike Rd	Side	Middle Rd	197359.17	893302	42.29019	-71.532
1	Greg Baldwin (DRG)	2022/08/18		372	2022/08/01	GrBa20220801090211	13:11:04	Oak, Northern Red	Quercus rubra	Wooded Space	No	37	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Low	Unlikely	Severe	Low	Yes	79	Middle Rd	Front	Middle Rd	197471.65	894184.7	42.29814	-71.5307
1	Greg Baldwin (DRG)	2022/08/01		374	2022/08/01	GrBa20220801074837	7:49:18	Spruce, Blue	Picea pungens	Open Space	No	26	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	123	Middle Rd	Front	Middle Rd	197449.36	893525.7	42.29221	-71.5309
1	Greg Baldwin (DRG)	2022/08/18	pole number 22	376	2022/08/01	GrBa20220801110222	11:56:58	Pine, Eastern White	Pinus strobus	Open Space	No	30	Dead	Remove	None	No Significant Defect	None	Possible	Very Low	Unlikely	Significant	Low	Yes	42	Middle Rd	Front	Middle Rd	197447.54	894298.4	42.29916	-71.531
1	Greg Baldwin (DRG)	2022/08/01		377	2022/08/01	GrBa20220801123831	12:38:46	Maple, Red	Acer rubrum	Open Space	No	15	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	156	Middle Rd	Front	Middle Rd	197283.15	892715.2	42.28491	-71.5329
1	Greg Baldwin (DRG)	2022/08/01	borderline	378	2022/08/01	GrBa20220801134939	13:50:24	Hickory, Shagbark	Carya ovata	Open Space	No	23	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	218	Turnpike Rd	Side	Middle Rd	197361.17	893311.7	42.29028	-71.532
1	Greg Baldwin (DRG)	2022/08/01		379	2022/08/01	GrBa20220801090417	9:06:40	Oak, White	Quercus alba	Wooded Space	No	25	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	79	Middle Rd	Front	Middle Rd	197470.5	894193.7	42.29822	-71.5307
1	Greg Baldwin (DRG)	2022/08/01	remove hardware	384	2022/08/01	GrBa20220801074950	7:50:19	Maple, Red	Acer rubrum	Open Space	No	2	Good	Train	None	No Significant Defect	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	123	Middle Rd	Front	Middle Rd	197455.66	893552.6	42.29245	-71.5309
1	Greg Baldwin (DRG)	2022/08/18	pole number 22	385	2022/08/01	GrBa20220801110430	11:56:58	Oak	Quercus species	Open Space	No	23	Dead	Remove	None	No Significant Defect	None	Possible	Very Low	Unlikely	Minor	Low	Yes	42	Middle Rd	Front	Middle Rd	197453.18	894286.8	42.29906	-71.5309
1	Greg Baldwin (DRG)	2022/08/01		388	2022/08/01	GrBa20220801123907	12:39:20	Maple, Red	Acer rubrum	Open Space	No	9	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Significant	Low	Yes	156	Middle Rd	Front	Middle Rd	197280.56	892709.1	42.28485	-71.533
1	Greg Baldwin (DRG)	2022/08/01		389	2022/08/01	GrBa20220801143557	14:36:48	Maple, Norway	Acer platanoides	Open Space	No	16	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	170	Middle Rd	Front	Middle Rd	197197.64	892444.8	42.28247	-71.534
1	Greg Baldwin (DRG)	2022/08/01		392	2022/08/01	GrBa20220801090716	9:07:39	Birch, Black	Betula lenta	Wooded Space	No	10	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	79	Middle Rd	Front	Middle Rd	197467.22	894202.8	42.2983	-71.5307
1	Greg Baldwin (DRG)	2022/08/01	borderline	394	2022/08/01	GrBa20220801075054	7:51:54	Walnut, Black	Juglans nigra	Open Space	No	12	Good	Routine Prune	None	Broken And/Or Hanging Branches	Low	Probable	Low	Unlikely	Negligible	Low	Yes	123	Middle Rd	Front	Middle Rd	197460.44	893581.5	42.29271	-71.5308
1	Greg Baldwin (DRG)	2022/08/18	pole number 24	395	2022/08/01	GrBa20220801110554	11:56:58	Maple, Red	Acer rubrum	Open Space	No	16	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	42	Middle Rd	Front	Middle Rd	197462.46	894258.5	42.2988	-71.5308
1	Greg Baldwin (DRG)	2022/08/01		399	2022/08/01	GrBa20220801143659	15:17:54	Plum	Prunus species	Open Space	No	9	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Minor	Low	Yes	172	Middle Rd	Front	Middle Rd	197179.28	892414.1	42.2822	-71.5342
1	Greg Baldwin (DRG)	2022/08/18	dbh estimated; poison ivy	401	2022/08/01	GrBa20220801090807	13:59:05	Oak, Northern Red	Quercus rubra	Wooded Space	No	17	Poor	Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Significant	Low	Yes	79	Middle Rd	Front	Middle Rd	197464.05	894215.4	42.29842	-71.5308
1	Greg Baldwin (DRG)	2022/08/01		402	2022/08/01	GrBa20220801123945	12:39:59	Maple, Red	Acer rubrum	Open Space	No	17	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	156	Middle Rd	Front	Middle Rd	197277.73	892703.2	42.2848	-71.533
1	Greg Baldwin (DRG)	2022/08/01	dbh estimated; poison ivy; vines >50%	403	2022/08/01	GrBa20220801075201	9:58:08	Redcedar, Eastern	Juniperus virginiana	Wooded Space	Yes	8	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	123	Middle Rd	Front	Middle Rd	197462.62	893590.2	42.29279	-71.5308
1	Greg Baldwin (DRG)	2022/08/18	pole number 24	405	2022/08/01	GrBa20220801110746	11:56:58	Maple, Red	Acer rubrum	Open Space	No	14	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	42	Middle Rd	Front	Middle Rd	197463.92	894252	42.29874	-71.5308
1	Greg Baldwin (DRG)	2022/08/01		409	2022/08/01	GrBa20220801143743	15:18:00	Plum	Prunus species	Open Space	No	9	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Negligible	Low	Yes	172	Middle Rd	Front	Middle Rd	197172.81	892404	42.28211	-71.5343
1	Greg Baldwin (DRG)	2022/08/01		410	2022/08/01	GrBa20220801090853	9:10:00	Maple, Red	Acer rubrum	Wooded Space	No	19	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	79	Middle Rd	Front	Middle Rd	197462.58	894218.7	42.29844	-71.5308
1	Greg Baldwin (DRG)	2022/08/01		413	2022/08/01	GrBa20220801124021	12:40:37	Maple, Red	Acer rubrum	Open Space	No	11	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	156	Middle Rd	Front	Middle Rd	197274.55	892695.7	42.28473	-71.533
1	Greg Baldwin (DRG)	2022/08/01	adelgids; borderline	414	2022/08/01	GrBa20220801075435	9:59:35	Hemlock, Eastern	Tsuga canadensis	Wooded Space	Yes	12	Poor	Routine Prune	Insect/Dis	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	21	General Henry Knc	Side	Middle Rd	197463.62	893598.5	42.29286	-71.5308
1	Greg Baldwin (DRG)	2022/08/18	pole number 24; utility pruned	415	2022/08/01	GrBa20220801110916	11:56:58	Maple, Red	Acer rubrum	Wooded Space	No	28	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	42	Middle Rd	Front	Middle Rd	197465.74	894246.5	42.29869	-71.5307
1	Greg Baldwin (DRG)	2022/08/01		419	2022/08/01	GrBa20220801143856	14:39:20	Plum	Prunus species	Open Space	No	9	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Minor	Low	Yes	172	Middle Rd	Front	Middle Rd	197165.57	892392.5	42.282	-71.5344
1	Greg Baldwin (DRG)	2022/08/01		422	2022/08/01	GrBa20220801124054	12:41:46	Hickory, Pignut	Carya glabra	Open Space	No	14	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	158	Middle Rd	Front	Middle Rd	197273.26	892690.5	42.28469	-71.5331
1	Greg Baldwin (DRG)	2022/08/01	borderline	423	2022/08/01	GrBa20220801075640	9:59:31	Hickory, Shagbark	Carya ovata	Wooded Space	No	11	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	21	General Henry Knc	Side	Middle Rd	197464.15	893601.7	42.29289	-71.5307
1	Greg Baldwin (DRG)	2022/08/01	borderline	424	2022/08/01	GrBa20220801111601	11:18:59	Oak, Scarlet	Quercus coccinea	Open Space	No	28	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Minor	Low	Yes	80	Middle Rd	Front	Middle Rd	197501.45	893899.6	42.29557	-71.5303
1	Greg Baldwin (DRG)	2022/08/01		425	2022/08/01	GrBa20220801091013	9:13:08	Maple, Red	Acer rubrum	Wooded Space	No	18	Fair	Routine Prune	None	Root Problems	Low	Improbable	High	Unlikely	Minor	Low	Yes	79	Middle Rd	Front	Middle Rd	197461.47	894225.7	42.29851	-71.5308
1	Greg Baldwin (DRG)	2022/08/01		429	2022/08/01	GrBa20220801144010	14:40:43	Maple, Norway	Acer platanoides	Wooded Space	No	11	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	172	Middle Rd	Front	Middle Rd	197156.8	892379.3	42.28188	-71.5345
1	Greg Baldwin (DRG)	2022/08/01	borderline	432	2022/08/01	GrBa20220801111715	11:18:19	Oak, Northern Red	Quercus rubra	Open Space	No	27	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	80	Middle Rd	Front	Middle Rd	197502.86	893890.8	42.29549	-71.5303
1	Greg Baldwin (DRG)	2022/08/01		433	2022/08/01	GrBa20220801075855	7:59:31	Oak, Northern Red	Quercus rubra	Wooded Space	No	10	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	21	General Henry Knc	Side	Middle Rd	197465.68	893613.6	42.293	-71.5307
1	Greg Baldwin (DRG)	2022/08/01		434	2022/08/01	GrBa20220801124153	12:51:57	Pine, Eastern White	Pinus strobus	Open Space	No	30	Good	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	158	Middle Rd	Front	Middle Rd	197265.02	892669.4	42.2845	-71.5332
1	Greg Baldwin (DRG)	2022/08/01		435	2022/08/01	GrBa20220801091219	9:12:59	Oak, Northern Red	Quercus rubra	Wooded Space	No	29	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	79	Middle Rd	Front	Middle Rd	197460.94	894229.4	42.29854	-71.5308
1	Greg Baldwin (DRG)	2022/08/01	borderline	440	2022/08/01	GrBa20220801111958	11:20:36	Oak, Black	Quercus velutina	Open Space	No	37	Poor	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	82	Middle Rd	Front	Middle Rd	197505.26	893858.5	42.2952	-71.5303
1	Greg Baldwin (DRG)	2022/08/01		442	2022/08/01	GrBa20220801144110	14:41:49	Elm, American	Ulmus americana	Wooded Space	No	16	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	172	Middle Rd	Front	Middle Rd	197150.68	892372.3	42.28182	-71.5345
1	Greg Baldwin (DRG)	2022/08/01	borderline	443	2022/08/01	GrBa20220801075958	9:59:07	Oak, Northern Red	Quercus rubra	Wooded Space	No	12	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	21	General Henry Knc	Side	Middle Rd	197464.56	893609	42.29296	-71.5307
1	Greg Baldwin (DRG)	2022/08/18		444	2022/08/01	GrBa20220801091352	11:58:50	Pine, Eastern White	Pinus strobus	Wooded Space	No	8	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	79	Middle Rd	Front	Middle Rd	197458.12	894235.9	42.2986	-71.5308
1	Greg Baldwin (DRG)	2022/08/01		445	2022/08/01	GrBa20220801124445	12:45:08	Maple, Red	Acer rubrum	Open Space	No	18	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	160	Middle Rd	Front	Middle Rd	197244.94	892608.3	42.28395	-71.5334
1	Greg Baldwin (DRG)	2022/08/01		450	2022/08/01	GrBa20220801144247	14:44:14	Elm, American	Ulmus americana	Wooded Space	No	12	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Significant	Low	Yes	172	Middle Rd	Front	Middle Rd	197136.86	892360.5	42.28171	-71.5347

1	Greg Baldwin (DRG)	2022/08/01	borderline	451	2022/08/01	GrBa20220801112349	11:24:20	Oak, Northern Red	Quercus rubra	Wooded Space	Yes	22	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	86	Middle Rd	Front	Middle Rd	197500	893803.3	42.2947	-71.5303
1	Greg Baldwin (DRG)	2022/08/01		452	2022/08/01	GrBa20220801080259	8:03:38	Oak, Black	Quercus velutina	Wooded Space	No	19	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	22	General Henry Knc	Side	Middle Rd	197471.4	893656.1	42.29338	-71.5307
1	Greg Baldwin (DRG)	2022/08/18	dbh estimated; poison ivy	453	2022/08/01	GrBa20220801091600	11:58:16	Maple, Red	Acer rubrum	Wooded Space	No	23	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Medium	Unlikely	Severe	Low	Yes	78	Middle Rd	Front	Middle Rd	197476.21	894212.2	42.29839	-71.5306
1	Greg Baldwin (DRG)	2022/08/01		455	2022/08/01	GrBa20220801124511	12:45:44	Spruce, Blue	Picea pungens	Open Space	No	3	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	160	Middle Rd	Front	Middle Rd	197243.82	892605.3	42.28392	-71.5334
1	Greg Baldwin (DRG)	2022/08/01		457	2022/08/01	GrBa20220801144444	14:45:31	Maple, Norway	Acer platanoides	Wooded Space	No	10	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	172	Middle Rd	Front	Middle Rd	197137.92	892360.5	42.28171	-71.5347
1	Greg Baldwin (DRG)	2022/08/01		459	2022/08/01	GrBa20220801112504	11:25:41	Hickory, Pignut	Carya glabra	Wooded Space	No	15	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	90	Middle Rd	Front	Middle Rd	197495.53	893773.5	42.29444	-71.5304
1	Greg Baldwin (DRG)	2022/08/01		462	2022/08/01	GrBa20220801124816	12:48:57	Maple, Sugar	Acer saccharum	Wooded Space	No	8	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Negligible	Low	Yes	187	Middle Rd	Front	Middle Rd	197228.11	892583	42.28372	-71.5336
1	Greg Baldwin (DRG)	2022/08/01		464	2022/08/01	GrBa20220801080418	8:04:41	Oak, Black	Quercus velutina	Wooded Space	No	41	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	22	General Henry Knc	Side	Middle Rd	197472.29	893661.3	42.29343	-71.5307
1	Greg Baldwin (DRG)	2022/08/18	borderline	465	2022/08/01	GrBa20220801091832	11:58:16	Oak, Northern Red	Quercus rubra	Wooded Space	No	42	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Significant	Low	Yes	78	Middle Rd	Front	Middle Rd	197483.42	894180.4	42.2981	-71.5305
1	Greg Baldwin (DRG)	2022/08/01	borderline	468	2022/08/01	GrBa20220801144654	14:47:38	Maple, Norway	Acer platanoides	Wooded Space	No	23	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	2	Hidden Meadow L	Side	Middle Rd	197127.8	892353	42.28165	-71.5348
1	Greg Baldwin (DRG)	2022/08/01		470	2022/08/01	GrBa20220801080505	8:05:49	Hickory, Pignut	Carya glabra	Wooded Space	No	13	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	22	General Henry Knc	Side	Middle Rd	197472.82	893668.5	42.29349	-71.5306
1	Greg Baldwin (DRG)	2022/08/26		471	2022/08/01	GrBa20220801125231	9:52:19	Maple, Sugar	Acer saccharum	Wooded Space	No	15	Fair	Routine Prune	None	Dead And Dying Branches	Low	Improbable	High	Unlikely	Minor	Low	Yes	181	Middle Rd	Front	Middle Rd	197260.14	892684.5	42.28463	-71.5332
1	Greg Baldwin (DRG)	2022/08/01	dbh estimated; poison ivy	472	2022/08/01	GrBa20220801112604	11:29:07	Oak, White	Quercus alba	Open Space	No	24	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	90	Middle Rd	Front	Middle Rd	197493.05	893761.7	42.29433	-71.5304
1	Greg Baldwin (DRG)	2022/08/18		474	2022/08/01	GrBa20220801091936	11:58:16	Oak, Northern Red	Quercus rubra	Wooded Space	No	36	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	78	Middle Rd	Front	Middle Rd	197482.9	894178.4	42.29808	-71.5305
1	Greg Baldwin (DRG)	2022/08/01	dbh estimated; poison ivy	479	2022/08/01	GrBa20220801144805	14:49:12	Maple, Norway	Acer platanoides	Wooded Space	Yes	15	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	184	Middle Rd	Front	Middle Rd	197105.62	892339.8	42.28153	-71.5351
1	Greg Baldwin (DRG)	2022/08/01	dbh estimated; poison ivy	480	2022/08/01	GrBa20220801080602	10:00:59	Oak, White	Quercus alba	Wooded Space	No	43	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	22	General Henry Knc	Side	Middle Rd	197473.94	893677.1	42.29357	-71.5306
1	Greg Baldwin (DRG)	2022/08/18	borderline; pole number 29	482	2022/08/01	GrBa20220801092203	11:58:16	Elm, American	Ulmus americana	Wooded Space	No	13	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Minor	Low	Yes	78	Middle Rd	Front	Middle Rd	197489.37	894088.1	42.29727	-71.5304
1	Greg Baldwin (DRG)	2022/08/01		483	2022/08/01	GrBa20220801112657	11:28:08	Oak, Black	Quercus velutina	Open Space	No	22	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	90	Middle Rd	Front	Middle Rd	197492.34	893754.1	42.29426	-71.5304
1	Greg Baldwin (DRG)	2022/08/01	utility pruned	485	2022/08/01	GrBa20220801125424	12:55:17	Pine, Eastern White	Pinus strobus	Wooded Space	No	11	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	181	Middle Rd	Front	Middle Rd	197260.51	892687.2	42.28466	-71.5332
1	Greg Baldwin (DRG)	2022/08/01		489	2022/08/01	GrBa20220801144953	14:50:15	Maple, Sugar	Acer saccharum	Wooded Space	No	15	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	184	Middle Rd	Front	Middle Rd	197097.8	892334.9	42.28148	-71.5352
1	Greg Baldwin (DRG)	2022/08/18	dbh estimated; poison ivy; borderline; pole number 32	490	2022/08/01	GrBa20220801092417	11:58:16	Ash, White	Fraxinus americana	Wooded Space	No	20	Poor	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	78	Middle Rd	Front	Middle Rd	197492.8	894016.9	42.29663	-71.5304
1	Greg Baldwin (DRG)	2022/08/01		491	2022/08/01	GrBa20220801080740	8:10:06	Redcedar, Eastern	Juniperus virginiana	Open Space	Yes	3	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	111	Middle Rd	Front	Middle Rd	197475.18	893690.7	42.29369	-71.5306
1	Greg Baldwin (DRG)	2022/08/01		492	2022/08/01	GrBa20220801125535	12:57:08	Oak, Northern Red	Quercus rubra	Wooded Space	No	28	Fair	Prune	None	Dead And Dying Branches	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	181	Middle Rd	Front	Middle Rd	197261.53	892689.2	42.28467	-71.5332
1	Greg Baldwin (DRG)	2022/08/01		493	2022/08/01	GrBa20220801112813	11:28:57	Maple, Red	Acer rubrum	Open Space	No	25	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	90	Middle Rd	Front	Middle Rd	197492.22	893748.5	42.29421	-71.5304
1	Greg Baldwin (DRG)	2022/08/01		499	2022/08/01	GrBa20220801145043	14:50:59	Maple, Sugar	Acer saccharum	Wooded Space	No	10	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Significant	Low	Yes	184	Middle Rd	Front	Middle Rd	197095.97	892334.2	42.28148	-71.5352
1	Greg Baldwin (DRG)	2022/08/18	pole number 34	500	2022/08/01	GrBa20220801092645	11:58:16	Ash, White	Fraxinus americana	Wooded Space	No	27	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	78	Middle Rd	Front	Middle Rd	197495.7	893943.4	42.29597	-71.5304
1	Greg Baldwin (DRG)	2022/08/01	utility pruned	501	2022/08/01	GrBa20220801125731	12:57:59	Pine, Eastern White	Pinus strobus	Wooded Space	No	11	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	181	Middle Rd	Front	Middle Rd	197262.72	892692.6	42.2847	-71.5332
1	Greg Baldwin (DRG)	2022/08/01		502	2022/08/01	GrBa20220801081016	8:11:03	Maple, Red	Acer rubrum	Open Space	Yes	20	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	111	Middle Rd	Front	Middle Rd	197477.89	893713.7	42.2939	-71.5306
1	Greg Baldwin (DRG)	2022/08/01		503	2022/08/01	GrBa20220801112918	11:30:32	Maple, Norway 'Crimson King'	Acer platanoides 'Crimson King'	Open Space	No	20	Poor	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	90	Middle Rd	Front	Middle Rd	197490.63	893738.7	42.29412	-71.5304
1	Greg Baldwin (DRG)	2022/08/01		509	2022/08/01	GrBa20220801145126	14:52:03	Maple, Norway	Acer platanoides	Wooded Space	No	16	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Significant	Low	Yes	184	Middle Rd	Front	Middle Rd	197087.97	892330.4	42.28144	-71.5353
1	Greg Baldwin (DRG)	2022/08/18	pole number 34; borderline	510	2022/08/01	GrBa20220801092904	11:58:16	Oak, Northern Red	Quercus rubra	Wooded Space	No	36	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	78	Middle Rd	Front	Middle Rd	197497.58	893937.6	42.29591	-71.5303
1	Greg Baldwin (DRG)	2022/08/01		511	2022/08/01	GrBa20220801125813	12:59	Maple, Red	Acer rubrum	Wooded Space	No	12	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	181	Middle Rd	Front	Middle Rd	197263.23	892695.1	42.28473	-71.5332
1	Greg Baldwin (DRG)	2022/08/01		513	2022/08/01	GrBa20220801081118	8:13:26	Hickory, Pignut	Carya glabra	Wooded Space	No	19	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	1	Devine Ln	Side	Middle Rd	197483.02	893746.6	42.29419	-71.5305
1	Greg Baldwin (DRG)	2022/08/01	dbh estimated; poison ivy; borderline	514	2022/08/01	GrBa20220801113043	11:31:36	Maple, Japanese	Acer palmatum	Open Space	Yes	9	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	90	Middle Rd	Front	Middle Rd	197488.62	893713.2	42.29389	-71.5305
1	Greg Baldwin (DRG)	2022/08/01		518	2022/08/01	GrBa20220801145435	14:55:07	Cherry, Black	Prunus serotina	Wooded Space	No	9	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	184	Middle Rd	Front	Middle Rd	197028.9	892284.8	42.28103	-71.536
1	Greg Baldwin (DRG)	2022/08/18	pole number 22	520	2022/08/01	GrBa20220801101012	11:56:30	Oak, Scarlet	Quercus coccinea	Open Space	No	17	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	43	Middle Rd	Front	Middle Rd	197418.93	894335.7	42.2995	-71.5313
1	Greg Baldwin (DRG)	2022/08/01	dbh estimated; poison ivy	521	2022/08/01	GrBa20220801113200	11:33:54	Oak, White	Quercus alba	Open Space	Yes	33	Fair	Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Severe	Low	Yes	94	Middle Rd	Front	Middle Rd	197483.68	893686.1	42.29365	-71.5305
1	Greg Baldwin (DRG)	2022/08/01		524	2022/08/01	GrBa20220801081401	8:15:33	Hickory, Pignut	Carya glabra	Open Space	No	16	Dead	Remove	None	No Significant Defect	None	Possible	High	Somewhat Likely	Significant	Moderate	Yes	107	Middle Rd	Front	Middle Rd	197484.26	893757.2	42.29429	-71.5305
1	Greg Baldwin (DRG)	2022/08/01	topped	525	2022/08/01	GrBa20220801125935	13:00:00	Pine, Eastern White	Pinus strobus	Wooded Space	No	14	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	179	Middle Rd	Front	Middle Rd	197276.41	892722.7	42.28498	-71.533
1	Greg Baldwin (DRG)	2022/08/01		528	2022/08/01	GrBa20220801145625	14:56:55	Maple, Sugar	Acer saccharum	Wooded Space	No	14	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	184	Middle Rd	Front	Middle Rd	197026.32	892282.5	42.28101	-71.5361
1	Greg Baldwin (DRG)	2022/08/18	pole number 19	530	2022/08/01	GrBa20220801101325	11:55:59	Maple, Red	Acer rubrum	Wooded Space	No	14	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	23	Middle Rd	Front	Middle Rd	197371.73	894418.8	42.30025	-71.5319
1	Greg Baldwin (DRG)	2022/08/18	start hedge row; 23	531	2022/08/01	GrBa20220801113411	10:21:42	Cedar, Northern White	Thuja occidentalis	Open Space	Yes	2	Good	N/A	None	No Significant Defect	Low	Improbable	Low	Unlikely	Minor	Low	Yes	34	Meetinghouse Ln	Side	Middle Rd	197479.48	893641.1	42.29324	-71.5306

1	Greg Baldwin (DRG)	2022/08/01		533	2022/08/01	GrBa20220801081618	8:17:47	Ash, White	Fraxinus americana	Wooded Space	No	14	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Significant	Low	Yes	107	Middle Rd	Front	Middle Rd	197487.62	893783.5	42.29453	-71.5305
1	Greg Baldwin (DRG)	2022/08/01		534	2022/08/01	GrBa20220801145657	14:57:24	Maple, Sugar	Acer saccharum	Wooded Space	Yes	9	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	184	Middle Rd	Front	Middle Rd	197024.79	892281	42.281	-71.5361
1	Greg Baldwin (DRG)	2022/08/01	lost major leader or limb	538	2022/08/01	GrBa20220801130142	13:03:08	Oak, Black	Quercus velutina	Wooded Space	Yes	17	Fair	Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Significant	Low	Yes	177	Middle Rd	Front	Middle Rd	197286.7	892754.5	42.28526	-71.5329
1	Greg Baldwin (DRG)	2022/08/01	end hedge row; 23	540	2022/08/01	GrBa20220801113653	11:38:14	Cedar, Northern White	Thuja occidentalis	Open Space	Yes	3	Good	N/A	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	34	Meetinghouse Ln	Side	Middle Rd	197477.71	893624.7	42.2931	-71.5306
1	Greg Baldwin (DRG)	2022/08/18	pole number 19	541	2022/08/01	GrBa20220801101443	11:55:59	Cherry, Black	Prunus serotina	Wooded Space	No	13	Poor	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	23	Middle Rd	Front	Middle Rd	197360.33	894438.9	42.30043	-71.532
1	Greg Baldwin (DRG)	2022/08/01	borderline	543	2022/08/01	GrBa20220801145828	14:58:49	Maple, Sugar	Acer saccharum	Wooded Space	Yes	10	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	188	Middle Rd	Front	Middle Rd	196990.96	892252.3	42.28074	-71.5365
1	Greg Baldwin (DRG)	2022/08/01		544	2022/08/01	GrBa20220801081840	8:22:04	Oak, Northern Red	Quercus rubra	Wooded Space	No	21	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	107	Middle Rd	Front	Middle Rd	197486.8	893786.7	42.29455	-71.5305
1	Greg Baldwin (DRG)	2022/08/01		549	2022/08/01	GrBa20220801130343	13:04:03	Maple, Red	Acer rubrum	Wooded Space	No	14	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	177	Middle Rd	Front	Middle Rd	197288.82	892758.7	42.2853	-71.5329
1	Greg Baldwin (DRG)	2022/08/01	borderline	550	2022/08/01	GrBa20220801114220	11:43:06	Maple, Sugar	Acer saccharum	Open Space	No	8	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Minor	Low	Yes	34	Meetinghouse Ln	Side	Middle Rd	197450.73	893481.1	42.2918	-71.5309
1	Greg Baldwin (DRG)	2022/08/18	pole number 19	553	2022/08/01	GrBa20220801101552	11:55:59	Maple, Red	Acer rubrum	Wooded Space	No	17	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	23	Middle Rd	Front	Middle Rd	197358.28	894442.3	42.30046	-71.532
1	Greg Baldwin (DRG)	2022/08/01		555	2022/08/01	GrBa20220801145920	15:00:34	Hickory, Pignut	Carya glabra	Wooded Space	No	16	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	188	Middle Rd	Front	Middle Rd	196982.49	892247.4	42.2807	-71.5366
1	Greg Baldwin (DRG)	2022/08/01	lost major leader or limb	556	2022/08/01	GrBa20220801082209	8:23	Oak, Northern Red	Quercus rubra	Wooded Space	No	23	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	107	Middle Rd	Front	Middle Rd	197487.44	893789.8	42.29458	-71.5305
1	Greg Baldwin (DRG)	2022/08/01	dbh estimated; poison ivy	559	2022/08/01	GrBa20220801120524	12:06:11	Maple, Red	Acer rubrum	Wooded Space	No	9	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Minor	Low	Yes	206	Turnpike Rd	Side	Middle Rd	197375.21	893323	42.29038	-71.5318
1	Greg Baldwin (DRG)	2022/08/01	borderline; vines >50%	562	2022/08/01	GrBa20220801150118	15:02:14	Maple, Red	Acer rubrum	Wooded Space	No	8	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	188	Middle Rd	Front	Middle Rd	196977.84	892240.6	42.28063	-71.5366
1	Greg Baldwin (DRG)	2022/08/18	pole number 19; borderline	563	2022/08/01	GrBa20220801101732	11:55:59	Maple, Red	Acer rubrum	Wooded Space	No	16	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	23	Middle Rd	Front	Middle Rd	197356.63	894445	42.30048	-71.5321
1	Greg Baldwin (DRG)	2022/08/01		565	2022/08/01	GrBa20220801082355	8:24:54	Tree, Unknown	Unknown Tree	Wooded Space	No	22	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Minor	Low	Yes	105	Middle Rd	Front	Middle Rd	197488.74	893797.1	42.29465	-71.5305
1	Greg Baldwin (DRG)	2022/08/01		568	2022/08/01	GrBa20220801120630	12:06:59	Maple, Red	Acer rubrum	Wooded Space	Yes	10	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	206	Turnpike Rd	Side	Middle Rd	197374.68	893320.4	42.29036	-71.5318
1	Greg Baldwin (DRG)	2022/08/18	lost major leader or limb	569	2022/08/01	GrBa20220801130559	10:18:58	Oak, Northern Red	Quercus rubra	Wooded Space	Yes	24	Fair	Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Significant	Low	Yes	177	Middle Rd	Front	Middle Rd	197295.46	892786.5	42.28555	-71.5328
1	Greg Baldwin (DRG)	2022/08/18	pole number 19; borderline	570	2022/08/01	GrBa20220801101818	11:55:59	Maple, Red	Acer rubrum	Wooded Space	No	14	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	23	Middle Rd	Front	Middle Rd	197354.87	894447.6	42.3005	-71.5321
1	Greg Baldwin (DRG)	2022/08/01	borderline	573	2022/08/01	GrBa20220801082504	8:27:12	Oak, White	Quercus alba	Wooded Space	No	11	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	105	Middle Rd	Front	Middle Rd	197488.68	893803.3	42.29471	-71.5305
1	Greg Baldwin (DRG)	2022/08/01		575	2022/08/01	GrBa20220801150243	15:02:59	Maple, Red	Acer rubrum	Wooded Space	Yes	8	Poor	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	188	Middle Rd	Front	Middle Rd	196972.25	892236.9	42.2806	-71.5367
1	Greg Baldwin (DRG)	2022/08/01		578	2022/08/01	GrBa20220801120725	12:08:19	Hickory, Shagbark	Carya ovata	Open Space	No	19	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	118	Middle Rd	Front	Middle Rd	197370.67	893308.6	42.29025	-71.5319
1	Greg Baldwin (DRG)	2022/08/01		579	2022/08/01	GrBa20220801130703	13:08:17	Oak, White	Quercus alba	Wooded Space	No	21	Dead	Remove	None	No Significant Defect	None	Possible	High	Somewhat Likely	Significant	Moderate	Yes	177	Middle Rd	Front	Middle Rd	197295.55	892789.8	42.28558	-71.5328
1	Greg Baldwin (DRG)	2022/08/18	dbh estimated; poison ivy; pole number 18; borderline	580	2022/08/01	GrBa20220801101843	11:55:59	Maple, Red	Acer rubrum	Wooded Space	Yes	16	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Very Low	Unlikely	Significant	Low	Yes	23	Middle Rd	Front	Middle Rd	197353.17	894450.6	42.30053	-71.5321
1	Greg Baldwin (DRG)	2022/08/01	borderline	584	2022/08/01	GrBa20220801082714	8:28:39	Oak	Quercus species	Wooded Space	No	14	Dead	Remove	None	No Significant Defect	None	Possible	High	Somewhat Likely	Significant	Moderate	Yes	105	Middle Rd	Front	Middle Rd	197489.15	893806	42.29473	-71.5304
1	Greg Baldwin (DRG)	2022/08/01	borderline; vines >50%; dbh estimated; poison ivy	585	2022/08/01	GrBa20220801150335	15:07:05	Oak, White	Quercus alba	Wooded Space	No	11	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	215	Middle Rd	Front	Middle Rd	196979.84	892260.7	42.28082	-71.5366
1	Greg Baldwin (DRG)	2022/08/18	dbh estimated; poison ivy; pole number 56	588	2022/08/01	GrBa20220801121010	12:05:53	Oak, Northern Red	Quercus rubra	Wooded Space	No	26	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Very Low	Unlikely	Significant	Low	Yes	130	Middle Rd	Front	Middle Rd	197366.39	893190.5	42.28919	-71.5319
1	Greg Baldwin (DRG)	2022/08/01		589	2022/08/01	GrBa20220801130823	13:09:34	Maple, Red	Acer rubrum	Wooded Space	No	21	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	177	Middle Rd	Front	Middle Rd	197296.57	892794.4	42.28562	-71.5328
1	Greg Baldwin (DRG)	2022/08/18	dbh estimated; poison ivy; borderline; pole number 18; vines >50%	591	2022/08/01	GrBa20220801102035	11:55:59	Maple, Red	Acer rubrum	Wooded Space	No	14	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	23	Middle Rd	Front	Middle Rd	197344.12	894466.6	42.30068	-71.5322
1	Greg Baldwin (DRG)	2022/08/01	borderline; large leader or limb decay	593	2022/08/01	GrBa20220801131023	13:11:11	Oak, Black	Quercus velutina	Wooded Space	No	16	Fair	Routine Prune	None	Tree Architecture	Low	Possible	Low	Unlikely	Significant	Low	Yes	177	Middle Rd	Front	Middle Rd	197294.57	892797.5	42.28565	-71.5328
1	Greg Baldwin (DRG)	2022/08/01	borderline	594	2022/08/01	GrBa20220801083051	8:32:09	Oak	Quercus species	Wooded Space	No	19	Dead	Remove	None	No Significant Defect	None	Possible	High	Somewhat Likely	Significant	Moderate	Yes	105	Middle Rd	Front	Middle Rd	197490.45	893820.2	42.29486	-71.5304
1	Greg Baldwin (DRG)	2022/08/18		597	2022/08/01	GrBa20220801102304	11:55:59	Oak, Pin	Quercus palustris	Open Space	No	21	Fair	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	23	Middle Rd	Front	Middle Rd	197316.27	894517.7	42.30114	-71.5325
1	Greg Baldwin (DRG)	2022/08/18	pole number 58	600	2022/08/01	GrBa20220801121233	12:05:53	Maple, Norway	Acer platanoides	Wooded Space	Yes	8	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	130	Middle Rd	Front	Middle Rd	197353.2	893121.1	42.28856	-71.5321
1	Greg Baldwin (DRG)	2022/08/01		601	2022/08/01	GrBa20220801150528	15:07:10	Apple	Malus species	Wooded Space	No	9	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	215	Middle Rd	Front	Middle Rd	196988.49	892267.1	42.28087	-71.5365
1	Greg Baldwin (DRG)	2022/08/01		603	2022/08/01	GrBa20220801131153	13:13:33	Oak, White	Quercus alba	Wooded Space	No	16	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	177	Middle Rd	Front	Middle Rd	197295.46	892805.7	42.28572	-71.5328
1	Greg Baldwin (DRG)	2022/08/01		607	2022/08/01	GrBa20220801121619	12:16:57	Maple, Sugar	Acer saccharum	Wooded Space	No	11	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Significant	Low	Yes	134	Middle Rd	Front	Middle Rd	197320.35	893034.9	42.28779	-71.5325
1	Greg Baldwin (DRG)	2022/08/01		608	2022/08/01	GrBa20220801083303	8:33:41	Oak, Northern Red	Quercus rubra	Wooded Space	No	21	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	105	Middle Rd	Front	Middle Rd	197493.22	893827.8	42.29493	-71.5304
1	Greg Baldwin (DRG)	2022/08/01		610	2022/08/01	GrBa20220801150756	15:08:25	Maple, Red	Acer rubrum	Wooded Space	Yes	8	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	215	Middle Rd	Front	Middle Rd	196993.95	892272.2	42.28092	-71.5364
1	Greg Baldwin (DRG)	2022/08/18	pole number 16	612	2022/08/01	GrBa20220801102457	11:55:59	Maple, Red	Acer rubrum	Open Space	No	21	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	23	Middle Rd	Front	Middle Rd	197308.1	894531.7	42.30126	-71.5326
1	Greg Baldwin (DRG)	2022/08/01		614	2022/08/01	GrBa20220801121822	12:19:31	Maple	Acer species	Wooded Space	No	10	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Minor	Low	Yes	136	Middle Rd	Front	Middle Rd	197313.84	892994.8	42.28743	-71.5326
1	Greg Baldwin (DRG)	2022/08/01	large leader or limb decay	616	2022/08/01	GrBa20220801083434	8:35:16	Oak, Northern Red	Quercus rubra	Wooded Space	Yes	17	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Severe	Low	Yes	105	Middle Rd	Front	Middle Rd	197494.4	893837.3	42.29501	-71.5304
1	Greg Baldwin (DRG)	2022/08/01	borderline	617	2022/08/01	GrBa20220801131400	13:15:51	Ash, White	Fraxinus americana	Wooded Space	No	17	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	High	Somewhat Likely	Significant	Moderate	Yes	171	Middle Rd	Front	Middle Rd	197293.54	892867.7	42.28628	-71.5328
1	Greg Baldwin (DRG)	2022/08/18		620	2022/08/01	GrBa20220801102623	11:55:59	Oak, Pin	Quercus palustris	Open Space	No	20	Fair	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	23	Middle Rd	Front	Middle Rd	197305.22	894537.5	42.30131	-71.5327
1	Greg Baldwin (DRG)	2022/08/01	borderline	623	2022/08/01	GrBa20220801151110	15:12:51	Oak, Black	Quercus velutina	Wooded Space	No	22	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Severe	Low	Yes	205	Middle Rd	Front	Middle Rd	197140.82	892380	42.28189	-71.5347
1	Greg Baldwin (DRG)	2022/08/18		624	2022/08/01	GrBa20220801131640	13:11:04	Oak, Scarlet	Quercus coccinea	Wooded Space	No	23	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Medium	Unlikely	Significant	Low	Yes	171	Middle Rd	Front	Middle Rd	197293.43	892872.7	42.28633	-71.5328

1	Greg Baldwin (DRG)	2022/08/01		625	2022/08/01	GrBa20220801121933	12:20:34	Maple, Sugar	Acer saccharum	Wooded Space	No	14	Good	Routine Prune	None	Tree Architecture Dead And Dying	Low	Improbable	High	Unlikely	Significant	Low	Yes	136	Middle Rd	Front	Middle Rd	197313.6	892991	42.28739	-71.5326
1	Greg Baldwin (DRG)	2022/08/18	dbh estimated; poison ivy; pole number 13	626	2022/08/01	GrBa20220801103030	11:55:59	Locust, Black	Robinia pseudoacacia	Wooded Space	No	14	Good	Routine Prune	None	Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	23	Middle Rd	Front	Middle Rd	197268.69	894641.6	42.30225	-71.5331
1	Greg Baldwin (DRG)	2022/08/01		629	2022/08/01	GrBa20220801083555	8:36:31	Hickory, Pignut	Carya glabra	Wooded Space	Yes	9	Fair	Routine Prune	None	Tree Architecture Missing Or Decayed	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	105	Middle Rd	Front	Middle Rd	197495.11	893844.7	42.29508	-71.5304
1	Greg Baldwin (DRG)	2022/08/01	borderline	631	2022/08/01	GrBa20220801151354	15:14:41	Hickory, Pignut	Carya glabra	Open Space	No	20	Good	Routine Prune	None	Wood Missing Or Decayed	Low	Improbable	High	Unlikely	Significant	Low	Yes	199	Middle Rd	Front	Middle Rd	197173.42	892431.3	42.28235	-71.5343
1	Greg Baldwin (DRG)	2022/08/01	lost major leader or limb	634	2022/08/01	GrBa20220801131822	13:19:27	Oak, White	Quercus alba	Wooded Space	No	17	Fair	Routine Prune	None	Wood Dead And Dying	Low	Improbable	High	Unlikely	Significant	Low	Yes	171	Middle Rd	Front	Middle Rd	197292.84	892876.9	42.28636	-71.5328
1	Greg Baldwin (DRG)	2022/08/01		635	2022/08/01	GrBa20220801122105	12:21:29	Pine, Eastern White	Pinus strobus	Wooded Space	No	9	Fair	Routine Prune	None	Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	142	Middle Rd	Front	Middle Rd	197309.06	892963.8	42.28715	-71.5326
1	Greg Baldwin (DRG)	2022/08/01	utility pruned; unbalanced crown	636	2022/08/01	GrBa20220801103607	10:37:07	Elm, Siberian	Ulmus pumila	Open Space	No	30	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	48	Main St	Side	Middle Rd	197431.65	894924	42.30479	-71.5311
1	Greg Baldwin (DRG)	2022/08/01	borderline	640	2022/08/01	GrBa20220801151857	15:20:44	Elm, American	Ulmus americana	Wooded Space	No	11	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Significant	Low	Yes	2	Hidden Meadow L	Side	Middle Rd	197126.74	892351.1	42.28163	-71.5348
1	Greg Baldwin (DRG)	2022/08/01		641	2022/08/01	GrBa20220801083725	10:04:21	Ash, White	Fraxinus americana	Wooded Space	No	20	Poor	Routine Prune	None	Tree Architecture Missing Or Decayed	Low	Improbable	High	Unlikely	Significant	Low	Yes	103	Middle Rd	Front	Middle Rd	197494.41	893864	42.29525	-71.5304
1	Greg Baldwin (DRG)	2022/08/18		643	2022/08/01	GrBa20220801132050	12:07:00	Oak, White	Quercus alba	Wooded Space	No	26	Fair	Prune	None	Wood Dead And Dying	Low	Possible	Medium	Unlikely	Significant	Low	Yes	169	Middle Rd	Front	Middle Rd	197292.32	892905.6	42.28662	-71.5328
1	Greg Baldwin (DRG)	2022/08/01	borderline	645	2022/08/01	GrBa20220801122201	12:23:57	Oak, White	Quercus alba	Wooded Space	No	21	Fair	Routine Prune	None	Branches Weakly Attached Branches And	Low	Possible	Medium	Unlikely	Minor	Low	Yes	142	Middle Rd	Front	Middle Rd	197305.53	892951	42.28703	-71.5327
1	Greg Baldwin (DRG)	2022/08/01		646	2022/08/01	GrBa20220801103932	10:40:03	Maple, Norway	Acer platanoides	Open Space	No	20	Good	Routine Prune	None	Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	2	Middle Rd	Front	Middle Rd	197446.42	894964.6	42.30516	-71.531
1	Greg Baldwin (DRG)	2022/08/01		650	2022/08/01	GrBa20220801083940	8:40:18	Hickory, Pignut	Carya glabra	Open Space	No	15	Good	Routine Prune	None	Cracks Missing Or Decayed	Low	Improbable	High	Unlikely	Minor	Low	Yes	103	Middle Rd	Front	Middle Rd	197493.77	893878.7	42.29538	-71.5304
1	Greg Baldwin (DRG)	2022/08/18		653	2022/08/01	GrBa20220801132127	12:07:00	Hickory, Pignut	Carya glabra	Wooded Space	No	18	Fair	Prune	None	Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	169	Middle Rd	Front	Middle Rd	197292.03	892915.1	42.28671	-71.5328
1	Greg Baldwin (DRG)	2022/08/01		654	2022/08/01	GrBa20220801122402	12:25:10	Oak	Quercus species	Wooded Space	No	19	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Significant	Low	Yes	142	Middle Rd	Front	Middle Rd	197302.35	892942.9	42.28696	-71.5327
1	Greg Baldwin (DRG)	2022/08/01		656	2022/08/01	GrBa20220801104110	10:41:48	Maple, Norway	Acer platanoides	Open Space	No	15	Good	Routine Prune	None	No Significant Defect Missing Or Decayed	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	12	Middle Rd	Front	Middle Rd	197414.17	894869.8	42.30431	-71.5314
1	Greg Baldwin (DRG)	2022/08/01		658	2022/08/01	GrBa20220801122549	12:26:36	Oak, White	Quercus alba	Wooded Space	No	15	Fair	Routine Prune	None	Wood Dead And Dying	Low	Improbable	High	Unlikely	Significant	Low	Yes	142	Middle Rd	Front	Middle Rd	197302.17	892926.1	42.28681	-71.5327
1	Greg Baldwin (DRG)	2022/08/18		662	2022/08/01	GrBa20220801132307	10:21:42	Oak, White	Quercus alba	Wooded Space	No	12	Fair	Routine Prune	None	Branches Missing Or Decayed	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	2	Leeds Way	Side	Middle Rd	197292.68	892929.1	42.28683	-71.5328
1	Greg Baldwin (DRG)	2022/08/01		663	2022/08/01	GrBa20220801084047	8:41:49	Maple, Red	Acer rubrum	Wooded Space	Yes	12	Fair	Routine Prune	None	Wood Dead And Dying	Low	Improbable	High	Unlikely	Minor	Low	Yes	103	Middle Rd	Front	Middle Rd	197491.77	893891.2	42.2955	-71.5304
1	Greg Baldwin (DRG)	2022/08/01		665	2022/08/01	GrBa20220801104150	10:42:20	Maple, Norway	Acer platanoides	Open Space	No	15	Good	Routine Prune	None	Branches Dead And Dying	Low	Possible	Low	Unlikely	Negligible	Low	Yes	12	Middle Rd	Front	Middle Rd	197411.82	894864.9	42.30426	-71.5314
1	Greg Baldwin (DRG)	2022/08/01		672	2022/08/01	GrBa20220801084237	8:43:26	Oak, Black	Quercus velutina	Wooded Space	No	24	Fair	Routine Prune	None	Branches Dead And Dying	Low	Possible	Low	Unlikely	Significant	Low	Yes	103	Middle Rd	Front	Middle Rd	197491.01	893900.4	42.29558	-71.5304
1	Greg Baldwin (DRG)	2022/08/01		674	2022/08/01	GrBa20220801132332	13:24:43	Oak, Northern Red	Quercus rubra	Wooded Space	No	32	Fair	Prune	None	Branches Dead And Dying	Low	Possible	Medium	Unlikely	Significant	Low	Yes	2	Leeds Way	Side	Middle Rd	197293.98	892939.4	42.28693	-71.5328
1	Greg Baldwin (DRG)	2022/08/01		676	2022/08/01	GrBa20220801084351	8:45:29	Oak, Northern Red	Quercus rubra	Wooded Space	No	19	Fair	Routine Prune	None	Branches Dead And Dying	Low	Possible	Low	Unlikely	Minor	Low	Yes	95	Middle Rd	Front	Middle Rd	197490.42	893906.7	42.29564	-71.5304
1	Greg Baldwin (DRG)	2022/08/01	dbh estimated; poison ivy	678	2022/08/01	GrBa20220801132515	13:26:32	Oak, White	Quercus alba	Wooded Space	No	25	Fair	Routine Prune	None	Branches Weakly Attached Branches And	Low	Possible	Low	Unlikely	Significant	Low	Yes	2	Leeds Way	Side	Middle Rd	197296.46	892956.4	42.28708	-71.5328

1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 22 DBH estimated; poison ivy; utility pole	1142	2022/08/05	AsCa20220805151349	11:47:26	Maple, Red	Acer rubrum	Wooded Space	Yes	12	Fair	Routine Prune	None	Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	59	Newton St	Front	Newton St	197856.36	895889.9	42.31349	-71.526
1	Greg Baldwin (DRG)	2022/08/18	83	1143	2022/08/05	AsCa20220805090902	10:57:07	Maple, Norway	Acer platanoides	Wooded Space	No	6	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	89	Newton St	Front	Newton St	197657.12	896391.4	42.31801	-71.5284
1	Ashley Casello (DRG)	2022/08/11	borderline	1144	2022/08/05	AsCa20220805125730	20:16:21	Plum	Prunus species	Open Space	No	4	Good	Train	None	No Significant Defect Weakly Attached Branches And	Low	Improbable	Low	Unlikely	Minor	Low	Yes	24	Newton St	Front	Newton St	197917.66	895473.1	42.30974	-71.5253
1	Ashley Casello (DRG)	2022/08/05		1145	2022/08/05	AsCa20220805123949	12:40:21	Pear, Callery	Pyrus calleryana	Open Space	No	7	Good	Routine Prune	None	Codominant Stems Dead And Dying	Low	Improbable	Low	Unlikely	Minor	Low	Yes	24	Newton St	Front	Newton St	197898.17	895587.4	42.31077	-71.5255
1	Ashley Casello (DRG)	2022/08/05	utility pole 91; DBH estimated; poison	1146	2022/08/05	AsCa20220805084042	8:42	Spruce, Norway	Picea abies	Open Space	No	19	Good	Routine Prune	None	Branches Dead And Dying	Low	Possible	Low	Unlikely	Negligible	Low	Yes	6	Cross St	Side	Newton St	197659.78	896508.4	42.31906	-71.5284
1	Greg Baldwin (DRG)	2022/08/18	ivy	1147	2022/08/05	AsCa20220805112836	11:10:12	Pine, Eastern White	Pinus strobus	Wooded Space	No	28	Fair	Prune	None	Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	62	Newton St	Front	Newton St	197770.11	896070.8	42.31512	-71.527
1	Greg Baldwin (DRG)	2022/08/18	utility pole 100	1148	2022/08/05	AsCa20220805120748	11:51:56	Apple	Malus species	Open Space	No	5	Good	Train	None	No Significant Defect	Low	Improbable	Low	Unlikely	Minor	Low	Yes	40	Newton St	Front	Newton St	197879.82	895781.2	42.31251	-71.5257
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 85	1149	2022/08/05	AsCa20220805100620	10:58:56	Oak, Black	Quercus velutina	Wooded Space	No	13	Fair	Routine Prune	None	Tree Architecture Dead And Dying	Low	Improbable	Low	Unlikely	Severe	Low	Yes	83	Newton St	Front	Newton St	197683.96	896314.2	42.31731	-71.5281
1	Greg Baldwin (DRG)	2022/08/18	utility pole 85	1150	2022/08/05	AsCa20220805103308	10:59:50	Pine, Pitch	Pinus rigida	Wooded Space	No	19	Fair	Prune	None	Branches Missing Or Decayed	Low	Possible	Low	Unlikely	Minor	Low	Yes	81	Newton St	Front	Newton St	197696.35	896283.7	42.31704	-71.5279
1	Ashley Casello (DRG)	2022/08/05		1151	2022/08/05	AsCa20220805142153	14:23:02	Maple, Sugar	Acer saccharum	Open Space	No	12	Fair	Routine Prune	None	Wood Dead And Dying	Low	Possible	Low	Unlikely	Severe	Low	Yes	5	Newton St	Front	Newton St	198017.4	895183.5	42.30713	-71.524
1	Ashley Casello (DRG)	2022/08/05	DBH estimated; poison ivy; utility pole	1152	2022/08/05	AsCa20220805075449	7:58:25	Oak, Scarlet	Quercus coccinea	Open Space	No	32	Good	Routine Prune	None	Branches Missing Or Decayed	Low	Possible	Low	Unlikely	Negligible	Low	Yes	84	Newton St	Front	Newton St	197659.15	896340.9	42.31755	-71.5284
1	Greg Baldwin (DRG)	2022/08/18	83	1153	2022/08/05	AsCa20220805090959	10:57:07	Maple, Norway	Acer platanoides	Wooded Space	No	9	Fair	Routine Prune	None	Wood	Low	Improbable	Low	Unlikely	Severe	Low	Yes	89	Newton St	Front	Newton St	197657.01	896389.8	42.31799	-71.5284
1	Ashley Casello (DRG)	2022/08/11	borderline	1154	2022/08/05	AsCa20220805125803	20:16:21	Plum	Prunus species	Open Space	No	4	Good	Train	None	No Significant Defect	Low	Improbable	Low	Unlikely	Minor	Low	Yes	24	Newton St	Front	Newton St	197919.13	895467.1	42.30969	-71.5252
1	Greg Baldwin (DRG)	2022/08/18	utility pole 91; DBH estimated; poison	1155	2022/08/05	AsCa20220805084211	13:08:34	Cedar, Northern White	Thuja occidentalis	Open Space	Yes	3	Good	Routine Prune	None	No Significant Defect Dead And Dying	Low	Improbable	Low	Unlikely	Minor	Low	Yes	6	Cross St	Side	Newton St	197659.89	896505.1	42.31903	-71.5284
1	Greg Baldwin (DRG)	2022/08/18	ivy; borderline	1156	2022/08/05	AsCa20220805112938	11:10:12	Oak, Black	Quercus velutina	Wooded Space	No	32	Fair	Routine Prune	None	Branches Weakly Attached Branches And	Low	Possible	Low	Unlikely	Minor	Low	Yes	62	Newton St	Front	Newton St	197774.22	896057.8	42.315	-71.527
1	Ashley Casello (DRG)	2022/08/05		1157	2022/08/05	AsCa20220805124036	12:41:11	Pear, Callery	Pyrus calleryana	Open Space	No	9	Good	Routine Prune	None	Codominant Stems Broken And/Or	Low	Improbable	Low	Unlikely	Minor	Low	Yes	24	Newton St	Front	Newton St	197898.99	895581.7	42.31072	-71.5255
1	Greg Baldwin (DRG)	2022/08/18	utility pole 85	1158	2022/08/05	AsCa20220805100854	10:58:56	Plum	Prunus species	Wooded Space	Yes	8	Poor	Routine Prune	None	Hanging Branches Dead And Dying	Low	Probable	Low	Unlikely	Negligible	Low	Yes	83	Newton St	Front	Newton St	197686.78	896309.4	42.31727	-71.5281
1	Ashley Casello (DRG)	2022/08/05		1159	2022/08/05	AsCa20220805080014	8:01:35	Pine, Pitch	Pinus rigida	Open Space	No	23	Fair	Prune	None	Branches Dead And Dying	Low	Possible	Low	Unlikely	Minor	Low	Yes	84	Newton St	Front	Newton St	197657.1	896345.6	42.31759	-71.5284
1	Ashley Casello (DRG)	2022/08/05	borderline	1160	2022/08/05	AsCa20220805142318	14:24:41	Maple, Sugar	Acer saccharum	Open Space	No	15	Good	Routine Prune	None	Branches Dead And Dying	Low	Possible	Low	Unlikely	Negligible	Low	Yes	5	Newton St	Front	Newton St	198015.22	895189.7	42.30719	-71.5241
1	Ashley Casello (DRG)	2022/08/11		1161	2022/08/05	AsCa20220805120839	20:16:21	Apple	Malus species	Open Space	No	4	Good	Train	None	No Significant Defect Dead And Dying	Low	Improbable	Low	Unlikely	Minor	Low	Yes	24	Newton St	Front	Newton St	197881.99	895772.1	42.31243	-71.5257
1	Greg Baldwin (DRG)	2022/08/18	utility pole 85; DBH estimated; poison ivy	1162	2022/08/05	AsCa20220805103405	10:59:50	Oak, Black	Quercus velutina	Wooded Space	No	10	Fair	Routine Prune	None	Branches Dead And Dying	Low	Possible	Low	Unlikely	Minor	Low	Yes	81	Newton St	Front	Newton St	197698.06	896282.7	42.31703	-71.5279
1	Ashley Casello (DRG)	2022/08/05	borderline	1163	2022/08/05	AsCa20220805135433	13:55:41	Spruce, White	Picea glauca	Open Space	No	11	Fair	Routine Prune	None	Branches Missing Or Decayed	Low	Possible	Low	Unlikely	Negligible	Low	Yes	22	Newton St	Front	Newton St	197946.37	895347.8	42.30861	-71.5249
1	Ashley Casello (DRG)	2022/08/05	basal decay	1164	2022/08/05	AsCa20220805084352	8:45:33	Spruce, Norway	Picea abies	Open Space	No	23	Fair	Routine Prune	Annual Ins	Wood	Low	Possible	Low	Unlikely	Severe	Low	Yes	6	Cross St	Side	Newton St	197659.72	896502.1	42.319	-71.5284

1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 83	1165	2022/08/05	AsCa20220805091029	10:57:07	Maple, Norway	Acer platanoides	Wooded Space	No	10	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Severe	Low	Yes	89	Newton St	Front	Newton St	197657.89	896387.5	42.31797	-71.5284
1	Ashley Casello (DRG)	2022/08/05	borderline	1166	2022/08/05	AsCa20220805143321	14:34:54	Maple, Sugar	Acer saccharum	Open Space	No	29	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	21	Newton St	Front	Newton St	197936.58	895441.6	42.30946	-71.525
1	Greg Baldwin (DRG)	2022/08/18	utility pole 85; DBH estimated; poison ivy	1167	2022/08/05	AsCa20220805101123	10:58:56	Pine, Pitch	Pinus rigida	Wooded Space	No	18	Good	Routine Prune	None	Broken And/Or Hanging Branches	Low	Imminent	Low	Somewhat Likely	Minor	Low	Yes	83	Newton St	Front	Newton St	197687.6	896307.1	42.31725	-71.5281
1	Ashley Casello (DRG)	2022/08/05		1168	2022/08/05	AsCa20220805124128	12:41:48	Pear, Callery	Pyrus calleryana	Open Space	No	7	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	24	Newton St	Front	Newton St	197899.82	895575.8	42.31066	-71.5255
1	Ashley Casello (DRG)	2022/08/05		1169	2022/08/05	AsCa20220805080141	8:02:34	Pine, Pitch	Pinus rigida	Open Space	No	20	Fair	Prune	None	Dead And Dying Branches	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	84	Newton St	Front	Newton St	197655.51	896351.5	42.31765	-71.5284
1	Greg Baldwin (DRG)	2022/08/18	utility pole 86	1170	2022/08/05	AsCa20220805104115	10:59:50	Pine, Pitch	Pinus rigida	Wooded Space	No	11	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	81	Newton St	Front	Newton St	197698.35	896280.3	42.31701	-71.5279
1	Ashley Casello (DRG)	2022/08/05	borderline	1171	2022/08/05	AsCa20220805120943	12:12:28	Apple	Malus species	Open Space	No	6	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	24	Newton St	Front	Newton St	197884.28	895755	42.31228	-71.5257
1	Greg Baldwin (DRG)	2022/08/18	utility pole 20; DBH estimated; poison ivy; borderline; vines >50%;	1172	2022/08/05	AsCa20220805113458	11:46:25	Maple, Red	Acer rubrum	Wooded Space	Yes	17	Poor	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	60	Newton St	Front	Newton St	197805.46	895980.6	42.31431	-71.5266
1	Ashley Casello (DRG)	2022/08/11		1173	2022/08/05	AsCa20220805140201	20:31:23	Maple, Norway	Acer platanoides	Open Space	No	27	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Severe	Low	Yes	6	East Main St	Side	Newton St	198058.23	895100.5	42.30638	-71.5236
1	Ashley Casello (DRG)	2022/08/05	DBH estimated; poison ivy	1174	2022/08/05	AsCa20220805084603	8:46:55	Spruce, Norway	Picea abies	Open Space	No	22	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	6	Cross St	Side	Newton St	197659.66	896499.5	42.31898	-71.5284
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 83	1175	2022/08/05	AsCa20220805091152	10:57:07	Maple, Norway	Acer platanoides	Wooded Space	No	12	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	89	Newton St	Front	Newton St	197657.95	896386.3	42.31796	-71.5284
1	Greg Baldwin (DRG)	2022/08/18	utility pole 85	1176	2022/08/05	AsCa20220805101310	10:58:56	Tree, Unknown	Unknown Tree	Wooded Space	No	5	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Minor	Low	Yes	83	Newton St	Front	Newton St	197687.95	896306	42.31724	-71.528
1	Greg Baldwin (DRG)	2022/08/18	utility pole 86	1177	2022/08/05	AsCa20220805104327	10:59:50	Pine, Pitch	Pinus rigida	Wooded Space	No	11	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	81	Newton St	Front	Newton St	197698.88	896279.2	42.317	-71.5279
1	Ashley Casello (DRG)	2022/08/05		1178	2022/08/05	AsCa20220805124225	12:42:55	Pear, Callery	Pyrus calleryana	Open Space	No	9	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	24	Newton St	Front	Newton St	197900.23	895569.3	42.3106	-71.5255
1	Ashley Casello (DRG)	2022/08/05	borderline	1179	2022/08/05	AsCa20220805143529	14:36:18	Maple, Sugar	Acer saccharum	Open Space	No	16	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Severe	Low	Yes	21	Newton St	Front	Newton St	197935.76	895443.4	42.30947	-71.525
1	Ashley Casello (DRG)	2022/08/05		1180	2022/08/05	AsCa20220805080518	8:06:04	Maple, Red	Acer rubrum	Wooded Space	No	9	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	92	Newton St	Front	Newton St	197644.49	896433.4	42.31838	-71.5286
1	Greg Baldwin (DRG)	2022/08/18	utility pole 20; DBH estimated; poison ivy; borderline	1181	2022/08/05	AsCa20220805113828	11:46:25	Maple, Red	Acer rubrum	Wooded Space	No	13	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Severe	Low	Yes	60	Newton St	Front	Newton St	197808.1	895971.9	42.31423	-71.5266
1	Ashley Casello (DRG)	2022/08/05	borderline	1182	2022/08/05	AsCa20220805121236	12:14:40	Apple	Malus species	Open Space	No	6	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	24	Newton St	Front	Newton St	197884.86	895744.3	42.31218	-71.5257
1	Ashley Casello (DRG)	2022/08/05	DBH estimated; poison ivy; remove vines	1183	2022/08/05	AsCa20220805084703	8:48:20	Spruce, Norway	Picea abies	Open Space	No	32	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	6	Cross St	Side	Newton St	197659.6	896496.3	42.31895	-71.5284
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 48	1184	2022/08/05	AsCa20220805140415	11:52:39	Maple, Norway	Acer platanoides	Open Space	No	30	Poor	Remove	None	Dead And Dying Branches	None	Possible	Low	Unlikely	Significant	Low	Yes	3	Newton St	Front	Newton St	198039.19	895133.5	42.30668	-71.5238
1	Greg Baldwin (DRG)	2022/08/18	utility pole 85; DBH estimated; poison ivy	1185	2022/08/05	AsCa20220805101457	10:58:56	Maple, Sugar	Acer saccharum	Wooded Space	No	9	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	83	Newton St	Front	Newton St	197689.31	896303	42.31721	-71.528
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 83	1186	2022/08/05	AsCa20220805091235	10:57:07	Maple, Norway	Acer platanoides	Wooded Space	No	7	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	89	Newton St	Front	Newton St	197658.24	896384.1	42.31794	-71.5284
1	Greg Baldwin (DRG)	2022/08/18	utility pole 86	1187	2022/08/05	AsCa20220805104425	10:59:50	Pine, Pitch	Pinus rigida	Wooded Space	No	12	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	81	Newton St	Front	Newton St	197698.64	896276.3	42.31697	-71.5279
1	Ashley Casello (DRG)	2022/08/05		1188	2022/08/05	AsCa20220805124309	12:44:04	Pear, Callery	Pyrus calleryana	Open Space	No	8	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	24	Newton St	Front	Newton St	197901.22	895562.4	42.31054	-71.5255
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 29; DBH estimated; poison ivy	1189	2022/08/05	AsCa20220805144139	11:51:04	Elm, American	Ulmus americana	Wooded Space	Yes	10	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	25	Newton St	Front	Newton St	197902.38	895682.7	42.31163	-71.5254
1	Ashley Casello (DRG)	2022/08/05	borderline	1190	2022/08/05	AsCa20220805121503	12:15:24	Apple	Malus species	Open Space	No	7	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	24	Newton St	Front	Newton St	197886.86	895731.6	42.31207	-71.5256
1	Ashley Casello (DRG)	2022/08/11		1191	2022/08/05	AsCa20220805080916	20:32:38	White Pine, Eastern	Pinus strobus	Open Space	No	17	Good	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Significant	Low	Yes	150	Framingham Rd	Side	Newton St	197649.67	896633.9	42.32019	-71.5285
1	Greg Baldwin (DRG)	2022/08/18	borderline; DBH estimated; poison ivy; utility pole 21	1192	2022/08/05	AsCa20220805114321	11:45:20	White Pine, Eastern	Pinus strobus	Wooded Space	No	12	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	60	Newton St	Front	Newton St	197826.31	895928.9	42.31384	-71.5264
1	Greg Baldwin (DRG)	2022/08/18	utility pole 85	1193	2022/08/05	AsCa20220805101620	10:59:50	Pine, Pitch	Pinus rigida	Wooded Space	No	15	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	81	Newton St	Front	Newton St	197690.36	896300	42.31718	-71.528
1	Ashley Casello (DRG)	2022/08/05	borderline	1194	2022/08/05	AsCa20220805124625	12:47:42	Pear, Callery	Pyrus calleryana	Open Space	No	11	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	24	Newton St	Front	Newton St	197903.75	895541.4	42.31035	-71.5254
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 48	1195	2022/08/05	AsCa20220805140854	11:52:39	Maple, Norway	Acer platanoides	Open Space	No	12	Fair	Prune	None	Broken And/Or Hanging Branches	Low	Imminent	Low	Somewhat Likely	Minor	Low	Yes	3	Newton St	Front	Newton St	198033.44	895148.7	42.30682	-71.5239
1	Ashley Casello (DRG)	2022/08/05	DBH estimated; poison ivy; remove vines	1196	2022/08/05	AsCa20220805084830	8:49:47	Spruce, Norway	Picea abies	Open Space	No	15	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	6	Cross St	Side	Newton St	197658.83	896494.2	42.31893	-71.5284
1	Greg Baldwin (DRG)	2022/08/18	utility pole 86	1197	2022/08/05	AsCa20220805104538	10:59:50	Pine, Pitch	Pinus rigida	Wooded Space	No	19	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Significant	Low	Yes	81	Newton St	Front	Newton St	197698.76	896271.4	42.31693	-71.5279
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 83	1198	2022/08/05	AsCa20220805091304	10:57:07	Maple, Norway	Acer platanoides	Wooded Space	No	12	Fair	Routine Prune	None	Cracks	Low	Improbable	Low	Unlikely	Severe	Low	Yes	89	Newton St	Front	Newton St	197659.18	896382.6	42.31793	-71.5284
1	Greg Baldwin (DRG)	2022/08/18	utility pole 29; DBH estimated; poison ivy	1199	2022/08/05	AsCa20220805144533	11:51:04	Oak, Scarlet	Quercus coccinea	Wooded Space	No	24	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	25	Newton St	Front	Newton St	197900.56	895706.5	42.31184	-71.5255
1	Ashley Casello (DRG)	2022/08/05		1200	2022/08/05	AsCa20220805081336	8:14:49	Redcedar, Eastern	Juniperus virginiana	Wooded Space	No	8	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	101	Newton St	Front	Newton St	197663.54	896614	42.32001	-71.5283
1	Ashley Casello (DRG)	2022/08/11	borderline	1201	2022/08/05	AsCa20220805121555	20:16:21	Apple	Malus species	Open Space	No	5	Good	Train	None	No Significant Defect	Low	Improbable	Low	Unlikely	Minor	Low	Yes	24	Newton St	Front	Newton St	197888.09	895715.7	42.31192	-71.5256
1	Greg Baldwin (DRG)	2022/08/18	borderline; DBH estimated; poison ivy; utility pole 21	1202	2022/08/05	AsCa20220805114504	11:45:20	Oak, Scarlet	Quercus coccinea	Wooded Space	No	25	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	60	Newton St	Front	Newton St	197830.84	895918.1	42.31375	-71.5263
1	Greg Baldwin (DRG)	2022/08/18	utility pole 85	1203	2022/08/05	AsCa20220805101841	10:59:50	Elm, American	Ulmus americana	Wooded Space	No	10	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	81	Newton St	Front	Newton St	197690.83	896299	42.31717	-71.528
1	Ashley Casello (DRG)	2022/08/05	borderline	1204	2022/08/05	AsCa20220805124755	12:48:14	Pear, Callery	Pyrus calleryana	Open Space	No	9	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	24	Newton St	Front	Newton St	197904.74	895533.3	42.31028	-71.5254
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 48	1205	2022/08/05	AsCa20220805140943	11:52:39	Maple, Norway	Acer platanoides	Open Space	No	9	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	3	Newton St	Front	Newton St	198034.44	895148.2	42.30681	-71.5238
1	Greg Baldwin (DRG)	2022/08/18	utility pole 28; DBH estimated; poison ivy	1206	2022/08/05	AsCa20220805144715	11:51:04	Oak, Scarlet	Quercus coccinea	Wooded Space	No	18	Good	Routine Prune	None	Broken And/Or Hanging Branches	Low	Imminent	Low	Somewhat Likely	Negligible	Low	Yes	25	Newton St	Front	Newton St	197899.63	895712.6	42.3119	-71.5255
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 83	1207	2022/08/05	AsCa20220805091353	10:57:07	Maple, Norway	Acer platanoides	Wooded Space	No	12	Good	Routine Prune	None	Broken And/Or Hanging Branches	Low	Improbable	Low	Unlikely	Minor	Low	Yes	89	Newton St	Front	Newton St	197660.23	896376.3	42.31787	-71.5284
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 80	1208	2022/08/05	AsCa20220805085130	10:57:07	Oak, Black	Quercus velutina	Open Space	No	24	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	89	Newton St	Front	Newton St	197658.34	896427	42.31833	-71.5284

1	Ashley Casello (DRG)	2022/08/05		1209	2022/08/05	AsCa20220805081512	8:16:12	Maple, Sugar	Acer saccharum	Open Space	No	23	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	101	Newton St	Front	Newton St	197662.12	896595	42.31984	-71.5284
1	Greg Baldwin (DRG)	2022/08/18	utility pole 86; DBH estimated; poison ivy	1210	2022/08/05	AsCa20220805104716	11:00:24	Maple, Red	Acer rubrum	Wooded Space	Yes	20	Poor	Remove	None	Dead And Dying Branches	None	Possible	Low	Unlikely	Severe	Low	Yes	79	Newton St	Front	Newton St	197705.57	896261.1	42.31683	-71.5278
1	Ashley Casello (DRG)	2022/08/11	borderline	1211	2022/08/05	AsCa20220805122825	20:16:21	Apple	Malus species	Open Space	No	4	Fair	Train	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	24	Newton St	Front	Newton St	197890.07	895695.6	42.31174	-71.5256
1	Greg Baldwin (DRG)	2022/08/18	off ROW; utility pole 22	1212	2022/08/05	AsCa20220805114814	11:45:20	Tree, Unknown	Unknown Tree	Open Space	Yes	30	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Severe	Low	Yes	60	Newton St	Front	Newton St	197836.06	895894.6	42.31353	-71.5262
1	Greg Baldwin (DRG)	2022/08/18	utility pole 85	1213	2022/08/05	AsCa20220805101929	10:59:50	Maple, Red	Acer rubrum	Wooded Space	Yes	9	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	81	Newton St	Front	Newton St	197691.71	896296.1	42.31715	-71.528
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 83	1214	2022/08/05	AsCa20220805091544	10:57:07	Maple, Red	Acer rubrum	Wooded Space	Yes	10	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	89	Newton St	Front	Newton St	197661.64	896370.5	42.31782	-71.5284
1	Ashley Casello (DRG)	2022/08/05	borderline	1216	2022/08/05	AsCa20220805124901	12:49:19	Pear, Callery	Pyrus calleryana	Open Space	No	7	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	24	Newton St	Front	Newton St	197906.57	895527	42.31022	-71.5254
1	Greg Baldwin (DRG)	2022/08/18	utility pole 28; DBH estimated; poison ivy; borderline	1217	2022/08/05	AsCa20220805144926	11:51:04	Sassafras	Sassafras albidum	Wooded Space	No	8	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	25	Newton St	Front	Newton St	197900.27	895715.6	42.31192	-71.5255
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; remove vines; utility pole 81	1218	2022/08/05	AsCa20220805085613	10:57:07	Oak, Northern Red	Quercus rubra	Wooded Space	No	7	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	89	Newton St	Front	Newton St	197657.01	896417.2	42.31824	-71.5284
1	Ashley Casello (DRG)	2022/08/11		1219	2022/08/05	AsCa20220805081700	20:30:05	Redcedar, Eastern	Juniperus virginiana	Open Space	No	6	Fair	Routine Prune	None	Root Problems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	5	Cross St	Side	Newton St	197662.64	896582.8	42.31973	-71.5284
1	Greg Baldwin (DRG)	2022/08/18	utility pole 86	1220	2022/08/05	AsCa20220805104949	11:00:24	Maple, Sugar	Acer saccharum	Wooded Space	No	8	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Significant	Low	Yes	79	Newton St	Front	Newton St	197706.92	896256.7	42.31679	-71.5278
1	Greg Baldwin (DRG)	2022/08/18	off ROW; utility pole 23	1221	2022/08/05	AsCa20220805115130	11:45:20	Tree, Unknown	Unknown Tree	Open Space	No	34	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	60	Newton St	Front	Newton St	197847.87	895864	42.31326	-71.5261
1	Ashley Casello (DRG)	2022/08/05	borderline	1222	2022/08/05	AsCa20220805122932	12:30:26	Pear, Callery	Pyrus calleryana	Open Space	No	9	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	24	Newton St	Front	Newton St	197889.48	895685.5	42.31165	-71.5256
1	Greg Baldwin (DRG)	2022/08/18	utility pole 85	1223	2022/08/05	AsCa20220805102108	10:59:50	Pine, Pitch	Pinus rigida	Wooded Space	No	17	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	81	Newton St	Front	Newton St	197692.65	896294.5	42.31713	-71.528
1	Ashley Casello (DRG)	2022/08/11	borderline	1224	2022/08/05	AsCa20220805124936	20:16:21	Pear, Callery	Pyrus calleryana	Open Space	No	4	Good	Train	None	No Significant Defect	Low	Possible	Low	Unlikely	Negligible	Low	Yes	24	Newton St	Front	Newton St	197907.97	895520.5	42.31017	-71.5254
1	Ashley Casello (DRG)	2022/08/11	multiple saplings in area	1225	2022/08/05	AsCa20220805141432	20:16:21	Maple, Sugar	Acer saccharum	Open Space	No	5	Good	Train	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Negligible	Low	Yes	5	Newton St	Front	Newton St	198026.5	895160.9	42.30693	-71.5239
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 27	1226	2022/08/05	AsCa20220805145617	11:50:18	Oak, Black	Quercus velutina	Wooded Space	No	31	Fair	Routine Prune	Annual Ins	Cracks	Low	Improbable	Low	Unlikely	Severe	Low	Yes	39	Newton St	Front	Newton St	197891.65	895777.9	42.31248	-71.5256
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 81	1227	2022/08/05	AsCa20220805085820	10:57:07	Maple, Norway	Acer platanoides	Wooded Space	Yes	12	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	89	Newton St	Front	Newton St	197656.54	896407.1	42.31815	-71.5284
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 83; remove vines	1228	2022/08/05	AsCa20220805091644	10:57:07	Maple, Norway	Acer platanoides	Wooded Space	No	11	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	89	Newton St	Front	Newton St	197662.7	896368.4	42.3178	-71.5284
1	Ashley Casello (DRG)	2022/08/11		1229	2022/08/05	AsCa20220805081804	20:30:24	Spruce, Norway	Picea abies	Open Space	No	30	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	5	Cross St	Side	Newton St	197661.17	896572.4	42.31964	-71.5284
1	Greg Baldwin (DRG)	2022/08/18	utility pole 86	1230	2022/08/05	AsCa20220805105151	11:00:24	Pine, Pitch	Pinus rigida	Wooded Space	No	18	Good	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	79	Newton St	Front	Newton St	197707.86	896250.5	42.31674	-71.5278
1	Greg Baldwin (DRG)	2022/08/18	utility pole 23	1231	2022/08/05	AsCa20220805115539	11:45:20	Apple	Malus species	Open Space	No	3	Good	Train	None	Tree Architecture	Low	Improbable	Low	Unlikely	Minor	Low	Yes	60	Newton St	Front	Newton St	197852.74	895859.1	42.31321	-71.526
1	Ashley Casello (DRG)	2022/08/05	borderline	1232	2022/08/05	AsCa20220805123049	12:31:15	Pear, Callery	Pyrus calleryana	Open Space	No	7	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	24	Newton St	Front	Newton St	197891.51	895674.2	42.31155	-71.5256
1	Greg Baldwin (DRG)	2022/08/18	utility pole 85	1233	2022/08/05	AsCa20220805102238	10:59:50	Catalpa, Northern	Catalpa speciosa	Wooded Space	No	13	Poor	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Severe	Low	Yes	81	Newton St	Front	Newton St	197693.48	896291.3	42.31711	-71.528
1	Ashley Casello (DRG)	2022/08/05	borderline	1234	2022/08/05	AsCa20220805125222	12:53:11	Pear, Callery	Pyrus calleryana	Open Space	No	7	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	24	Newton St	Front	Newton St	197908.68	895513.2	42.3101	-71.5254
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 81	1235	2022/08/05	AsCa20220805090007	10:57:07	Maple, Norway	Acer platanoides	Wooded Space	No	7	Dead	Remove	None	No Significant Defect	None	Possible	Very Low	Unlikely	Minor	Low	Yes	89	Newton St	Front	Newton St	197657.19	896404.5	42.31812	-71.5284
1	Ashley Casello (DRG)	2022/08/11		1236	2022/08/05	AsCa20220805141521	20:16:21	Maple, Sugar	Acer saccharum	Open Space	No	4	Fair	Train	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	5	Newton St	Front	Newton St	198025.8	895162.5	42.30694	-71.5239
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 83	1237	2022/08/05	AsCa20220805091800	10:57:07	Maple, Red	Acer rubrum	Wooded Space	No	5	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Minor	Low	Yes	89	Newton St	Front	Newton St	197662.82	896366.3	42.31778	-71.5284
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 26	1238	2022/08/05	AsCa20220805150129	11:49:57	Oak, Northern Red	Quercus rubra	Wooded Space	Yes	21	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	49	Newton St	Front	Newton St	197887.01	895799.6	42.31268	-71.5256
1	Greg Baldwin (DRG)	2022/08/18	utility pole 86	1240	2022/08/05	AsCa20220805105250	11:00:24	Pine, Pitch	Pinus rigida	Wooded Space	No	15	Good	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	79	Newton St	Front	Newton St	197708.74	896246.8	42.3167	-71.5278
1	Greg Baldwin (DRG)	2022/08/18	utility pole 24	1241	2022/08/05	AsCa20220805115742	11:45:20	Apple	Malus species	Open Space	No	5	Good	Train	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	60	Newton St	Front	Newton St	197855.62	895851.7	42.31315	-71.526
1	Ashley Casello (DRG)	2022/08/05	borderline	1242	2022/08/05	AsCa20220805123131	12:31:56	Pear, Callery	Pyrus calleryana	Open Space	No	10	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	24	Newton St	Front	Newton St	197892.02	895665.8	42.31147	-71.5256
1	Greg Baldwin (DRG)	2022/08/18	utility pole 85	1243	2022/08/05	AsCa20220805102556	10:59:50	Maple, Red	Acer rubrum	Wooded Space	Yes	8	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	81	Newton St	Front	Newton St	197694.12	896292.2	42.31711	-71.528
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 81	1244	2022/08/05	AsCa20220805090249	10:57:07	Maple, Norway	Acer platanoides	Wooded Space	No	15	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	89	Newton St	Front	Newton St	197655.78	896403.7	42.31812	-71.5284
1	Ashley Casello (DRG)	2022/08/11		1245	2022/08/05	AsCa20220805141542	20:16:21	Maple, Sugar	Acer saccharum	Open Space	No	5	Good	Train	None	No Significant Defect	Low	Improbable	Low	Unlikely	Significant	Low	Yes	5	Newton St	Front	Newton St	198025.09	895163.6	42.30695	-71.524
1	Ashley Casello (DRG)	2022/08/05	borderline	1246	2022/08/05	AsCa20220805125325	12:53:41	Pear, Callery	Pyrus calleryana	Open Space	No	6	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	24	Newton St	Front	Newton St	197909.91	895507	42.31004	-71.5254
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 99	1247	2022/08/05	AsCa20220805150445	11:49:57	Oak, White	Quercus alba	Wooded Space	No	21	Good	Routine Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Minor	Low	Yes	49	Newton St	Front	Newton St	197882.26	895815.2	42.31282	-71.5257
1	Ashley Casello (DRG)	2022/08/26	DBH estimated; poison ivy; utility pole 83	1248	2022/08/05	AsCa20220805091940	8:26:09	Pine, Pitch	Pinus rigida	Wooded Space	No	22	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	89	Newton St	Front	Newton St	197663.35	896363.8	42.31776	-71.5283
1	Ashley Casello (DRG)	2022/08/11		1249	2022/08/05	AsCa20220805082235	20:30:35	Maple, Norway	Acer platanoides	Open Space	No	30	Good	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	6	Cross St	Side	Newton St	197659.51	896530.4	42.31926	-71.5284
1	Greg Baldwin (DRG)	2022/08/18	utility pole 86	1250	2022/08/05	AsCa20220805105402	11:00:24	Pine, Pitch	Pinus rigida	Wooded Space	No	10	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	79	Newton St	Front	Newton St	197711.39	896244.8	42.31669	-71.5278
1	Ashley Casello (DRG)	2022/08/11		1251	2022/08/05	AsCa20220805115842	20:16:21	Apple	Malus species	Open Space	No	4	Good	Train	None	Tree Architecture	Low	Improbable	Low	Unlikely	Minor	Low	Yes	24	Newton St	Front	Newton St	197860.44	895836.3	42.31301	-71.526
1	Ashley Casello (DRG)	2022/08/05		1252	2022/08/05	AsCa20220805123405	12:36:12	Pear, Callery	Pyrus calleryana	Open Space	No	9	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	24	Newton St	Front	Newton St	197894.13	895642	42.31126	-71.5255
1	Greg Baldwin (DRG)	2022/08/18	utility pole 85	1253	2022/08/05	AsCa20220805102707	10:59:50	Oak, Black	Quercus velutina	Wooded Space	No	9	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	81	Newton St	Front	Newton St	197694.83	896290.9	42.3171	-71.528
1	Ashley Casello (DRG)	2022/08/11	borderline	1254	2022/08/05	AsCa20220805125400	20:16:21	Pear, Callery	Pyrus calleryana	Open Space	No	4	Good	Train	None	No Significant Defect	Low	Improbable	Low	Unlikely	Minor	Low	Yes	24	Newton St	Front	Newton St	197911.91	895499.6	42.30998	-71.5253
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 83	1255	2022/08/05	AsCa20220805092353	10:57:07	Maple, Norway	Acer platanoides	Wooded Space	Yes	6	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	89	Newton St	Front	Newton St	197665.28	896361.7	42.31774	-71.5283

1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 99	1256	2022/08/05	AsCa20220805150554	11:49:57	Oak, White	Quercus alba	Wooded Space	No	8	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Significant	Low	Yes	49	Newton St	Front	Newton St	197881.55	895819	42.31285	-71.5257
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 81	1257	2022/08/05	AsCa20220805090358	10:57:07	Maple, Norway	Acer platanoides	Wooded Space	No	9	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	89	Newton St	Front	Newton St	197655.95	896402.6	42.31811	-71.5284
1	Ashley Casello (DRG)	2022/08/05		1258	2022/08/05	AsCa20220805141637	14:18:44	Maple, Sugar	Acer saccharum	Open Space	Yes	8	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	5	Newton St	Front	Newton St	198024.33	895164.5	42.30696	-71.524
1	Greg Baldwin (DRG)	2022/08/18	utility pole 87	1259	2022/08/05	AsCa20220805105505	11:00:49	Pine, Pitch	Pinus rigida	Wooded Space	No	12	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	77	Newton St	Front	Newton St	197712.97	896240.5	42.31665	-71.5277
1	Greg Baldwin (DRG)	2022/08/18	borderline; start hedgerow; 5 trees in ROW	1260	2022/08/05	AsCa20220805082458	13:08:34	Cedar, Northern White	Thuja occidentalis	Open Space	No	3	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Minor	Low	Yes	6	Cross St	Side	Newton St	197660.92	896525	42.31921	-71.5284
1	Ashley Casello (DRG)	2022/08/11		1261	2022/08/05	AsCa20220805115929	20:16:21	Apple	Malus species	Open Space	No	5	Good	Train	None	No Significant Defect	Low	Improbable	Low	Unlikely	Minor	Low	Yes	24	Newton St	Front	Newton St	197864.08	895826.3	42.31292	-71.5259
1	Greg Baldwin (DRG)	2022/08/18	utility pole 85	1262	2022/08/05	AsCa20220805102825	10:59:50	Maple, Sugar	Acer saccharum	Wooded Space	Yes	11	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	81	Newton St	Front	Newton St	197694.89	896289.8	42.31709	-71.528
1	Ashley Casello (DRG)	2022/08/05	borderline	1263	2022/08/05	AsCa20220805125444	12:55:23	Plum	Prunus species	Open Space	No	7	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Minor	Low	Yes	24	Newton St	Front	Newton St	197912.55	895494.1	42.30993	-71.5253
1	Ashley Casello (DRG)	2022/08/05		1264	2022/08/05	AsCa20220805123628	12:36:55	Pear, Callery	Pyrus calleryana	Open Space	No	8	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	24	Newton St	Front	Newton St	197894.13	895636.4	42.31121	-71.5255
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 83	1265	2022/08/05	AsCa20220805092443	10:57:07	Elm, American	Ulmus americana	Wooded Space	No	26	Good	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	89	Newton St	Front	Newton St	197664.17	896359.6	42.31772	-71.5283
1	Ashley Casello (DRG)	2022/08/05		1266	2022/08/05	AsCa20220805141724	14:18:39	Maple, Sugar	Acer saccharum	Open Space	Yes	8	Good	Routine Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Negligible	Low	Yes	5	Newton St	Front	Newton St	198023.68	895166.6	42.30698	-71.524
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 81	1267	2022/08/05	AsCa20220805090457	10:57:07	Maple, Norway	Acer platanoides	Wooded Space	No	12	Fair	Routine Prune	None	Cracks	Low	Improbable	Low	Unlikely	Severe	Low	Yes	89	Newton St	Front	Newton St	197655.78	896401	42.31809	-71.5284
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 25	1268	2022/08/05	AsCa20220805150655	11:49:57	Oak, White	Quercus alba	Wooded Space	No	15	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	49	Newton St	Front	Newton St	197880.38	895822.5	42.31288	-71.5257
1	Greg Baldwin (DRG)	2022/08/18	borderline; end hedgerow; 5 trees in ROW; DBH estimated; poison ivy	1269	2022/08/05	AsCa20220805082714	13:08:34	Cedar, Northern White	Thuja occidentalis	Open Space	No	3	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Minor	Low	Yes	6	Cross St	Side	Newton St	197660.51	896517.7	42.31914	-71.5284
1	Greg Baldwin (DRG)	2022/08/18	utility pole 87	1270	2022/08/05	AsCa20220805105645	11:00:49	Pine, Pitch	Pinus rigida	Wooded Space	No	16	Poor	Remove	None	Dead And Dying Branches	None	Possible	Low	Unlikely	Severe	Low	Yes	77	Newton St	Front	Newton St	197714.21	896236.2	42.31661	-71.5277
1	Ashley Casello (DRG)	2022/08/11		1271	2022/08/05	AsCa20220805120318	20:16:21	Apple	Malus species	Open Space	No	4	Good	Train	None	Dead And Dying Branches	Low	Probable	Very Low	Unlikely	Negligible	Low	Yes	24	Newton St	Front	Newton St	197869.07	895811.3	42.31278	-71.5258
1	Greg Baldwin (DRG)	2022/08/18	utility pole 85	1272	2022/08/05	AsCa20220805102944	10:59:50	Pine, Pitch	Pinus rigida	Wooded Space	No	11	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	81	Newton St	Front	Newton St	197695.24	896287.9	42.31707	-71.528
1	Greg Baldwin (DRG)	2022/08/18	utility pole 84	1273	2022/08/05	AsCa20220805092648	10:57:47	Tree, Unknown	Unknown Tree	Open Space	No	14	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Severe	Low	Yes	85	Newton St	Front	Newton St	197673.74	896340.2	42.31754	-71.5282
1	Ashley Casello (DRG)	2022/08/05	borderline	1274	2022/08/05	AsCa20220805125552	12:56:28	Plum	Prunus species	Open Space	No	6	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Minor	Low	Yes	24	Newton St	Front	Newton St	197914.61	895486.4	42.30986	-71.5253
1	Ashley Casello (DRG)	2022/08/05		1275	2022/08/05	AsCa20220805123708	12:37:31	Pear, Callery	Pyrus calleryana	Open Space	No	9	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	24	Newton St	Front	Newton St	197894.89	895629.9	42.31115	-71.5255
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 25	1276	2022/08/05	AsCa20220805150831	11:49:57	Oak, Northern Red	Quercus rubra	Wooded Space	Yes	18	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	49	Newton St	Front	Newton St	197878.38	895826.9	42.31292	-71.5257
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 81	1277	2022/08/05	AsCa20220805090621	10:57:07	Maple, Norway	Acer platanoides	Wooded Space	No	10	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Severe	Low	Yes	89	Newton St	Front	Newton St	197655.72	896398.6	42.31807	-71.5284
1	Ashley Casello (DRG)	2022/08/05	DBH estimated; poison ivy	1278	2022/08/05	AsCa20220805112043	11:22:20	Maple, Red	Acer rubrum	Wooded Space	No	40	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	70	Newton St	Front	Newton St	197748.43	896122.8	42.31559	-71.5273
1	Ashley Casello (DRG)	2022/08/11		1279	2022/08/05	AsCa20220805141808	20:16:21	Maple, Sugar	Acer saccharum	Open Space	Yes	5	Good	Train	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	5	Newton St	Front	Newton St	198023.1	895167.5	42.30699	-71.524
1	Ashley Casello (DRG)	2022/08/11	borderline; DBH estimated; poison ivy	1280	2022/08/05	AsCa20220805082922	20:31:09	Pine, Scotch	Pinus sylvestris	Open Space	No	8	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Significant	Low	Yes	6	Cross St	Side	Newton St	197661.27	896517.3	42.31914	-71.5284
1	Greg Baldwin (DRG)	2022/08/18	utility pole 84; remove vines	1281	2022/08/05	AsCa20220805094644	10:58:56	Pine, Pitch	Pinus rigida	Open Space	No	23	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	83	Newton St	Front	Newton St	197678.67	896326.2	42.31742	-71.5282
1	Greg Baldwin (DRG)	2022/08/18	utility pole 85; DBH estimated; poison ivy	1282	2022/08/05	AsCa20220805103036	10:59:50	Oak, Black	Quercus velutina	Wooded Space	No	10	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	81	Newton St	Front	Newton St	197696.71	896285	42.31705	-71.5279
1	Ashley Casello (DRG)	2022/08/11		1283	2022/08/05	AsCa20220805120525	20:16:21	Apple	Malus species	Open Space	No	5	Good	Train	None	Dead And Dying Branches	Low	Probable	Very Low	Unlikely	Negligible	Low	Yes	24	Newton St	Front	Newton St	197872.83	895801.1	42.31269	-71.5258
1	Ashley Casello (DRG)	2022/08/05		1284	2022/08/05	AsCa20220805123742	12:38	Pear, Callery	Pyrus calleryana	Open Space	No	8	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	24	Newton St	Front	Newton St	197895.23	895624.9	42.31111	-71.5255
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 83	1285	2022/08/05	AsCa20220805090714	10:57:07	Maple, Norway	Acer platanoides	Wooded Space	No	11	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	89	Newton St	Front	Newton St	197656.24	896393.6	42.31803	-71.5284
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 25; DBH estimated; slope	1286	2022/08/05	AsCa20220805151033	11:49:57	Oak, Northern Red	Quercus rubra	Wooded Space	No	16	Good	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	49	Newton St	Front	Newton St	197876.09	895832.7	42.31298	-71.5258
1	Ashley Casello (DRG)	2022/08/11	borderline	1287	2022/08/05	AsCa20220805125657	20:16:21	Plum	Prunus species	Open Space	No	5	Good	Train	None	No Significant Defect	Low	Improbable	Low	Unlikely	Minor	Low	Yes	24	Newton St	Front	Newton St	197915.96	895479.6	42.3098	-71.5253
1	Greg Baldwin (DRG)	2022/08/18	off ROW; utility pole 91; DBH estimated; poison ivy	1288	2022/08/05	AsCa20220805112530	11:10:12	Ash, White	Fraxinus americana	Wooded Space	No	20	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Severe	Low	Yes	62	Newton St	Front	Newton St	197764.23	896079.1	42.31519	-71.5271
1	Ashley Casello (DRG)	2022/08/11	multiple saplings in area	1289	2022/08/05	AsCa20220805141959	20:16:21	Maple, Sugar	Acer saccharum	Open Space	No	4	Fair	Train	None	Cracks	Low	Improbable	Low	Unlikely	Minor	Low	Yes	5	Newton St	Front	Newton St	198018.16	895179.9	42.3071	-71.524
1	Ashley Casello (DRG)	2022/08/05		1290	2022/08/05	AsCa20220805083653	8:39:34	Spruce, Norway	Picea abies	Open Space	No	19	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	6	Cross St	Side	Newton St	197660.13	896513.5	42.31911	-71.5284
1	Greg Baldwin (DRG)	2022/08/18	utility pole 100	1291	2022/08/05	AsCa20220805120615	11:51:56	Apple	Malus species	Open Space	No	4	Good	Train	None	Tree Architecture	Low	Improbable	Low	Unlikely	Minor	Low	Yes	40	Newton St	Front	Newton St	197875.47	895791.9	42.31261	-71.5258
1	Ashley Casello (DRG)	2022/08/05		1292	2022/08/05	AsCa20220805123844	12:42:06	Pear, Callery	Pyrus calleryana	Open Space	No	6	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Significant	Low	Yes	24	Newton St	Front	Newton St	197897.94	895591.3	42.3108	-71.5255
1	Greg Baldwin (DRG)	2022/08/18	utility pole 16; DBH estimated; poison ivy; borderline	1294	2022/08/08	AsCa20220808075727	11:03:26	Maple, Red	Acer rubrum	Wooded Space	No	8	Poor	Remove	None	Dead And Dying Branches	None	Possible	Low	Unlikely	Severe	Low	Yes	67	Newton St	Front	Newton St	197762.97	896121.5	42.31558	-71.5271
1	Greg Baldwin (DRG)	2022/08/18	utility pole 87; DBH estimated; poison ivy; in failure	1299	2022/08/08	AsCa20220808082130	11:00:49	Tree, Unknown	Unknown Tree	Wooded Space	No	7	Dead	Remove	None	No Significant Defect	None	Probable	Low	Unlikely	Significant	Low	Yes	77	Newton St	Front	Newton St	197721.27	896222.9	42.31649	-71.5276
1	Greg Baldwin (DRG)	2022/08/18	utility pole 16; DBH estimated; poison ivy; borderline	1301	2022/08/08	AsCa20220808075952	11:03:26	Maple, Red	Acer rubrum	Wooded Space	No	10	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Severe	Low	Yes	67	Newton St	Front	Newton St	197762.09	896124.7	42.3156	-71.5271
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 22; DBH estimated; slope	1302	2022/08/08	AsCa20220808072027	11:49:57	Oak, Northern Red	Quercus rubra	Wooded Space	Yes	16	Fair	Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Minor	Low	Yes	49	Newton St	Front	Newton St	197857.71	895885.6	42.31345	-71.526
1	Greg Baldwin (DRG)	2022/08/18	utility pole 87; DBH estimated; poison ivy	1306	2022/08/08	AsCa20220808082443	11:00:49	Pine, Pitch	Pinus rigida	Wooded Space	No	18	Good	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	77	Newton St	Front	Newton St	197719.21	896225.6	42.31651	-71.5277
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 22	1308	2022/08/08	AsCa20220808072338	11:47:26	Oak, Northern Red	Quercus rubra	Wooded Space	No	11	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	59	Newton St	Front	Newton St	197853.54	895897.2	42.31356	-71.526
1	Greg Baldwin (DRG)	2022/08/18	utility pole 16; DBH estimated; poison ivy	1310	2022/08/08	AsCa20220808080130	11:03:26	Maple, Red	Acer rubrum	Wooded Space	No	10	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Severe	Low	Yes	67	Newton St	Front	Newton St	197761.21	896126.8	42.31562	-71.5272
1	Greg Baldwin (DRG)	2022/08/18	utility pole 87; DBH estimated; poison ivy	1314	2022/08/08	AsCa20220808082813	11:00:49	Pine, Pitch	Pinus rigida	Wooded Space	No	18	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	77	Newton St	Front	Newton St	197717.27	896229.9	42.31655	-71.5277
1	Greg Baldwin (DRG)	2022/08/18	utility pole 16; DBH estimated; poison ivy	1317	2022/08/08	AsCa20220808080221	11:03:26	Maple, Red	Acer rubrum	Wooded Space	No	17	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	67	Newton St	Front	Newton St	197759.68	896129.6	42.31565	-71.5272

1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 22	1318	2022/08/08	AsCa20220808072526	11:47:26	Oak, Northern Red	Quercus rubra	Wooded Space	No	31	Fair	Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Significant	Low	Yes	59	Newton St	Front	Newton St	197848.96	895908.4	42.31366	-71.5261
1	Greg Baldwin (DRG)	2022/08/18	utility pole 87	1324	2022/08/08	AsCa20220808082917	11:00:49	Maple, Sugar	Acer saccharum	Wooded Space	Yes	10	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	77	Newton St	Front	Newton St	197716.57	896231.3	42.31656	-71.5277
1	Greg Baldwin (DRG)	2022/08/18	utility pole 16; DBH estimated; poison ivy	1326	2022/08/08	AsCa20220808080305	11:03:26	Maple, Red	Acer rubrum	Wooded Space	No	12	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	67	Newton St	Front	Newton St	197758.68	896132.9	42.31568	-71.5272
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 21	1327	2022/08/08	AsCa20220808072748	11:47:26	Hickory, Pignut	Carya glabra	Wooded Space	No	9	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	59	Newton St	Front	Newton St	197840.15	895931.2	42.31386	-71.5262
1	Greg Baldwin (DRG)	2022/08/18	utility pole 16; DBH estimated; poison ivy	1334	2022/08/08	AsCa20220808080420	11:01:54	Maple, Red	Acer rubrum	Wooded Space	No	13	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Severe	Low	Yes	71	Newton St	Front	Newton St	197755.69	896139.7	42.31574	-71.5272
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 21	1336	2022/08/08	AsCa20220808073107	11:47:26	Oak, Northern Red	Quercus rubra	Wooded Space	No	13	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	59	Newton St	Front	Newton St	197832.63	895952	42.31405	-71.5263
1	Greg Baldwin (DRG)	2022/08/18	utility pole 87; borderline	1337	2022/08/08	AsCa20220808083159	11:00:49	Pine, Pitch	Pinus rigida	Wooded Space	No	11	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	77	Newton St	Front	Newton St	197716.1	896232.4	42.31657	-71.5277
1	Greg Baldwin (DRG)	2022/08/18	utility pole 15; DBH estimated; poison ivy	1344	2022/08/08	AsCa20220808080515	11:01:54	Oak, Northern Red	Quercus rubra	Wooded Space	No	12	Fair	Routine Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Minor	Low	Yes	71	Newton St	Front	Newton St	197753.1	896146.8	42.3158	-71.5273
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 21	1345	2022/08/08	AsCa20220808073254	11:47:26	Oak, White	Quercus alba	Wooded Space	No	8	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	59	Newton St	Front	Newton St	197822.53	895974.6	42.31425	-71.5264
1	Greg Baldwin (DRG)	2022/08/18	utility pole 87	1347	2022/08/08	AsCa20220808083304	11:00:49	Pine, Pitch	Pinus rigida	Wooded Space	No	13	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	77	Newton St	Front	Newton St	197714.98	896232.4	42.31657	-71.5277
1	Greg Baldwin (DRG)	2022/08/18	utility pole 15; DBH estimated; poison ivy	1351	2022/08/08	AsCa20220808080634	11:01:54	Oak, Northern Red	Quercus rubra	Wooded Space	No	30	Fair	Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Minor	Low	Yes	71	Newton St	Front	Newton St	197750.52	896151.2	42.31584	-71.5273
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 20	1356	2022/08/08	AsCa20220808073449	11:47:26	Oak, Northern Red	Quercus rubra	Wooded Space	No	9	Fair	Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Minor	Low	Yes	59	Newton St	Front	Newton St	197819.18	895984	42.31434	-71.5265
1	Greg Baldwin (DRG)	2022/08/18	utility pole 87	1359	2022/08/08	AsCa20220808083333	11:00:49	Oak, Northern Red	Quercus rubra	Wooded Space	No	9	Good	Routine Prune	None	Broken And/Or Hanging Branches	Low	Probable	Low	Unlikely	Minor	Low	Yes	77	Newton St	Front	Newton St	197713.75	896235	42.3166	-71.5277
1	Greg Baldwin (DRG)	2022/08/18	utility pole 15; DBH estimated; poison ivy	1362	2022/08/08	AsCa20220808080759	11:01:25	Maple, Red	Acer rubrum	Wooded Space	No	13	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	73	Newton St	Front	Newton St	197748.23	896157.8	42.3159	-71.5273
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 20	1366	2022/08/08	AsCa20220808073822	11:47:26	Hickory, Shagbark	Carya ovata	Wooded Space	No	14	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	59	Newton St	Front	Newton St	197817.48	895988.8	42.31438	-71.5265
1	Greg Baldwin (DRG)	2022/08/18	utility pole 15; DBH estimated; poison ivy; borderline	1372	2022/08/08	AsCa20220808080902	11:01:25	Maple, Red	Acer rubrum	Wooded Space	No	9	Good	Routine Prune	None	Dead And Dying Branches	Low	Probable	Very Low	Unlikely	Minor	Low	Yes	73	Newton St	Front	Newton St	197749.46	896157.7	42.3159	-71.5273
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 19	1374	2022/08/08	AsCa20220808074259	11:47:26	Maple, Red	Acer rubrum	Wooded Space	No	14	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Severe	Low	Yes	59	Newton St	Front	Newton St	197809.25	896008.2	42.31456	-71.5266
1	Greg Baldwin (DRG)	2022/08/18	utility pole 15; DBH estimated; poison ivy	1382	2022/08/08	AsCa20220808081026	11:01:25	Hickory, Pignut	Carya glabra	Wooded Space	No	22	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	73	Newton St	Front	Newton St	197742.59	896171.2	42.31602	-71.5274
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 19	1385	2022/08/08	AsCa20220808074423	11:47:26	Hickory, Pignut	Carya glabra	Wooded Space	No	8	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	59	Newton St	Front	Newton St	197808.43	896011.7	42.31459	-71.5266
1	Greg Baldwin (DRG)	2022/08/18	utility pole 14; DBH estimated; poison ivy; borderline	1390	2022/08/08	AsCa20220808081154	11:01:25	Maple, Red	Acer rubrum	Wooded Space	Yes	12	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	73	Newton St	Front	Newton St	197738.07	896183.4	42.31613	-71.5274
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 19	1391	2022/08/08	AsCa20220808074611	11:47:26	Hickory, Pignut	Carya glabra	Wooded Space	No	12	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	59	Newton St	Front	Newton St	197801.44	896028.8	42.31474	-71.5267
1	Greg Baldwin (DRG)	2022/08/18	utility pole 14; DBH estimated; poison ivy; borderline	1400	2022/08/08	AsCa20220808081342	11:01:25	Oak, Scarlet	Quercus coccinea	Wooded Space	No	22	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	73	Newton St	Front	Newton St	197734.31	896192.5	42.31622	-71.5275
1	Greg Baldwin (DRG)	2022/08/18	utility pole 14; DBH estimated; poison ivy; remove vines	1410	2022/08/08	AsCa20220808081554	11:00:49	Maple, Red	Acer rubrum	Wooded Space	No	21	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	77	Newton St	Front	Newton St	197725.5	896210.6	42.31638	-71.5276
1	Ashley Casello (DRG)	2022/08/08		1411	2022/08/08	AsCa20220808074903	7:50:12	Pine, Eastern White	Pinus strobus	Open Space	No	27	Good	Routine Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Minor	Low	Yes	61	Newton St	Front	Newton St	197794.34	896046.7	42.3149	-71.5268
1	Greg Baldwin (DRG)	2022/08/18	utility pole 14; DBH estimated; poison ivy	1418	2022/08/08	AsCa20220808081735	11:00:49	Pine, Pitch	Pinus rigida	Wooded Space	No	15	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	77	Newton St	Front	Newton St	197723.21	896215.7	42.31642	-71.5276
1	Ashley Casello (DRG)	2022/08/08		1423	2022/08/08	AsCa20220808075053	7:51:45	Maple, Red	Acer rubrum	Open Space	No	23	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Severe	Low	Yes	61	Newton St	Front	Newton St	197792.34	896052	42.31495	-71.5268
1	Greg Baldwin (DRG)	2022/08/18	utility pole 87; DBH estimated; poison ivy	1428	2022/08/08	AsCa20220808081911	11:00:49	Pine, Pitch	Pinus rigida	Wooded Space	No	13	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	77	Newton St	Front	Newton St	197721.91	896219.6	42.31646	-71.5276
1	Ashley Casello (DRG)	2022/08/08		1432	2022/08/08	AsCa20220808075312	7:53:59	Maple, Red	Acer rubrum	Open Space	No	21	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Severe	Low	Yes	61	Newton St	Front	Newton St	197785.94	896069.5	42.31511	-71.5269
1	Greg Baldwin (DRG)	2022/08/18	utility pole 87; DBH estimated; poison ivy	1438	2022/08/08	AsCa20220808082007	11:00:49	Maple, Red	Acer rubrum	Wooded Space	No	8	Fair	Routine Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Negligible	Low	Yes	77	Newton St	Front	Newton St	197722.68	896220.2	42.31646	-71.5276
1	Greg Baldwin (DRG)	2022/08/18	utility pole 16; DBH estimated; poison ivy	1444	2022/08/08	AsCa20220808075440	11:03:26	Maple, Red	Acer rubrum	Wooded Space	No	32	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	67	Newton St	Front	Newton St	197768.37	896108	42.31545	-71.5271
1	Ashley Casello (DRG)	2022/08/08	borderline	1295	2022/08/08	AsCa20220808113232	11:33:54	Maple, Sugar	Acer saccharum	Open Space	No	20	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	7	Nichols St	Front	Nichols St	200770.49	895813	42.3128	-71.4907
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy; borderline	1296	2022/08/08	AsCa20220808124207	12:42:56	Oak, Northern Red	Quercus rubra	Wooded Space	No	10	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Significant	Low	Yes	1	Nichols St	Front	Nichols St	200692.63	895687.9	42.31168	-71.4916
1	Greg Baldwin (DRG)	2022/08/18	borderline	1297	2022/08/08	AsCa20220808131717	13:09:16	Spruce, Norway	Picea abies	Open Space	No	5	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Significant	Low	Yes	8	Nichols St	Front	Nichols St	200796.76	895821.7	42.31288	-71.4903
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy; borderline	1303	2022/08/08	AsCa20220808124302	12:43:38	Oak, Northern Red	Quercus rubra	Wooded Space	No	9	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Significant	Low	Yes	1	Nichols St	Front	Nichols St	200691.87	895686.4	42.31166	-71.4916
1	Ashley Casello (DRG)	2022/08/08	borderline	1304	2022/08/08	AsCa20220808113359	11:34:38	Maple, Sugar	Acer saccharum	Open Space	No	12	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	7	Nichols St	Front	Nichols St	200765.2	895807.7	42.31275	-71.4907
1	Ashley Casello (DRG)	2022/08/11		1305	2022/08/08	AsCa20220808131850	20:09:39	Sassafras	Sassafras albidum	Open Space	No	14	Poor	Remove	None	Dead And Dying Branches	None	Possible	Low	Unlikely	Severe	Low	Yes	8	Nichols St	Front	Nichols St	200799.81	895826.6	42.31292	-71.4903
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy	1311	2022/08/08	AsCa20220808124425	12:45:15	Pine, Eastern White	Pinus strobus	Wooded Space	No	27	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	1	Nichols St	Front	Nichols St	200673.65	895649.6	42.31133	-71.4918
1	Ashley Casello (DRG)	2022/08/08	borderline	1312	2022/08/08	AsCa20220808113449	11:35:11	Maple, Sugar	Acer saccharum	Open Space	No	12	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Severe	Low	Yes	7	Nichols St	Front	Nichols St	200760.15	895802.2	42.3127	-71.4908
1	Ashley Casello (DRG)	2022/08/08		1313	2022/08/08	AsCa20220808132117	13:22:12	Oak, Northern Red	Quercus rubra	Open Space	No	20	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Severe	Low	Yes	8	Nichols St	Front	Nichols St	200802.28	895828.1	42.31294	-71.4903
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy	1316	2022/08/08	AsCa20220808135218	13:53:59	Oak, Scarlet	Quercus coccinea	Wooded Space	No	36	Fair	Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Significant	Low	Yes	15	Nichols St	Front	Nichols St	200900.07	895989.2	42.31439	-71.4891
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy; borderline	1320	2022/08/08	AsCa20220808124558	12:46:46	Pine, Eastern White	Pinus strobus	Wooded Space	No	12	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	1	Nichols St	Front	Nichols St	200672.89	895646	42.3113	-71.4918
1	Ashley Casello (DRG)	2022/08/08	borderline	1321	2022/08/08	AsCa20220808113824	11:40:25	Hawthorn	Crataegus species	Open Space	No	8	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Significant	Low	Yes	7	Nichols St	Front	Nichols St	200758.5	895799.8	42.31268	-71.4908
1	Ashley Casello (DRG)	2022/08/08		1323	2022/08/08	AsCa20220808132243	13:23:26	Sassafras	Sassafras albidum	Open Space	No	10	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	8	Nichols St	Front	Nichols St	200800.75	895828.5	42.31294	-71.4903
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy	1325	2022/08/08	AsCa20220808135401	13:54:33	Oak, White	Quercus alba	Wooded Space	No	30	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	15	Nichols St	Front	Nichols St	200897.43	895977.9	42.31429	-71.4891

1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy; borderline	1329	2022/08/08	AsCa20220808124652	12:48:56	Pine, Eastern White	Pinus strobus	Wooded Space	No	9	Poor	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	1	Nichols St	Front	Nichols St	200672	895644.4	42.31128	-71.4918
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; in shrub	1330	2022/08/08	AsCa20220808113909	11:40:25	Hickory, Pignut	Carya glabra	Open Space	No	13	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	7	Nichols St	Front	Nichols St	200755.27	895795.7	42.31265	-71.4908
1	Ashley Casello (DRG)	2022/08/08		1332	2022/08/08	AsCa20220808132344	13:25:11	Sassafras	Sassafras albidum	Open Space	No	9	Poor	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Severe	Low	Yes	8	Nichols St	Front	Nichols St	200801.93	895828.8	42.31294	-71.4903
1	Ashley Casello (DRG)	2022/08/11	off ROW	1333	2022/08/08	AsCa20220808135847	20:32:57	Tree, Unknown	Unknown Tree	Wooded Space	No	7	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Significant	Low	Yes	1	Joslin Ln	Side	Nichols St	200872.16	895931.3	42.31387	-71.4894
1	Ashley Casello (DRG)	2022/08/08		1339	2022/08/08	AsCa20220808114028	11:41:50	Oak, White	Quercus alba	Open Space	No	36	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	7	Nichols St	Front	Nichols St	200747.98	895786.9	42.31257	-71.4909
1	Ashley Casello (DRG)	2022/08/08		1341	2022/08/08	AsCa20220808132552	13:27:10	Sassafras	Sassafras albidum	Open Space	No	14	Poor	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Severe	Low	Yes	8	Nichols St	Front	Nichols St	200802.81	895830.4	42.31296	-71.4903
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; poison ivy; borderline	1343	2022/08/08	AsCa20220808135956	20:33:11	Oak, Northern Red	Quercus rubra	Wooded Space	No	8	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	1	Joslin Ln	Side	Nichols St	200868.05	895925	42.31381	-71.4895
1	Ashley Casello (DRG)	2022/08/08		1349	2022/08/08	AsCa20220808114312	11:44:15	Apple	Malus species	Open Space	Yes	6	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	5	Nichols St	Front	Nichols St	200734.58	895766.4	42.31238	-71.4911
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy	1352	2022/08/08	AsCa20220808132814	13:29:20	Maple, Red	Acer rubrum	Open Space	Yes	14	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Severe	Low	Yes	8	Nichols St	Front	Nichols St	200816.39	895846.3	42.3131	-71.4901
1	Ashley Casello (DRG)	2022/08/11	borderline	1353	2022/08/08	AsCa20220808140139	20:33:24	Maple, Red	Acer rubrum	Wooded Space	No	16	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Severe	Low	Yes	1	Joslin Ln	Side	Nichols St	200864.64	895921.4	42.31378	-71.4895
1	Ashley Casello (DRG)	2022/08/11		1357	2022/08/08	AsCa20220808114441	20:16:21	Birch, Gray	Betula populifolia	Open Space	No	3	Fair	Train	None	Tree Architecture	Low	Improbable	Low	Unlikely	Minor	Low	Yes	5	Nichols St	Front	Nichols St	200732.82	895763.1	42.31235	-71.4911
1	Ashley Casello (DRG)	2022/08/08	utility guy line	1360	2022/08/08	AsCa20220808125357	12:57:57	Oak, White	Quercus alba	Open Space	No	33	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	2	Nichols St	Front	Nichols St	200698.22	895677.2	42.31158	-71.4915
1	Ashley Casello (DRG)	2022/08/08		1361	2022/08/08	AsCa20220808132952	13:30:16	Maple, Red	Acer rubrum	Open Space	No	9	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Severe	Low	Yes	8	Nichols St	Front	Nichols St	200818.62	895850.8	42.31314	-71.4901
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; poison ivy; borderline; remove poison ivy	1364	2022/08/08	AsCa20220808140307	20:33:34	Oak, Northern Red	Quercus rubra	Open Space	No	14	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	1	Joslin Ln	Side	Nichols St	200862.93	895919.6	42.31376	-71.4895
1	Ashley Casello (DRG)	2022/08/08		1367	2022/08/08	AsCa20220808114601	11:46:32	Apple	Malus species	Open Space	Yes	7	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	5	Nichols St	Front	Nichols St	200725.82	895750.7	42.31224	-71.4912
1	Ashley Casello (DRG)	2022/08/08		1368	2022/08/08	AsCa20220808125554	12:57:34	Maple, Red	Acer rubrum	Open Space	No	8	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	2	Nichols St	Front	Nichols St	200698.75	895678.8	42.31159	-71.4915
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy; borderline	1371	2022/08/08	AsCa20220808133104	13:32:10	Aspen, Bigtooth	Populus grandidentata	Wooded Space	Yes	13	Fair	Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Minor	Low	Yes	8	Nichols St	Front	Nichols St	200821.91	895850.8	42.31314	-71.49
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; poison ivy; remove poison ivy	1375	2022/08/08	AsCa20220808140416	20:33:44	Hickory, Pignut	Carya glabra	Open Space	No	8	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	1	Joslin Ln	Side	Nichols St	200861.7	895917.7	42.31374	-71.4895
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 8	1377	2022/08/08	AsCa20220808114815	11:11:36	Pine, Eastern White	Pinus strobus	Wooded Space	No	30	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	3	Nichols St	Front	Nichols St	200714.48	895726.9	42.31203	-71.4913
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; behind fence	1378	2022/08/08	AsCa20220808130129	13:02:52	Butternut	Juglans cinerea	Open Space	No	13	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	2	Nichols St	Front	Nichols St	200713.88	895698.6	42.31177	-71.4913
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; poison ivy; remove poison ivy	1381	2022/08/08	AsCa20220808133221	20:09:39	Redcedar, Eastern	Juniperus virginiana	Wooded Space	No	5	Poor	Remove	None	Dead And Dying Branches	None	Possible	Low	Unlikely	Negligible	Low	Yes	8	Nichols St	Front	Nichols St	200820.44	895849.5	42.31313	-71.49
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; poison ivy; utility pole 9	1384	2022/08/08	AsCa20220808140533	20:33:55	Hickory, Pignut	Carya glabra	Open Space	No	13	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	1	Joslin Ln	Side	Nichols St	200861.05	895916.3	42.31373	-71.4896
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; remove poison ivy	1387	2022/08/08	AsCa20220808115021	11:11:36	Hickory, Pignut	Carya glabra	Wooded Space	No	13	Fair	Routine Prune	None	Tree Architecture Dead And Dying Branches	Low	Improbable	Low	Unlikely	Severe	Low	Yes	3	Nichols St	Front	Nichols St	200707.6	895716.1	42.31193	-71.4914
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy; remove poison ivy	1389	2022/08/08	AsCa20220808133431	13:35:57	Cherry, Black	Prunus serotina	Wooded Space	No	12	Fair	Routine Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Minor	Low	Yes	8	Nichols St	Front	Nichols St	200825.2	895857.3	42.3132	-71.49
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; poison ivy; remove poison ivy	1393	2022/08/08	AsCa20220808140655	20:34:04	Redcedar, Eastern	Juniperus virginiana	Open Space	No	9	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	1	Joslin Ln	Side	Nichols St	200859.99	895915.6	42.31373	-71.4896
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy; borderline; utility pole 9	1394	2022/08/08	AsCa20220808130637	13:08:35	Hickory, Pignut	Carya glabra	Open Space	No	21	Fair	Prune	None	Broken And/Or Hanging Branches	Low	Imminent	Low	Somewhat Likely	Significant	Moderate	Yes	6	Nichols St	Front	Nichols St	200766.07	895789.6	42.31259	-71.4907
1	Greg Baldwin (DRG)	2022/08/18	9	1397	2022/08/08	AsCa20220808115128	11:11:36	Elm, American	Ulmus americana	Wooded Space	No	12	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	3	Nichols St	Front	Nichols St	200704.55	895710	42.31187	-71.4915
1	Ashley Casello (DRG)	2022/08/11		1399	2022/08/08	AsCa20220808133620	20:09:39	Birch, Gray	Betula populifolia	Wooded Space	No	6	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Minor	Low	Yes	8	Nichols St	Front	Nichols St	200826.14	895858.2	42.31321	-71.49
1	Ashley Casello (DRG)	2022/08/11		1401	2022/08/08	AsCa20220808130908	20:09:39	Maple, Red	Acer rubrum	Open Space	Yes	20	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Low	Unlikely	Severe	Low	Yes	6	Nichols St	Front	Nichols St	200768.48	895792.3	42.31262	-71.4907
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; borderline; utility pole 9	1406	2022/08/08	AsCa20220808115238	11:11:36	Maple, Red	Acer rubrum	Wooded Space	Yes	10	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	3	Nichols St	Front	Nichols St	200703.6	895708.8	42.31186	-71.4915
1	Ashley Casello (DRG)	2022/08/08		1408	2022/08/08	AsCa20220808133753	13:38:37	Maple, Red	Acer rubrum	Wooded Space	Yes	8	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Severe	Low	Yes	8	Nichols St	Front	Nichols St	200829.2	895862.1	42.31324	-71.4899
1	Ashley Casello (DRG)	2022/08/08		1412	2022/08/08	AsCa20220808131115	13:11:53	Redcedar, Eastern	Juniperus virginiana	Open Space	No	12	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	8	Nichols St	Front	Nichols St	200775.54	895801.1	42.31269	-71.4906
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 9	1416	2022/08/08	AsCa20220808115336	11:11:36	Hickory, Pignut	Carya glabra	Wooded Space	No	12	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	3	Nichols St	Front	Nichols St	200702.43	895706.6	42.31184	-71.4915
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; poison ivy	1417	2022/08/08	AsCa20220808134223	20:16:21	Apple	Malus species	Open Space	Yes	3	Fair	Train	None	Tree Architecture	Low	Improbable	Low	Unlikely	Minor	Low	Yes	10	Nichols St	Front	Nichols St	200869.22	895910.8	42.31368	-71.4895
1	Ashley Casello (DRG)	2022/08/08		1419	2022/08/08	AsCa20220808131216	13:12:52	Hickory, Pignut	Carya glabra	Open Space	No	13	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Severe	Low	Yes	8	Nichols St	Front	Nichols St	200784.47	895811.2	42.31279	-71.4905
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy; borderline	1426	2022/08/08	AsCa20220808123756	12:39:11	Hickory, Pignut	Carya glabra	Wooded Space	No	8	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	1	Nichols St	Front	Nichols St	200701.8	895706	42.31184	-71.4915
1	Ashley Casello (DRG)	2022/08/11	off ROW	1427	2022/08/08	AsCa20220808134450	20:34:14	Elm, American	Ulmus americana	Wooded Space	No	8	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Significant	Low	Yes	16	Pine Hill Rd	Side	Nichols St	200895.2	895940.5	42.31395	-71.4891
1	Ashley Casello (DRG)	2022/08/08		1430	2022/08/08	AsCa20220808131305	13:13:33	Maple, Red	Acer rubrum	Open Space	Yes	9	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Severe	Low	Yes	8	Nichols St	Front	Nichols St	200788.53	895816.7	42.31284	-71.4904
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy	1436	2022/08/08	AsCa20220808123952	12:41:02	Oak, Scarlet	Quercus coccinea	Wooded Space	No	20	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	1	Nichols St	Front	Nichols St	200695.51	895692.2	42.31171	-71.4916
1	Ashley Casello (DRG)	2022/08/08	remove vines	1437	2022/08/08	AsCa20220808134902	13:50:00	Maple, Red	Acer rubrum	Wooded Space	No	9	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Severe	Low	Yes	17	Nichols St	Front	Nichols St	200917	896024.7	42.31471	-71.4889
1	Ashley Casello (DRG)	2022/08/08		1439	2022/08/08	AsCa20220808131407	13:14:39	Maple, Red	Acer rubrum	Open Space	No	28	Fair	Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Significant	Low	Yes	8	Nichols St	Front	Nichols St	200791.76	895821.6	42.31288	-71.4904
1	Ashley Casello (DRG)	2022/08/08		1445	2022/08/08	AsCa20220808124112	12:41:56	Maple, Red	Acer rubrum	Wooded Space	Yes	9	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	1	Nichols St	Front	Nichols St	200694.22	895690.1	42.3117	-71.4916
1	Ashley Casello (DRG)	2022/08/08	borderline	1447	2022/08/08	AsCa20220808135006	13:51:24	Maple, Red	Acer rubrum	Open Space	No	16	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Severe	Low	Yes	17	Nichols St	Front	Nichols St	200906.83	896012.7	42.3146	-71.489
1	Ashley Casello (DRG)	2022/08/08		1448	2022/08/08	AsCa20220808131547	13:17:02	Sassafras	Sassafras albidum	Open Space	No	14	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Severe	Low	Yes	8	Nichols St	Front	Nichols St	200797.34	895825.8	42.31292	-71.4903
1	Ashley Casello (DRG)	2022/08/08		1453	2022/08/08	AsCa20220808112703	11:29:00	Oak, Northern Red	Quercus rubra	Open Space	No	20	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	11	Nichols St	Front	Nichols St	200814.34	895857.4	42.3132	-71.4901
1	Ashley Casello (DRG)	2022/08/08		1458	2022/08/08	AsCa20220808113025	11:31:47	Hickory, Pignut	Carya glabra	Open Space	No	25	Good	Prune	None	Dead And Dying Branches	Low	Improbable	Low	Unlikely	Significant	Low	Yes	9	Nichols St	Front	Nichols St	200795.29	895837.3	42.31302	-71.4904
1	Greg Baldwin (DRG)	2022/08/01		560	2022/08/01	GrBa20220801130405	13:04:42	Maple, Red	Acer rubrum	Wooded Space	No	15	Poor	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	177	Middle Rd	Side	No Name	197290.18	892761.1	42.28532	-71.5329
1	Greg Baldwin (DRG)	2022/08/03		696	2022/08/03	GrBa20220803090711	9:07:41	Hickory, Pignut	Carya glabra	Wooded Space	No	14	Good	Routine Prune	None	Root Problems	Low	Improbable	High	Unlikely	Significant	Low	Yes	10	Jacobs Ln	Side	No Name	195140.52	894566.3	42.30156	-71.5589
1	Greg Baldwin (DRG)	2022/08/03	borderline	744	2022/08/03	GrBa20220803114948	11:51:11	Oak, Black	Quercus velutina	Open Space	No	31	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	22	Bigelow Rd	Side	No Name	193876.26	895256.3	42.30777	-71.5743
1	Greg Baldwin (DRG)	2022/07/29		22	2022/07/29	GrBa20220729132956	13:30:34	Plum	Prunus species	Open Space	No	1	Good	Train	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	92	Oak Hill Rd	Front	Oak Hill Rd	200008.43	892959.2	42.28711	-71.4999

1	Greg Baldwin (DRG)	2022/07/29		23	2022/07/29	GrBa20220729142645	14:27:52	Oak, Black	Quercus velutina	Open Space	No	35	Poor	Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Significant	Low	Yes	77	Oak Hill Rd	Front	Oak Hill Rd	199981.74	892979.6	42.28729	-71.5002
1	Greg Baldwin (DRG)	2022/07/29		32	2022/07/29	GrBa20220729133038	13:30:53	Plum	Prunus species	Open Space	No	1	Good	Train	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	92	Oak Hill Rd	Front	Oak Hill Rd	200009.19	892957.1	42.28709	-71.4999
1	Greg Baldwin (DRG)	2022/07/29		33	2022/07/29	GrBa20220729142801	14:30:27	Oak, White	Quercus alba	Open Space	No	40	Fair	Prune	None	Weakly Attached Branches And Codominant Stems	Low	Possible	Low	Unlikely	Minor	Low	Yes	77	Oak Hill Rd	Front	Oak Hill Rd	199975.74	892990.6	42.28739	-71.5003
1	Greg Baldwin (DRG)	2022/07/29		42	2022/07/29	GrBa20220729133226	13:33:23	Oak, Black	Quercus velutina	Open Space	No	32	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Significant	Low	Yes	94	Oak Hill Rd	Front	Oak Hill Rd	200019.78	892935.2	42.28689	-71.4998
1	Greg Baldwin (DRG)	2022/07/29		43	2022/07/29	GrBa20220729143029	14:31:40	Oak, White	Quercus alba	Open Space	No	37	Good	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	77	Oak Hill Rd	Front	Oak Hill Rd	199966.27	893007	42.28754	-71.5004
1	Greg Baldwin (DRG)	2022/07/29		50	2022/07/29	GrBa20220729133420	13:34:40	Oak, Black	Quercus velutina	Open Space	No	35	Poor	Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Significant	Low	Yes	94	Oak Hill Rd	Front	Oak Hill Rd	200022.13	892931.8	42.28686	-71.4997
1	Greg Baldwin (DRG)	2022/07/29	Co-dominants	53	2022/07/29	GrBa20220729143216	14:32:50	Maple, Red	Acer rubrum	Open Space	No	23	Poor	Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Minor	Low	Yes	75	Oak Hill Rd	Front	Oak Hill Rd	199963.21	893012.7	42.28759	-71.5004
1	Greg Baldwin (DRG)	2022/07/29		57	2022/07/29	GrBa20220729133454	13:35:15	Maple, Red	Acer rubrum	Open Space	No	7	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	94	Oak Hill Rd	Front	Oak Hill Rd	200023.13	892933.2	42.28688	-71.4997
1	Greg Baldwin (DRG)	2022/07/29	start hedge row; 10	63	2022/07/29	GrBa20220729143301	14:35:37	Cedar, Northern White	Thuja occidentalis	Open Space	No	6	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Minor	Low	Yes	75	Oak Hill Rd	Front	Oak Hill Rd	199960.15	893016.7	42.28763	-71.5005
1	Moriah Day (DRG)	2022/08/23		65	2022/07/29	GrBa20220729133517	10:28:29	Redcedar, Eastern Cedar, Northern	Juniperus virginiana	Open Space	No	1	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	94	Oak Hill Rd	Front	Oak Hill Rd	200021.19	892933.6	42.28688	-71.4997
1	Greg Baldwin (DRG)	2022/07/29	end hedge row; 10	73	2022/07/29	GrBa20220729143448	14:35:26	White	Thuja occidentalis	Open Space	Yes	10	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Significant	Low	Yes	75	Oak Hill Rd	Front	Oak Hill Rd	199955.51	893024.8	42.2877	-71.5005
1	Greg Baldwin (DRG)	2022/07/29		74	2022/07/29	GrBa20220729133658	13:37:51	Cherry, Black	Prunus serotina	Open Space	No	12	Poor	Routine Prune	Annual Ins	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	94	Oak Hill Rd	Front	Oak Hill Rd	200031.47	892916.1	42.28672	-71.4996
1	Greg Baldwin (DRG)	2022/07/29		83	2022/07/29	GrBa20220729143622	14:37:36	Oak, White	Quercus alba	Open Space	No	4	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Possible	Medium	Unlikely	Minor	Low	Yes	73	Oak Hill Rd	Front	Oak Hill Rd	199949.39	893037.9	42.28782	-71.5006
1	Greg Baldwin (DRG)	2022/07/29	vines >50%	84	2022/07/29	GrBa20220729133847	13:39:42	Cherry, Black	Prunus serotina	Open Space	No	9	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Negligible	Low	Yes	94	Oak Hill Rd	Front	Oak Hill Rd	200037.75	892907.8	42.28665	-71.4995
1	Greg Baldwin (DRG)	2022/07/29		93	2022/07/29	GrBa20220729133945	13:40:58	Hickory, Pignut	Carya glabra	Open Space	No	5	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	94	Oak Hill Rd	Front	Oak Hill Rd	200038.52	892906.2	42.28663	-71.4995
1	Greg Baldwin (DRG)	2022/07/29		94	2022/07/29	GrBa20220729143817	14:39:09	Spruce, Blue	Picea pungens	Open Space	No	4	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	71	Oak Hill Rd	Front	Oak Hill Rd	199932.99	893068.1	42.28809	-71.5008
1	Greg Baldwin (DRG)	2022/07/29		103	2022/07/29	GrBa20220729134144	13:43:24	Ash, White	Fraxinus americana	Wooded Space	No	21	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Significant	Low	Yes	94	Oak Hill Rd	Front	Oak Hill Rd	200041.07	892900.7	42.28658	-71.4995
1	Greg Baldwin (DRG)	2022/07/29		104	2022/07/29	GrBa20220729143912	14:39:25	Spruce, Blue	Picea pungens	Open Space	No	3	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	71	Oak Hill Rd	Front	Oak Hill Rd	199931.51	893071.1	42.28812	-71.5008
1	Greg Baldwin (DRG)	2022/07/29		113	2022/07/29	GrBa20220729134533	13:46:40	Oak, Black	Quercus velutina	Wooded Space	No	28	Poor	Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Significant	Low	Yes	98	Oak Hill Rd	Front	Oak Hill Rd	200042.85	892897.6	42.28656	-71.4995
1	Greg Baldwin (DRG)	2022/07/29		114	2022/07/29	GrBa20220729143941	14:40:19	Dogwood, Kousa	Cornus kousa	Open Space	No	1	Good	Train	None	No Significant Defect	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	71	Oak Hill Rd	Front	Oak Hill Rd	199929.4	893075.1	42.28815	-71.5009
1	Greg Baldwin (DRG)	2022/08/27		122	2022/07/29	GrBa20220729134759	7:43:10	Oak, Black	Quercus velutina	Wooded Space	No	39	Poor	Prune	None	Weakly Attached Branches And Codominant Stems	Low	Possible	Medium	Unlikely	Significant	Low	Yes	98	Oak Hill Rd	Front	Oak Hill Rd	200044.63	892894.7	42.28653	-71.4995
1	Greg Baldwin (DRG)	2022/07/29	borderline	124	2022/07/29	GrBa20220729144135	14:42:06	Spruce, Blue	Picea pungens	Open Space	No	3	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	65	Oak Hill Rd	Front	Oak Hill Rd	199902.58	893120.5	42.28856	-71.5012
1	Greg Baldwin (DRG)	2022/07/29		132	2022/07/29	GrBa20220729135042	13:51:53	Oak, Black	Quercus velutina	Open Space	No	15	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Medium	Unlikely	Significant	Low	Yes	98	Oak Hill Rd	Front	Oak Hill Rd	200050.41	892886.1	42.28645	-71.4994
1	Greg Baldwin (DRG)	2022/07/29	borderline	134	2022/07/29	GrBa20220729144242	14:44:47	Fir, Balsam	Abies balsamea	Open Space	No	10	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	65	Oak Hill Rd	Front	Oak Hill Rd	199898.41	893129	42.28864	-71.5012
1	Greg Baldwin (DRG)	2022/07/29	crown dieback	143	2022/07/29	GrBa20220729135542	13:57:24	Spruce, Blue	Picea pungens	Open Space	No	12	Poor	Remove	None	Dead And Dying Branches	None	Possible	High	Somewhat Likely	Minor	Low	Yes	87	Oak Hill Rd	Front	Oak Hill Rd	200058.83	892857	42.28619	-71.4993
1	Greg Baldwin (DRG)	2022/07/29		144	2022/07/29	GrBa20220729144450	14:46:20	Fir, Balsam	Abies balsamea	Open Space	No	9	Poor	Routine Prune	None	Tree Architecture	Low	Possible	Low	Unlikely	Minor	Low	Yes	65	Oak Hill Rd	Front	Oak Hill Rd	199896.53	893132.6	42.28867	-71.5013
1	Greg Baldwin (DRG)	2022/07/29	borderline	153	2022/07/29	GrBa20220729135819	13:59:09	Maple, Red	Acer rubrum	Wooded Space	Yes	9	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	98	Oak Hill Rd	Front	Oak Hill Rd	200068.83	892866.5	42.28627	-71.4992
1	Greg Baldwin (DRG)	2022/07/29	borderline	154	2022/07/29	GrBa20220729144642	14:47:42	Maple, Norway	Acer platanoides	Open Space	No	26	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	65	Oak Hill Rd	Front	Oak Hill Rd	199889.59	893144.7	42.28878	-71.5013
1	Greg Baldwin (DRG)	2022/07/29		160	2022/07/29	GrBa20220729130100	15:07:34	Hickory, Pignut	Carya glabra	Open Space	No	30	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	38	Oak Hill Rd	Front	Oak Hill Rd	199754.47	893431.3	42.29136	-71.503
1	Greg Baldwin (DRG)	2022/07/29		163	2022/07/29	GrBa20220729135912	13:59:51	Maple, Red	Acer rubrum	Wooded Space	No	11	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	98	Oak Hill Rd	Front	Oak Hill Rd	200070.06	892865.1	42.28626	-71.4992
1	Greg Baldwin (DRG)	2022/07/29	dbh estimated; poison ivy	164	2022/07/29	GrBa20220729144805	14:49:08	Maple, Red	Acer rubrum	Open Space	No	22	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	65	Oak Hill Rd	Front	Oak Hill Rd	199881.65	893161.8	42.28893	-71.5014
1	Greg Baldwin (DRG)	2022/07/29		171	2022/07/29	GrBa20220729130458	13:05:33	Cherry, Black	Prunus serotina	Open Space	Yes	1	Fair	Train	None	Tree Architecture	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	52	Oak Hill Rd	Front	Oak Hill Rd	199838.69	893267.3	42.28988	-71.502
1	Greg Baldwin (DRG)	2022/07/29		173	2022/07/29	GrBa20220729140232	14:03:49	Oak, Northern Red	Quercus rubra	Open Space	No	44	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Significant	Low	Yes	85	Oak Hill Rd	Front	Oak Hill Rd	200040.48	892879.3	42.28639	-71.4995
1	Greg Baldwin (DRG)	2022/08/27	leaning	174	2022/07/29	GrBa20220729145026	7:23:26	Locust, Black	Robinia pseudoacacia	Open Space	No	31	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Severe	Low	Yes	65	Oak Hill Rd	Front	Oak Hill Rd	199877.89	893168.8	42.289	-71.5015
1	Greg Baldwin (DRG)	2022/07/29	utility pruned	180	2022/07/29	GrBa20220729130608	13:06:52	Maple, Sugar	Acer saccharum	Open Space	No	15	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	52	Oak Hill Rd	Front	Oak Hill Rd	199840.1	893265.4	42.28987	-71.5019
1	Greg Baldwin (DRG)	2022/07/29	lost main leader; epicormic sprouts	183	2022/07/29	GrBa20220729140441	14:05:53	Oak, Black	Quercus velutina	Open Space	No	38	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	85	Oak Hill Rd	Front	Oak Hill Rd	200038.84	892882.2	42.28642	-71.4995
1	Greg Baldwin (DRG)	2022/07/29	borderline; leaning	186	2022/07/29	GrBa20220729145258	14:53:49	Hickory, Pignut	Carya glabra	Open Space	No	20	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	59	Oak Hill Rd	Front	Oak Hill Rd	199855.3	893205.8	42.28933	-71.5018
1	Greg Baldwin (DRG)	2022/07/29	hangers	191	2022/07/29	GrBa20220729130655	13:07:38	Maple, Sugar	Acer saccharum	Open Space	No	14	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	52	Oak Hill Rd	Front	Oak Hill Rd	199840.8	893263.5	42.28985	-71.5019
1	Greg Baldwin (DRG)	2022/07/29		193	2022/07/29	GrBa20220729140707	14:09:08	Hickory, Pignut	Carya glabra	Open Space	No	12	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Medium	Unlikely	Significant	Low	Yes	83	Oak Hill Rd	Front	Oak Hill Rd	200037.43	892883.4	42.28643	-71.4995
1	Greg Baldwin (DRG)	2022/07/29		194	2022/07/29	GrBa20220729145408	14:55:03	Maple, Red	Acer rubrum	Open Space	No	11	Poor	Routine Prune	None	Missing Or Decayed Wood	None	Probable	Low	Unlikely	Minor	Low	Yes	59	Oak Hill Rd	Front	Oak Hill Rd	199852.72	893210.6	42.28937	-71.5018
1	Greg Baldwin (DRG)	2022/07/29	borderline	200	2022/07/29	GrBa20220729130830	13:09:12	Maple, Sugar	Acer saccharum	Wooded Space	No	8	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Significant	Low	Yes	66	Oak Hill Rd	Front	Oak Hill Rd	199865.03	893219.1	42.28945	-71.5016
1	Greg Baldwin (DRG)	2022/08/27		203	2022/07/29	GrBa20220729141017	7:45:12	Oak, Black	Quercus velutina	Open Space	No	39	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	83	Oak Hill Rd	Front	Oak Hill Rd	200033.43	892889.8	42.28648	-71.4996
1	Greg Baldwin (DRG)	2022/07/29		204	2022/07/29	GrBa20220729145614	14:57:27	Oak, White	Quercus alba	Open Space	No	32	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	59	Oak Hill Rd	Front	Oak Hill Rd	199851.01	893216	42.28942	-71.5018

1	Greg Baldwin (DRG)	2022/07/29	trunk wounds	211	2022/07/29	GrBa20220729131041	13:11:34	Maple, Sugar	Acer saccharum	Wooded Space	No	14	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	66	Oak Hill Rd	Front	Oak Hill Rd	199880.27	893190.4	42.28919	-71.5015
1	Greg Baldwin (DRG)	2022/07/29		212	2022/07/29	GrBa20220729145729	14:58	Oak, White	Quercus alba	Open Space	No	25	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	59	Oak Hill Rd	Front	Oak Hill Rd	199849.31	893217.9	42.28944	-71.5018
1	Greg Baldwin (DRG)	2022/07/29		213	2022/07/29	GrBa20220729141214	14:12:47	Oak, White	Quercus alba	Open Space	No	33	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	83	Oak Hill Rd	Front	Oak Hill Rd	200021.43	892908.6	42.28665	-71.4997
1	Greg Baldwin (DRG)	2022/07/29		220	2022/07/29	GrBa20220729131242	13:13:48	Maple, Red	Acer rubrum	Open Space	No	21	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	70	Oak Hill Rd	Front	Oak Hill Rd	199889.65	893172.8	42.28903	-71.5013
1	Greg Baldwin (DRG)	2022/07/29		222	2022/07/29	GrBa20220729145948	15:00:27	Maple, Norway	Acer platanoides	Open Space	Yes	7	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	49	Oak Hill Rd	Front	Oak Hill Rd	199808.09	893297.6	42.29016	-71.5023
1	Greg Baldwin (DRG)	2022/07/29	utility guy line; root decay; fruiting bodies	224	2022/07/29	GrBa20220729141355	14:17	Oak, Scarlet	Quercus coccinea	Open Space	No	40	Poor	Prune	Advanced	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Severe	Low	Yes	81	Oak Hill Rd	Front	Oak Hill Rd	200014.31	892921.1	42.28677	-71.4998
1	Greg Baldwin (DRG)	2022/07/29	borderline	229	2022/07/29	GrBa20220729131443	13:15:19	Maple, Red	Acer rubrum	Wooded Space	No	8	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	74	Oak Hill Rd	Front	Oak Hill Rd	199912.88	893133.6	42.28868	-71.5011
1	Greg Baldwin (DRG)	2022/07/29		232	2022/07/29	GrBa20220729150030	15:01:03	Maple, Norway	Acer platanoides	Open Space	No	6	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Minor	Low	Yes	49	Oak Hill Rd	Front	Oak Hill Rd	199807.56	893300.4	42.29018	-71.5023
1	Greg Baldwin (DRG)	2022/07/29	utility guy line	234	2022/07/29	GrBa20220729141757	14:19:10	Oak, Northern Red	Quercus rubra	Open Space	No	39	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	81	Oak Hill Rd	Front	Oak Hill Rd	200007.14	892933.3	42.28688	-71.4999
1	Greg Baldwin (DRG)	2022/07/29		238	2022/07/29	GrBa20220729131613	13:17:02	Ash, White	Fraxinus americana	Wooded Space	No	18	Poor	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	74	Oak Hill Rd	Front	Oak Hill Rd	199919.88	893119.6	42.28855	-71.501
1	Greg Baldwin (DRG)	2022/07/29		242	2022/07/29	GrBa20220729150117	15:01:31	Maple, Norway	Acer platanoides	Open Space	No	15	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	49	Oak Hill Rd	Front	Oak Hill Rd	199806.2	893303.6	42.29021	-71.5023
1	Greg Baldwin (DRG)	2022/07/29		243	2022/07/29	GrBa20220729142002	14:21:00	Oak, White	Quercus alba	Open Space	No	26	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	81	Oak Hill Rd	Front	Oak Hill Rd	200000.91	892944.1	42.28697	-71.5
1	Greg Baldwin (DRG)	2022/07/29	borderline	250	2022/07/29	GrBa20220729131844	13:20:08	Spruce, Blue	Picea pungens	Open Space	No	4	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Minor	Low	Yes	84	Oak Hill Rd	Front	Oak Hill Rd	199978.32	893014.8	42.28761	-71.5003
1	Greg Baldwin (DRG)	2022/07/29	borderline	252	2022/07/29	GrBa20220729150256	15:05:27	Oak, Scarlet	Quercus coccinea	Open Space	No	21	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	41	Oak Hill Rd	Front	Oak Hill Rd	199762	893387	42.29096	-71.5029
1	Greg Baldwin (DRG)	2022/07/29		254	2022/07/29	GrBa20220729142109	14:22:19	Oak, White	Quercus alba	Open Space	No	29	Fair	Routine Prune	None	Root Problems	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	79	Oak Hill Rd	Front	Oak Hill Rd	199994.03	892956.3	42.28708	-71.5001
1	Greg Baldwin (DRG)	2022/07/29	borderline	259	2022/07/29	GrBa20220729131931	13:19:59	Spruce, Blue	Picea pungens	Open Space	No	3	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Minor	Low	Yes	84	Oak Hill Rd	Front	Oak Hill Rd	199982.61	893006.5	42.28754	-71.5002
1	Greg Baldwin (DRG)	2022/07/29		262	2022/07/29	GrBa20220729150646	15:08:25	Oak, White	Quercus alba	Open Space	No	50	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Significant	Low	Yes	41	Oak Hill Rd	Front	Oak Hill Rd	199747.01	893418.2	42.29124	-71.5031
1	Greg Baldwin (DRG)	2022/07/29		263	2022/07/29	GrBa20220729142231	14:25:57	Oak, White	Quercus alba	Open Space	No	31	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	79	Oak Hill Rd	Front	Oak Hill Rd	199984.26	892974.4	42.28725	-71.5002
1	Greg Baldwin (DRG)	2022/07/29	borderline	268	2022/07/29	GrBa20220729150913	15:10:22	Oak, Black	Quercus velutina	Open Space	No	54	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	41	Oak Hill Rd	Front	Oak Hill Rd	199734.36	893443.5	42.29147	-71.5032
1	Greg Baldwin (DRG)	2022/07/29	borderline	271	2022/07/29	GrBa20220729132011	13:21:10	Apple	Malus species	Open Space	No	5	Fair	Train	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	84	Oak Hill Rd	Front	Oak Hill Rd	199984.02	893004.1	42.28751	-71.5002
1	Greg Baldwin (DRG)	2022/07/29	borderline; topped	273	2022/07/29	GrBa20220729151212	15:13:33	Spruce, Blue	Picea pungens	Open Space	No	21	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	35	Oak Hill Rd	Front	Oak Hill Rd	199691.68	893524.9	42.2922	-71.5037
1	Greg Baldwin (DRG)	2022/07/29	trunk decay	280	2022/07/29	GrBa20220729132228	13:29:22	Oak, Black	Quercus velutina	Open Space	No	43	Poor	Prune	Advanced	Missing Or Decayed Wood	Moderate	Possible	High	Somewhat Likely	Significant	Moderate	Yes	90	Oak Hill Rd	Front	Oak Hill Rd	200002.72	892969.4	42.2872	-71.5
1	Greg Baldwin (DRG)	2022/07/29	hangers	282	2022/07/29	GrBa20220729151346	15:15:41	Oak, Northern Red	Quercus rubra	Open Space	No	23	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	25	Oak Hill Rd	Front	Oak Hill Rd	199661.4	893584.4	42.29274	-71.5041
1	Greg Baldwin (DRG)	2022/07/29	frost cracking	284	2022/07/29	GrBa20220729151701	15:17:41	Maple, Red	Acer rubrum	Open Space	No	18	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	19	Oak Hill Rd	Front	Oak Hill Rd	199654.44	893598.2	42.29286	-71.5042
1	Greg Baldwin (DRG)	2022/07/29		285	2022/07/29	GrBa20220729151805	15:19:02	Oak, Black	Quercus velutina	Open Space	No	17	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	19	Oak Hill Rd	Front	Oak Hill Rd	199648.56	893611	42.29298	-71.5043
1	Greg Baldwin (DRG)	2022/08/01		293	2022/08/01	GrBa20220801071918	7:20:12	Lilac, Japanese Tree	Syringa reticulata	Open Space	Yes	8	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	19	Oak Hill Rd	Front	Oak Hill Rd	199637.51	893627.7	42.29313	-71.5044
1	Greg Baldwin (DRG)	2022/08/01		304	2022/08/01	GrBa20220801072059	7:21:29	Oak, Northern Red	Quercus rubra	Open Space	No	18	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	17	Oak Hill Rd	Front	Oak Hill Rd	199630.57	893642.9	42.29326	-71.5045
1	Greg Baldwin (DRG)	2022/08/01		315	2022/08/01	GrBa20220801072137	7:22:24	Maple, Norway 'Crimson King'	Acer platanoides 'Crimson King'	Open Space	No	11	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	17	Oak Hill Rd	Front	Oak Hill Rd	199623.4	893654.8	42.29337	-71.5046
1	Greg Baldwin (DRG)	2022/08/01		328	2022/08/01	GrBa20220801072256	7:23:37	Maple, Norway	Acer platanoides	Open Space	No	19	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	11	Oak Hill Rd	Front	Oak Hill Rd	199609.87	893680.1	42.2936	-71.5047
1	Greg Baldwin (DRG)	2022/08/01	prune for clearance; remove weed trees	336	2022/08/01	GrBa20220801072356	7:24:17	Maple, Norway	Acer platanoides	Open Space	No	16	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	11	Oak Hill Rd	Front	Oak Hill Rd	199603.35	893691.5	42.2937	-71.5048
1	Greg Baldwin (DRG)	2022/08/01	borderline	346	2022/08/01	GrBa20220801072747	7:45:33	Maple, Norway	Acer platanoides	Wooded Space	Yes	1	Good	Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	76	Turnpike Rd	Side	Oak Hill Rd	199592.18	893741.5	42.29415	-71.5049
1	Greg Baldwin (DRG)	2022/08/18	borderline	1581	2022/08/09	AsCa20220809092347	13:09:16	Spruce, Blue	Picea pungens	Open Space	No	2	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Minor	Low	Yes	174	Southville Rd	Side	Parkerville Rd	196974.18	890676	42.26655	-71.5367
1	Greg Baldwin (DRG)	2022/07/29	reduce for building clearance	225	2022/07/29	GrBa20220729071401	7:41:03	Linden, Littleleaf	Tilia cordata	Open Space	No	8	Good	Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Minor	Low	Yes	106	Southville Rd	Side	River St	198149.42	890798.3	42.26765	-71.5224
1	Greg Baldwin (DRG)	2022/07/29	reduce for building clearance	236	2022/07/29	GrBa20220729071551	7:41:08	Linden, Littleleaf	Tilia cordata	Open Space	No	8	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Minor	Low	Yes	106	Southville Rd	Side	River St	198152.39	890787.5	42.26756	-71.5224
1	Greg Baldwin (DRG)	2022/07/29		245	2022/07/29	GrBa20220729071914	7:21:16	Oak, Pin	Quercus palustris	Open Space	No	9	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	10	River St	Front	River St	198167.76	890725.8	42.267	-71.5222
1	Greg Baldwin (DRG)	2022/07/28	behind fence	15	2022/07/28	GrBa20220728104240	10:47:37	Cedar, Northern White	Thuja occidentalis	Open Space	Yes	6	Good	N/A	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Minor	Low	No	279	Cordaville Rd	Side	Southville Rd	198044.72	890802.6	42.26769	-71.5237
1	Ashley Casello (DRG)	2022/08/08	borderline	1338	2022/08/08	AsCa20220808145204	14:53:20	Hemlock, Eastern	Tsuga canadensis	Open Space	No	10	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	210	Southville Rd	Front	Southville Rd	196383.01	890701.2	42.26677	-71.5438
1	Ashley Casello (DRG)	2022/08/08	borderline	1348	2022/08/08	AsCa20220808145322	14:53:45	Hemlock, Eastern	Tsuga canadensis	Open Space	No	7	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	210	Southville Rd	Front	Southville Rd	196381.95	890701	42.26677	-71.5439
1	Ashley Casello (DRG)	2022/08/08	borderline	1358	2022/08/08	AsCa20220808145356	14:54:30	Hemlock, Eastern	Tsuga canadensis	Open Space	No	7	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	210	Southville Rd	Front	Southville Rd	196380.6	890701.2	42.26677	-71.5439
1	Greg Baldwin (DRG)	2022/08/18	possible bacterial wetwood	1369	2022/08/08	AsCa20220808145457	13:49:13	Oak, Northern Red	Quercus rubra	Open Space	No	28	Fair	Routine Prune	Insect/Dis	Dead And Dying Branches	Low	Probable	Low	Unlikely	Minor	Low	Yes	210	Southville Rd	Front	Southville Rd	196381.25	890703.7	42.26679	-71.5439
1	Ashley Casello (DRG)	2022/08/08	borderline; basal decay	1379	2022/08/08	AsCa20220808145737	14:58:30	Oak, Northern Red	Quercus rubra	Open Space	No	32	Fair	Prune	Annual Ins	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	210	Southville Rd	Front	Southville Rd	196377.9	890701.7	42.26678	-71.5439
1	Ashley Casello (DRG)	2022/08/08	borderline; start hedgerow; 10 trees in ROW	1388	2022/08/08	AsCa20220808145858	15:00:18	Hemlock, Eastern	Tsuga canadensis	Open Space	No	7	Good	Routine Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Negligible	Low	Yes	210	Southville Rd	Front	Southville Rd	196374.78	890701.6	42.26678	-71.5439
1	Ashley Casello (DRG)	2022/08/08	borderline; end hedgerow; 10 trees in ROW	1398	2022/08/08	AsCa20220808150029	15:08:18	Hemlock, Eastern	Tsuga canadensis	Open Space	No	11	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	210	Southville Rd	Front	Southville Rd	196359.78	890702	42.26678	-71.5441

1	Ashley Casello (DRG)	2022/08/08	borderline	1403	2022/08/08	AsCa20220808143429	14:36:03	Oak, Northern Red	Quercus rubra	Open Space	Yes	37	Good	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	200	Southville Rd	Front	Southville Rd	196490.31	890700.4	42.26677	-71.5425
1	Ashley Casello (DRG)	2022/08/11		1409	2022/08/08	AsCa20220808150138	20:16:21	Hickory, Pignut	Carya glabra	Open Space	No	2	Good	Train	None	Tree Architecture	Low	Improbable	Low	Unlikely	Minor	Low	Yes	210	Southville Rd	Front	Southville Rd	196373.13	890703.2	42.26679	-71.544
1	Ashley Casello (DRG)	2022/08/08	borderline	1413	2022/08/08	AsCa20220808143644	14:37:53	Pine, Eastern White	Pinus strobus	Open Space	No	7	Fair	Routine Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Negligible	Low	Yes	200	Southville Rd	Front	Southville Rd	196487.02	890700.3	42.26677	-71.5426
1	Ashley Casello (DRG)	2022/08/08	borderline	1421	2022/08/08	AsCa20220808150240	15:08:10	Oak, Northern Red	Quercus rubra	Open Space	No	23	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	210	Southville Rd	Front	Southville Rd	196361.37	890703.5	42.26679	-71.5441
1	Ashley Casello (DRG)	2022/08/08		1424	2022/08/08	AsCa20220808143849	14:39:14	Pine, Eastern White	Pinus strobus	Open Space	No	8	Fair	Routine Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Negligible	Low	Yes	200	Southville Rd	Front	Southville Rd	196483.25	890701.2	42.26677	-71.5426
1	Ashley Casello (DRG)	2022/08/08	borderline	1429	2022/08/08	AsCa20220808150834	15:09:51	Oak, Scarlet	Quercus coccinea	Open Space	No	13	Fair	Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Minor	Low	Yes	210	Southville Rd	Front	Southville Rd	196358.07	890701.9	42.26678	-71.5441
1	Ashley Casello (DRG)	2022/08/08	borderline	1434	2022/08/08	AsCa20220808143953	14:41:31	Spruce, Blue	Picea pungens	Open Space	No	8	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	200	Southville Rd	Front	Southville Rd	196480.72	890700.9	42.26677	-71.5427
1	Ashley Casello (DRG)	2022/08/11		1440	2022/08/08	AsCa20220808151003	20:16:21	Maple, Red	Acer rubrum	Open Space	Yes	4	Fair	Train	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	210	Southville Rd	Front	Southville Rd	196352.37	890703	42.26679	-71.5442
1	Ashley Casello (DRG)	2022/08/08		1443	2022/08/08	AsCa20220808144222	14:44:27	Oak, Northern Red	Quercus rubra	Open Space	No	37	Poor	Prune	Annual Ins	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	200	Southville Rd	Front	Southville Rd	196477.78	890701.9	42.26678	-71.5427
1	Ashley Casello (DRG)	2022/08/11		1450	2022/08/08	AsCa20220808151056	20:16:21	Maple, Red	Acer rubrum	Open Space	No	5	Good	Train	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	210	Southville Rd	Front	Southville Rd	196350.13	890702.8	42.26679	-71.5442
1	Ashley Casello (DRG)	2022/08/08	borderline	1451	2022/08/08	AsCa20220808144907	14:53:19	Hemlock, Eastern	Tsuga canadensis	Open Space	No	11	Fair	Routine Prune	None	Broken And/Or Hanging Branches	Low	Probable	Low	Unlikely	Negligible	Low	Yes	210	Southville Rd	Front	Southville Rd	196386.13	890701.1	42.26677	-71.5438
1	Ashley Casello (DRG)	2022/08/08		1452	2022/08/08	AsCa20220808144516	14:46:59	Oak, White	Quercus alba	Open Space	No	39	Good	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	204	Southville Rd	Front	Southville Rd	196451.78	890702.1	42.26678	-71.543
1	Ashley Casello (DRG)	2022/08/08		1454	2022/08/08	AsCa20220808151605	15:17:03	Oak, White	Quercus alba	Open Space	No	21	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	212	Southville Rd	Front	Southville Rd	196332.84	890703.1	42.26679	-71.5444
1	Ashley Casello (DRG)	2022/08/11		1455	2022/08/08	AsCa20220808151410	20:16:21	Maple, Red	Acer rubrum	Open Space	No	3	Fair	Train	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	212	Southville Rd	Front	Southville Rd	196337.84	890702.6	42.26678	-71.5444
1	Ashley Casello (DRG)	2022/08/08		1456	2022/08/08	AsCa20220808151144	15:12:50	Birch, Black	Betula lenta	Open Space	No	10	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	212	Southville Rd	Front	Southville Rd	196345.42	890702.6	42.26679	-71.5443
1	Ashley Casello (DRG)	2022/08/08	borderline	1459	2022/08/08	AsCa20220808151740	15:18:42	Oak, Northern Red	Quercus rubra	Open Space	No	22	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	212	Southville Rd	Front	Southville Rd	196323.01	890702.4	42.26678	-71.5446
1	Ashley Casello (DRG)	2022/08/08	DBH estimated; poison ivy; borderline	1460	2022/08/08	AsCa20220808145039	14:53:20	Hemlock, Eastern	Tsuga canadensis	Open Space	No	6	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Minor	Low	Yes	210	Southville Rd	Front	Southville Rd	196384.6	890701	42.26677	-71.5438
1	Ashley Casello (DRG)	2022/08/11		1461	2022/08/08	AsCa20220808151454	20:16:21	Maple, Red	Acer rubrum	Open Space	No	4	Good	Train	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	212	Southville Rd	Front	Southville Rd	196336.89	890702.6	42.26678	-71.5444
1	Ashley Casello (DRG)	2022/08/08	borderline	1462	2022/08/08	AsCa20220808151306	15:13:33	Birch, Black	Betula lenta	Open Space	Yes	7	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	212	Southville Rd	Front	Southville Rd	196344.42	890701.2	42.26677	-71.5443
1	Ashley Casello (DRG)	2022/08/11		1463	2022/08/08	AsCa20220808151937	20:09:39	Oak, Black	Quercus velutina	Open Space	No	39	Poor	Remove	None	Dead And Dying Branches	None	Possible	Medium	Unlikely	Severe	Low	Yes	212	Southville Rd	Front	Southville Rd	196316.66	890703.9	42.2668	-71.5446
1	Ashley Casello (DRG)	2022/08/11	utility pole 38; DBH estimated; poison	1464	2022/08/08	AsCa20220808151339	20:16:21	Oak, Northern Red	Quercus rubra	Open Space	No	5	Good	Train	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	212	Southville Rd	Front	Southville Rd	196342.54	890702.5	42.26678	-71.5443
1	Greg Baldwin (DRG)	2022/08/18	ivy	1466	2022/08/09	AsCa20220809121031	12:46:23	Maple, Red	Acer rubrum	Wooded Space	No	9	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	124	Southville Rd	Front	Southville Rd	197637.8	890739.3	42.26712	-71.5286
1	Ashley Casello (DRG)	2022/08/09	utility pole 34; DBH estimated; poison	1467	2022/08/09	AsCa20220809084235	8:42:59	Maple, Sugar	Acer saccharum Fraxinus	Open Space	No	7	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	2	Cain Cir	Side	Southville Rd	196880.37	890704	42.2668	-71.5378
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 17; remove vines	1468	2022/08/09	AsCa20220809131640	12:45:50	Ash, White	americana	Wooded Space	No	12	Poor	Remove	None	Dead And Dying Branches	None	Possible	Medium	Unlikely	Minor	Low	Yes	154	Southville Rd	Front	Southville Rd	197480.29	890724.2	42.26698	-71.5305
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; behind fence; borderline	1469	2022/08/09	AsCa20220809093225	12:44:59	Ash, White	Fraxinus americana	Open Space	Yes	12	Fair	Routine Prune	Insect/Dis	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	182	Southville Rd	Front	Southville Rd	196829.71	890691.6	42.26669	-71.5384
1	Ashley Casello (DRG)	2022/08/09		1470	2022/08/09	AsCa20220809090433	9:05:04	Oak, Northern Red	Quercus rubra	Open Space	No	9	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	260	Parkerville Rd	Side	Southville Rd	197024.08	890686	42.26664	-71.5361
1	Ashley Casello (DRG)	2022/08/09		1471	2022/08/09	AsCa20220809080502	8:05:42	Maple, Sugar	Acer saccharum	Open Space	Yes	6	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	159	Southville Rd	Front	Southville Rd	196643.75	890708	42.26683	-71.5407
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 32; borderline; remove poison ivy	1472	2022/08/09	AsCa20220809145333	12:45:50	Maple, Red	Acer rubrum	Wooded Space	No	10	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Negligible	Low	Yes	154	Southville Rd	Front	Southville Rd	197368.22	890712.5	42.26688	-71.5319
1	Ashley Casello (DRG)	2022/08/11		1473	2022/08/09	AsCa20220809072325	20:16:21	Sassafras	Sassafras albidum	Open Space	No	4	Good	Train	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	212	Southville Rd	Front	Southville Rd	196307.14	890705.1	42.26681	-71.5448
1	Ashley Casello (DRG)	2022/08/09		1474	2022/08/09	AsCa20220809113241	11:33:09	Pine, Eastern White	Pinus strobus	Open Space	No	20	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	123	Southville Rd	Front	Southville Rd	197414.18	890731.3	42.26705	-71.5313
1	Ashley Casello (DRG)	2022/08/09	borderline	1475	2022/08/09	AsCa20220809110648	11:07:26	Maple, Red	Acer rubrum	Open Space	No	16	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Severe	Low	Yes	131	Southville Rd	Front	Southville Rd	197179.27	890696.5	42.26673	-71.5342
1	Greg Baldwin (DRG)	2022/08/18	utility pole 16; remove vines	1476	2022/08/09	AsCa20220809093701	12:44:59	Elm, American	Ulmus americana	Wooded Space	No	7	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	182	Southville Rd	Front	Southville Rd	196810.65	890692.6	42.2667	-71.5387
1	Ashley Casello (DRG)	2022/08/11		1477	2022/08/09	AsCa20220809084308	20:16:21	Maple, Sugar	Acer saccharum	Open Space	Yes	5	Fair	Train	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	2	Cain Cir	Side	Southville Rd	196881.37	890704	42.2668	-71.5378
1	Greg Baldwin (DRG)	2022/08/18	utility pole 34; DBH estimated; poison ivy; off ROW; leaning over road	1478	2022/08/09	AsCa20220809131902	12:45:50	Tree, Unknown	Unknown Tree	Wooded Space	No	10	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	154	Southville Rd	Front	Southville Rd	197477.41	890723.3	42.26698	-71.5306
1	Ashley Casello (DRG)	2022/08/09		1479	2022/08/09	AsCa20220809080546	8:06:31	Maple, Sugar	Acer saccharum	Open Space	No	6	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	159	Southville Rd	Front	Southville Rd	196647.22	890708.5	42.26684	-71.5406
1	Greg Baldwin (DRG)	2022/08/18	utility pole 38; DBH estimated; poison ivy	1480	2022/08/09	AsCa20220809121132	12:46:23	Oak, Northern Red	Quercus rubra	Wooded Space	No	15	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	124	Southville Rd	Front	Southville Rd	197633.86	890738.6	42.26711	-71.5287
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; behind fence; borderline	1481	2022/08/09	AsCa20220809090547	20:09:39	Ash, Green	Fraxinus pennsylvanica	Open Space	No	14	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	260	Parkerville Rd	Side	Southville Rd	197024.9	890686.4	42.26664	-71.5361
1	Ashley Casello (DRG)	2022/08/09		1482	2022/08/09	AsCa20220809113336	11:34:28	Oak, Northern Red	Quercus rubra	Open Space	Yes	23	Good	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	123	Southville Rd	Front	Southville Rd	197416.77	890731.3	42.26705	-71.5313
1	Ashley Casello (DRG)	2022/08/11		1483	2022/08/09	AsCa20220809072452	20:16:21	Sassafras	Sassafras albidum	Open Space	No	3	Good	Train	None	Tree Architecture	Low	Improbable	Low	Unlikely	Minor	Low	Yes	212	Southville Rd	Front	Southville Rd	196308.24	890705.3	42.26681	-71.5447
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 32; borderline	1484	2022/08/09	AsCa20220809145435	12:45:50	Elm, American	Ulmus americana	Wooded Space	No	9	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	154	Southville Rd	Front	Southville Rd	197369.22	890712.3	42.26688	-71.5319
1	Ashley Casello (DRG)	2022/08/09	borderline	1485	2022/08/09	AsCa20220809110800	11:09:23	Maple, Sugar	Acer saccharum	Open Space	No	11	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Severe	Low	Yes	131	Southville Rd	Front	Southville Rd	197189.45	890697.5	42.26674	-71.5341
1	Ashley Casello (DRG)	2022/08/11		1486	2022/08/09	AsCa20220809084356	20:09:39	Tree, Unknown	Unknown Tree	Open Space	Yes	12	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	2	Cain Cir	Side	Southville Rd	196882.9	890703.8	42.2668	-71.5378
1	Greg Baldwin (DRG)	2022/08/18	utility pole 16; DBH estimated; poison ivy	1487	2022/08/09	AsCa20220809093911	12:44:59	Maple, Red	Acer rubrum	Wooded Space	Yes	22	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Low	Unlikely	Severe	Low	Yes	182	Southville Rd	Front	Southville Rd	196799.36	890691.8	42.26669	-71.5388
1	Ashley Casello (DRG)	2022/08/09	DBH estimated; poison ivy; borderline	1488	2022/08/09	AsCa20220809080702	8:08:20	Maple, Sugar	Acer saccharum	Wooded Space	Yes	16	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	159	Southville Rd	Front	Southville Rd	196654.69	890708.7	42.26684	-71.5405
1	Greg Baldwin (DRG)	2022/08/18	utility pole 37; DBH estimated; poison ivy; off ROW	1489	2022/08/09	AsCa20220809121257	12:46:23	Tree, Unknown	Unknown Tree	Wooded Space	No	27	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	124	Southville Rd	Front	Southville Rd	197617.62	890734.7	42.26708	-71.5289

1	Ashley Casello (DRG)	2022/08/09	DBH estimated; poison ivy; borderline	1490	2022/08/09	AsCa20220809113446	11:36:03	Oak, Northern Red	Quercus rubra	Wooded Space	Yes	8	Fair	Routine Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Minor	Low	Yes	123	Southville Rd	Front	Southville Rd	197419.24	890731.9	42.26705	-71.5313
1	Greg Baldwin (DRG)	2022/08/18	utility pole 34; DBH estimated; poison ivy	1491	2022/08/09	AsCa20220809132035	12:45:50	Catalpa, Northern	Catalpa speciosa	Wooded Space	No	20	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	154	Southville Rd	Front	Southville Rd	197469.76	890722	42.26696	-71.5307
1	Ashley Casello (DRG)	2022/08/09	DBH estimated; behind fence; borderline	1492	2022/08/09	AsCa20220809090655	9:07:21	Maple, Sugar	Acer saccharum	Open Space	Yes	7	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	260	Parkerville Rd	Side	Southville Rd	197025.96	890686.6	42.26664	-71.536
1	Greg Baldwin (DRG)	2022/08/18	borderline	1493	2022/08/09	AsCa20220809111012	13:49:13	Maple, Sugar	Acer saccharum	Open Space	No	11	Fair	Routine Prune	Annual Ins	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	131	Southville Rd	Front	Southville Rd	197213.22	890701.8	42.26678	-71.5338
1	Moriah Day (DRG)	2022/08/23	borderline	1494	2022/08/09	AsCa20220809072543	10:30:44	Pine, Eastern White	Pinus strobus	Open Space	No	5	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Minor	Low	Yes	214	Southville Rd	Front	Southville Rd	196304.08	890704.1	42.2668	-71.5448
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 31; borderline	1495	2022/08/09	AsCa20220809145531	12:45:50	Maple, Red	Acer rubrum	Wooded Space	Yes	16	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	154	Southville Rd	Front	Southville Rd	197345.92	890710.5	42.26686	-71.5322
1	Ashley Casello (DRG)	2022/08/11		1496	2022/08/09	AsCa20220809084442	20:16:21	Maple, Sugar	Acer saccharum	Open Space	No	5	Good	Train	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	2	Cain Cir	Side	Southville Rd	196884.49	890703.8	42.2668	-71.5378
1	Greg Baldwin (DRG)	2022/08/18	utility pole 16; DBH estimated; poison ivy; borderline	1497	2022/08/09	AsCa20220809094254	13:20:54	Cherry, Black	Prunus serotina	Wooded Space	No	12	Poor	Remove	None	Dead And Dying Branches	None	Possible	Medium	Unlikely	Significant	Low	Yes	182	Southville Rd	Front	Southville Rd	196790.47	890691.8	42.26669	-71.5389
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; poison ivy; borderline	1498	2022/08/09	AsCa20220809080948	20:09:39	Tree, Unknown	Unknown Tree	Wooded Space	No	10	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	159	Southville Rd	Front	Southville Rd	196658.16	890708.9	42.26684	-71.5405
1	Greg Baldwin (DRG)	2022/08/18	utility pole 37; DBH estimated; poison ivy	1499	2022/08/09	AsCa20220809121352	12:46:23	Tree, Unknown	Unknown Tree	Wooded Space	No	30	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	124	Southville Rd	Front	Southville Rd	197611.62	890737.8	42.26711	-71.5289
1	Greg Baldwin (DRG)	2022/08/18	utility pole 34	1500	2022/08/09	AsCa20220809132339	12:45:50	Tree, Unknown	Unknown Tree	Wooded Space	No	14	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	154	Southville Rd	Front	Southville Rd	197453.99	890721.8	42.26696	-71.5309
1	Ashley Casello (DRG)	2022/08/09	DBH estimated; poison ivy	1501	2022/08/09	AsCa20220809113615	11:37:39	Catalpa, Northern	Catalpa speciosa	Wooded Space	Yes	25	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	123	Southville Rd	Front	Southville Rd	197421.18	890731.7	42.26705	-71.5313
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; behind fence	1502	2022/08/09	AsCa20220809090745	20:09:39	Ash, Green	Fraxinus pennsylvanica	Open Space	No	13	Poor	Remove	None	Dead And Dying Branches	None	Possible	Medium	Unlikely	Minor	Low	Yes	260	Parkerville Rd	Side	Southville Rd	197027.08	890685.4	42.26663	-71.536
1	Ashley Casello (DRG)	2022/08/09	borderline	1503	2022/08/09	AsCa20220809111118	11:12:18	Maple, Sugar	Acer saccharum	Open Space	No	13	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Severe	Low	Yes	131	Southville Rd	Front	Southville Rd	197218.69	890702.6	42.26679	-71.5337
1	Ashley Casello (DRG)	2022/08/09	borderline	1504	2022/08/09	AsCa20220809072657	7:27:28	Maple, Red	Acer rubrum	Open Space	No	7	Fair	Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Minor	Low	Yes	214	Southville Rd	Front	Southville Rd	196299.14	890705.2	42.26681	-71.5449
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 31	1505	2022/08/09	AsCa20220809145743	12:45:50	Tree, Unknown	Unknown Tree	Wooded Space	No	18	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	154	Southville Rd	Front	Southville Rd	197331.81	890708	42.26684	-71.5323
1	Ashley Casello (DRG)	2022/08/09		1506	2022/08/09	AsCa20220809084506	8:45:30	Maple, Sugar	Acer saccharum	Open Space	No	6	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	2	Cain Cir	Side	Southville Rd	196885.84	890703.6	42.2668	-71.5377
1	Ashley Casello (DRG)	2022/08/09		1507	2022/08/09	AsCa20220809081556	8:16:44	Maple, Sugar	Acer saccharum	Wooded Space	No	12	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	159	Southville Rd	Front	Southville Rd	196661.28	890708.2	42.26684	-71.5405
1	Greg Baldwin (DRG)	2022/08/18	utility pole 37; DBH estimated; poison ivy	1508	2022/08/09	AsCa20220809121441	12:46:23	Oak, Northern Red	Quercus rubra	Wooded Space	No	10	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	124	Southville Rd	Front	Southville Rd	197608.33	890737.1	42.2671	-71.529
1	Greg Baldwin (DRG)	2022/08/18	utility pole 15; DBH estimated; poison ivy; borderline	1509	2022/08/09	AsCa20220809094638	12:44:59	Maple, Sugar	Acer saccharum	Wooded Space	Yes	9	Poor	Remove	None	Dead And Dying Branches	None	Possible	Medium	Unlikely	Significant	Low	Yes	182	Southville Rd	Front	Southville Rd	196774.41	890692.6	42.2667	-71.5391
1	Ashley Casello (DRG)	2022/08/11		1510	2022/08/09	AsCa20220809114021	20:09:39	Tree, Unknown	Unknown Tree	Wooded Space	No	10	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Significant	Low	Yes	121	Southville Rd	Front	Southville Rd	197423.65	890732	42.26705	-71.5312
1	Greg Baldwin (DRG)	2022/08/18	utility pole 34; DBH estimated; poison ivy; borderline	1511	2022/08/09	AsCa20220809132545	12:45:50	Maple, Red	Acer rubrum	Wooded Space	Yes	13	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	154	Southville Rd	Front	Southville Rd	197448.23	890720.2	42.26695	-71.5309
1	Ashley Casello (DRG)	2022/08/09	DBH estimated; behind fence; borderline	1512	2022/08/09	AsCa20220809090947	9:10:22	Oak, Northern Red	Quercus rubra	Open Space	No	6	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	260	Parkerville Rd	Side	Southville Rd	197030.66	890686	42.26664	-71.536
1	Greg Baldwin (DRG)	2022/08/18	utility pole 31; borderline	1513	2022/08/09	AsCa20220809145933	12:45:50	Maple, Sugar	Acer saccharum	Wooded Space	No	9	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	154	Southville Rd	Front	Southville Rd	197324.98	890706.7	42.26683	-71.5324
1	Ashley Casello (DRG)	2022/08/11	borderline	1514	2022/08/09	AsCa20220809111307	20:09:39	Maple, Sugar	Acer saccharum	Wooded Space	No	10	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Medium	Unlikely	Severe	Low	Yes	127	Southville Rd	Front	Southville Rd	197235.4	890705.5	42.26681	-71.5335
1	Ashley Casello (DRG)	2022/08/11	borderline	1515	2022/08/09	AsCa20220809072740	20:16:21	Birch, Black	Betula lenta	Open Space	No	5	Good	Train	None	No Significant Defect	Low	Improbable	Low	Unlikely	Significant	Low	Yes	214	Southville Rd	Front	Southville Rd	196295.2	890704.4	42.2668	-71.5449
1	Ashley Casello (DRG)	2022/08/11		1516	2022/08/09	AsCa20220809084535	20:16:21	Maple, Sugar	Acer saccharum	Open Space	No	4	Good	Train	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	2	Cain Cir	Side	Southville Rd	196887.02	890703.9	42.2668	-71.5377
1	Greg Baldwin (DRG)	2022/08/18	start hedgerow; 5 trees in ROW	1517	2022/08/09	AsCa20220809081658	13:08:34	Cedar, Northern White	Thuja occidentalis	Open Space	Yes	2	Good	Routine Prune	None	Dead And Dying Branches	Low	Probable	Very Low	Unlikely	Negligible	Low	Yes	157	Southville Rd	Front	Southville Rd	196672.22	890707.8	42.26683	-71.5403
1	Greg Baldwin (DRG)	2022/08/18	utility pole 37; DBH estimated; poison ivy	1518	2022/08/09	AsCa20220809121530	12:46:23	Maple, Red	Acer rubrum	Wooded Space	Yes	14	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Severe	Low	Yes	124	Southville Rd	Front	Southville Rd	197607.27	890736.2	42.26709	-71.529
1	Greg Baldwin (DRG)	2022/08/18	utility pole 15; DBH estimated; poison ivy; borderline	1519	2022/08/09	AsCa20220809095013	12:44:59	Catalpa, Northern	Catalpa speciosa	Wooded Space	No	12	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	182	Southville Rd	Front	Southville Rd	196769.47	890693.3	42.2667	-71.5392
1	Ashley Casello (DRG)	2022/08/09		1520	2022/08/09	AsCa20220809114129	11:42:21	Elm, American	Ulmus americana	Wooded Space	Yes	8	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	121	Southville Rd	Front	Southville Rd	197427	890732.6	42.26706	-71.5312
1	Greg Baldwin (DRG)	2022/08/18	utility pole 33; DBH estimated; poison ivy; borderline	1521	2022/08/09	AsCa20220809132957	12:45:50	Oak, Northern Red	Quercus rubra	Wooded Space	No	14	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	154	Southville Rd	Front	Southville Rd	197419.55	890717.7	42.26693	-71.5313
1	Greg Baldwin (DRG)	2022/08/18	utility pole 31; borderline; DBH estimated; poison ivy	1522	2022/08/09	AsCa20220809150052	12:45:50	Maple, Sugar	Acer saccharum	Wooded Space	No	13	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	154	Southville Rd	Front	Southville Rd	197312.98	890704.5	42.26681	-71.5326
1	Ashley Casello (DRG)	2022/08/09		1523	2022/08/09	AsCa20220809072854	7:29:40	Maple, Red	Acer rubrum	Open Space	No	9	Good	Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Minor	Low	Yes	214	Southville Rd	Front	Southville Rd	196292.97	890706.2	42.26682	-71.5449
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; behind fence; borderline	1524	2022/08/09	AsCa20220809091241	20:09:39	Oak, Northern Red	Quercus rubra	Open Space	No	8	Poor	Remove	None	Tree Architecture	None	Improbable	Medium	Unlikely	Significant	Low	Yes	260	Parkerville Rd	Side	Southville Rd	197036.08	890685.3	42.26663	-71.5359
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; poison ivy	1525	2022/08/09	AsCa20220809084705	20:09:39	Ash, Green	Fraxinus pennsylvanica	Open Space	No	9	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Significant	Low	Yes	2	Cain Cir	Side	Southville Rd	196899.79	890702.7	42.26679	-71.5376
1	Ashley Casello (DRG)	2022/08/09		1526	2022/08/09	AsCa20220809111539	11:16:17	Maple, Sugar	Acer saccharum	Wooded Space	No	12	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	127	Southville Rd	Front	Southville Rd	197242.51	890706.8	42.26683	-71.5334
1	Greg Baldwin (DRG)	2022/08/18	end hedgerow; 5 trees in ROW	1527	2022/08/09	AsCa20220809081801	13:08:34	Cedar, Northern White	Thuja occidentalis	Open Space	No	2	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	157	Southville Rd	Front	Southville Rd	196676.34	890707.8	42.26683	-71.5403
1	Greg Baldwin (DRG)	2022/08/18	utility pole 37; DBH estimated; poison ivy	1528	2022/08/09	AsCa20220809121932	12:46:23	Oak, Northern Red	Quercus rubra	Wooded Space	Yes	12	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	124	Southville Rd	Front	Southville Rd	197596.74	890735.8	42.26709	-71.5291
1	Greg Baldwin (DRG)	2022/08/18	utility pole 15; borderline	1529	2022/08/09	AsCa20220809095119	12:44:59	Elm, American	Ulmus americana	Wooded Space	Yes	28	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	182	Southville Rd	Front	Southville Rd	196758.59	890693	42.2667	-71.5393
1	Greg Baldwin (DRG)	2022/08/18	utility pole 33	1530	2022/08/09	AsCa20220809133442	12:45:50	Maple, Red	Acer rubrum	Wooded Space	No	14	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Severe	Low	Yes	154	Southville Rd	Front	Southville Rd	197414.43	890717.7	42.26693	-71.5313
1	Ashley Casello (DRG)	2022/08/26	DBH estimated; poison ivy	1531	2022/08/09	AsCa20220809114233	12:27:07	Ash, White	Fraxinus americana	Wooded Space	No	13	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	121	Southville Rd	Front	Southville Rd	197429.71	890732.5	42.26706	-71.5312
1	Ashley Casello (DRG)	2022/08/09		1532	2022/08/09	AsCa20220809150239	15:09:16	Maple, Norway	Acer platanoides	Open Space	No	15	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	158	Southville Rd	Front	Southville Rd	197261.8	890696.7	42.26674	-71.5332
1	Ashley Casello (DRG)	2022/08/09	DBH estimated; poison ivy; borderline	1533	2022/08/09	AsCa20220809084937	8:51:42	Maple, Sugar	Acer saccharum	Open Space	No	8	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	2	Cain Cir	Side	Southville Rd	196914.2	890703	42.26679	-71.5374
1	Ashley Casello (DRG)	2022/08/09		1534	2022/08/09	AsCa20220809111627	11:16:58	Maple, Sugar	Acer saccharum	Wooded Space	Yes	5	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	127	Southville Rd	Front	Southville Rd	197245.4	890707.1	42.26683	-71.5334
1	Ashley Casello (DRG)	2022/08/09	DBH estimated; behind fence; borderline	1535	2022/08/09	AsCa20220809091400	9:16:15	Birch, River	Betula nigra	Open Space	Yes	8	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	260	Parkerville Rd	Side	Southville Rd	197041.08	890684.7	42.26663	-71.5359
1	Ashley Casello (DRG)	2022/08/09	borderline; DBH estimated; poison ivy	1536	2022/08/09	AsCa20220809073004	7:33:42	Oak, Northern Red	Quercus rubra	Open Space	No	28	Good	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	214	Southville Rd	Front	Southville Rd	196286.91	890706.8	42.26682	-71.545
1	Ashley Casello (DRG)	2022/08/09	DBH estimated; poison ivy; borderline	1537	2022/08/09	AsCa20220809082102	8:22:22	Maple, Red	Acer rubrum	Wooded Space	No	13	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Severe	Low	Yes	157	Southville Rd	Front	Southville Rd	196694.07	890709	42.26684	-71.5401

1	Greg Baldwin (DRG)	2022/08/18	utility pole 37; DBH estimated; poison ivy	1538	2022/08/09	AsCa20220809122159	12:46:23	Tree, Unknown	Unknown Tree	Wooded Space	No	13	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	124	Southville Rd	Front	Southville Rd	197587.85	890735	42.26708	-71.5292
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; thorns	1539	2022/08/09	AsCa20220809095537	20:09:39	Ash, White	Fraxinus americana	Wooded Space	No	10	Poor	Remove	None	Dead And Dying Branches	None	Possible	Medium	Unlikely	Minor	Low	Yes	188	Southville Rd	Front	Southville Rd	196719.88	890694.1	42.26671	-71.5398
1	Greg Baldwin (DRG)	2022/08/18	utility pole 33	1540	2022/08/09	AsCa20220809133800	12:45:50	Ash, White	Fraxinus americana	Wooded Space	No	16	Poor	Remove	None	Dead And Dying Branches	None	Possible	Medium	Unlikely	Minor	Low	Yes	154	Southville Rd	Front	Southville Rd	197411.55	890718.6	42.26693	-71.5314
1	Ashley Casello (DRG)	2022/08/09	DBH estimated; behind fence; borderline	1541	2022/08/09	AsCa20220809091620	9:16:58	Maple, Sugar	Acer saccharum	Open Space	No	11	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Severe	Low	Yes	260	Parkerville Rd	Side	Southville Rd	197036.78	890685.9	42.26664	-71.5359
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; poison ivy	1542	2022/08/09	AsCa20220809085146	20:16:21	Maple, Sugar	Acer saccharum	Open Space	No	4	Poor	Train	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Minor	Low	Yes	2	Cain Cir	Side	Southville Rd	196913.79	890702.6	42.26679	-71.5374
1	Ashley Casello (DRG)	2022/08/09	start hedgerow; 15 trees in ROW	1543	2022/08/09	AsCa20220809150925	15:10:59	Elm, Siberian	Ulmus pumila	Open Space	Yes	7	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	162	Southville Rd	Front	Southville Rd	197165.2	890680.5	42.26659	-71.5344
1	Ashley Casello (DRG)	2022/08/11	borderline; DBH estimated; poison ivy	1544	2022/08/09	AsCa20220809073349	20:16:21	Birch, Black	Betula lenta	Open Space	No	4	Fair	Train	None	Tree Architecture	Low	Improbable	Low	Unlikely	Minor	Low	Yes	214	Southville Rd	Front	Southville Rd	196285.67	890706.8	42.26682	-71.545
1	Ashley Casello (DRG)	2022/08/26		1545	2022/08/09	AsCa20220809114514	11:51:35	Ash, Green	Fraxinus pennsylvanica	Open Space	No	27	Fair	Prune	Insect/Dis	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	32	Highland St	Rear	Southville Rd	197467.42	890735.5	42.26709	-71.5307
1	Ashley Casello (DRG)	2022/08/09		1546	2022/08/09	AsCa20220809111727	11:18:14	Maple, Sugar	Acer saccharum	Wooded Space	No	8	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	127	Southville Rd	Front	Southville Rd	197249.63	890708.5	42.26684	-71.5333
1	Ashley Casello (DRG)	2022/08/09	DBH estimated; poison ivy; borderline	1547	2022/08/09	AsCa20220809082527	8:26:35	Maple, Sugar	Acer saccharum	Wooded Space	No	20	Fair	Routine Prune	Annual Ins	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	153	Southville Rd	Front	Southville Rd	196699.66	890708	42.26684	-71.54
1	Greg Baldwin (DRG)	2022/08/18	utility pole 36; DBH estimated; poison ivy	1548	2022/08/09	AsCa20220809130002	12:46:23	Maple, Red	Acer rubrum	Wooded Space	No	12	Poor	Remove	None	Dead And Dying Branches	None	Possible	Medium	Unlikely	Significant	Low	Yes	124	Southville Rd	Front	Southville Rd	197581.79	890734.2	42.26707	-71.5293
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 33	1549	2022/08/09	AsCa20220809143747	12:45:50	Elm, American	Ulmus americana	Wooded Space	No	19	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	154	Southville Rd	Front	Southville Rd	197402.02	890716.2	42.26691	-71.5315
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; vines	1550	2022/08/09	AsCa20220809095806	20:09:39	Ash, White	Fraxinus americana	Wooded Space	No	12	Poor	Remove	None	Dead And Dying Branches	None	Possible	Medium	Unlikely	Significant	Low	Yes	188	Southville Rd	Front	Southville Rd	196715.35	890693.7	42.26671	-71.5398
1	Greg Baldwin (DRG)	2022/08/18	end hedgerow; 15 trees in ROW; utility pole 26	1551	2022/08/09	AsCa20220809151115	12:46:56	Elm, Siberian	Ulmus pumila	Open Space	No	2	Fair	Train	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Negligible	Low	Yes	164	Southville Rd	Front	Southville Rd	197144.37	890677.9	42.26657	-71.5346
1	Ashley Casello (DRG)	2022/08/09	borderline; DBH estimated; poison ivy	1552	2022/08/09	AsCa20220809073425	7:35:10	Oak, Northern Red	Quercus rubra	Open Space	No	34	Good	Prune	None	Dead And Dying Branches	Low	Probable	Medium	Somewhat Likely	Minor	Low	Yes	214	Southville Rd	Front	Southville Rd	196281.2	890707.4	42.26683	-71.5451
1	Ashley Casello (DRG)	2022/08/11	borderline	1553	2022/08/09	AsCa20220809085339	20:16:21	Elm, American	Ulmus americana	Open Space	No	4	Fair	Train	None	Tree Architecture	Low	Improbable	Low	Unlikely	Minor	Low	Yes	2	Cain Cir	Side	Southville Rd	196913.73	890703.4	42.26679	-71.5374
1	Ashley Casello (DRG)	2022/08/09	DBH estimated; behind fence; borderline	1554	2022/08/09	AsCa20220809091749	9:18:18	Maple, Sugar	Acer saccharum	Open Space	No	6	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	260	Parkerville Rd	Side	Southville Rd	197044.78	890684.3	42.26662	-71.5358
1	Ashley Casello (DRG)	2022/08/09		1555	2022/08/09	AsCa20220809111819	11:23:37	Maple, Sugar	Acer saccharum	Open Space	Yes	6	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	127	Southville Rd	Front	Southville Rd	197251.4	890708.8	42.26684	-71.5333
1	Ashley Casello (DRG)	2022/08/09	DBH estimated; behind fence; borderline	1556	2022/08/09	AsCa20220809082705	8:29:58	Maple, Red	Acer rubrum	Open Space	No	24	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Significant	Low	No	153	Southville Rd	Front	Southville Rd	196722.43	890708	42.26684	-71.5397
1	Ashley Casello (DRG)	2022/08/11		1557	2022/08/09	AsCa20220809114832	20:09:39	Maple, Red	Acer rubrum	Open Space	No	25	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	High	Somewhat Likely	Severe	Moderate	Yes	26	Highland St	Side	Southville Rd	197536.66	890743.6	42.26716	-71.5299
1	Greg Baldwin (DRG)	2022/08/18	utility pole 36; DBH estimated; poison ivy	1558	2022/08/09	AsCa20220809130211	12:46:23	Maple, Red	Acer rubrum	Wooded Space	No	12	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Negligible	Low	Yes	124	Southville Rd	Front	Southville Rd	197578.24	890733.7	42.26707	-71.5294
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; shrubs	1559	2022/08/09	AsCa20220809100023	20:09:39	Ash, White	Fraxinus americana	Wooded Space	No	20	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	188	Southville Rd	Front	Southville Rd	196711.71	890694.6	42.26671	-71.5399
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; borderline; utility pole 33	1560	2022/08/09	AsCa20220809143955	12:45:50	Tree, Unknown	Unknown Tree	Wooded Space	No	11	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	154	Southville Rd	Front	Southville Rd	197399.55	890715.4	42.2669	-71.5315
1	Ashley Casello (DRG)	2022/08/09	borderline; DBH estimated; behind fence	1561	2022/08/09	AsCa20220809151354	15:16:15	Maple, Sugar	Acer saccharum	Open Space	No	7	Good	Routine Prune	None	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Negligible	Low	No	162	Southville Rd	Front	Southville Rd	197159.32	890679.1	42.26658	-71.5344
1	Ashley Casello (DRG)	2022/08/09		1562	2022/08/09	AsCa20220809111905	11:23:42	Oak, Pin	Quercus palustris	Open Space	No	14	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	127	Southville Rd	Front	Southville Rd	197258.22	890709.3	42.26685	-71.5332
1	Ashley Casello (DRG)	2022/08/09	borderline; remove vines	1563	2022/08/09	AsCa20220809092037	9:22:12	Pine, Eastern White	Pinus strobus	Open Space	No	16	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	262	Parkerville Rd	Side	Southville Rd	197001.89	890675.8	42.26655	-71.5363
1	Ashley Casello (DRG)	2022/08/09	DBH estimated; poison ivy; borderline	1564	2022/08/09	AsCa20220809085410	8:54:59	Maple, Sugar	Acer saccharum	Open Space	No	6	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	2	Cain Cir	Side	Southville Rd	196915.26	890702.8	42.26679	-71.5374
1	Ashley Casello (DRG)	2022/08/09	borderline	1565	2022/08/09	AsCa20220809073847	7:39:37	Oak, Northern Red	Quercus rubra	Wooded Space	No	21	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	173	Southville Rd	Front	Southville Rd	196314.15	890715.7	42.2669	-71.5447
1	Ashley Casello (DRG)	2022/08/09	DBH estimated; poison ivy	1566	2022/08/09	AsCa20220809083011	8:32:04	Oak, Pin	Quercus palustris	Open Space	No	17	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	149	Southville Rd	Front	Southville Rd	196814.67	890705.2	42.26681	-71.5386
1	Ashley Casello (DRG)	2022/08/09		1567	2022/08/09	AsCa20220809115437	11:56:59	Oak, Northern Red	Quercus rubra	Open Space	No	32	Fair	Prune	None	Dead And Dying Branches	Low	Probable	Medium	Somewhat Likely	Minor	Low	Yes	26	Highland St	Side	Southville Rd	197651.33	890752.9	42.26724	-71.5285
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; shrubs	1568	2022/08/09	AsCa20220809100239	20:09:39	Ash, White	Fraxinus americana	Wooded Space	No	8	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	188	Southville Rd	Front	Southville Rd	196707.71	890694.4	42.26671	-71.5399
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; borderline; utility pole 32	1569	2022/08/09	AsCa20220809144216	12:45:50	Maple, Red	Acer rubrum	Wooded Space	Yes	9	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	154	Southville Rd	Front	Southville Rd	197395.9	890715.5	42.26691	-71.5316
1	Ashley Casello (DRG)	2022/08/09	borderline; DBH estimated; behind fence	1570	2022/08/09	AsCa20220809151527	15:19:05	Maple, Sugar	Acer saccharum	Open Space	No	6	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Significant	Low	No	162	Southville Rd	Front	Southville Rd	197155.2	890677.8	42.26657	-71.5345
1	Greg Baldwin (DRG)	2022/08/18	utility pole 36; DBH estimated; poison ivy; borderline	1571	2022/08/09	AsCa20220809130346	12:46:23	Tree, Unknown	Unknown Tree	Wooded Space	No	16	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	124	Southville Rd	Front	Southville Rd	197561.47	890731.8	42.26705	-71.5296
1	Ashley Casello (DRG)	2022/08/09	borderline	1572	2022/08/09	AsCa20220809092232	9:23:07	Spruce, Blue	Picea pungens	Open Space	No	8	Good	Routine Prune	None	Dead And Dying Branches	Low	Probable	Very Low	Unlikely	Negligible	Low	Yes	262	Parkerville Rd	Side	Southville Rd	196997.65	890676.4	42.26655	-71.5364
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; poison ivy; borderline	1573	2022/08/09	AsCa20220809085511	20:09:39	Tree, Unknown	Unknown Tree	Open Space	No	5	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Minor	Low	Yes	2	Cain Cir	Side	Southville Rd	196916.08	890702.9	42.26679	-71.5374
1	Ashley Casello (DRG)	2022/08/09	borderline	1574	2022/08/09	AsCa20220809112027	11:21:21	Hickory, Shagbark	Carya ovata	Open Space	No	9	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Severe	Low	Yes	127	Southville Rd	Front	Southville Rd	197260.05	890710.5	42.26686	-71.5332
1	Ashley Casello (DRG)	2022/08/09	borderline	1575	2022/08/09	AsCa20220809115739	11:58:50	Oak, Northern Red	Quercus rubra	Open Space	No	25	Good	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Severe	Low	Yes	26	Highland St	Side	Southville Rd	197673.1	890756.3	42.26727	-71.5282
1	Ashley Casello (DRG)	2022/08/11	borderline	1576	2022/08/09	AsCa20220809083355	20:09:39	Tree, Unknown	Unknown Tree	Open Space	No	11	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	2	Cain Cir	Side	Southville Rd	196876.96	890703.9	42.2668	-71.5379
1	Ashley Casello (DRG)	2022/08/09	borderline	1577	2022/08/09	AsCa20220809073946	7:40:59	Oak, Northern Red	Quercus rubra	Wooded Space	No	15	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	173	Southville Rd	Front	Southville Rd	196319.5	890715.7	42.2669	-71.5446
1	Ashley Casello (DRG)	2022/08/11		1578	2022/08/09	AsCa20220809100351	20:09:39	Ash, White	Fraxinus americana	Wooded Space	No	18	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	188	Southville Rd	Front	Southville Rd	196703.88	890693.7	42.26671	-71.54
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 32	1579	2022/08/09	AsCa20220809144312	12:45:50	Hickory, Shagbark	Carya ovata	Wooded Space	No	18	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Severe	Low	Yes	154	Southville Rd	Front	Southville Rd	197394.25	890717.1	42.26692	-71.5316
1	Ashley Casello (DRG)	2022/08/09	borderline; DBH estimated; behind fence	1580	2022/08/09	AsCa20220809151622	15:19:05	Maple, Sugar	Acer saccharum	Open Space	No	6	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	No	162	Southville Rd	Front	Southville Rd	197153.61	890677.2	42.26656	-71.5345
1	Greg Baldwin (DRG)	2022/08/18	utility pole 35; DBH estimated; poison ivy	1582	2022/08/09	AsCa20220809130543	12:46:23	Tree, Unknown	Unknown Tree	Wooded Space	No	25	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	124	Southville Rd	Front	Southville Rd	197540.23	890729.4	42.26703	-71.5298
1	Ashley Casello (DRG)	2022/08/09	DBH estimated; behind fence; borderline	1583	2022/08/09	AsCa20220809090007	9:01:20	Ash, Green	Fraxinus pennsylvanica	Open Space	Yes	12	Fair	Routine Prune	Insect/Dis	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	260	Parkerville Rd	Side	Southville Rd	197016.22	890687	42.26665	-71.5362
1	Ashley Casello (DRG)	2022/08/09	borderline	1584	2022/08/09	AsCa20220809112133	11:22:03	Maple, Sugar	Acer saccharum	Open Space	No	7	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Significant	Low	Yes	127	Southville Rd	Front	Southville Rd	197259.28	890711.3	42.26687	-71.5332

1	Greg Baldwin (DRG)	2022/08/19		1585	2022/08/09	AsCa20220809115950	14:29:20	Oak, Scarlet	Quercus coccinea	Open Space	No	32	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	26	Highland St	Side	Southville Rd	197700.28	890758.7	42.2673	-71.5279
1	Ashley Casello (DRG)	2022/08/09	borderline	1586	2022/08/09	AsCa20220809083456	8:35:49	Maple, Sugar	Acer saccharum	Open Space	No	8	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	2	Cain Cir	Side	Southville Rd	196878.37	890703.7	42.2668	-71.5378
1	Ashley Casello (DRG)	2022/08/09		1587	2022/08/09	AsCa20220809074424	7:46:07	Hickory, Pignut	Carya glabra	Open Space	No	29	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Severe	Low	Yes	169	Southville Rd	Front	Southville Rd	196449.39	890714.4	42.26689	-71.543
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 32	1588	2022/08/09	AsCa20220809144434	12:45:50	Tree, Unknown	Unknown Tree	Wooded Space	No	15	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	154	Southville Rd	Front	Southville Rd	197391.13	890716.4	42.26691	-71.5316
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; shrubs	1589	2022/08/09	AsCa20220809100558	20:09:39	Ash, White	Fraxinus americana	Wooded Space	No	17	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	188	Southville Rd	Front	Southville Rd	196693.7	890694.2	42.26671	-71.5401
1	Greg Baldwin (DRG)	2022/08/18	borderline; DBH estimated; behind fence	1590	2022/08/09	AsCa20220809151657	12:46:56	Maple, Sugar	Acer saccharum	Open Space	No	7	Poor	Remove	None	Dead And Dying Branches	None	Possible	Low	Unlikely	Minor	Low	No	164	Southville Rd	Front	Southville Rd	197143.61	890676.2	42.26655	-71.5346
1	Ashley Casello (DRG)	2022/08/11	top half broken off and suspended	1591	2022/08/09	AsCa20220809083609	20:09:39	Tree, Unknown	Unknown Tree	Open Space	No	8	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Significant	Low	Yes	2	Cain Cir	Side	Southville Rd	196878.2	890702.8	42.26679	-71.5378
1	Ashley Casello (DRG)	2022/08/11	borderline; DBH estimated; behind fence	1592	2022/08/09	AsCa20220809112215	20:09:39	Maple, Sugar	Acer saccharum	Open Space	No	30	Dead	Remove	None	No Significant Defect	None	Possible	High	Somewhat Likely	Severe	Moderate	Yes	127	Southville Rd	Front	Southville Rd	197250.93	890709.8	42.26685	-71.5333
1	Greg Baldwin (DRG)	2022/08/19	DBH estimated; poison ivy; remove vines	1593	2022/08/09	AsCa20220809120235	14:18:06	Oak, Scarlet	Quercus coccinea	Wooded Space	No	15	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	122	Southville Rd	Front	Southville Rd	197724.57	890748.3	42.2672	-71.5276
1	Ashley Casello (DRG)	2022/08/09		1594	2022/08/09	AsCa20220809092448	9:26:21	Oak, Pin	Quercus palustris	Open Space	Yes	14	Fair	Routine Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Minor	Low	Yes	174	Southville Rd	Front	Southville Rd	196963.89	890682.5	42.26661	-71.5368
1	Greg Baldwin (DRG)	2022/08/18	utility pole 35; DBH estimated; poison ivy; borderline	1595	2022/08/09	AsCa20220809130730	12:46:23	Tree, Unknown	Unknown Tree	Wooded Space	No	16	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	124	Southville Rd	Front	Southville Rd	197531.88	890729.8	42.26703	-71.5299
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; behind fence; borderline	1596	2022/08/09	AsCa20220809090145	20:16:21	Maple, Sugar	Acer saccharum	Open Space	No	4	Fair	Train	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	260	Parkerville Rd	Side	Southville Rd	197021.05	890686.7	42.26664	-71.5361
1	Ashley Casello (DRG)	2022/08/09		1597	2022/08/09	AsCa20220809074855	7:49:38	Elm, American	Ulmus americana	Open Space	No	13	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	167	Southville Rd	Front	Southville Rd	196480.68	890712.8	42.26688	-71.5427
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 32	1598	2022/08/09	AsCa20220809144825	12:45:50	Ash, Green	Fraxinus pennsylvanica	Wooded Space	No	16	Fair	Routine Prune	Insect/Dis	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	154	Southville Rd	Front	Southville Rd	197388.25	890715.5	42.26691	-71.5317
1	Greg Baldwin (DRG)	2022/08/18	borderline; DBH estimated; behind fence; multiple saplings in area	1599	2022/08/09	AsCa20220809151913	12:46:56	Maple, Sugar	Acer saccharum	Open Space	No	4	Fair	Train	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	164	Southville Rd	Front	Southville Rd	197141.25	890675.4	42.26654	-71.5347
1	Ashley Casello (DRG)	2022/08/09	DBH estimated; shrubs; borderline	1600	2022/08/09	AsCa20220809100706	10:08:52	Maple, Silver	Acer saccharinum	Open Space	No	60	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Severe	Low	Yes	188	Southville Rd	Front	Southville Rd	196685.53	890694.4	42.26671	-71.5402
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; behind fence;	1601	2022/08/09	AsCa20220809083733	20:16:21	Maple, Sugar	Acer saccharum	Open Space	No	5	Fair	Train	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	2	Cain Cir	Side	Southville Rd	196877.61	890702.5	42.26679	-71.5378
1	Ashley Casello (DRG)	2022/08/11	borderline	1602	2022/08/09	AsCa20220809090213	20:09:39	Ash, Green	Fraxinus pennsylvanica	Open Space	No	6	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Significant	Low	Yes	260	Parkerville Rd	Side	Southville Rd	197022.16	890686.8	42.26665	-71.5361
1	Ashley Casello (DRG)	2022/08/09	remove vines	1603	2022/08/09	AsCa20220809092853	9:29:37	Catalpa, Northern	Catalpa speciosa	Wooded Space	No	7	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	178	Southville Rd	Front	Southville Rd	196868.59	890690.3	42.26668	-71.538
1	Greg Baldwin (DRG)	2022/08/18	utility pole 35; DBH estimated; poison ivy	1604	2022/08/09	AsCa20220809131032	12:46:23	Tree, Unknown	Unknown Tree	Wooded Space	No	30	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	124	Southville Rd	Front	Southville Rd	197516.06	890727.8	42.26702	-71.5301
1	Ashley Casello (DRG)	2022/08/09		1605	2022/08/09	AsCa20220809112402	11:24:35	Maple, Sugar	Acer saccharum	Open Space	No	7	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	127	Southville Rd	Front	Southville Rd	197264.46	890711.1	42.26687	-71.5332
1	Greg Baldwin (DRG)	2022/08/19	DBH estimated; poison ivy	1606	2022/08/09	AsCa20220809120448	14:20:17	Maple, Red	Acer rubrum	Wooded Space	No	8	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Medium	Unlikely	Significant	Low	Yes	122	Southville Rd	Front	Southville Rd	197696.8	890745.4	42.26718	-71.5279
1	Ashley Casello (DRG)	2022/08/11		1607	2022/08/09	AsCa20220809075746	20:32:27	Ash, White	Fraxinus americana	Open Space	No	25	Fair	Prune	Insect/Dis	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	3	Fiddleneck Ln	Side	Southville Rd	196594.69	890709.9	42.26685	-71.5413
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 32; borderline	1608	2022/08/09	AsCa20220809145004	12:45:50	Tree, Unknown	Unknown Tree	Wooded Space	No	17	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	154	Southville Rd	Front	Southville Rd	197378.54	890712.7	42.26688	-71.5318
1	Ashley Casello (DRG)	2022/08/09	borderline	1609	2022/08/09	AsCa20220809101100	10:12:14	Oak, White	Quercus alba	Open Space	No	36	Good	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	196	Southville Rd	Front	Southville Rd	196580.58	890696.4	42.26673	-71.5414
1	Greg Baldwin (DRG)	2022/08/18	borderline; DBH estimated; behind fence	1610	2022/08/09	AsCa20220809151957	12:46:56	Ash, White	Fraxinus americana	Open Space	No	13	Fair	Routine Prune	Insect/Dis	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	164	Southville Rd	Front	Southville Rd	197139.96	890675.1	42.26654	-71.5347
1	Greg Baldwin (DRG)	2022/08/18	utility pole 35; DBH estimated; poison ivy; borderline	1611	2022/08/09	AsCa20220809131239	12:46:23	Elm, American	Ulmus americana	Wooded Space	No	10	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Negligible	Low	Yes	124	Southville Rd	Front	Southville Rd	197516.53	890727.4	42.26701	-71.5301
1	Ashley Casello (DRG)	2022/08/09	remove vines	1612	2022/08/09	AsCa20220809092952	9:30:40	Catalpa, Northern	Catalpa speciosa	Wooded Space	No	8	Good	Routine Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Negligible	Low	Yes	178	Southville Rd	Front	Southville Rd	196866.01	890690.7	42.26668	-71.538
1	Greg Baldwin (DRG)	2022/08/19	DBH estimated; poison ivy	1613	2022/08/09	AsCa20220809120721	14:21:28	Maple, Red	Acer rubrum	Wooded Space	Yes	14	Fair	Routine Prune	None	Broken And/Or Hanging Branches	Low	Imminent	Low	Somewhat Likely	Minor	Low	Yes	122	Southville Rd	Front	Southville Rd	197663.98	890741.3	42.26714	-71.5283
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; behind fence; borderline	1614	2022/08/09	AsCa20220809090320	20:16:21	Cherry, Black	Prunus serotina	Open Space	No	5	Good	Train	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	260	Parkerville Rd	Side	Southville Rd	197022.75	890686.5	42.26664	-71.5361
1	Ashley Casello (DRG)	2022/08/11		1615	2022/08/09	AsCa20220809083838	20:09:39	Tree, Unknown	Unknown Tree	Open Space	Yes	4	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Minor	Low	Yes	2	Cain Cir	Side	Southville Rd	196877.2	890702.2	42.26678	-71.5379
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 32; borderline	1616	2022/08/09	AsCa20220809145223	12:45:50	Maple, Red	Acer rubrum	Wooded Space	Yes	14	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	154	Southville Rd	Front	Southville Rd	197374.04	890713.3	42.26689	-71.5318
1	Ashley Casello (DRG)	2022/08/11		1617	2022/08/09	AsCa20220809080032	20:09:39	Tree, Unknown	Unknown Tree	Open Space	No	41	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	3	Fiddleneck Ln	Side	Southville Rd	196615.75	890709.5	42.26685	-71.541
1	Ashley Casello (DRG)	2022/08/09	borderline	1618	2022/08/09	AsCa20220809112544	11:27:30	Locust, Black	Robinia pseudoacacia	Open Space	No	20	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	2	Harrington Ct	Side	Southville Rd	197328.99	890721.4	42.26696	-71.5324
1	Ashley Casello (DRG)	2022/08/09	borderline	1619	2022/08/09	AsCa20220809110442	11:06:23	Walnut, Black	Juglans nigra	Open Space	No	13	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Severe	Low	Yes	131	Southville Rd	Front	Southville Rd	197177.04	890695.7	42.26673	-71.5342
1	Greg Baldwin (DRG)	2022/08/18	borderline; DBH estimated; behind fence	1620	2022/08/09	AsCa20220809152127	12:46:56	Ash, White	Fraxinus americana	Open Space	No	8	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	164	Southville Rd	Front	Southville Rd	197139.31	890675.7	42.26655	-71.5347
1	Ashley Casello (DRG)	2022/08/09	multiple saplings in area	1621	2022/08/09	AsCa20220809093043	9:31:44	Elm, American	Ulmus americana	Wooded Space	Yes	5	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	178	Southville Rd	Front	Southville Rd	196863.01	890690.2	42.26668	-71.538
1	Greg Baldwin (DRG)	2022/08/18	utility pole 34	1622	2022/08/09	AsCa20220809131426	12:46:23	Maple, Red	Acer rubrum	Wooded Space	No	19	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	124	Southville Rd	Front	Southville Rd	197489.52	890724.8	42.26699	-71.5304
1	Greg Baldwin (DRG)	2022/08/19	utility pole 38	1623	2022/08/09	AsCa20220809120834	14:21:59	Maple, Red	Acer rubrum	Wooded Space	No	8	Poor	Remove	None	Dead And Dying Branches	None	Possible	Low	Unlikely	Significant	Low	Yes	124	Southville Rd	Front	Southville Rd	197643.68	890740	42.26713	-71.5286
1	Ashley Casello (DRG)	2022/08/09		1624	2022/08/09	AsCa20220809080151	8:03:34	Oak, White	Quercus alba	Open Space	No	45	Good	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	159	Southville Rd	Front	Southville Rd	196621.45	890709.1	42.26685	-71.541
1	Ashley Casello (DRG)	2022/08/09	borderline	1625	2022/08/09	AsCa20220809112946	11:30:18	Locust, Black	Robinia pseudoacacia	Open Space	No	6	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	125	Southville Rd	Front	Southville Rd	197344.11	890723.7	42.26698	-71.5322
1	Greg Baldwin (DRG)	2022/08/19		1626	2022/08/10	AsCa20220810072134	14:12:22	Ash, Green	Fraxinus pennsylvanica	Open Space	No	17	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	116	Southville Rd	Front	Southville Rd	197888.74	890764	42.26734	-71.5256
1	Ashley Casello (DRG)	2022/08/10		1627	2022/08/10	AsCa20220810093228	9:33:29	Oak, Northern Red	Quercus rubra	Open Space	No	30	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	39	Southville Rd	Front	Southville Rd	198910.38	890855.5	42.26817	-71.5132
1	Ashley Casello (DRG)	2022/08/10		1628	2022/08/10	AsCa20220810095240	9:53:37	Oak, Northern Red	Quercus rubra	Open Space	No	13	Good	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	23	Southville Rd	Front	Southville Rd	199090.44	890790.6	42.26758	-71.511
1	Ashley Casello (DRG)	2022/08/10		1629	2022/08/10	AsCa20220810075514	7:56	Pine, Eastern White	Pinus strobus	Open Space	No	18	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	4	Highland St	Side	Southville Rd	197888.16	890776.4	42.26745	-71.5256
1	Ashley Casello (DRG)	2022/08/10	borderline	1630	2022/08/10	AsCa20220810100849	10:09:40	Maple, Red	Acer rubrum	Open Space	No	19	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Severe	Low	Yes	15	Southville Rd	Front	Southville Rd	199236.09	890743.5	42.26716	-71.5093
1	Greg Baldwin (DRG)	2022/08/18		1631	2022/08/10	AsCa20220810112422	13:08:34	Cedar, Northern White	Thuja occidentalis	Open Space	Yes	1	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	106	Southville Rd	Front	Southville Rd	198212.24	890828.6	42.26793	-71.5217
1	Greg Baldwin (DRG)	2022/08/18	utility pole 74; DBH estimated; poison ivy	1632	2022/08/10	AsCa20220810124719	12:47:43	Maple, Red	Acer rubrum	Wooded Space	Yes	14	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	20	Southville Rd	Front	Southville Rd	199112.74	890767.6	42.26738	-71.5108

1	Ashley Casello (DRG)	2022/08/10	DBH estimated; behind fence; borderline	1633	2022/08/10	AsCa20220810103345	10:34:34	Hickory, Shagbark	Carya ovata	Open Space	No	12	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Severe	Low	No	1	Constitution Dr	Side	Southville Rd	199407.42	890702.6	42.26679	-71.5072
1	Ashley Casello (DRG)	2022/08/10	borderline; DBH estimated; behind stonewall	1634	2022/08/10	AsCa20220810090849	9:09:35	Oak, Northern Red	Quercus rubra	Open Space	No	9	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	51	Southville Rd	Front	Southville Rd	198718.03	890911.8	42.26868	-71.5155
1	Ashley Casello (DRG)	2022/08/10		1635	2022/08/10	AsCa20220810115906	11:59:52	Oak, Northern Red	Quercus rubra	Wooded Space	No	20	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	50	Southville Rd	Front	Southville Rd	198772.72	890888.8	42.26847	-71.5149
1	Ashley Casello (DRG)	2022/08/10		1636	2022/08/10	AsCa20220810093342	9:34:17	Maple, Red	Acer rubrum	Open Space	No	20	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	39	Southville Rd	Front	Southville Rd	198916.03	890853.7	42.26815	-71.5131
1	Greg Baldwin (DRG)	2022/08/19		1637	2022/08/10	AsCa20220810072345	14:13:15	Oak, Northern Red	Quercus rubra	Open Space	No	58	Good	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	118	Southville Rd	Front	Southville Rd	197837.91	890758.4	42.26729	-71.5262
1	Ashley Casello (DRG)	2022/08/10	borderline	1638	2022/08/10	AsCa20220810095524	9:56:15	Oak, Northern Red	Quercus rubra	Open Space	No	23	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	23	Southville Rd	Front	Southville Rd	199104.15	890785.8	42.26754	-71.5109
1	Ashley Casello (DRG)	2022/08/10		1639	2022/08/10	AsCa20220810083300	8:34:09	Elm, American	Ulmus americana	Wooded Space	No	6	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	93	Southville Rd	Front	Southville Rd	197951.69	890782.9	42.26751	-71.5248
1	Ashley Casello (DRG)	2022/08/10	DBH estimated; poison ivy	1640	2022/08/10	AsCa20220810120010	12:01:04	Oak, Black	Quercus velutina	Wooded Space	No	26	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	50	Southville Rd	Front	Southville Rd	198768.54	890890.2	42.26848	-71.5149
1	Ashley Casello (DRG)	2022/08/10	borderline; DBH estimated; behind stonewall	1641	2022/08/10	AsCa20220810090939	9:10:29	Maple, Red	Acer rubrum	Open Space	Yes	12	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Severe	Low	No	51	Southville Rd	Front	Southville Rd	198724.92	890911.5	42.26867	-71.5155
1	Greg Baldwin (DRG)	2022/08/18		1642	2022/08/10	AsCa20220810112517	13:08:34	Cedar, Northern White	Thuja occidentalis	Open Space	Yes	1	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	106	Southville Rd	Front	Southville Rd	198207.71	890827.5	42.26792	-71.5217
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 74	1643	2022/08/10	AsCa20220810124906	12:47:43	Oak, Northern Red	Quercus rubra	Wooded Space	No	8	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	20	Southville Rd	Front	Southville Rd	199118.15	890765.5	42.26736	-71.5107
1	Ashley Casello (DRG)	2022/08/10	DBH estimated; behind fence	1644	2022/08/10	AsCa20220810103446	10:35:43	Maple, Red	Acer rubrum	Open Space	Yes	14	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Severe	Low	No	1	Constitution Dr	Side	Southville Rd	199408.01	890701	42.26678	-71.5072
1	Ashley Casello (DRG)	2022/08/10	borderline	1645	2022/08/10	AsCa20220810101019	10:11:26	Oak, Northern Red	Quercus rubra	Open Space	No	25	Good	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	15	Southville Rd	Front	Southville Rd	199243.73	890741.7	42.26715	-71.5092
1	Ashley Casello (DRG)	2022/08/10		1646	2022/08/10	AsCa20220810093451	9:35:43	Maple, Norway	Acer platanoides	Open Space	No	11	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	39	Southville Rd	Front	Southville Rd	198936.27	890846	42.26808	-71.5129
1	Greg Baldwin (DRG)	2022/08/19	DBH estimated; poison ivy	1647	2022/08/10	AsCa20220810072556	14:14:22	Maple, Red	Acer rubrum	Wooded Space	No	23	Poor	Remove	None	Dead And Dying Branches	None	Possible	Medium	Unlikely	Significant	Low	Yes	122	Southville Rd	Front	Southville Rd	197814.56	890756.8	42.26728	-71.5265
1	Greg Baldwin (DRG)	2022/08/18	borderline; start hedgerow; 8 trees in ROW	1648	2022/08/10	AsCa20220810095658	13:08:34	Cedar, Northern White	Thuja occidentalis	Open Space	Yes	2	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	19	Southville Rd	Front	Southville Rd	199147.85	890769.7	42.2674	-71.5103
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; poison ivy	1649	2022/08/10	AsCa20220810083438	20:09:39	Tree, Unknown	Unknown Tree	Open Space	No	11	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Significant	Low	Yes	93	Southville Rd	Front	Southville Rd	197980.63	890785.1	42.26753	-71.5245
1	Ashley Casello (DRG)	2022/08/10	DBH estimated; poison ivy	1650	2022/08/10	AsCa20220810120133	12:01:54	Oak, Northern Red	Quercus rubra	Wooded Space	No	27	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	50	Southville Rd	Front	Southville Rd	198755.95	890892.9	42.26851	-71.5151
1	Ashley Casello (DRG)	2022/08/10	borderline	1651	2022/08/10	AsCa20220810091047	9:11:56	Oak, Northern Red	Quercus rubra	Open Space	No	11	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	49	Southville Rd	Front	Southville Rd	198741.27	890910	42.26866	-71.5153
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 75	1652	2022/08/10	AsCa20220810125156	12:47:43	Oak, Northern Red	Quercus rubra	Wooded Space	No	30	Good	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	20	Southville Rd	Front	Southville Rd	199186.33	890744	42.26717	-71.5099
1	Ashley Casello (DRG)	2022/08/10	borderline	1653	2022/08/10	AsCa20220810112753	11:28:34	Maple, Red	Acer rubrum	Open Space	No	8	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	106	Southville Rd	Front	Southville Rd	198193.83	890823.1	42.26788	-71.5219
1	Greg Baldwin (DRG)	2022/08/18	borderline; start hedgerow; 12 trees in ROW	1654	2022/08/10	AsCa20220810101216	13:08:34	Cedar, Northern White	Thuja occidentalis	Open Space	Yes	2	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	11	Southville Rd	Front	Southville Rd	199259.09	890736.7	42.2671	-71.509
1	Ashley Casello (DRG)	2022/08/10	DBH estimated; behind fence	1655	2022/08/10	AsCa20220810103545	10:36:19	Hickory, Shagbark	Carya ovata	Open Space	No	10	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Severe	Low	No	1	Constitution Dr	Side	Southville Rd	199409.18	890701.9	42.26679	-71.5072
1	Ashley Casello (DRG)	2022/08/10		1656	2022/08/10	AsCa20220810093603	9:37:04	Maple, Norway	Acer platanoides	Open Space	No	19	Good	Routine Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Minor	Low	Yes	39	Southville Rd	Front	Southville Rd	198944.56	890843.2	42.26806	-71.5128
1	Ashley Casello (DRG)	2022/08/10	DBH estimated; poison ivy	1657	2022/08/10	AsCa20220810120208	12:02:48	Oak, Northern Red	Quercus rubra	Wooded Space	No	16	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	50	Southville Rd	Front	Southville Rd	198748.6	890894.6	42.26852	-71.5152
1	Greg Baldwin (DRG)	2022/08/18	borderline; end hedgerow; 8 trees in ROW	1658	2022/08/10	AsCa20220810095816	13:08:34	Cedar, Northern White	Thuja occidentalis	Open Space	Yes	1	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	19	Southville Rd	Front	Southville Rd	199160.85	890765.5	42.26736	-71.5102
1	Ashley Casello (DRG)	2022/08/10	borderline	1659	2022/08/10	AsCa20220810091207	9:12:52	Pine, Eastern White	Pinus strobus	Open Space	No	7	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	49	Southville Rd	Front	Southville Rd	198740.39	890910.1	42.26866	-71.5153
1	Greg Baldwin (DRG)	2022/08/19	DBH estimated; poison ivy; borderline	1660	2022/08/10	AsCa20220810073107	14:15:18	Maple, Red	Acer rubrum	Wooded Space	No	10	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	122	Southville Rd	Front	Southville Rd	197807.91	890754.3	42.26726	-71.5266
1	Ashley Casello (DRG)	2022/08/10	borderline	1661	2022/08/10	AsCa20220810084102	8:41:54	Hickory, Shagbark	Carya ovata	Open Space	No	12	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Negligible	Low	Yes	2	North St	Side	Southville Rd	198219.54	890844.6	42.26807	-71.5216
1	Greg Baldwin (DRG)	2022/08/18	borderline; end hedgerow; 12 trees in ROW	1662	2022/08/10	AsCa20220810101413	13:08:34	Cedar, Northern White	Thuja occidentalis	Open Space	Yes	3	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	11	Southville Rd	Front	Southville Rd	199280.12	890732.8	42.26707	-71.5087
1	Ashley Casello (DRG)	2022/08/10	borderline	1663	2022/08/10	AsCa20220810112847	11:29:18	Maple, Red	Acer rubrum	Open Space	No	8	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	106	Southville Rd	Front	Southville Rd	198188.77	890821.8	42.26786	-71.522
1	Ashley Casello (DRG)	2022/08/10	DBH estimated; poison ivy; borderline; remove vines	1664	2022/08/10	AsCa20220810093755	9:39:37	Pine, Eastern White	Pinus strobus	Open Space	No	13	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	2	Liberty Dr	Side	Southville Rd	198986.62	890828.6	42.26793	-71.5123
1	Ashley Casello (DRG)	2022/08/10		1665	2022/08/10	AsCa20220810103642	10:37:37	Oak, Northern Red	Quercus rubra	Open Space	Yes	9	Good	Routine Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Negligible	Low	Yes	1	Constitution Dr	Side	Southville Rd	199415.42	890700	42.26677	-71.5071
1	Greg Baldwin (DRG)	2022/08/18	utility pole 75	1666	2022/08/10	AsCa20220810125621	12:47:43	Oak, Northern Red	Quercus rubra	Wooded Space	No	19	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	20	Southville Rd	Front	Southville Rd	199188.56	890743	42.26716	-71.5098
1	Greg Baldwin (DRG)	2022/08/18	borderline	1667	2022/08/10	AsCa20220810095851	13:08:34	Cedar, Northern White	Thuja occidentalis	Open Space	Yes	1	Poor	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	19	Southville Rd	Front	Southville Rd	199168.5	890762.5	42.26733	-71.5101
1	Ashley Casello (DRG)	2022/08/10	DBH estimated; poison ivy	1668	2022/08/10	AsCa20220810120252	12:03:27	Oak, Northern Red	Quercus rubra	Wooded Space	No	15	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	50	Southville Rd	Front	Southville Rd	198745.37	890894.5	42.26852	-71.5152
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy	1669	2022/08/10	AsCa20220810084750	10:22:54	Oak, Scarlet	Quercus coccinea	Wooded Space	No	30	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	57	Southville Rd	Front	Southville Rd	198579.85	890914	42.2687	-71.5172
1	Ashley Casello (DRG)	2022/08/10		1670	2022/08/10	AsCa20220810091315	9:15:08	Oak, Northern Red	Quercus rubra	Open Space	No	15	Fair	Routine Prune	Annual Ins	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Severe	Low	Yes	49	Southville Rd	Front	Southville Rd	198754.68	890907.4	42.26864	-71.5151
1	Greg Baldwin (DRG)	2022/08/19	DBH estimated; poison ivy	1671	2022/08/10	AsCa20220810073212	14:15:49	Oak, White	Quercus alba	Wooded Space	No	18	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	122	Southville Rd	Front	Southville Rd	197803.74	890756.1	42.26727	-71.5266
1	Greg Baldwin (DRG)	2022/08/18	utility pole 75	1672	2022/08/10	AsCa20220810125831	12:47:43	Oak, Northern Red	Quercus rubra	Wooded Space	No	14	Good	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	20	Southville Rd	Front	Southville Rd	199203.09	890737.1	42.2671	-71.5097
1	Ashley Casello (DRG)	2022/08/10		1673	2022/08/10	AsCa20220810101540	10:15:59	Oak, Northern Red	Quercus rubra	Open Space	No	7	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	11	Southville Rd	Front	Southville Rd	199292.3	890729.4	42.26703	-71.5086
1	Ashley Casello (DRG)	2022/08/10		1674	2022/08/10	AsCa20220810114449	11:45:31	Oak, White	Quercus alba	Wooded Space	No	21	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	30	Southville Rd	Front	Southville Rd	198940.3	890831.3	42.26795	-71.5128
1	Ashley Casello (DRG)	2022/08/10	DBH estimated; poison ivy; borderline; remove vines	1675	2022/08/10	AsCa20220810093950	9:40:32	Pine, Eastern White	Pinus strobus	Open Space	No	20	Fair	Routine Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Minor	Low	Yes	2	Liberty Dr	Side	Southville Rd	198989.26	890827.4	42.26792	-71.5123

1	Ashley Casello (DRG)	2022/08/10	DBH estimated; behind fence; borderline	1676	2022/08/10	AsCa20220810103746	10:38:42	Maple, Red	Acer rubrum	Open Space	Yes	12	Good	Routine Prune	None	Broken And/Or Hanging Branches	Low	Probable	Low	Unlikely	Negligible	Low	No	1	Constitution Dr	Side	Southville Rd	199418.6	890700	42.26677	-71.507
1	Ashley Casello (DRG)	2022/08/10		1677	2022/08/10	AsCa20220810095935	10:00:20	Maple, Red	Acer rubrum	Open Space	No	10	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	19	Southville Rd	Front	Southville Rd	199178.09	890759.9	42.26731	-71.51
1	Ashley Casello (DRG)	2022/08/10		1678	2022/08/10	AsCa20220810091540	9:16:43	Oak, Scarlet	Quercus coccinea	Open Space	No	37	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	47	Southville Rd	Front	Southville Rd	198774.21	890903	42.2686	-71.5149
1	Ashley Casello (DRG)	2022/08/10		1679	2022/08/10	AsCa20220810120530	12:07:03	Oak, Northern Red	Quercus rubra	Wooded Space	No	16	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	50	Southville Rd	Front	Southville Rd	198736.84	890896.1	42.26853	-71.5153
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy	1680	2022/08/10	AsCa20220810084946	10:22:54	Elm, American	Ulmus americana	Wooded Space	No	10	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Significant	Low	Yes	57	Southville Rd	Front	Southville Rd	198579.33	890914.6	42.2687	-71.5172
1	Greg Baldwin (DRG)	2022/08/19	DBH estimated; poison ivy; borderline	1681	2022/08/10	AsCa20220810073409	14:16:15	Oak, Northern Red	Quercus rubra	Wooded Space	No	28	Good	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	122	Southville Rd	Front	Southville Rd	197794.61	890754.4	42.26726	-71.5267
1	Ashley Casello (DRG)	2022/08/10	borderline	1682	2022/08/10	AsCa20220810101655	10:17:52	Oak, Northern Red	Quercus rubra	Wooded Space	No	15	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	11	Southville Rd	Front	Southville Rd	199301.01	890726.9	42.26701	-71.5085
1	Greg Baldwin (DRG)	2022/08/18	utility pole 76	1683	2022/08/10	AsCa20220810130007	12:47:43	Oak, Black	Quercus velutina	Wooded Space	No	16	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	20	Southville Rd	Front	Southville Rd	199226.68	890732.1	42.26706	-71.5094
1	Ashley Casello (DRG)	2022/08/10		1684	2022/08/10	AsCa20220810114549	11:46:24	Oak, White	Quercus alba	Wooded Space	No	17	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	30	Southville Rd	Front	Southville Rd	198935.13	890834.2	42.26798	-71.5129
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; behind fence; borderline; multiple saplings in area	1685	2022/08/10	AsCa20220810103942	20:16:21	Cherry, Black	Prunus serotina	Open Space	No	5	Fair	Train	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	1	Constitution Dr	Side	Southville Rd	199426.77	890696.9	42.26674	-71.5069
1	Ashley Casello (DRG)	2022/08/10	DBH estimated; poison ivy; borderline; remove vines	1686	2022/08/10	AsCa20220810094038	9:41:10	Pine, Eastern White	Pinus strobus	Open Space	Yes	14	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Significant	Low	Yes	2	Liberty Dr	Side	Southville Rd	198993.5	890825.6	42.2679	-71.5122
1	Ashley Casello (DRG)	2022/08/10		1687	2022/08/10	AsCa20220810100032	10:01:37	Oak, Northern Red	Quercus rubra	Open Space	No	15	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Negligible	Low	Yes	17	Southville Rd	Front	Southville Rd	199179.62	890759.1	42.2673	-71.5099
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; poison ivy; in failure	1688	2022/08/10	AsCa20220810101800	20:09:39	Tree, Unknown	Unknown Tree	Wooded Space	No	12	Dead	Remove	None	No Significant Defect	None	Probable	Low	Unlikely	Significant	Low	Yes	11	Southville Rd	Front	Southville Rd	199303.24	890726.7	42.26701	-71.5084
1	Ashley Casello (DRG)	2022/08/10	DBH estimated; poison ivy	1689	2022/08/10	AsCa20220810121955	12:21:03	Oak, Northern Red	Quercus rubra	Wooded Space	No	25	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	50	Southville Rd	Front	Southville Rd	198698.9	890898.8	42.26856	-71.5158
1	Ashley Casello (DRG)	2022/08/10	DBH estimated; poison ivy; borderline	1690	2022/08/10	AsCa20220810091800	9:18:58	Hickory, Shagbark	Carya ovata	Wooded Space	No	8	Good	Routine Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Negligible	Low	Yes	43	Southville Rd	Front	Southville Rd	198842.33	890881.8	42.26841	-71.514
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy	1691	2022/08/10	AsCa20220810085103	10:22:54	Elm, American	Ulmus americana	Wooded Space	No	4	Dead	Remove	None	No Significant Defect	None	Probable	Medium	Somewhat Likely	Minor	Low	Yes	57	Southville Rd	Front	Southville Rd	198578.15	890913.8	42.26869	-71.5172
1	Ashley Casello (DRG)	2022/08/10		1692	2022/08/10	AsCa20220810073938	7:41:05	Aspen, Bigtooth	Populus grandidentata	Open Space	No	8	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	8	Highland St	Side	Southville Rd	197822.45	890769.3	42.26739	-71.5264
1	Greg Baldwin (DRG)	2022/08/18	utility pole 76	1693	2022/08/10	AsCa20220810130125	12:47:43	Oak, Northern Red	Quercus rubra	Wooded Space	No	21	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	20	Southville Rd	Front	Southville Rd	199229.62	890732.9	42.26707	-71.5093
1	Ashley Casello (DRG)	2022/08/10	borderline	1694	2022/08/10	AsCa20220810104114	10:42:12	Pine, Eastern White	Pinus strobus	Open Space	Yes	20	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	5	Southville Rd	Front	Southville Rd	199435.24	890695.3	42.26673	-71.5068
1	Ashley Casello (DRG)	2022/08/10	borderline	1695	2022/08/10	AsCa20220810114728	11:48:23	Oak, Northern Red	Quercus rubra	Wooded Space	No	28	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	30	Southville Rd	Front	Southville Rd	198927.18	890836.8	42.268	-71.513
1	Ashley Casello (DRG)	2022/08/10	DBH estimated; poison ivy; borderline; remove vines	1696	2022/08/10	AsCa20220810094119	9:42:45	Pine, Eastern White	Pinus strobus	Open Space	No	17	Fair	Routine Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Minor	Low	Yes	2	Liberty Dr	Side	Southville Rd	198998.21	890823.9	42.26788	-71.5121
1	Ashley Casello (DRG)	2022/08/10		1697	2022/08/10	AsCa20220810100202	10:02:32	Oak, Northern Red	Quercus rubra	Open Space	Yes	10	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	17	Southville Rd	Front	Southville Rd	199194.67	890754.2	42.26726	-71.5098
1	Ashley Casello (DRG)	2022/08/10	borderline; remove vines	1698	2022/08/10	AsCa20220810122410	12:25:06	Maple, Red	Acer rubrum	Wooded Space	No	8	Good	Routine Prune	None	Dead And Dying Branches	Low	Probable	Very Low	Unlikely	Negligible	Low	Yes	50	Southville Rd	Front	Southville Rd	198688.13	890898.8	42.26856	-71.5159
1	Ashley Casello (DRG)	2022/08/10	DBH estimated; poison ivy	1699	2022/08/10	AsCa20220810102102	10:22:16	Oak, Black	Quercus velutina	Wooded Space	No	30	Good	Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Significant	Low	Yes	11	Southville Rd	Front	Southville Rd	199312.3	890723.8	42.26698	-71.5083
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; vines; borderline	1700	2022/08/10	AsCa20220810085202	10:22:54	Tree, Unknown	Unknown Tree	Open Space	No	15	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	57	Southville Rd	Front	Southville Rd	198594.5	890915	42.2687	-71.517
1	Ashley Casello (DRG)	2022/08/10	DBH estimated; poison ivy; borderline	1701	2022/08/10	AsCa20220810091937	9:20:09	Oak, Northern Red	Quercus rubra	Wooded Space	No	12	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	43	Southville Rd	Front	Southville Rd	198843.92	890880.9	42.2684	-71.514
1	Greg Baldwin (DRG)	2022/08/18	utility pole 76; DBH estimated; poison ivy	1702	2022/08/10	AsCa20220810130245	12:47:43	Oak, Northern Red	Quercus rubra	Wooded Space	No	16	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	20	Southville Rd	Front	Southville Rd	199245.15	890726.3	42.26701	-71.5091
1	Ashley Casello (DRG)	2022/08/10	carpenter ants	1703	2022/08/10	AsCa20220810114842	11:49:49	Red	Quercus rubra	Open Space	No	16	Fair	Routine Prune	Insect/Dis	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	40	Southville Rd	Front	Southville Rd	198910.66	890841	42.26804	-71.5132
1	Ashley Casello (DRG)	2022/08/10		1704	2022/08/10	AsCa20220810100245	10:03:15	Maple, Red	Acer rubrum	Open Space	No	6	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	17	Southville Rd	Front	Southville Rd	199200.09	890752.3	42.26724	-71.5097
1	Ashley Casello (DRG)	2022/08/11	remove vines	1705	2022/08/10	AsCa20220810074155	20:16:21	Cherry, Black	Prunus serotina	Open Space	Yes	2	Fair	Train	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	4	Highland St	Side	Southville Rd	197829.8	890769.9	42.2674	-71.5263
1	Ashley Casello (DRG)	2022/08/10	borderline; remove vines	1706	2022/08/10	AsCa20220810094251	9:43:49	Pine, Eastern White	Pinus strobus	Open Space	No	18	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	2	Liberty Dr	Side	Southville Rd	199001.62	890822.5	42.26787	-71.5121
1	Ashley Casello (DRG)	2022/08/10	borderline	1707	2022/08/10	AsCa20220810104331	10:45:12	Oak, Swamp White	Quercus bicolor	Open Space	No	10	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	5	Southville Rd	Front	Southville Rd	199446.6	890692.9	42.26671	-71.5067
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; borderline; utility pole 77	1708	2022/08/10	AsCa20220810102251	12:48:23	Maple, Red	Acer rubrum	Wooded Space	Yes	14	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	9	Southville Rd	Front	Southville Rd	199333.89	890718.9	42.26694	-71.5081
1	Greg Baldwin (DRG)	2022/08/18	basal decay	1709	2022/08/10	AsCa20220810085405	10:22:54	Oak, Pin	Quercus palustris	Open Space	No	34	Fair	Prune	Annual Ins	Dead And Dying Branches	Low	Probable	Medium	Somewhat Likely	Minor	Low	Yes	57	Southville Rd	Front	Southville Rd	198606.38	890914.6	42.2687	-71.5169
1	Ashley Casello (DRG)	2022/08/11		1710	2022/08/10	AsCa20220810122755	20:16:21	Elm, American	Ulmus americana	Open Space	No	4	Good	Train	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	86	Southville Rd	Front	Southville Rd	198563.72	890901.2	42.26858	-71.5174
1	Ashley Casello (DRG)	2022/08/10		1711	2022/08/10	AsCa20220810092120	9:22:52	Hickory, Shagbark	Carya ovata	Wooded Space	No	21	Good	Routine Prune	None	Broken And/Or Hanging Branches	Low	Imminent	Low	Somewhat Likely	Minor	Low	Yes	43	Southville Rd	Front	Southville Rd	198856.03	890875.3	42.26835	-71.5139
1	Ashley Casello (DRG)	2022/08/10	borderline; remove vines	1712	2022/08/10	AsCa20220810094409	9:44:53	Pine, Eastern White	Pinus strobus	Open Space	No	12	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	2	Liberty Dr	Side	Southville Rd	199004.38	890821.8	42.26787	-71.5121
1	Greg Baldwin (DRG)	2022/08/18	utility pole 76	1713	2022/08/10	AsCa20220810130350	12:47:43	Tree, Unknown	Unknown Tree	Wooded Space	No	26	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	20	Southville Rd	Front	Southville Rd	199255.98	890724.4	42.26699	-71.509
1	Ashley Casello (DRG)	2022/08/10		1714	2022/08/10	AsCa20220810115041	11:51:07	Maple, Red	Acer rubrum	Open Space	No	6	Good	Train	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	40	Southville Rd	Front	Southville Rd	198887.66	890850	42.26812	-71.5135
1	Greg Baldwin (DRG)	2022/08/19	poor location	1715	2022/08/10	AsCa20220810074359	14:32:31	Butternut	Juglans cinerea	Open Space	No	4	Poor	Remove	None	Tree Architecture	None	Improbable	Medium	Unlikely	Minor	Low	Yes	4	Highland St	Side	Southville Rd	197836.74	890770.6	42.2674	-71.5262
1	Ashley Casello (DRG)	2022/08/10		1716	2022/08/10	AsCa20220810100325	10:03:43	Maple, Red	Acer rubrum	Open Space	No	3	Good	Train	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	17	Southville Rd	Front	Southville Rd	199201.85	890751.5	42.26723	-71.5097
1	Ashley Casello (DRG)	2022/08/10		1717	2022/08/10	AsCa20220810104546	10:46:37	Oak, White	Quercus alba	Open Space	No	13	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	5	Southville Rd	Front	Southville Rd	199455.89	890691.1	42.26669	-71.5066
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; borderline; utility pole 77	1718	2022/08/10	AsCa20220810102515	12:48:23	Oak, White	Quercus alba	Wooded Space	No	16	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	9	Southville Rd	Front	Southville Rd	199338.24	890718.7	42.26694	-71.508
1	Greg Baldwin (DRG)	2022/08/18	borderline	1719	2022/08/10	AsCa20220810085740	10:22:54	Elm, American	Ulmus americana	Wooded Space	No	8	Poor	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	57	Southville Rd	Front	Southville Rd	198618.27	890914.7	42.2687	-71.5167
1	Ashley Casello (DRG)	2022/08/10	borderline; remove vines	1720	2022/08/10	AsCa20220810092409	9:25:44	Maple, Red	Acer rubrum	Open Space	Yes	6	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	41	Southville Rd	Front	Southville Rd	198860.5	890875.1	42.26835	-71.5138
1	Ashley Casello (DRG)	2022/08/11	borderline; DBH estimated; poison ivy	1721	2022/08/10	AsCa20220810123121	20:09:39	Tree, Unknown	Unknown Tree	Wooded Space	No	12	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	50	Southville Rd	Front	Southville Rd	198692.13	890898.1	42.26855	-71.5159
1	Greg Baldwin (DRG)	2022/08/18	utility pole 76; borderline	1722	2022/08/10	AsCa20220810130729	12:47:43	Tree, Unknown	Unknown Tree	Wooded Space	No	27	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Severe	Low	Yes	20	Southville Rd	Front	Southville Rd	199275.3	890719.6	42.26695	-71.5088
1	Ashley Casello (DRG)	2022/08/10		1723	2022/08/10	AsCa20220810110650	11:07:24	Maple, Red	Acer rubrum	Open Space	No	3	Good	Train	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	98	Southville Rd	Front	Southville Rd	198389.2	890873.6	42.26833	-71.5195
1	Ashley Casello (DRG)	2022/08/11		1724	2022/08/10	AsCa20220810074629	20:16:21	Pear, Callery	Pyrus calleryana	Open Space	No	5	Fair	Train	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	4	Highland St	Side	Southville Rd	197864.15	890774.4	42.26744	-71.5259
1	Ashley Casello (DRG)	2022/08/10		1725	2022/08/10	AsCa20220810100358	10:04:51	Oak, Northern Red	Quercus rubra	Open Space	No	9	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Negligible	Low	Yes	17	Southville Rd	Front	Southville Rd	199204.38	890750.7	42.26723	-71.5096
1	Ashley Casello (DRG)	2022/08/10	borderline; remove vines	1726	2022/08/10	AsCa20220810094458	9:46:09	Pine, Eastern White	Pinus strobus	Open Space	No	16	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	2	Liberty Dr	Side	Southville Rd	199006.62	890821.2	42.26786	-71.512
1	Ashley Casello (DRG)	2022/08/10		1727	2022/08/10	AsCa20220810115127	11:51:50	Maple, Red	Acer rubrum	Open Space	No	7	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	40	Southville Rd	Front	Southville Rd	198880.42	890852.5	42.26814	-71.5136

1	Greg Baldwin (DRG)	2022/08/18		1728	2022/08/10	AsCa20220810090142	10:22:54	Oak, Northern Red	Quercus rubra	Open Space	No	15	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	53	Southville Rd	Front	Southville Rd	198692.21	890913	42.26869	-71.5159
1	Greg Baldwin (DRG)	2022/08/18	DBH estimated; poison ivy; utility pole 77	1729	2022/08/10	AsCa20220810102644	12:48:23	Tree, Unknown	Unknown Tree	Wooded Space	No	6	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Minor	Low	Yes	9	Southville Rd	Front	Southville Rd	199341.24	890717.9	42.26693	-71.508
1	Ashley Casello (DRG)	2022/08/10	borderline; remove vines; DBH estimated; poison ivy	1730	2022/08/10	AsCa20220810092554	9:26:49	Redcedar, Eastern	Juniperus virginiana	Open Space	No	6	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	41	Southville Rd	Front	Southville Rd	198859.68	890875.3	42.26835	-71.5138
1	Ashley Casello (DRG)	2022/08/11	borderline; DBH estimated; behind stonewall	1731	2022/08/10	AsCa20220810123316	20:09:39	Birch, Paper	Betula papyrifera	Wooded Space	No	6	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Significant	Low	Yes	53	Southville Rd	Front	Southville Rd	198704.25	890913.1	42.26869	-71.5157
1	Greg Baldwin (DRG)	2022/08/18	utility pole 76; borderline	1732	2022/08/10	AsCa20220810130912	12:47:43	Oak, Northern Red	Quercus rubra	Wooded Space	No	16	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	20	Southville Rd	Front	Southville Rd	199270.77	890720.2	42.26695	-71.5088
1	Ashley Casello (DRG)	2022/08/10		1733	2022/08/10	AsCa20220810100520	10:05:51	Maple, Red	Acer rubrum	Open Space	No	6	Fair	Routine Prune	None	Root Problems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	17	Southville Rd	Front	Southville Rd	199212.2	890748.2	42.2672	-71.5095
1	Greg Baldwin (DRG)	2022/08/18		1734	2022/08/10	AsCa20220810094820	10:22:54	Apple	Malus species	Open Space	No	7	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	23	Southville Rd	Front	Southville Rd	199079.79	890793.9	42.26761	-71.5112
1	Ashley Casello (DRG)	2022/08/10	DBH estimated; poison ivy	1735	2022/08/10	AsCa20220810074931	7:51:05	Maple, Red	Acer rubrum	Open Space	No	7	Poor	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	4	Highland St	Side	Southville Rd	197874.51	890775.1	42.26744	-71.5258
1	Greg Baldwin (DRG)	2022/08/18		1736	2022/08/10	AsCa20220810110845	13:20:25	Ash, Green	Fraxinus pennsylvanica	Open Space	No	24	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Medium	Unlikely	Severe	Low	Yes	100	Southville Rd	Front	Southville Rd	198351.72	890865	42.26825	-71.52
1	Greg Baldwin (DRG)	2022/08/18		1737	2022/08/10	AsCa20220810124149	13:08:34	Cedar, Northern White	Thuja occidentalis	Open Space	Yes	1	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	106	Southville Rd	Front	Southville Rd	198210.81	890827.9	42.26792	-71.5217
1	Ashley Casello (DRG)	2022/08/10		1738	2022/08/10	AsCa20220810115212	11:52:43	Maple, Red	Acer rubrum	Open Space	No	6	Good	Train	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	40	Southville Rd	Front	Southville Rd	198859.3	890860.9	42.26822	-71.5138
1	Greg Baldwin (DRG)	2022/08/18		1739	2022/08/10	AsCa20220810103035	13:08:34	Cedar, Northern White	Thuja occidentalis	Open Space	Yes	3	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	1	Constitution Dr	Side	Southville Rd	199397.48	890704	42.26681	-71.5073
1	Greg Baldwin (DRG)	2022/08/18	borderline; DBH estimated; behind stonewall	1740	2022/08/10	AsCa20220810090349	10:22:54	Oak, Black	Quercus velutina	Open Space	No	26	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	53	Southville Rd	Front	Southville Rd	198699.62	890913.4	42.26869	-71.5158
1	Ashley Casello (DRG)	2022/08/10		1741	2022/08/10	AsCa20220810092705	9:28:21	Maple, Red	Acer rubrum	Open Space	No	13	Poor	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	41	Southville Rd	Front	Southville Rd	198864.5	890873	42.26833	-71.5138
1	Greg Baldwin (DRG)	2022/08/18	utility pole 76; borderline	1742	2022/08/10	AsCa20220810131034	12:47:43	Oak, Northern Red	Quercus rubra	Wooded Space	No	8	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	20	Southville Rd	Front	Southville Rd	199240.77	890726.5	42.26701	-71.5092
1	Ashley Casello (DRG)	2022/08/10	borderline	1743	2022/08/10	AsCa20220810100615	10:07:13	Maple, Red	Acer rubrum	Open Space	Yes	11	Fair	Prune	None	Broken And/Or Hanging Branches	Low	Probable	Low	Unlikely	Significant	Low	Yes	15	Southville Rd	Front	Southville Rd	199229.32	890746.1	42.26718	-71.5093
1	Ashley Casello (DRG)	2022/08/10		1744	2022/08/10	AsCa20220810075138	7:52:31	Maple, Sugar	Acer saccharum	Open Space	No	14	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	4	Highland St	Side	Southville Rd	197876.15	890774.8	42.26744	-71.5257
1	Ashley Casello (DRG)	2022/08/10	borderline; DBH estimated; poison ivy	1745	2022/08/10	AsCa20220810115425	11:55:23	Oak, Northern Red	Quercus rubra	Wooded Space	Yes	14	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	No	50	Southville Rd	Front	Southville Rd	198814.36	890875.5	42.26835	-71.5144
1	Greg Baldwin (DRG)	2022/08/18		1746	2022/08/10	AsCa20220810124207	13:08:34	Cedar, Northern White	Thuja occidentalis	Open Space	Yes	1	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	106	Southville Rd	Front	Southville Rd	198209.45	890827.7	42.26792	-71.5217
1	Greg Baldwin (DRG)	2022/08/18		1747	2022/08/10	AsCa20220810094935	10:22:54	Apple	Malus species	Open Space	No	10	Good	Routine Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Negligible	Low	Yes	23	Southville Rd	Front	Southville Rd	199081.91	890793.5	42.26761	-71.5111
1	Greg Baldwin (DRG)	2022/08/18		1748	2022/08/10	AsCa20220810103150	13:08:34	Cedar, Northern White	Thuja occidentalis	Open Space	Yes	3	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	1	Constitution Dr	Side	Southville Rd	199401.13	890703.4	42.2668	-71.5073
1	Ashley Casello (DRG)	2022/08/10	DBH estimated; poison ivy; remove poison ivy	1749	2022/08/10	AsCa20220810111340	11:15:53	Ash, Green	Fraxinus pennsylvanica	Open Space	Yes	15	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	100	Southville Rd	Front	Southville Rd	198314.07	890856.4	42.26818	-71.5204
1	Greg Baldwin (DRG)	2022/08/18	borderline; DBH estimated; behind stonewall	1750	2022/08/10	AsCa20220810090610	10:22:54	Oak, Northern Red	Quercus rubra	Open Space	No	7	Fair	Routine Prune	None	Dead And Dying Branches	Low	Probable	Low	Unlikely	Negligible	Low	No	51	Southville Rd	Front	Southville Rd	198711.33	890911.8	42.26868	-71.5156
1	Ashley Casello (DRG)	2022/08/11	borderline; DBH estimated; poison ivy;	1751	2022/08/10	AsCa20220810092837	20:09:39	Ash, Green	Fraxinus pennsylvanica	Open Space	No	17	Poor	Remove	None	Dead And Dying Branches	None	Possible	Low	Unlikely	Significant	Low	Yes	41	Southville Rd	Front	Southville Rd	198866.97	890872.5	42.26832	-71.5137
1	Greg Baldwin (DRG)	2022/08/18	utility pole 78	1752	2022/08/10	AsCa20220810131742	12:48:23	Tree, Unknown	Unknown Tree	Wooded Space	No	10	Dead	Remove	None	No Significant Defect	None	Possible	Medium	Unlikely	Significant	Low	Yes	9	Southville Rd	Front	Southville Rd	199359.13	890714.2	42.2669	-71.5078
1	Greg Baldwin (DRG)	2022/08/18	basal decay	1753	2022/08/10	AsCa20220810095022	13:53:07	Oak, Scarlet	Quercus coccinea	Open Space	No	35	Fair	Prune	Annual Ins	Dead And Dying Branches	Low	Possible	Medium	Unlikely	Minor	Low	Yes	23	Southville Rd	Front	Southville Rd	199086.44	890791.8	42.2676	-71.5111
1	Ashley Casello (DRG)	2022/08/11	remove vines	1754	2022/08/10	AsCa20220810075309	20:16:21	Pear, Callery	Pyrus calleryana	Open Space	Yes	4	Fair	Train	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	4	Highland St	Side	Southville Rd	197881.51	890775.1	42.26744	-71.5257
1	Ashley Casello (DRG)	2022/08/10	DBH estimated; poison ivy	1755	2022/08/10	AsCa20220810115601	11:57:25	Oak, Northern Red	Quercus rubra	Wooded Space	No	24	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	50	Southville Rd	Front	Southville Rd	198791.13	890884	42.26843	-71.5147
1	Ashley Casello (DRG)	2022/08/10		1756	2022/08/10	AsCa20220810100733	10:08:19	Oak, Northern Red	Quercus rubra	Open Space	No	14	Good	Prune	None	Dead And Dying Branches	Low	Probable	Medium	Somewhat Likely	Minor	Low	Yes	15	Southville Rd	Front	Southville Rd	199232.79	890743.8	42.26716	-71.5093
1	Greg Baldwin (DRG)	2022/08/18		1757	2022/08/10	AsCa20220810124518	13:08:34	Cedar, Northern White	Thuja occidentalis	Open Space	Yes	3	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	1	Constitution Dr	Side	Southville Rd	199399.01	890703.5	42.2668	-71.5073
1	Ashley Casello (DRG)	2022/08/10	DBH estimated; behind fence	1758	2022/08/10	AsCa20220810103224	10:33:42	Oak, White	Quercus alba	Open Space	No	22	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	1	Constitution Dr	Side	Southville Rd	199407.3	890701.9	42.26679	-71.5072
1	Ashley Casello (DRG)	2022/08/11	DBH estimated; poison ivy	1759	2022/08/10	AsCa20220810111617	20:09:39	Oak, Scarlet	Quercus coccinea	Open Space	No	12	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Medium	Unlikely	Significant	Low	Yes	100	Southville Rd	Front	Southville Rd	198294.37	890851.1	42.26813	-71.5207
1	Greg Baldwin (DRG)	2022/08/18	borderline; DBH estimated; poison ivy; utility pole 77	1760	2022/08/10	AsCa20220810132125	12:48:23	Oak, Northern Red	Quercus rubra	Wooded Space	No	9	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	9	Southville Rd	Front	Southville Rd	199326.6	890722.2	42.26697	-71.5082
1	Ashley Casello (DRG)	2022/08/10		1761	2022/08/10	AsCa20220810093055	9:32:02	Oak, Northern Red	Quercus rubra	Open Space	No	25	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	39	Southville Rd	Front	Southville Rd	198902.91	890858.3	42.26819	-71.5133
1	Ashley Casello (DRG)	2022/08/10	borderline; DBH estimated; behind stonewall	1762	2022/08/10	AsCa20220810090743	9:08:45	Oak, Northern Red	Quercus rubra	Open Space	No	11	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	51	Southville Rd	Front	Southville Rd	198715.97	890912	42.26868	-71.5156
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 74	1763	2022/08/10	AsCa20220810132940	12:47:43	Oak, Northern Red	Quercus rubra	Wooded Space	No	29	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	20	Southville Rd	Front	Southville Rd	199156.77	890750.8	42.26723	-71.5102
1	Ashley Casello (DRG)	2022/08/10	DBH estimated; poison ivy	1764	2022/08/10	AsCa20220810115750	11:58:44	Oak, Northern Red	Quercus rubra	Wooded Space	No	26	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	50	Southville Rd	Front	Southville Rd	198783.42	890885.6	42.26844	-71.5147
1	Ashley Casello (DRG)	2022/08/10	remove vines	1765	2022/08/10	AsCa20220810075403	7:55:05	Pine, Eastern White	Pinus strobus	Open Space	No	10	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	4	Highland St	Side	Southville Rd	197884.98	890775.3	42.26745	-71.5256
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 53; DBH estimated; poison ivy; remove vines	1766	2022/08/10	AsCa20220810112057	12:38:31	Hickory, Shagbark	Carya ovata	Open Space	No	12	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	102	Southville Rd	Front	Southville Rd	198246.48	890836.5	42.268	-71.5213
1	Ashley Casello (DRG)	2022/08/10	borderline	1767	2022/08/10	AsCa20220810140305	14:04:33	Pine, Eastern White	Pinus strobus	Open Space	No	19	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	2	Liberty Dr	Side	Southville Rd	199011.13	890820.1	42.26785	-71.512
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 74	1768	2022/08/10	AsCa20220810135806	12:47:43	Oak, Northern Red	Quercus rubra	Wooded Space	No	11	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	20	Southville Rd	Front	Southville Rd	199114.89	890765.7	42.26736	-71.5107
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 74	1769	2022/08/10	AsCa20220810135619	12:47:43	Oak, Northern Red	Quercus rubra	Wooded Space	Yes	16	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	20	Southville Rd	Front	Southville Rd	199108.94	890767.9	42.26738	-71.5108
1	Greg Baldwin (DRG)	2022/08/18	borderline; utility pole 74	1770	2022/08/10	AsCa20220810135920	12:47:43	Oak, Northern Red	Quercus rubra	Wooded Space	No	9	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	20	Southville Rd	Front	Southville Rd	199118.42	890764.5	42.26735	-71.5107
1	Greg Baldwin (DRG)	2022/08/02	pole number 21; borderline	286	2022/08/02	GrBa20220802095529	9:56:38	Oak, White	Quercus alba	Wooded Space	No	30	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	47	Valley Rd	Front	Valley Rd	199849.29	894950.9	42.30504	-71.5018
1	Greg Baldwin (DRG)	2022/08/02	pole number 26	288	2022/08/02	GrBa20220802090422	9:04:47	Maple, Red	Acer rubrum	Wooded Space	No	13	Poor	Prune	None	Broken And/Or Hanging Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Valley Rd	199753.34	895118.1	42.30655	-71.503
1	Greg Baldwin (DRG)	2022/08/18	pole number 12; utility guy line	291	2022/08/02	GrBa20220802112003	11:26:22	Maple, Sugar	Acer saccharum	Wooded Space	No	32	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	24	Valley Rd	Front	Valley Rd	200069.39	894676.1	42.30257	-71.4992

1	Greg Baldwin (DRG)	2022/08/02	pole number 20	297	2022/08/02	GrBa20220802095854	10:00:09	Oak, Black	Quercus velutina	Wooded Space	No	29	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	47	Valley Rd	Front	Valley Rd	199869.04	894933	42.30488	-71.5016
1	Greg Baldwin (DRG)	2022/08/02	pole number 26	298	2022/08/02	GrBa20220802090449	9:05:10	Maple, Red	Acer rubrum	Wooded Space	No	12	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Possible	Low	Unlikely	Negligible	Low	Yes	265	Boston Rd	Side	Valley Rd	199753.98	895116.6	42.30653	-71.503
1	Greg Baldwin (DRG)	2022/08/18	pole number 12	301	2022/08/02	GrBa20220802112159	11:26:22	Maple, Sugar	Acer saccharum	Wooded Space	No	29	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	24	Valley Rd	Front	Valley Rd	200068.74	894679.5	42.3026	-71.4992
1	Greg Baldwin (DRG)	2022/08/02	pole number 25	307	2022/08/02	GrBa20220802090622	9:10:10	Oak, Black	Quercus velutina	Wooded Space	No	43	Fair	Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Severe	Low	Yes	265	Boston Rd	Side	Valley Rd	199755.04	895114.2	42.30651	-71.503
1	Greg Baldwin (DRG)	2022/08/02	dbh estimated; poison ivy; borderline	308	2022/08/02	GrBa20220802100504	10:08:42	Hickory, Pignut	Carya glabra	Wooded Space	No	18	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Minor	Low	Yes	41	Valley Rd	Front	Valley Rd	199991.22	894841.6	42.30406	-71.5001
1	Greg Baldwin (DRG)	2022/08/18	pole number 12	310	2022/08/02	GrBa20220802112321	11:26:22	Maple, Sugar	Acer saccharum	Wooded Space	No	29	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	24	Valley Rd	Front	Valley Rd	200067.98	894682.7	42.30263	-71.4992
1	Greg Baldwin (DRG)	2022/08/02	dbh estimated; poison ivy; borderline	314	2022/08/02	GrBa20220802100725	10:08:26	Ash, White	Fraxinus americana	Wooded Space	No	21	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	37	Valley Rd	Front	Valley Rd	200041.19	894780.6	42.30351	-71.4995
1	Greg Baldwin (DRG)	2022/08/02	pole number 25; borderline	318	2022/08/02	GrBa20220802090849	9:09:33	Maple, Sugar	Acer saccharum	Wooded Space	Yes	11	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Valley Rd	199759.63	895107.4	42.30645	-71.5029
1	Greg Baldwin (DRG)	2022/08/18	borderline; emerald ash borer	324	2022/08/02	GrBa20220802101045	13:18:54	Ash, White	Fraxinus americana	Open Space	No	29	Poor	Remove	None	Dead And Dying Branches	None	Possible	High	Somewhat Likely	Significant	Moderate	Yes	33	Valley Rd	Front	Valley Rd	200073.06	894702.6	42.30281	-71.4991
1	Greg Baldwin (DRG)	2022/08/18	pole number 13	327	2022/08/02	GrBa20220802112454	11:26:22	Maple, Sugar	Acer saccharum	Wooded Space	No	9	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	24	Valley Rd	Front	Valley Rd	200065.57	894695.1	42.30274	-71.4992
1	Greg Baldwin (DRG)	2022/08/02	pole number 25; hangers	329	2022/08/02	GrBa20220802091015	9:11:07	Maple, Red	Acer rubrum	Wooded Space	No	16	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Valley Rd	199759.75	895103.7	42.30642	-71.5029
1	Greg Baldwin (DRG)	2022/08/02		334	2022/08/02	GrBa20220802101446	11:19:56	Maple, Sugar	Acer saccharum	Wooded Space	No	40	Fair	Prune	None	Dead And Dying Branches	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	25	Valley Rd	Front	Valley Rd	200079.21	894661.9	42.30244	-71.499
1	Greg Baldwin (DRG)	2022/08/18	dbh estimated; poison ivy; pole number 13	338	2022/08/02	GrBa20220802112540	11:26:22	Ash, White	Fraxinus americana	Wooded Space	No	25	Dead	Remove	None	No Significant Defect	None	Possible	Very Low	Unlikely	Severe	Low	Yes	24	Valley Rd	Front	Valley Rd	200066.16	894694.2	42.30273	-71.4992
1	Greg Baldwin (DRG)	2022/08/02	pole number 25; lost major leader or limb	340	2022/08/02	GrBa20220802091216	9:13:24	Oak, White	Quercus alba	Wooded Space	No	48	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Severe	Low	Yes	265	Boston Rd	Side	Valley Rd	199765.45	895091.3	42.3063	-71.5028
1	Greg Baldwin (DRG)	2022/08/02	pole number 25	344	2022/08/02	GrBa20220802091402	9:14:27	Maple, Red	Acer rubrum	Wooded Space	No	10	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Valley Rd	199769.86	895083.5	42.30623	-71.5028
1	Greg Baldwin (DRG)	2022/08/18	pole number 13	347	2022/08/02	GrBa20220802112815	11:22:54	Maple, Sugar	Acer saccharum	Wooded Space	No	8	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	32	Valley Rd	Front	Valley Rd	200064.16	894703.3	42.30281	-71.4992
1	Greg Baldwin (DRG)	2022/08/02	dbh estimated; poison ivy	348	2022/08/02	GrBa20220802101715	11:16:30	Ash, White	Fraxinus americana	Wooded Space	Yes	18	Dead	Remove	None	No Significant Defect	None	Possible	Very Low	Unlikely	Severe	Low	Yes	25	Valley Rd	Front	Valley Rd	200092.38	894611.1	42.30198	-71.4989
1	Greg Baldwin (DRG)	2022/08/02	pole number 25	353	2022/08/02	GrBa20220802091530	9:17:14	Oak, Northern Red	Quercus rubra	Wooded Space	No	30	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Valley Rd	199769.74	895080	42.3062	-71.5028
1	Greg Baldwin (DRG)	2022/08/18	pole number 13	356	2022/08/02	GrBa20220802113010	11:22:54	Maple, Sugar	Acer saccharum	Wooded Space	No	12	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	32	Valley Rd	Front	Valley Rd	200059.87	894719.2	42.30295	-71.4993
1	Greg Baldwin (DRG)	2022/08/02	borderline	359	2022/08/02	GrBa20220802102046	10:21:34	Maple, Sugar	Acer saccharum	Wooded Space	Yes	11	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	17	Valley Rd	Front	Valley Rd	200125.71	894484.9	42.30085	-71.4985
1	Greg Baldwin (DRG)	2022/08/02	pole number 25	363	2022/08/02	GrBa20220802091753	9:18:18	Maple, Red	Acer rubrum	Wooded Space	No	22	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Valley Rd	199769.97	895078.7	42.30619	-71.5028
1	Greg Baldwin (DRG)	2022/08/18	pole number 16	366	2022/08/02	GrBa20220802113214	11:22:22	Elm, American	Ulmus americana	Wooded Space	No	14	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Minor	Low	Yes	36	Valley Rd	Front	Valley Rd	200027.53	894786.8	42.30356	-71.4997
1	Greg Baldwin (DRG)	2022/08/02	borderline	368	2022/08/02	GrBa20220802102415	10:26:24	Pine, Eastern White	Pinus strobus	Open Space	Yes	5	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	11	Valley Rd	Front	Valley Rd	200138.34	894387.6	42.29997	-71.4983
1	Greg Baldwin (DRG)	2022/08/02	pole number 25	373	2022/08/02	GrBa20220802091856	9:19:55	Maple, Red	Acer rubrum	Wooded Space	No	11	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Valley Rd	199774.5	895067.3	42.30609	-71.5027
1	Greg Baldwin (DRG)	2022/08/18	pole number 16	375	2022/08/02	GrBa20220802113410	11:21:57	Oak, Swamp White	Quercus bicolor	Wooded Space	No	20	Fair	Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	38	Valley Rd	Front	Valley Rd	200017.83	894799.4	42.30368	-71.4998
1	Greg Baldwin (DRG)	2022/08/02	borderline	380	2022/08/02	GrBa20220802102529	10:27:47	Pine, Eastern White	Pinus strobus	Open Space	No	7	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Minor	Low	Yes	11	Valley Rd	Front	Valley Rd	200138.75	894383.6	42.29993	-71.4983
1	Greg Baldwin (DRG)	2022/08/02	pole number 24	383	2022/08/02	GrBa20220802092029	9:21:21	Maple, Red	Acer rubrum	Wooded Space	Yes	11	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Valley Rd	199774.85	895064.6	42.30606	-71.5027
1	Greg Baldwin (DRG)	2022/08/18	pole number 16	386	2022/08/02	GrBa20220802113504	11:21:57	Maple, Red	Acer rubrum	Wooded Space	No	11	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	38	Valley Rd	Front	Valley Rd	200015.18	894802.6	42.30371	-71.4998
1	Greg Baldwin (DRG)	2022/08/02	borderline	387	2022/08/02	GrBa20220802102628	10:27:31	Pine, Eastern White	Pinus strobus	Open Space	No	7	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Minor	Low	Yes	11	Valley Rd	Front	Valley Rd	200139.52	894381.5	42.29991	-71.4983
1	Greg Baldwin (DRG)	2022/08/02	pole number 24	391	2022/08/02	GrBa20220802092149	9:22:33	Oak, Northern Red	Quercus rubra	Wooded Space	No	18	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Low	Unlikely	Severe	Low	Yes	265	Boston Rd	Side	Valley Rd	199776.15	895063.6	42.30606	-71.5027
1	Greg Baldwin (DRG)	2022/08/18	off ROW; pole number 16	396	2022/08/02	GrBa20220802113605	11:21:57	Elm, American	Ulmus americana	Wooded Space	No	12	Dead	Remove	None	No Significant Defect	None	Possible	High	Somewhat Likely	Minor	Low	Yes	38	Valley Rd	Front	Valley Rd	200003.31	894814.1	42.30381	-71.5
1	Greg Baldwin (DRG)	2022/08/02		397	2022/08/02	GrBa20220802102846	10:30:15	Elm, American	Ulmus americana	Open Space	No	5	Good	Train	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	5	Valley Rd	Front	Valley Rd	200170.33	894331.2	42.29946	-71.4979
1	Greg Baldwin (DRG)	2022/08/18	pole number 20	400	2022/08/02	GrBa20220802081810	11:19:44	Ash, White	Fraxinus americana	Wooded Space	No	8	Dead	Remove	None	No Significant Defect	None	Possible	Very Low	Unlikely	Significant	Low	Yes	38	Meadow Ln	Side	Valley Rd	199865.51	894925.6	42.30481	-71.5016
1	Greg Baldwin (DRG)	2022/08/02	pole number 24	404	2022/08/02	GrBa20220802092316	9:23:37	Oak, Northern Red	Quercus rubra	Wooded Space	No	8	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Valley Rd	199780.97	895054.1	42.30597	-71.5027
1	Greg Baldwin (DRG)	2022/08/02		406	2022/08/02	GrBa20220802102938	10:30:05	Apple	Malus species	Open Space	Yes	3	Fair	Train	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Negligible	Low	Yes	5	Valley Rd	Front	Valley Rd	200172.21	894329.6	42.29945	-71.4979
1	Greg Baldwin (DRG)	2022/08/18	pole number 16	407	2022/08/02	GrBa20220802113823	11:21:57	Elm, American	Ulmus americana	Wooded Space	No	8	Dead	Remove	None	No Significant Defect	None	Possible	High	Somewhat Likely	Minor	Low	Yes	38	Valley Rd	Front	Valley Rd	200003.78	894816	42.30383	-71.5
1	Greg Baldwin (DRG)	2022/08/18	pole number 20	411	2022/08/02	GrBa20220802082126	11:19:44	Maple, Red	Acer rubrum	Wooded Space	No	14	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Significant	Low	Yes	38	Meadow Ln	Side	Valley Rd	199864.62	894927.1	42.30483	-71.5016
1	Greg Baldwin (DRG)	2022/08/02	pole number 24	412	2022/08/02	GrBa20220802092431	9:24:54	Oak, Northern Red	Quercus rubra	Wooded Space	No	9	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Valley Rd	199784.02	895045.6	42.30589	-71.5026
1	Greg Baldwin (DRG)	2022/08/02		416	2022/08/02	GrBa20220802103053	10:31:51	Spruce, White	Picea glauca	Open Space	No	9	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	5	Valley Rd	Front	Valley Rd	200185.97	894317.8	42.29934	-71.4977
1	Greg Baldwin (DRG)	2022/08/18	pole number 16; borderline	417	2022/08/02	GrBa20220802114105	11:21	Oak, Northern Red	Quercus rubra	Wooded Space	No	29	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	40	Valley Rd	Front	Valley Rd	199977.56	894842	42.30406	-71.5003
1	Greg Baldwin (DRG)	2022/08/18	pole number 20	420	2022/08/02	GrBa20220802082215	11:19:44	Hickory, Pignut	Carya glabra	Wooded Space	No	8	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	38	Meadow Ln	Side	Valley Rd	199850.1	894939.1	42.30493	-71.5018
1	Greg Baldwin (DRG)	2022/08/02	pole number 24	421	2022/08/02	GrBa20220802092609	9:26:55	Oak, White	Quercus alba	Wooded Space	No	39	Good	Prune	None	Weakly Attached Branches And Codominant Stems	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Valley Rd	199785.67	895034.5	42.30579	-71.5026

1	Greg Baldwin (DRG)	2022/08/02		426	2022/08/02	GrBa20220802103309	10:33:43	Fir, White	Abies concolor	Open Space	No	11	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	5	Valley Rd	Front	Valley Rd	200188.17	894316.1	42.29933	-71.4977
1	Greg Baldwin (DRG)	2022/08/02	pole number 19	427	2022/08/02	GrBa20220802114456	11:46:00	Elm, American	Ulmus americana	Wooded Space	Yes	10	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	39	Meadow Ln	Side	Valley Rd	199911.06	894893.6	42.30452	-71.5011
1	Greg Baldwin (DRG)	2022/08/02		428	2022/08/02	GrBa20220802092707	9:29:29	Hickory, Pignut	Carya glabra	Open Space	No	7	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	51	Valley Rd	Front	Valley Rd	199788.67	895026.5	42.30572	-71.5026
1	Greg Baldwin (DRG)	2022/08/18	pole number 20	431	2022/08/02	GrBa20220802082250	11:19:44	Maple, Red	Acer rubrum	Wooded Space	No	18	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	38	Meadow Ln	Side	Valley Rd	199847.99	894940.6	42.30495	-71.5018
1	Greg Baldwin (DRG)	2022/08/02		436	2022/08/02	GrBa20220802103346	10:34:05	Fir, White	Abies concolor	Open Space	No	10	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	5	Valley Rd	Front	Valley Rd	200190.39	894314.7	42.29931	-71.4977
1	Greg Baldwin (DRG)	2022/08/02		437	2022/08/02	GrBa20220802092806	9:29:29	Pine, Eastern White	Pinus strobus	Open Space	No	8	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	51	Valley Rd	Front	Valley Rd	199789.78	895024.2	42.3057	-71.5025
1	Greg Baldwin (DRG)	2022/08/18	pole number 20	439	2022/08/02	GrBa20220802082418	11:19:44	Birch	Betula species	Wooded Space	No	15	Dead	Remove	None	No Significant Defect	None	Possible	Very Low	Unlikely	Significant	Low	Yes	38	Meadow Ln	Side	Valley Rd	199842.28	894946.2	42.305	-71.5019
1	Greg Baldwin (DRG)	2022/08/02		446	2022/08/02	GrBa20220802103516	10:36:17	Maple, Sugar	Acer saccharum	Open Space	No	21	Poor	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	3	Valley Rd	Front	Valley Rd	200212.45	894298.9	42.29917	-71.4974
1	Greg Baldwin (DRG)	2022/08/02		449	2022/08/02	GrBa20220802092932	9:29:53	Maple, Sugar	Acer saccharum	Open Space	No	9	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	51	Valley Rd	Front	Valley Rd	199791.2	895022.6	42.30569	-71.5025
1	Greg Baldwin (DRG)	2022/08/18	pole number 21	454	2022/08/02	GrBa20220802082610	11:19:44	Pine, Eastern White	Pinus strobus	Wooded Space	No	25	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Severe	Low	Yes	38	Meadow Ln	Side	Valley Rd	199836.29	894950.9	42.30504	-71.502
1	Greg Baldwin (DRG)	2022/08/02		456	2022/08/02	GrBa20220802103711	10:37:43	Maple, Sugar	Acer saccharum	Open Space	No	21	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	3	Valley Rd	Front	Valley Rd	200219.97	894292.2	42.29911	-71.4973
1	Greg Baldwin (DRG)	2022/08/18	pole number 21	458	2022/08/02	GrBa20220802082927	11:19:44	Elm, American	Ulmus americana	Wooded Space	No	16	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	38	Meadow Ln	Side	Valley Rd	199818.65	894969.5	42.30521	-71.5022
1	Greg Baldwin (DRG)	2022/08/02		463	2022/08/02	GrBa20220802092959	9:30:16	Pine, Eastern White	Pinus strobus	Open Space	No	11	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	51	Valley Rd	Front	Valley Rd	199791.14	895021.2	42.30567	-71.5025
1	Greg Baldwin (DRG)	2022/08/18		466	2022/08/02	GrBa20220802103941	10:21:42	Oak, Northern Red	Quercus rubra	Open Space	No	40	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	212	Boston Rd	Side	Valley Rd	200279.12	894229.8	42.29855	-71.4966
1	Greg Baldwin (DRG)	2022/08/18	pole number 21	467	2022/08/02	GrBa20220802083000	11:19:44	Elm, American	Ulmus americana	Wooded Space	No	11	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Minor	Low	Yes	38	Meadow Ln	Side	Valley Rd	199817.71	894970.9	42.30522	-71.5022
1	Greg Baldwin (DRG)	2022/08/02	borderline	473	2022/08/02	GrBa20220802093026	9:31:25	Hickory, Pignut	Carya glabra	Open Space	No	21	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Severe	Low	Yes	51	Valley Rd	Front	Valley Rd	199794.43	895017.9	42.30564	-71.5025
1	Greg Baldwin (DRG)	2022/08/18		476	2022/08/02	GrBa20220802104105	10:21:42	Oak, Northern Red	Quercus rubra	Open Space	No	43	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Medium	Unlikely	Significant	Low	Yes	212	Boston Rd	Side	Valley Rd	200285.41	894223.1	42.29849	-71.4965
1	Greg Baldwin (DRG)	2022/08/18	pole number 21; borderline	477	2022/08/02	GrBa20220802083120	11:19:44	Maple, Red	Acer rubrum	Wooded Space	Yes	8	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	38	Meadow Ln	Side	Valley Rd	199813.83	894975	42.30526	-71.5023
1	Greg Baldwin (DRG)	2022/08/02		481	2022/08/02	GrBa20220802093204	9:32:47	Maple, Red	Acer rubrum	Open Space	No	14	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Minor	Low	Yes	51	Valley Rd	Front	Valley Rd	199795.72	895012.8	42.3056	-71.5025
1	Greg Baldwin (DRG)	2022/08/02	emerald ash borer	486	2022/08/02	GrBa20220802083351	8:35:09	Ash, White	Fraxinus americana	Wooded Space	No	12	Poor	Remove	None	Missing Or Decayed Wood	None	Possible	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Valley Rd	199771.73	895048.6	42.30592	-71.5028
1	Greg Baldwin (DRG)	2022/08/02	borderline	487	2022/08/02	GrBa20220802104334	10:43:55	Maple, Sugar	Acer saccharum	Wooded Space	Yes	9	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Medium	Unlikely	Significant	Low	Yes	6	Valley Rd	Front	Valley Rd	200268.07	894231.8	42.29857	-71.4967
1	Greg Baldwin (DRG)	2022/08/02		494	2022/08/02	GrBa20220802093254	9:33:48	Oak, White	Quercus alba	Open Space	No	23	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	51	Valley Rd	Front	Valley Rd	199795.78	895011.8	42.30559	-71.5025
1	Greg Baldwin (DRG)	2022/08/02		496	2022/08/02	GrBa20220802083630	8:37:00	Oak, Black	Quercus velutina	Wooded Space	No	23	Fair	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Valley Rd	199761.68	895073	42.30614	-71.5029
1	Greg Baldwin (DRG)	2022/08/02		498	2022/08/02	GrBa20220802104404	10:47:46	Oak, Northern Red	Quercus rubra	Open Space	No	39	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	6	Valley Rd	Front	Valley Rd	200261.66	894239.2	42.29863	-71.4968
1	Greg Baldwin (DRG)	2022/08/02	borderline; dbh estimated; poison ivy	504	2022/08/02	GrBa20220802093414	9:35:07	Oak, White	Quercus alba	Open Space	No	24	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	51	Valley Rd	Front	Valley Rd	199797.84	895011.7	42.30559	-71.5025
1	Greg Baldwin (DRG)	2022/08/02	large leader or limb decay	506	2022/08/02	GrBa20220802083750	8:38:41	Ash, White	Fraxinus americana	Wooded Space	Yes	16	Poor	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Valley Rd	199759.33	895080.8	42.30621	-71.5029
1	Greg Baldwin (DRG)	2022/08/02		508	2022/08/02	GrBa20220802104643	10:47:53	Oak, Black	Quercus velutina	Open Space	No	30	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	6	Valley Rd	Front	Valley Rd	200254.49	894247.5	42.29871	-71.4969
1	Greg Baldwin (DRG)	2022/08/02	utility pruned	512	2022/08/02	GrBa20220802093559	9:36:45	Pine, Eastern White	Pinus strobus	Open Space	No	18	Poor	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Minor	Low	Yes	51	Valley Rd	Front	Valley Rd	199798.49	895009	42.30556	-71.5024
1	Greg Baldwin (DRG)	2022/08/02		515	2022/08/02	GrBa20220802104804	10:48:44	Maple, Sugar	Acer saccharum	Open Space	No	14	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	6	Valley Rd	Front	Valley Rd	200250.78	894252.4	42.29875	-71.497
1	Greg Baldwin (DRG)	2022/08/02	pole number 25	516	2022/08/02	GrBa20220802083939	8:51:38	Maple, Red	Acer rubrum	Wooded Space	Yes	14	Fair	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Valley Rd	199758.21	895084.3	42.30624	-71.5029
1	Greg Baldwin (DRG)	2022/08/02	utility pruned	522	2022/08/02	GrBa20220802104932	10:50:25	Maple, Sugar	Acer saccharum	Open Space	No	18	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	6	Valley Rd	Front	Valley Rd	200240.79	894262.6	42.29884	-71.4971
1	Greg Baldwin (DRG)	2022/08/02	borderline	523	2022/08/02	GrBa20220802093700	9:38:07	Oak, Scarlet	Quercus coccinea	Open Space	No	32	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	51	Valley Rd	Front	Valley Rd	199803.84	895002.9	42.30551	-71.5024
1	Greg Baldwin (DRG)	2022/08/02	pole number 25	526	2022/08/02	GrBa20220802084039	8:51:32	Pine, Eastern White	Pinus strobus	Wooded Space	No	11	Good	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Valley Rd	199755.8	895087.3	42.30627	-71.503
1	Greg Baldwin (DRG)	2022/08/02		532	2022/08/02	GrBa20220802093855	9:39:49	Oak, Northern Red	Quercus rubra	Open Space	No	33	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	51	Valley Rd	Front	Valley Rd	199806.19	894999.1	42.30547	-71.5024
1	Greg Baldwin (DRG)	2022/08/02	utility pruned	536	2022/08/02	GrBa20220802105037	10:51:39	Maple, Sugar	Acer saccharum	Open Space	No	25	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	6	Valley Rd	Front	Valley Rd	200229.5	894274.1	42.29895	-71.4972
1	Greg Baldwin (DRG)	2022/08/02	pole number 25	537	2022/08/02	GrBa20220802084158	8:51:21	Corktree, Amur	Phellodendron amurense	Wooded Space	No	11	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Valley Rd	199751.51	895099.2	42.30638	-71.503
1	Greg Baldwin (DRG)	2022/08/02	utility pruned	542	2022/08/02	GrBa20220802093952	9:40:33	Pine, Eastern White	Pinus strobus	Open Space	No	11	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Minor	Low	Yes	51	Valley Rd	Front	Valley Rd	199804.9	894999.4	42.30548	-71.5024
1	Greg Baldwin (DRG)	2022/08/02	pole number 25	546	2022/08/02	GrBa20220802084317	8:51:15	Pine, Eastern White	Pinus strobus	Wooded Space	No	19	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	265	Boston Rd	Side	Valley Rd	199749.69	895104.2	42.30642	-71.503
1	Greg Baldwin (DRG)	2022/08/02	trunk wounds	548	2022/08/02	GrBa20220802105536	10:56:30	Cherry, Black	Prunus serotina	Wooded Space	No	16	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	89	Carriage Hill Cir	Side	Valley Rd	200113.02	894502.8	42.30101	-71.4986
1	Greg Baldwin (DRG)	2022/08/02	utility pruned	551	2022/08/02	GrBa20220802094037	9:41	Pine, Eastern White	Pinus strobus	Open Space	No	9	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Minor	Low	Yes	51	Valley Rd	Front	Valley Rd	199805.78	894997.3	42.30546	-71.5024
1	Greg Baldwin (DRG)	2022/08/02	pole number 26	554	2022/08/02	GrBa20220802084436	8:50:39	Cherry, Black	Prunus serotina	Wooded Space	No	12	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Valley Rd	199743.4	895121.9	42.30658	-71.5031

1	Greg Baldwin (DRG)	2022/08/02	borderline; dbh estimated; poison ivy	558	2022/08/02	GrBa20220802105648	10:58:07	Maple, Sugar	Acer saccharum	Wooded Space	No	8	Poor	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	89	Carriage Hill Cir	Side	Valley Rd	200111.67	894508.8	42.30106	-71.4986
1	Greg Baldwin (DRG)	2022/08/02		561	2022/08/02	GrBa20220802094220	9:42:44	Oak, White	Quercus alba	Open Space	No	20	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Medium	Unlikely	Severe	Low	Yes	51	Valley Rd	Front	Valley Rd	199808.54	894994.8	42.30544	-71.5023
1	Greg Baldwin (DRG)	2022/08/02	pole number 26	566	2022/08/02	GrBa20220802084601	8:50:28	Maple, Red	Acer rubrum	Wooded Space	Yes	11	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Valley Rd	199740.81	895131.8	42.30667	-71.5031
1	Greg Baldwin (DRG)	2022/08/18	pole number 8	571	2022/08/02	GrBa20220802105922	11:29:05	Maple, Sugar	Acer saccharum	Wooded Space	No	31	Poor	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	19	Valley Rd	Front	Valley Rd	200107.9	894524.4	42.3012	-71.4987
1	Greg Baldwin (DRG)	2022/08/02	borderline	572	2022/08/02	GrBa20220802094248	9:43:25	Oak, White	Quercus alba	Open Space	No	12	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Significant	Low	Yes	51	Valley Rd	Front	Valley Rd	199810.31	894993.8	42.30543	-71.5023
1	Greg Baldwin (DRG)	2022/08/02	pole number 26; borderline	576	2022/08/02	GrBa20220802084739	8:50:18	Maple, Red Oak, Northern	Acer rubrum	Wooded Space	Yes	11	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	265	Boston Rd	Side	Valley Rd	199735.05	895142.9	42.30677	-71.5032
1	Greg Baldwin (DRG)	2022/08/02	borderline	581	2022/08/02	GrBa20220802094330	9:45:33	Red	Quercus rubra	Open Space	No	29	Fair	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	51	Valley Rd	Front	Valley Rd	199814.07	894988.5	42.30538	-71.5023
1	Greg Baldwin (DRG)	2022/08/18	borderline; pole number 9	583	2022/08/02	GrBa20220802110052	11:28:09	Maple, Sugar	Acer saccharum	Wooded Space	No	9	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	20	Valley Rd	Front	Valley Rd	200102.08	894545.6	42.30139	-71.4988
1	Greg Baldwin (DRG)	2022/08/02	pole number 26; borderline	586	2022/08/02	GrBa20220802084827	8:50:15	Maple, Red	Acer rubrum	Wooded Space	Yes	15	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Valley Rd	199733.23	895147.4	42.30681	-71.5032
1	Greg Baldwin (DRG)	2022/08/02	borderline	590	2022/08/02	GrBa20220802094650	9:47:44	Aspen, Bigtooth	Populus grandidentata	Open Space	No	13	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	51	Valley Rd	Front	Valley Rd	199819.07	894982.9	42.30533	-71.5022
1	Greg Baldwin (DRG)	2022/08/18	borderline; pole number 9	595	2022/08/02	GrBa20220802110224	11:28:09	Maple, Sugar	Acer saccharum	Wooded Space	No	9	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	20	Valley Rd	Front	Valley Rd	200100.67	894553.1	42.30146	-71.4988
1	Greg Baldwin (DRG)	2022/08/02	pole number 26; borderline	598	2022/08/02	GrBa20220802084900	8:50:10	Maple, Red	Acer rubrum	Wooded Space	Yes	10	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Valley Rd	199732.29	895149.9	42.30683	-71.5032
1	Greg Baldwin (DRG)	2022/08/02		599	2022/08/02	GrBa20220802094748	9:48:19	Hickory, Pignut	Carya glabra	Open Space	No	17	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	Low	Unlikely	Significant	Low	Yes	51	Valley Rd	Front	Valley Rd	199820.71	894980.8	42.30531	-71.5022
1	Greg Baldwin (DRG)	2022/08/18	pole number 9; utility guy line	604	2022/08/02	GrBa20220802110420	11:28:09	Maple, Sugar	Acer saccharum	Wooded Space	No	24	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	Low	Unlikely	Minor	Low	Yes	20	Valley Rd	Front	Valley Rd	200100.08	894560.4	42.30153	-71.4988
1	Greg Baldwin (DRG)	2022/08/02	pole number 27	606	2022/08/02	GrBa20220802085341	8:54:26	Hickory, Pignut	Carya glabra	Wooded Space	No	8	Good	Routine Prune	None	No Significant Defect	Low	Improbable	Medium	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Valley Rd	199727.88	895161.3	42.30693	-71.5033
1	Greg Baldwin (DRG)	2022/08/02		609	2022/08/02	GrBa20220802094829	9:49:11	Oak, White	Quercus alba	Open Space	No	14	Fair	Routine Prune	None	Tree Architecture	Low	Improbable	High	Unlikely	Significant	Low	Yes	51	Valley Rd	Front	Valley Rd	199822.3	894977.2	42.30528	-71.5022
1	Greg Baldwin (DRG)	2022/08/18	pole number 9	613	2022/08/02	GrBa20220802110642	11:28:09	Maple, Sugar	Acer saccharum	Wooded Space	No	17	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Significant	Low	Yes	20	Valley Rd	Front	Valley Rd	200095.44	894573.2	42.30164	-71.4988
1	Greg Baldwin (DRG)	2022/08/02	pole number 27; borderline	615	2022/08/02	GrBa20220802085500	8:55:26	Elm, American	Ulmus americana	Wooded Space	No	10	Poor	Routine Prune	None	Tree Architecture	Low	Possible	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Valley Rd	199729.53	895177	42.30708	-71.5033
1	Greg Baldwin (DRG)	2022/08/02		619	2022/08/02	GrBa20220802094920	9:50:16	Oak, White	Quercus alba	Open Space	No	25	Fair	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Significant	Low	Yes	47	Valley Rd	Front	Valley Rd	199826.06	894973.5	42.30524	-71.5021
1	Greg Baldwin (DRG)	2022/08/18	pole number 9	621	2022/08/02	GrBa20220802110822	11:28:09	Maple, Sugar	Acer saccharum	Wooded Space	No	11	Good	Routine Prune	None	No Significant Defect	Low	Improbable	High	Unlikely	Minor	Low	Yes	20	Valley Rd	Front	Valley Rd	200093.44	894581.5	42.30172	-71.4989
1	Greg Baldwin (DRG)	2022/08/02	pole number 27; borderline	627	2022/08/02	GrBa20220802085553	8:56:13	Oak, Northern Red	Quercus rubra	Wooded Space	No	8	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	265	Boston Rd	Side	Valley Rd	199731.88	895173.7	42.30705	-71.5033
1	Greg Baldwin (DRG)	2022/08/02	pole number 21	628	2022/08/02	GrBa20220802095115	9:51:46	Oak, White	Quercus alba	Wooded Space	No	27	Good	Routine Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Severe	Low	Yes	47	Valley Rd	Front	Valley Rd	199833.06	894965.8	42.30517	-71.502
1	Greg Baldwin (DRG)	2022/08/18	pole number 10; trunk wounds	632	2022/08/02	GrBa20220802111002	11:28:09	Maple, Sugar	Acer saccharum	Wooded Space	No	23	Poor	Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Significant	Low	Yes	20	Valley Rd	Front	Valley Rd	200091.67	894591.2	42.3018	-71.4989
1	Greg Baldwin (DRG)	2022/08/02	pole number 26	637	2022/08/02	GrBa20220802085653	8:57:26	Oak, Northern Red	Quercus rubra	Wooded Space	No	15	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Valley Rd	199739.52	895155.1	42.30688	-71.5032
1	Greg Baldwin (DRG)	2022/08/02	pole number 21	638	2022/08/02	GrBa20220802095223	9:54:59	Oak, White	Quercus alba	Wooded Space	No	17	Fair	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Minor	Low	Yes	47	Valley Rd	Front	Valley Rd	199841.47	894956.6	42.30509	-71.5019
1	Greg Baldwin (DRG)	2022/08/18	pole number 10; borderline	639	2022/08/02	GrBa20220802111125	11:26:22	Maple, Sugar	Acer saccharum	Wooded Space	No	10	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Low	Unlikely	Negligible	Low	Yes	24	Valley Rd	Front	Valley Rd	200088.68	894600	42.30188	-71.4989
1	Greg Baldwin (DRG)	2022/08/02	pole number 26	647	2022/08/02	GrBa20220802085831	8:58:50	Maple, Red Oak, Northern	Acer rubrum	Wooded Space	No	24	Poor	Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Significant	Low	Yes	265	Boston Rd	Side	Valley Rd	199744.17	895141.5	42.30676	-71.5031
1	Greg Baldwin (DRG)	2022/08/02	pole number 21	648	2022/08/02	GrBa20220802095351	9:54:59	Red	Quercus rubra	Wooded Space	Yes	20	Poor	Prune	None	Missing Or Decayed Wood	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	47	Valley Rd	Front	Valley Rd	199843.29	894954.2	42.30507	-71.5019
1	Greg Baldwin (DRG)	2022/08/18	pole number 10	649	2022/08/02	GrBa20220802111256	11:26:22	Maple, Sugar	Acer saccharum	Wooded Space	No	15	Poor	Prune	None	Missing Or Decayed Wood	Low	Improbable	High	Unlikely	Minor	Low	Yes	24	Valley Rd	Front	Valley Rd	200087.68	894603.4	42.30191	-71.4989
1	Greg Baldwin (DRG)	2022/08/18	pole number 10; borderline; crown dieback	657	2022/08/02	GrBa20220802111529	11:26:22	Maple, Sugar	Acer saccharum	Wooded Space	No	10	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	High	Somewhat Likely	Minor	Low	Yes	24	Valley Rd	Front	Valley Rd	200085.56	894611.2	42.30198	-71.499
1	Greg Baldwin (DRG)	2022/08/02	pole number 26	661	2022/08/02	GrBa20220802090119	9:01:47	Maple, Red	Acer rubrum	Wooded Space	Yes	17	Poor	Routine Prune	None	Missing Or Decayed Wood	Low	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Valley Rd	199747.87	895132.3	42.30667	-71.5031
1	Greg Baldwin (DRG)	2022/08/02	pole number 21; borderline	664	2022/08/02	GrBa20220802095501	9:55:24	Hickory, Pignut	Carya glabra	Wooded Space	No	8	Good	Routine Prune	None	Dead And Dying Branches	Low	Possible	Very Low	Unlikely	Negligible	Low	Yes	47	Valley Rd	Front	Valley Rd	199845.35	894954.1	42.30507	-71.5019
1	Greg Baldwin (DRG)	2022/08/18	pole number 10; trunk wounds	667	2022/08/02	GrBa20220802111725	11:26:22	Maple, Sugar	Acer saccharum	Wooded Space	No	11	Good	Routine Prune	None	Weakly Attached Branches And Codominant Stems	Low	Improbable	High	Unlikely	Minor	Low	Yes	24	Valley Rd	Front	Valley Rd	200080.62	894630.3	42.30215	-71.499
1	Greg Baldwin (DRG)	2022/08/18	pole number 26	670	2022/08/02	GrBa20220802090253	13:11:04	Maple, Red	Acer rubrum	Wooded Space	Yes	19	Dead	Remove	None	No Significant Defect	None	Possible	Low	Unlikely	Minor	Low	Yes	265	Boston Rd	Side	Valley Rd	199752.22	895123.6	42.3066	-71.503